



# CESCOM 10 - Aircraft Status Report

Owner: **SBM CLEANING COMPANY LLC**  
 Aircraft Model: **560 - CITATION V**  
 Aircraft Serial: **560-0096** Unit: **0096** Reg No: **N10TD**  
 Airworthiness: **09-Apr-1991**  
 Print Date: **31-Aug-2015 3:12PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>6339.1</b>	<b>5713</b>	<b>25-Aug-2015</b>	<b>.57</b>
<b>ENG 1</b>	<b>6307.4</b>	<b>5661</b>	<b>25-Aug-2015</b>	<b>.57</b>
<b>ENG 2</b>	<b>6307.4</b>	<b>5661</b>	<b>25-Aug-2015</b>	<b>.57</b>

## Maintenance Inspections

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
055601 LEFT	INSPECT WINDSHIELD INSPECTION	SMF			MTH 09-Oct-2014 HRS 6147.1 LDG 5586		24 300		31-Oct-2016 6447.1	14 m 0 d 108
055601 RIGHT	INSPECT WINDSHIELD INSPECTION	SMF			MTH 09-Oct-2014 HRS 6147.1 LDG 5586		24 300		31-Oct-2016 6447.1	14 m 0 d 108
055602 LEFT	INSPECT SIDE WINDOW INSPECTION	SMF			MTH 09-Oct-2014 HRS 6147.1 LDG 5586		24 300		31-Oct-2016 6447.1	14 m 0 d 108
5-12-01 051201	PHASE 1	SMF			MTH 11-Apr-2014 HRS 6043.9 LDG 5528		24 300		30-Apr-2016 6343.9	8 m 0 d 4.8
5-12-02 051202	PHASE 2	SMF			MTH 11-Apr-2014 HRS 6043.9 LDG 5528		24 300		30-Apr-2016 6343.9	8 m 0 d 4.8
5-12-03 051203	PHASE 3	SMF			MTH 29-Jan-2015 HRS 6147.1 LDG 5586		24 300		31-Jan-2017 6447.1	17 m 0 d 108
5-12-04 051204	PHASE 4	SMF			MTH 29-Jan-2015 HRS 6147.1 LDG 5586		24 300		31-Jan-2017 6447.1	17 m 0 d 108
5-12-05 051205	PHASE 5	SMF			MTH 22-May-2015 HRS 6283.9 LDG 5674		36 1200		31-May-2018 7483.9	33 m 0 d 1144.8
5-12-11 051211	PHASE 11	SMF			MTH 22-May-2015 HRS 6283.9 LDG 5674		6		30-Nov-2015	3 m 0 d
5-12-13 051213	PHASE 13	SMF			MTH 07-Jun-2007 HRS 4969		5000		9969	3629.9
5-12-14 051214	PHASE 14	*CF			MTH 09-Apr-1991 HRS 0		12000		12000	5660.9
5-12-15 051215	PHASE 15	*CF			MTH 09-Apr-1991 HRS 0		10000		10000	3660.9
5-12-16 051216	PHASE 16	*CF			MTH 09-Apr-1991 HRS 0		10000		10000	3660.9
5-12-17 051217	PHASE 17	*CF			MTH 09-Apr-1991 HRS 0		10000		10000	3660.9
5-12-18 051218	PHASE 18	SMF			MTH 29-Jan-2015 HRS 6147.1 LDG 5586		12		31-Jan-2016	5 m 0 d
PHASE 56 SHOULD BE ACCOMPLISHED IN CONJUNCTION WITH THE PHASE 18. PHASE 56 ADDED PER REV 21 TO 560 MM. OCTOBER 2005										
A262003 CABIN 051208	INSPECT/WEIGH PORTABLE HALON FIRE EXTINGUISHER : PHASE 18	SMF		GH2-1/2J V461840	MTH 28-Jan-2015		12		31-Jan-2016	5 m 0 d
A262003 COCKPIT 051208	INSPECT/WEIGH PORTABLE HALON FIRE EXTINGUISHER : PHASE 18	SMF		GH2-1/2J V467489	MTH 28-Jan-2015		12		31-Jan-2016	5 m 0 d
5-12-20	PHASE 20	SMF			MTH 09-Sep-2013 HRS 5961.8 LDG 5486		24			
A341012 051220	PERFORM STATIC PORT HEIGHT AND SLOPE CHECK (AIRPLANES -0001 THRU -0259 CERTIFIED FOR RVSM): PHASE 20	SMF			MTH 09-Sep-2013 HRS 5961.8 LDG 5486		24		30-Sep-2015	1 m 0 d



# CESCOM 10 - Aircraft Status Report

Owner: **SBM CLEANING COMPANY LLC**

Aircraft Model: **560 - CITATION V**

Aircraft Serial: **560-0096** Unit: **0096** Reg No: **N10TD**

Airworthiness: **09-Apr-1991**

Print Date: **31-Aug-2015 3:12PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>6339.1</b>	<b>5713</b>	<b>25-Aug-2015</b>	<b>.57</b>
<b>ENG 1</b>	<b>6307.4</b>	<b>5661</b>	<b>25-Aug-2015</b>	<b>.57</b>
<b>ENG 2</b>	<b>6307.4</b>	<b>5661</b>	<b>25-Aug-2015</b>	<b>.57</b>

## Maintenance Inspections

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
B341001 NO. 1 <i>051220 : L-A/S</i>	CALIBRATION TEST AIRSPEED INDICATOR (AIRPLANES -0001 THRU -0259) NOT CERTIFIED FOR RVSM (FAR 91.411): PHASE 20	SMF		C661063-0106 W20628	MTH 03-Sep-2013		24		30-Sep-2015	1 m 0 d
B341001 NO. 2 <i>051220 : R-A/S</i>	CALIBRATION TEST AIRSPEED INDICATOR (AIRPLANES -0001 THRU -0259) NOT CERTIFIED FOR RVSM (FAR 91.411): PHASE 20	SMF		C661063-0106 W27154H	MTH 03-Sep-2013		24		30-Sep-2015	1 m 0 d
B341003 LEFT <i>051220 : L-ALT</i>	CALIBRATION TEST ALTIMETER (91.411): PHASE 20	SMF		4016341-905 90116311	MTH 03-Sep-2013		24		30-Sep-2015	1 m 0 d
B341003 STANDBY <i>051220 : STDBY</i>	CALIBRATION TEST ALTIMETER (91.411): PHASE 20	SMF		570-24929-013 3555	MTH 03-Sep-2013		24		30-Sep-2015	1 m 0 d
B341005 LEFT <i>051220 : L</i>	LEAK TEST STATIC SYSTEM (FAR 91.411) AIRPLANES -0001 THRU -0259 NOT CERTIFIED FOR RVSM: PHASE 20	SMF			MTH 03-Sep-2013		24		30-Sep-2015	1 m 0 d
B341005 RIGHT <i>051220 : R</i>	LEAK TEST STATIC SYSTEM (FAR 91.411) AIRPLANES -0001 THRU -0259 NOT CERTIFIED FOR RVSM: PHASE 20	SMF			MTH 03-Sep-2013		24		30-Sep-2015	1 m 0 d
B341011 NO. 1 <i>051220 : ADC</i>	CALIBRATION TEST AIR DATA COMPUTER (FAR 91.411) AIRPLANES -0001 THRU -0259 CERTIFIED FOR RVSM: PHASE 20	SMF		7024900-30302 04060795	MTH 03-Sep-2013		24		30-Sep-2015	1 m 0 d
B345001 NO. 1 <i>051220 : XPDR1</i>	CALIBRATION TEST ATC TRANSPONDER (FAR 91.413): PHASE 20	SMF		7510774-901 900304483	MTH 03-Sep-2013		24		30-Sep-2015	1 m 0 d
B345001 NO. 2 <i>051220 : XPDR2</i>	CALIBRATION TEST ATC TRANSPONDER (FAR 91.413): PHASE 20	SMF		7510774-901 91120762	MTH 03-Sep-2013		24		30-Sep-2015	1 m 0 d
5-12-21	PHASE 21	SMF			MTH 09-Oct-2014 HRS 6147.1 LDG 5586		24			
A237003 <i>051221 : CVR</i>	INSPECT CVR UNDERWATER LOCATOR BEACON : PHASE 21	SMF		DK100 SC48989	MTH 09-Oct-2014 HRS 6147.1 LDG 5586		24		31-Oct-2016	14 m 0 d
B237004 <i>051221 : CVR</i>	OPERATIONAL TEST CVR UNDERWATER LOCATOR BEACON : PHASE 21	SMF		DK100 SC48989	MTH 09-Oct-2014 HRS 6147.1 LDG 5586		24		31-Oct-2016	14 m 0 d
5-12-28	PHASE 28	SMF			MTH 22-May-2015 HRS 6283.9 LDG 5674		100			
B243002	FUNCTIONAL CHECK MAIN SHIP BATTERY MARATHON NI-CAD BATTERY (CAPACITY CHECK): PHASE 28	SMF		30978-002 11402005	MTH 22-May-2015 HRS 6283.9 LDG 5674		100		6383.9	44.8
5-12-30 <i>051230</i>	PHASE 30	SMF			MTH 09-Oct-2014 HRS 6147.1 LDG 5586		600		6747.1	408
5-12-32 <i>051232</i>	PHASE 32	*CF			MTH 09-Apr-1991 LDG 0		15000		15000	9287
5-12-33 <i>051233</i>	PHASE 33	*CF			MTH 09-Apr-1991 LDG 0		15000		15000	9287
5-12-34 <i>051234</i>	PHASE 34	*CF			MTH 09-Apr-1991 HRS 0		6725		6725	385.9
5-12-48	PHASE 48				MTH 09-Apr-1991		72			

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



# CESCOM 10 - Aircraft Status Report

Owner: **SBM CLEANING COMPANY LLC**

Aircraft Model: **560 - CITATION V**

Aircraft Serial: **560-0096** Unit: **0096** Reg No: **N10TD**

Airworthiness: **09-Apr-1991**

Print Date: **31-Aug-2015 3:12PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>6339.1</b>	<b>5713</b>	<b>25-Aug-2015</b>	<b>.57</b>
<b>ENG 1</b>	<b>6307.4</b>	<b>5661</b>	<b>25-Aug-2015</b>	<b>.57</b>
<b>ENG 2</b>	<b>6307.4</b>	<b>5661</b>	<b>25-Aug-2015</b>	<b>.57</b>

## Maintenance Inspections

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
B262004 CABIN <i>051248 : A</i>	EMPTY/INSPECT/RECHARGE PORTABLE HALON FIRE EXTINGUISHER : PHASE 48	SMF		GH2-1/2J V461840	MTH 09-Jul-2010 HRS 5437.2 LDG 5216		72		31-Jul-2016	11 m 0 d
B262004 COCKPIT <i>051248 : F</i>	EMPTY/INSPECT/RECHARGE PORTABLE HALON FIRE EXTINGUISHER : PHASE 48	SMF		GH2-1/2J V467489	MTH 09-Jul-2010 HRS 5437.2 LDG 5216		72		31-Jul-2016	11 m 0 d
5-12-49 <i>051249</i>	PHASE 49	SMF			MTH 09-Oct-2014 HRS 6147.1 LDG 5586		36 1200		31-Oct-2017 7347.1	26 m 0 d 1008
5-12-54	PHASE 54				MTH HRS		12 600		31-Aug-2015 6695.17	0 d 356.07
5-12-56 <i>051256</i>	PHASE 56	SMF			MTH 09-Oct-2014 HRS 6147.1 LDG 5586		12		31-Oct-2015	2 m 0 d
5-12-59	PHASE 59				MTH 09-Apr-1991 HRS 0 LDG 0		A/R			<b>Over Due</b>
A561004 RIGHT INBOARD	PERFORM CO-PILOTS INNER WINDOW COPILOT SIDE WINDOW INSPECTION : PHASE 59			5511285-6 110104	MTH 09-Apr-1991		A/R			
A561004 RIGHT OUTBOARD	PERFORM CO-PILOTS OUTER WINDOW COPILOT'S SIDE WINDOW INSPECTION : PHASE 59			5511285-78 3705	MTH 09-Apr-1991		A/R			
5-12-60	PHASE 60	SMF			MTH 09-Sep-2013 HRS 5961.8 LDG 5486		500		6461.8	122.7
5-12-61	PHASE 61				MTH 09-Apr-1991 HRS 0		13200		13200	6860.9
5-12-62	PHASE 62				MTH 09-Apr-1991 HRS 0		15600		15600	9260.9
5-12-63	PHASE 63				MTH 09-Apr-1991 HRS 0		15600		15600	9260.9
5-12-64	PHASE 64	SMF			MTH 22-May-2015 HRS 6283.9 LDG 5674		6		30-Nov-2015	3 m 0 d
5-12-65	PHASE 65	SMF			MTH 11-Apr-2014 HRS 6043.9 LDG 5528 ACH 0		500		500	500
5-12-66	PHASE 66				MTH HRS		180 6000		31-Aug-2028 11956.05	156 m 0 d 5616.95
5-12-67	PHASE 67				MTH HRS		10000		10000	3660.9
5-12-MC <i>0512MC</i>	PHASE MC	SMF			MTH 29-Jan-2015 HRS 6147.1 LDG 5586		1456		7603.1	1264
5-12-MD <i>0512MD</i>	PHASE MD	SMF			MTH 17-Nov-2005 HRS 4766		2523		7289	949.9
5-12-ME <i>0512ME</i>	PHASE ME	MHR			MTH 16-Apr-2002 HRS 4056		4450		8506	2166.9
5-12-MF <i>0512MF</i>	PHASE MF	SMF			MTH 17-Nov-2005 HRS 4766		5000		9766	3426.9

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



# CESCOM 10 - Aircraft Status Report

Owner: **SBM CLEANING COMPANY LLC**

Aircraft Model: **560 - CITATION V**

Aircraft Serial: **560-0096** Unit: **0096** Reg No: **N10TD**

Airworthiness: **09-Apr-1991**

Print Date: **31-Aug-2015 3:12PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>6339.1</b>	<b>5713</b>	<b>25-Aug-2015</b>	<b>.57</b>
<b>ENG 1</b>	<b>6307.4</b>	<b>5661</b>	<b>25-Aug-2015</b>	<b>.57</b>
<b>ENG 2</b>	<b>6307.4</b>	<b>5661</b>	<b>25-Aug-2015</b>	<b>.57</b>

## Maintenance Inspections

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
5-12-MG	PHASE MG				MTH 09-Apr-1991 LDG 0		10000			
A325009 0512MG	INSPECT NOSE GEAR FORK/PISTON NOSE LANDING GEAR FORK: PHASE MG	*CF		6642000-3 SN-UNKNOWN	MTH LDG		10000		10000	4287
5-12-MI 0512MI	PHASE MI	SMF			MTH 25-Jun-2008 HRS 5180		5130		10310	3970.9
5-12-MJ 0512MJ	PHASE MJ	ICT			MTH 14-Jun-2013 HRS 5917.1 LDG 5466	-17.1	5900		11800	5460.9
5-12-MK 0512MK	PHASE MK	*CF			MTH 09-Apr-1991 HRS 0		6725		6725	385.9
5-12-ML	PHASE ML	SMF			MTH 11-Apr-2014 HRS 6043.9 LDG 5528		300		6343.9	4.8
057110 E1	MINOR INSPECTION	SMF			MTH 29-Jan-2015 HRS 6147.1 LDG 5586		24 300		31-Jan-2017 (6415.4)6447.1	17 m 0 d 108
057110 E2	MINOR INSPECTION	SMF			MTH 29-Jan-2015 HRS 6147.1 LDG 5586		24 300		31-Jan-2017 (6415.4)6447.1	17 m 0 d 108
129999	INSPECT AIRCRAFT SURVEY	SMF			MTH 31-Mar-2000 HRS 3718		O/C			
215012	REPLACE MOTOR COMPRESSOR DRIVE MOTOR BRUSHES (COMPRESSOR MOTORS P/N 1134104-1, -5 OR FWA1134104-1, -5 ONLY)	SMF		1250150 444	MTH 11-Apr-2014 HRS 6043.9 LDG 5528		N/R			
263005 FORWARD LEFT 262003 : FL	REPLACE (MAX LIFE) CARTRIDGE (SERVICE LIFE)	MHR		873364-1 021632	MTH	84	N/A			
263007 FORWARD RIGHT 262003 : FR	REPLACE (MAX LIFE) CARTRIDGE (SERVICE LIFE)	MHR		873364-1 051485	MTH	84	N/A			
263009 AFT LEFT 262003 : AL	REPLACE (MAX LIFE) CARTRIDGE (SERVICE LIFE)	MHR		873364-1 051474	MTH	84	N/A			
263011 AFT RIGHT 262003 : AR	REPLACE (MAX LIFE) CARTRIDGE (SERVICE LIFE)	MHR		873364-1 041409	MTH	84	N/A			
B262002 AFT 051223 : A	HYDROSTATIC TEST ENGINE FIRE BOTTLE	SMF		898066-2 92793EK	MTH 04-Mar-2011 HRS 5568.6 LDG 5282		60		31-Mar-2016	7 m 0 d
B262002 FORWARD 051223 : F	HYDROSTATIC TEST ENGINE FIRE BOTTLE	SMF		898066-2 92770EK	MTH 04-Mar-2011 HRS 5568.6 LDG 5282		60		31-Mar-2016	7 m 0 d
B262003 CABIN 051247 : A	HYDROSTATIC TEST PORTABLE HALON FIRE EXTINGUISHER	SMF		GH2-1/2J V461840	MTH 06-Sep-2013		144		30-Sep-2025	121 m 0 d
B262003 COCKPIT 051247 : F	HYDROSTATIC TEST PORTABLE HALON FIRE EXTINGUISHER	SMF		GH2-1/2J V467489	MTH 06-Sep-2013		144		30-Sep-2025	121 m 0 d
324201 LEFT	NON DESTRUCTIVE TEST MLG WHEEL ASSEMBLY	SMF		3-1490-1 1677	MTH 22-May-2015 HRS 6283.9 LDG 5674		T/C			

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



# CESCOM 10 - Aircraft Status Report

Owner: **SBM CLEANING COMPANY LLC**

Aircraft Model: **560 - CITATION V**

Aircraft Serial: **560-0096** Unit: **0096** Reg No: **N10TD**

Airworthiness: **09-Apr-1991**

Print Date: **31-Aug-2015 3:12PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>6339.1</b>	<b>5713</b>	<b>25-Aug-2015</b>	<b>.57</b>
<b>ENG 1</b>	<b>6307.4</b>	<b>5661</b>	<b>25-Aug-2015</b>	<b>.57</b>
<b>ENG 2</b>	<b>6307.4</b>	<b>5661</b>	<b>25-Aug-2015</b>	<b>.57</b>

## Maintenance Inspections

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
324201 RIGHT	NON DESTRUCTIVE TEST MLG WHEEL ASSEMBLY	SMF		3-1490-1 1488/3066	MTH 22-May-2015 HRS 6283.9 LDG 5674		T/C			
324202	NON DESTRUCTIVE TEST NOSE WHEEL ASSEMBLY	SMF		3-1418 6630	MTH 22-May-2015 HRS 6283.9 LDG 5674		T/C			
B326003 051222 : GEAR	HYDROSTATIC TEST PNEUMATIC BLOWDOWN/EMERGENCY BRAKE BOTTLE	SMF		212940-2 8392	MTH 27-Jan-2015		36		31-Jan-2018	29 m 0 d
341090 RVSM 051220 : RVSM	CALIBRATION TEST ADC ALTIMETER (91.411)	SMF		70251N02D04 04111502D	MTH 09-Sep-2013 HRS 5961.8 LDG 5486		24		30-Sep-2015	1 m 0 d
350004 051222 : OXY	HYDROSTATIC TEST OXYGEN CYLINDER	SMF		89520077 C06110084	MTH 06-Apr-2014		60		30-Apr-2019	44 m 0 d
710010 E1	OVERHAUL				MTH 23-Jul-1999 HRS 3514		3500		(7086)7014	674.9
710010 E2	OVERHAUL				MTH 23-Jul-1999 HRS 3514		3500		(7086)7014	674.9
710020 E1	HOT SECTION INSPECTION	SMF			MTH 19-Jul-2009 HRS 5308		1800		(7180)7108	768.9
710020 E2	HOT SECTION INSPECTION	SMF			MTH 19-Jul-2009 HRS 5308		1800		(7180)7108	768.9
710030 E1	WASH ENGINE				DAYS 09-Apr-1991		A/R			
710030 E2	WASH ENGINE				DAYS 09-Apr-1991		A/R			
720010 E1	OIL ANALYSIS				MTH 09-Apr-1991		A/R			
720010 E2	OIL ANALYSIS				MTH 09-Apr-1991		A/R			
731025 E1	VISUALLY INSPECT FUEL-OIL COOLER	SMF		11438-001J 551	MTH 11-Apr-2014 HRS 6043.9 LDG 5528		3500		(9512.2)9543.9	3204.8
731025 E2	VISUALLY INSPECT FUEL-OIL COOLER	SMF		11438-001J 513	MTH 11-Apr-2014 HRS 6043.9 LDG 5528		3500		(9512.2)9543.9	3204.8
731035 E1	VISUALLY INSPECT MOTIVE FLOW VALVE			PN SN-UNKNOWN	MTH 09-Apr-1991 HRS 31.7		3500		(7086)7117.7	778.6
731035 E2	VISUALLY INSPECT MOTIVE FLOW VALVE			PN SN-UNKNOWN	MTH 09-Apr-1991 HRS 31.7		3500		(7086)7117.7	778.6
731060 E1	VISUAL INSPECT BLEED VALVE ACTUATOR	SMF		PN SN-UNKNOWN	MTH 29-Jan-2015 HRS 6147.1 LDG 5586		24 300		31-Jan-2017 (6415.4)6447.1	17 m 0 d 108
731060 E2	VISUAL INSPECT BLEED VALVE ACTUATOR	SMF		PN SN-UNKNOWN	MTH 29-Jan-2015 HRS 6147.1 LDG 5586		24 300		31-Jan-2017 (6415.4)6447.1	17 m 0 d 108
731090 E1	VISUALLY INSPECT FLOW DIVIDER VALVE			26395-2 259	MTH 09-Apr-1991 HRS 31.7		3500		(7086)7117.7	778.6
731090 E2	VISUALLY INSPECT FLOW DIVIDER VALVE			26395-2 403	MTH 09-Apr-1991 HRS 31.7		3500		(7086)7117.7	778.6

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



# CESCOM 10 - Aircraft Status Report

Owner: **SBM CLEANING COMPANY LLC**

Aircraft Model: **560 - CITATION V**

Aircraft Serial: **560-0096** Unit: **0096** Reg No: **N10TD**

Airworthiness: **09-Apr-1991**

Print Date: **31-Aug-2015 3:12PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>6339.1</b>	<b>5713</b>	<b>25-Aug-2015</b>	<b>.57</b>
<b>ENG 1</b>	<b>6307.4</b>	<b>5661</b>	<b>25-Aug-2015</b>	<b>.57</b>
<b>ENG 2</b>	<b>6307.4</b>	<b>5661</b>	<b>25-Aug-2015</b>	<b>.57</b>

## Maintenance Inspections

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
732050 E1	VISUAL INSPECT ELECTRONIC BLEED VALVE CONTROL	SMF		PN SN-UNKNOWN	MTH 29-Jan-2015 HRS 6147.1 LDG 5586		24 300		31-Jan-2017 (6415.4)6447.1	17 m 0 d 108
732050 E2	VISUAL INSPECT ELECTRONIC BLEED VALVE CONTROL	SMF		PN SN-UNKNOWN	MTH 29-Jan-2015 HRS 6147.1 LDG 5586		24 300		31-Jan-2017 (6415.4)6447.1	17 m 0 d 108
732060 E1	VISUAL INSPECT MAIN WIRING HARNESS	SMF		PN SN-UNKNOWN	MTH 29-Jan-2015 HRS 6147.1 LDG 5586		24 300		31-Jan-2017 (6415.4)6447.1	17 m 0 d 108
732060 E2	VISUAL INSPECT MAIN WIRING HARNESS	SMF		PN SN-UNKNOWN	MTH 29-Jan-2015 HRS 6147.1 LDG 5586		24 300		31-Jan-2017 (6415.4)6447.1	17 m 0 d 108
741030 E1 INBOARD	VISUAL INSPECT IGNITION EXCITER	SMF		NB01201 R5948	MTH 29-Jan-2015 HRS 6147.1 LDG 5586		24 300		31-Jan-2017 (6415.4)6447.1	17 m 0 d 108
741030 E1 OUTBOARD	VISUAL INSPECT IGNITION EXCITER	SMF		NB01201 R5958	MTH 29-Jan-2015 HRS 6147.1 LDG 5586		24 300		31-Jan-2017 (6415.4)6447.1	17 m 0 d 108
741030 E2 INBOARD	VISUAL INSPECT IGNITION EXCITER	SMF		305013 682	MTH 29-Jan-2015 HRS 6147.1 LDG 5586		24 300		31-Jan-2017 (6415.4)6447.1	17 m 0 d 108
741030 E2 OUTBOARD	VISUAL INSPECT IGNITION EXCITER	SMF		CH92028 01030791	MTH 29-Jan-2015 HRS 6147.1 LDG 5586		24 300		31-Jan-2017 (6415.4)6447.1	17 m 0 d 108
792010 E1	CHANGE OIL	SMF			MTH 09-Jul-2010 HRS 5437.2 LDG 5216		O/C			
792010 E2	CHANGE OIL	SMF			MTH 09-Jul-2010 HRS 5437.2 LDG 5216		O/C			



# CESCOM 10 - Aircraft Status Report

Owner: **SBM CLEANING COMPANY LLC**

Aircraft Model: **560 - CITATION V**

Aircraft Serial: **560-0096** Unit: **0096** Reg No: **N10TD**

Airworthiness: **09-Apr-1991**

Print Date: **31-Aug-2015 3:12PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>6339.1</b>	<b>5713</b>	<b>25-Aug-2015</b>	<b>.57</b>
<b>ENG 1</b>	<b>6307.4</b>	<b>5661</b>	<b>25-Aug-2015</b>	<b>.57</b>
<b>ENG 2</b>	<b>6307.4</b>	<b>5661</b>	<b>25-Aug-2015</b>	<b>.57</b>

## Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
211002	EMERGENCY PRESSURE VALVE *CF			27441482-06 10AF76	MTH 09-Apr-1991		O/C			
211004	S243 PRIMARY PRESSURE SWITCH SMF			1103P240-1 1536	MTH 07-Jun-2007 HRS 4969		O/C	0		
211005	S244 SECONDARY PRESSURE SWITCH *CF			1103P240-2 SN-UNKNOWN	MTH 09-Apr-1991		O/C			
211006	THERMAL ACTUATOR ASSEMBLY LGB			56CD1660-9-8/13 SN-UNKNOWN	MTH 01-Dec-1996 HRS 2692		O/C	0		
212001	INSTRUMENT PANEL FAN *CF			4124X SN-UNKNOWN	MTH 09-Apr-1991		O/C			
212002	AVIONICS BAY COOLING BOX FAN *CF			032105 SN-UNKNOWN	MTH 09-Apr-1991		O/C			
212004	OVERHEAD CABIN FAN 9912323-2	SMF		BC61A901-2 1390A	MTH 14-Jun-2014 HRS 6078.3 LDG 5548		1000	0	7078.3	739.2
212006	COCKPIT DEFOGGER FAN SMF			5703-4 241	MTH 06-Jul-1997 HRS 2844		3500	0	8886.72	2547.62
212009	FLOW DIVIDER CABIN UNDERFLOOR ACTUATOR *CF			NYLC50466 951	MTH 09-Apr-1991		O/C			
212010	AVIONICS BAY VANE AXIAL BLOWER *CF			19A827 SN-UNKNOWN	MTH 09-Apr-1991		O/C			
212011	TEMP DUCT SENSOR 9912085-3	*CF		27221274 SN-UNKNOWN	MTH 09-Apr-1991		O/C			
213001	CABIN PRESSURE INDICATOR 3001J50	*CF		C668511-0103 19209	MTH 09-Apr-1991		O/C			
213003	RATE OF CHANGE INDICATOR 35060-1128	*CF		C668513-0101 W27144H	MTH 09-Apr-1991		O/C			
213006	CABIN ALTITUDE CONTROLLER LGB			130620-2 12A0002	MTH 27-Jan-1996 HRS 2409		O/C	0		
213007 NO. 1	PRIMARY OUTFLOW VALVE *CF			103648-14 119323	MTH 09-Apr-1991		O/C			
213007 NO. 2	SECONDARY OUTFLOW VALVE *CF			103648-14 119298	MTH 09-Apr-1991		O/C			
213009 NO. 1	FLOW CONTROL PRESSURE REGULATOR VALVE 9912162-1	*CF		34E16-4 9900255	MTH 09-Apr-1991		O/C			
213009 NO. 2	FLOW CONTROL PRESSURE REGULATOR VALVE 9912162-1	*CF		34E16-4 7900290	MTH 09-Apr-1991		O/C			
213013	PNEUMATIC RELAY *CF			130358-1 501793	MTH 09-Apr-1991		O/C			

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.





# CESCOM 10 - Aircraft Status Report

Owner: **SBM CLEANING COMPANY LLC**  
 Aircraft Model: **560 - CITATION V**  
 Aircraft Serial: **560-0096** Unit: **0096** Reg No: **N10TD**  
 Airworthiness: **09-Apr-1991**  
 Print Date: **31-Aug-2015 3:12PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>6339.1</b>	<b>5713</b>	<b>25-Aug-2015</b>	<b>.57</b>
<b>ENG 1</b>	<b>6307.4</b>	<b>5661</b>	<b>25-Aug-2015</b>	<b>.57</b>
<b>ENG 2</b>	<b>6307.4</b>	<b>5661</b>	<b>25-Aug-2015</b>	<b>.57</b>

## Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
215001	ACM REFRIGERATOR PACKAGE ASSEMBLY 9912069-26	*CF		782343-2 900720	MTH 09-Apr-1991		O/C			
215004	AIR CYCLE MACHINE	SMF		738384-26 9906214	MTH 07-Jun-2007 HRS 4969		5000	0	9969	3629.9
RECOMMENDED ECONOMIC OVERHAUL PERIOD DEFINED BY HAMILTON STANDARD.										
215005	ACM BYPASS VALVE	PIT		754751-2 85102495	MTH 24-Jan-2000 HRS 3695		O/C	0		
215007	COMPRESSION ACTUATOR 9912294-1	*CF		BYLB50907 SN-UNKNOWN	MTH 09-Apr-1991		O/C			
215008	DUCT OVERHEAT SENSOR *CF			1173T42-1 SN-UNKNOWN	MTH 09-Apr-1991		O/C			
215009	ACM OVERHEAT SWITCH TOL			1173T0396 324	MTH 17-Dec-1992 HRS 1119		O/C	0		
215016	AC COMPRESSOR SMF			1134160 2084	MTH 19-Mar-2012 HRS 5725.6 LDG 5363		O/C	0 0		
215017	AC CONDENSER *CF			1250180-7 916	MTH 09-Apr-1991		O/C			
215021	MOTOR *CF			1250150 444	MTH 09-Apr-1991		O/C			
215022	AFT EVAPORATOR *CF			1250240-3 379	MTH 09-Apr-1991		O/C			
215023	FWD EVAPORATOR *CF			1250240-1 373	MTH 09-Apr-1991		O/C			
215024	PRESSURE SWITCH SMF			1250232-4 10742	MTH 11-Apr-2014 HRS 6043.9 LDG 5528		O/C			
215026	FREON A/C-HOBBS METER SMF			1250703-3 NSN	MTH 11-Apr-2014 HRS 6043.9 LDG 5528		O/C	0 0 0		
216001	CABIN TEMPERATURE SENSOR TOL			1942T100-3 174A	MTH 25-Feb-1993 HRS 1203		O/C	0		
216002	CABIN TEMPERATURE CONTROLLER 9912069-22	SAC		754661-5 97064929	MTH 28-Jun-2004 HRS 4560		O/C	0		
216003	DUCT TEMPERATURE SENSOR 9912069-14	SMF		754691-3 N0032	MTH 07-Jun-2007 HRS 4969		O/C	0		
216005	CENTRIFUGAL BLOWER *CF			3A1003-10 SN-UNKNOWN	MTH 09-Apr-1991		O/C			
216010	DOOR ACTUATOR MOTOR ASSEMBLY 9910059-3	*CF		5A3032 SN-UNKNOWN	MTH 09-Apr-1991		O/C			





# CESCOM 10 - Aircraft Status Report

Owner: **SBM CLEANING COMPANY LLC**

Aircraft Model: **560 - CITATION V**

Aircraft Serial: **560-0096** Unit: **0096** Reg No: **N10TD**

Airworthiness: **09-Apr-1991**

Print Date: **31-Aug-2015 3:12PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>6339.1</b>	<b>5713</b>	<b>25-Aug-2015</b>	<b>.57</b>
<b>ENG 1</b>	<b>6307.4</b>	<b>5661</b>	<b>25-Aug-2015</b>	<b>.57</b>
<b>ENG 2</b>	<b>6307.4</b>	<b>5661</b>	<b>25-Aug-2015</b>	<b>.57</b>

## Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
217001	WATER SEPARATOR 9912069-13	*CF		738386-3 900718	MTH 09-Apr-1991		O/C			
221001 NO. 1	ROLL RATE MONITOR RZ-220	*CF		4015901-920 89121729	MTH 09-Apr-1991		O/C			
221001 NO. 2	ROLL RATE MONITOR RZ-220	*CF		4015901-920 91011824	MTH 09-Apr-1991		O/C			
221008	AUTOPILOT COMPUTER SP-200	*CF		4008519-952 90064435	MTH 09-Apr-1991		O/C			
221009	AUTOPILOT CONTROL PC-500	*CF		4018639-933 90103366	MTH 09-Apr-1991		O/C			
221010 AILERON	SERVO SM-200	*CF		4006719-906 90105129	MTH 09-Apr-1991		O/C			
221010 ELEVATOR	SERVO SM-200	TOL		4006719-914 80126454	MTH 05-Jun-1998 HRS 3159		O/C	412		
221010 RUDDER	SERVO SM-200	*CF		4006719-906 90105138	MTH 09-Apr-1991		O/C			
221011 ELEVATOR	SERVO-BRACKET --	SMF		4005842 04016890	MTH 06-Feb-2009 HRS 5261		O/C	0		
232001 NO. 3	VHF COMM ANTENNA			VF10-347 3967	MTH 23-May-2012 HRS 5743.2 LDG 5371		O/C	0	0	0
232002 NO. 2	VHF COMM ANTENNA 9912084-1	*CF		VF10-108-1 1803	MTH 09-Apr-1991		O/C			
232003 NO. 1	VHF COMM ANTENNA	*CF		VFS10-90-5 2558	MTH 09-Apr-1991		O/C			
232004	TRANSCEIVER PHONE	PIT		724855-801 940	MTH 21-Jan-1999 HRS 3391		O/C	0		
232005 CABIN	HANDSET PHONE	LNK		725729-815 GH51445	MTH 17-Jul-1996 HRS 2553		O/C	0		
232006 COCKPIT	HANDSET PHONE	LNK		725729-815 MX22419	MTH 17-Jul-1996 HRS 2553		O/C	0		
232008 NO. 1	VHF INTEGRATED CONTROL UNIT RCZ-850	KALN		7510700-901 900905501	MTH 23-May-2012 HRS 5743.2 LDG 5371		O/C			
232008 NO. 2	VHF INTEGRATED CONTROL UNIT RCZ-850	KALN		7510700-901 90010436	MTH 23-May-2012 HRS 5743.2 LDG 5371		O/C			
232010 NO. 1	VHF COMMUNICATION TRANSCEIVER TR-850	TOL		7510764-901 89110421	MTH 30-Sep-1992 HRS 983		O/C	0		
232010 NO. 2	VHF COMMUNICATION TRANSCEIVER TR-850	LBE		7510764-901 SN-UNKNOWN	MTH 18-Apr-1991 HRS 29		O/C	0		

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



# CESCOM 10 - Aircraft Status Report

Owner: **SBM CLEANING COMPANY LLC**

Aircraft Model: **560 - CITATION V**

Aircraft Serial: **560-0096** Unit: **0096** Reg No: **N10TD**

Airworthiness: **09-Apr-1991**

Print Date: **31-Aug-2015 3:12PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>6339.1</b>	<b>5713</b>	<b>25-Aug-2015</b>	<b>.57</b>
<b>ENG 1</b>	<b>6307.4</b>	<b>5661</b>	<b>25-Aug-2015</b>	<b>.57</b>
<b>ENG 2</b>	<b>6307.4</b>	<b>5661</b>	<b>25-Aug-2015</b>	<b>.57</b>

## Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
232013 NO. 1	COMM CLUSTER MODULE XC-850	TOL		7510784-901 89120443	MTH 30-Sep-1992 HRS 983		O/C	0		
232013 NO. 2	COMM CLUSTER MODULE XC-850	LBE		7510784-901 SN-UNKNOWN	MTH 18-Apr-1991 HRS 29		O/C	0		
232018	CDBR REPEATER	LNK		724864-801 1285	MTH 17-Jul-1996 HRS 2553		O/C	0		
232019	MAGNASTAR DUPLEXER	LNK		620317-1 ZM048	MTH 17-Jul-1996 HRS 2553		O/C	0		
232020	CABIN ALERTER SWITCH	LNK		725256-801 MSL0507	MTH 17-Jul-1996 HRS 2553		O/C	0		
235001 NO. 1	AUDIO AMPLIFIER AV-850A	TOL		7511001-915 90090298	MTH 06-Nov-1992 HRS 1057		O/C	0		
235001 NO. 2	AUDIO AMPLIFIER AV-850A	TOL		7511001-915 90090301	MTH 06-Nov-1992 HRS 1057		O/C	0		
237001	COCKPIT VOICE RECORDER GA-100	SMF		GA100-0000 1179	MTH 09-Feb-2007 HRS 4922		O/C	4445		
237006	CVR UNDERWATER LOCATOR BEACON	SMF		DK100 SC48989	MTH 09-Jul-2010 HRS 5437.2 LDG 5216		72	9	31-Oct-2015	2 m 0 d
242001 NO. 1	STATIC INVERTER	ICT		SPC38B 2018	MTH 21-May-2008 HRS 5163		O/C	957		
242001 NO. 2	STATIC INVERTER	ICT		SPC38B 2234	MTH 21-May-2008 HRS 5163		O/C	3210		
243001 LEFT	STARTER/GENERATOR 9912125-3	SMF		23085-004-1 96112	MTH 04-Mar-2011 HRS 5568.6 LDG 5282		1000	0	6568.6	229.5
243001 RIGHT	STARTER/GENERATOR 9912125-3	SMF		23085-004-1 94100	MTH 04-Mar-2011 HRS 5568.6 LDG 5282		1000	0	6568.6	229.5
243003 NO. 1	GENERATOR CONTROL UNIT 9912039-6	MCC		51539-006F 2457AB	MTH 04-Mar-2005 HRS 4661		O/C	0		
243003 NO. 2	GENERATOR CONTROL UNIT 9912039-6	*CF		51539-006F 8364AB	MTH 09-Apr-1991		O/C			
243004 NO. 1	AMMETER	*CF		C662501-0104 528	MTH 09-Apr-1991		O/C			
243004 NO. 2	AMMETER	*CF		C662501-0104 532	MTH 09-Apr-1991		O/C			
243005	DC VOLTMETER	*CF		C662502-0101 1739	MTH 09-Apr-1991		O/C			
243007	MAIN SHIP BATTERY 9914058-6 / ATSP-44	SMF		30978-002 11402005	MTH 09-Oct-2014 HRS 6147.1 LDG 5586		O/C	0 0		

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



## CESCOM 10 - Aircraft Status Report

Owner: **SBM CLEANING COMPANY LLC**  
 Aircraft Model: **560 - CITATION V**  
 Aircraft Serial: **560-0096** Unit: **0096** Reg No: **N10TD**  
 Airworthiness: **09-Apr-1991**  
 Print Date: **31-Aug-2015 3:12PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>6339.1</b>	<b>5713</b>	<b>25-Aug-2015</b>	<b>.57</b>
<b>ENG 1</b>	<b>6307.4</b>	<b>5661</b>	<b>25-Aug-2015</b>	<b>.57</b>
<b>ENG 2</b>	<b>6307.4</b>	<b>5661</b>	<b>25-Aug-2015</b>	<b>.57</b>

### Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
243008	BATTERY TEMP MONITOR	*CF		1529-1 1913	MTH 09-Apr-1991		O/C			
243009	BATTERY TEMP GAGE	*CF		1229-1 1635	MTH 09-Apr-1991		O/C			
243010	BATTERY TEMP SENSOR	*CF		1166-1 SN-UNKNOWN	MTH 09-Apr-1991		O/C			
243011	CURRENT/VOLTAGE CONTROLLER TOL			1301-1 447A	MTH 06-Jul-1997 HRS 2844		O/C	0		
243015	BATTERY DISCONNECT RELAY TOL			A876K CJ82764	MTH 06-Nov-1992 HRS 1057		O/C	0		
243016	CURRENT/VOLTAGE SENSOR LGB			1302-1 378	MTH 28-Aug-1995 HRS 2247		O/C	0		
245002	CABIN ALTITUDE SWITCH 9910095-6	*CF		GB300NA161 8940892	MTH 09-Apr-1991		O/C			
256002	EMERGENCY LOCATOR TRANSMITTER *CF			3000-1 321459	MTH 09-Apr-1991		O/C			
256003	EMERGENCY LOCATOR TRANSMITTER BEACON BATTERY 2020BATTERY	SMF		2020 -NSN-	MTH 09-Oct-2014 HRS 6147.1 LDG 5586		24	0	30-Sep-2016	13 m 0 d
Expiration Date: 30-Sep-2016										
256004 NO. 1	ELT ANTENNA	*CF		ELT10-177-1 920	MTH 09-Apr-1991		O/C			
256004 NO. 2	ELT ANTENNA	*CF		ELT10-177-2 590	MTH 09-Apr-1991		O/C			
261001 NO. 1 ENGINE	FIRE DETECTOR SENSOR 9912036-3	*CF		244-18882 SN-UNKNOWN	MTH 09-Apr-1991		O/C			
261001 NO. 2 ENGINE	FIRE DETECTOR SENSOR 9912036-3	*CF		244-18882 SN-UNKNOWN	MTH 09-Apr-1991		O/C			
261002 NO. 1	FIRE DETECTOR CONTROL 9912036-2	*CF		377-02808 9035013	MTH 09-Apr-1991		O/C			
261002 NO. 2	FIRE DETECTOR CONTROL 9912036-2	*CF		377-02808 9035007	MTH 09-Apr-1991		O/C			
262001 AFT	ENGINE FIRE BOTTLE 9912048-3	*CF		898066-2 92793EK	MTH 09-Apr-1991		O/C	0		
262001 FORWARD	ENGINE FIRE BOTTLE 9912048-3	*CF		898066-2 92770EK	MTH 09-Apr-1991		O/C	0		
262002 CABIN	PORTABLE HALON FIRE EXTINGUISHER SMF			GH2-1/2J V461840	MTH 25-Jun-2001 HRS 3926		O/C	118		



# CESCOM 10 - Aircraft Status Report

Owner: **SBM CLEANING COMPANY LLC**  
 Aircraft Model: **560 - CITATION V**  
 Aircraft Serial: **560-0096** Unit: **0096** Reg No: **N10TD**  
 Airworthiness: **09-Apr-1991**  
 Print Date: **31-Aug-2015 3:12PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>6339.1</b>	<b>5713</b>	<b>25-Aug-2015</b>	<b>.57</b>
<b>ENG 1</b>	<b>6307.4</b>	<b>5661</b>	<b>25-Aug-2015</b>	<b>.57</b>
<b>ENG 2</b>	<b>6307.4</b>	<b>5661</b>	<b>25-Aug-2015</b>	<b>.57</b>

## Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
262002 COCKPIT	PORTABLE HALON FIRE EXTINGUISHER	SMF		GH2-1/2J V467489	MTH 25-Jun-2001 HRS 3926		O/C	118		
262003 AFT LEFT	(MAX LIFE) CARTRIDGE	SMF		873364-1 051474	MTH 09-Jul-2010 HRS 5437.2 LDG 5216		120		30-Sep-2017	25 m 0 d
Manufacture Date: 30-Sep-2007										
262003 AFT RIGHT	(MAX LIFE) CARTRIDGE	SMF		873364-1 041409	MTH 09-Jul-2010 HRS 5437.2 LDG 5216		120		30-Jun-2017	22 m 0 d
Manufacture Date: 30-Jun-2007										
262003 FORWARD LEFT	(MAX LIFE) CARTRIDGE	SMF		873364-1 021632	MTH 09-Jul-2010 HRS 5437.2 LDG 5216		120		31-Aug-2018	36 m 0 d
Manufacture Date: 31-Aug-2008										
262003 FORWARD RIGHT	(MAX LIFE) CARTRIDGE	SMF		873364-1 051485	MTH 09-Jul-2010 HRS 5437.2 LDG 5216		120		30-Sep-2017	25 m 0 d
Manufacture Date: 30-Sep-2007										
271001	AILERON TRIM ACTUATOR	*CF		5565450-72 SN-UNKNOWN	MTH 09-Apr-1991		O/C			
272001	RUDDER TRIM ACTUATOR	*CF		5565450-71 SN-UNKNOWN	MTH 09-Apr-1991		O/C			
273002	TRIM MIXER ACTUATOR	SMF		1U662-001 T361	MTH 11-Apr-2014 HRS 6043.9 LDG 5528		O/C			
273003 LEFT	ELEVATOR TRIM ACTUATOR			5565450-81 SN-UNKNOWN	MTH 07-Nov-1997 HRS 2948		O/C	0		
273003 RIGHT	ELEVATOR TRIM ACTUATOR	*CF		5565450-82 SN-UNKNOWN	MTH 09-Apr-1991		O/C			
275001	FLAP CONTROL VALVE	*CF		66720 654	MTH 09-Apr-1991		O/C			
275003 NO. 1	FLAP ACTUATOR	SMF		1535000-3 2748	MTH 06-Feb-2009 HRS 5261		O/C	0		
275003 NO. 2	FLAP ACTUATOR	*CF		55800-1 681	MTH 09-Apr-1991		O/C			
275004 LEFT WING LEFT INBOARD	AFT FLAP ROLLER	SMF		CC50380 NSN	MTH 25-Jun-2008 HRS 5180 LDG 5051		5000	0	10051	4338
275004 LEFT WING LEFT OUTBOARD	AFT FLAP ROLLER	SMF		CC50380 NSN	MTH 25-Jun-2008 HRS 5180 LDG 5051		5000	0	10051	4338
275004 LEFT WING RIGHT INBOARD	AFT FLAP ROLLER	SMF		CC50380 -NSN-	MTH 17-Nov-2005 HRS 4766 LDG 4735		5000	0	9735	4022
275004 LEFT WING RIGHT OUTBOARD	AFT FLAP ROLLER	SMF		CC50380 -NSN-	MTH 17-Nov-2005 HRS 4766 LDG 4735		5000	0	9735	4022



## CESCOM 10 - Aircraft Status Report

Owner: **SBM CLEANING COMPANY LLC**

Aircraft Model: **560 - CITATION V**

Aircraft Serial: **560-0096** Unit: **0096** Reg No: **N10TD**

Airworthiness: **09-Apr-1991**

Print Date: **31-Aug-2015 3:12PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>6339.1</b>	<b>5713</b>	<b>25-Aug-2015</b>	<b>.57</b>
<b>ENG 1</b>	<b>6307.4</b>	<b>5661</b>	<b>25-Aug-2015</b>	<b>.57</b>
<b>ENG 2</b>	<b>6307.4</b>	<b>5661</b>	<b>25-Aug-2015</b>	<b>.57</b>

### Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
275004 RIGHT WING LEFT INBOARD	AFT FLAP ROLLER	SMF		CC50380 NSN	MTH 25-Jun-2008 HRS 5180 LDG 5051		5000	0	10051	4338
275004 RIGHT WING LEFT OUTBOARD	AFT FLAP ROLLER	SMF		CC50380 NSN	MTH 25-Jun-2008 HRS 5180 LDG 5051		5000	0	10051	4338
275004 RIGHT WING RIGHT INBOARD	AFT FLAP ROLLER	SMF		CC50380 NSN	MTH 25-Jun-2008 HRS 5180 LDG 5051		5000	0	10051	4338
275004 RIGHT WING RIGHT OUTBOARD	AFT FLAP ROLLER	SMF		CC50380 NSN	MTH 25-Jun-2008 HRS 5180 LDG 5051		5000	0	10051	4338
276001 NO. 1	SPEED BRAKE ACTUATOR 9912344-1	*CF		55850-1 297	MTH 09-Apr-1991		O/C			
276001 NO. 2	SPEED BRAKE ACTUATOR 9912344-1	*CF		55850-1 286	MTH 09-Apr-1991		O/C			
276002	SPEED BRAKE FLAP CONTROL VALVE *CF			66720 687	MTH 09-Apr-1991		O/C			
276003	SAFETY SPDBK VALVE *CF			68930 169	MTH 09-Apr-1991		O/C			
282001 NO. 1	ELECTRIC FUEL BOOST PUMP 9912017-2	*CF		1C7-12 8AF122	MTH 09-Apr-1991		O/C			
282001 NO. 2	ELECTRIC FUEL BOOST PUMP 9912017-2	*CF		1C7-12 8AF119	MTH 09-Apr-1991		O/C			
282002 NO. 1	MOTOR ACTUATOR VALVE *CF			AV24B1325C N77639	MTH 09-Apr-1991		O/C			
282002 NO. 2	MOTOR ACTUATOR VALVE *CF			AV24B1325C N77625	MTH 09-Apr-1991		O/C			
282010 LEFT	MOTIVE FUEL VALVE	PIT		3244850 B28224	MTH 23-Jul-1999 HRS 3514		O/C	0		
282010 RIGHT	MOTIVE FUEL VALVE	PIT		3244850 B28191	MTH 23-Jul-1999 HRS 3514		O/C	0		
284001 NO. 1	FUEL LOW LEVEL SWITCH *CF			L15H-3 SN-UNKNOWN	MTH 09-Apr-1991		O/C			
284001 NO. 2	FUEL LOW LEVEL SWITCH SMF			L15H-3 7141	MTH 06-Feb-2009 HRS 5261		O/C	0		
284002 LEFT	FUEL QTY COMPENSATOR 9912019-4	SMF		300047-13001 16460T	MTH 19-Jul-2013 HRS 5941 LDG 5476		O/C			
284002 RIGHT	FUEL QTY COMPENSATOR 9912019-4	SMF		300047-13001 16235T	MTH 19-Jul-2013 HRS 5941 LDG 5476		O/C			
284007	FUEL QTY INDICATOR 9912147-26	TOL		VSDL-OC403F-1 273X	MTH 14-Mar-1999 HRS 3430		O/C	3430		

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



# CESCOM 10 - Aircraft Status Report

Owner: **SBM CLEANING COMPANY LLC**

Aircraft Model: **560 - CITATION V**

Aircraft Serial: **560-0096** Unit: **0096** Reg No: **N10TD**

Airworthiness: **09-Apr-1991**

Print Date: **31-Aug-2015 3:12PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>6339.1</b>	<b>5713</b>	<b>25-Aug-2015</b>	<b>.57</b>
<b>ENG 1</b>	<b>6307.4</b>	<b>5661</b>	<b>25-Aug-2015</b>	<b>.57</b>
<b>ENG 2</b>	<b>6307.4</b>	<b>5661</b>	<b>25-Aug-2015</b>	<b>.57</b>

## Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
291001	MAIN HYD RESERVOIR 9912052-12	TOL		40500-7 1	MTH 09-Jan-1998 HRS 2999		O/C	0		
291002 LEFT	HYDRAULIC PUMP 9912062-4	MHR		24195-LAA 3751	MTH 15-Apr-2002 HRS 4056		O/C	0		
291002 RIGHT	HYDRAULIC PUMP 9912062-4	VNY		24195-LAA 1642	MTH 13-Feb-1996 HRS 2430		O/C	0		
291005 NO. 1	CK VALVE HYDRAULIC FLOW SWITCH 9912194-3	*CF		3520020100-4 2924	MTH 09-Apr-1991		O/C			
291005 NO. 2	CK VALVE HYDRAULIC FLOW SWITCH 9912194-3	*CF		3520020100-4 2681	MTH 09-Apr-1991		O/C			
291008	THERMAL RELIEF VALVE *CF			20900-1 1435	MTH 09-Apr-1991		O/C			
291009	PRESSURE RELIEF VALVE TOL			4614 207A	MTH 26-Oct-1999 HRS 3608		O/C	0		
291012	SOLENOID BYPASS VALVE *CF			61510-1 847A	MTH 09-Apr-1991		O/C			
301001 LEFT	TEMP CONTROL SL002 SWITCH *CF			1173T42-3 SN-UNKNOWN	MTH 09-Apr-1991		O/C			
301001 NO. 1	OUTBRD WING DEICE BOOT KALN			P35-5D5230-01 NAF3740	MTH 23-May-2012 HRS 5743.2 LDG 5371		O/C	0		0
SL560-57-01 IS MANDATORY AND NEEDS TO BE INCORPORATED WHEN DE-ICE BOOTS ARE REMOVED.										
301001 NO. 2	OUTBRD WING DEICE BOOT KALN			P35-5D5230-02 NAC4210	MTH 23-May-2012 HRS 5743.2 LDG 5371		O/C	0		0
SL560-57-01 IS MANDATORY AND NEEDS TO BE INCORPORATED WHEN DE-ICE BOOTS ARE REMOVED.										
301001 RIGHT	TEMP CONTROL SR002 SWITCH *CF			1173T42-3 SN-UNKNOWN	MTH 09-Apr-1991		O/C			
301001 WING	ANTI-ICE BLEED AIR CROSSFLOW ISOLATION VALVE 9914121-1	*CF		320495 SN-UNKNOWN	MTH 09-Apr-1991		O/C			
301002 NO. 1	HORIZONTAL STABILIZER DEICE BOOT SMF			P29S-5D5225-05 NCJ6440	MTH 22-May-2015 HRS 6283.9 LDG 5674		O/C	0		0
301002 NO. 2	HORIZONTAL STABILIZER DEICE BOOT LNK			29S-5D5225-04 M493270	MTH 19-Jul-1996 HRS 2553		O/C	0		0
301003	SURFACE DEICE TIMER *CF			878 41	MTH 09-Apr-1991		O/C			
301004 LEFT WING	ANTI-ICE BLEED AIR PRESSURE REG SHUTOFF VT001 VLV 9912086-4	TOL G		67410-2 2469	MTH 06-Jul-1997 HRS 2844		O/C	0		
301004 RIGHT WING	ANTI-ICE BLEED AIR PRESSURE REG SHUTOFF VT002 VLV 9912086-4	*CF		67410-2 1340	MTH 09-Apr-1991		O/C			

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



## CESCOM 10 - Aircraft Status Report

Owner: **SBM CLEANING COMPANY LLC**

Aircraft Model: **560 - CITATION V**

Aircraft Serial: **560-0096** Unit: **0096** Reg No: **N10TD**

Airworthiness: **09-Apr-1991**

Print Date: **31-Aug-2015 3:12PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>6339.1</b>	<b>5713</b>	<b>25-Aug-2015</b>	<b>.57</b>
<b>ENG 1</b>	<b>6307.4</b>	<b>5661</b>	<b>25-Aug-2015</b>	<b>.57</b>
<b>ENG 2</b>	<b>6307.4</b>	<b>5661</b>	<b>25-Aug-2015</b>	<b>.57</b>

### Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
301007 LEFT	RAM AIR MODULATING TEMP CONTROL VLV 9912362-1	*CF		27441500-01 10AF85	MTH 09-Apr-1991		O/C			
301007 RIGHT	RAM AIR MODULATING TEMP CONTROL VLV 9912362-1	*CF		27441500-01 10AF83	MTH 09-Apr-1991		O/C			
301008 LEFT	DEICE CONTROL SLV19 VLV 9912362-1	*CF		3D2353-06 SN-UNKNOWN	MTH 09-Apr-1991		O/C			
301008 RIGHT	DEICE CONTROL SLV18 VLV 9912362-1	SMF		3D2353-06 N084687	MTH 04-Mar-2011 HRS 5568.6 LDG 5282		O/C	0	0	
301009 LEFT	TEMP CONTROL S95 SENSOR 9912362-3	TOL		27431501-04 4AH64	MTH 29-May-1992 HRS 759		O/C		0	
301009 RIGHT	TEMP CONTROL S94 SENSOR 9912362-3	TOL		27431501-04 4AH56	MTH 29-May-1992 HRS 759		O/C		0	
302003 LEFT ENGINE	ANTI-ICE SOLENOID VLV 9912086-7	LGB		67410-1 1573AE	MTH 06-Apr-1994 HRS 1794		O/C		0	
302003 RIGHT ENGINE	ANTI-ICE SOLENOID VLV 9912086-7	PIT G		67410-1 811	MTH 22-Sep-1999 HRS 3575		O/C		0	
302004 LEFT ENGINE	INLET TEMPERATURE S95 SWITCH 9912086-7	SMF		M1002-505 000154	MTH 19-Mar-2012 HRS 5725.6 LDG 5363		O/C	0	0	
302004 RIGHT ENGINE	INLET TEMPERATURE S94 SWITCH 9912086-7	*CF		21548-2-19-6 SN-UNKNOWN	MTH 09-Apr-1991		O/C			
302005 LEFT	ANTI ICING VALVE 3033057	SMF		10018200C 454	MTH 22-May-2015 HRS 6283.9 LDG 5674		O/C		2769.9	
302005 RIGHT	ANTI ICING VALVE 3033057	SMF		10018200C 486	MTH 22-May-2015 HRS 6283.9 LDG 5674		O/C		2769.9	
302006 LEFT	BLEED VALVE ACTUATOR 3037074	PIT		800888-1 F20552	MTH 23-Jul-1999 HRS 3514		O/C		0	
302006 RIGHT	BLEED VALVE ACTUATOR 3037074	PIT		800888-1 F16153	MTH 23-Jul-1999 HRS 3514		O/C		0	
303001 LEFT	PITOT TUBE 303001	*CF		PH502 SN-UNKNOWN	MTH 09-Apr-1991		O/C			
303001 RIGHT	PITOT TUBE 303001	*CF		PH502 SN-UNKNOWN	MTH 09-Apr-1991		O/C			
304001	BLEED AIR MONITOR 304001	*CF		1169-1 1379	MTH 09-Apr-1991		O/C			
304002	ANTI-ICE BLEED AIR WNDSHLD HEAT EXCHANGER 9912041-4	*CF		10663A 527	MTH 09-Apr-1991		O/C			
304004	ALCOHOL WINDSHIELD ANTI-ICE PUMP 304004	*CF		476411 SN-UNKNOWN	MTH 09-Apr-1991		O/C			

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.





# CESCOM 10 - Aircraft Status Report

Owner: **SBM CLEANING COMPANY LLC**

Aircraft Model: **560 - CITATION V**

Aircraft Serial: **560-0096** Unit: **0096** Reg No: **N10TD**

Airworthiness: **09-Apr-1991**

Print Date: **31-Aug-2015 3:12PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>6339.1</b>	<b>5713</b>	<b>25-Aug-2015</b>	<b>.57</b>
<b>ENG 1</b>	<b>6307.4</b>	<b>5661</b>	<b>25-Aug-2015</b>	<b>.57</b>
<b>ENG 2</b>	<b>6307.4</b>	<b>5661</b>	<b>25-Aug-2015</b>	<b>.57</b>

## Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
304005	TEMP CONTROL VALVE 9912085-1	*CF		27241287 8AF94	MTH 09-Apr-1991		O/C			
304006	ANTI-ICE BLEED AIR WNDSHLD TEMP XMTR26 SENSOR 9912085-2	*CF		27231272-10 8AF80	MTH 09-Apr-1991		O/C			
304007	ANTI-ICE BLEED AIR WNDSHLD HEAT EXCHANGER PRESS S130 SWITCH 9912085-2	*CF		1115P25 SN-UNKNOWN	MTH 09-Apr-1991		O/C			
304009	WINDSHIELD ANTI-ICE BLEED AIR CONTROL VALVE 9912086-4	SMF		67410-2 3693	MTH 06-Feb-2009 HRS 5261		O/C	0		
312001 COPILOT	DIGITAL CLOCK	*CF		M877A5V 3358	MTH 09-Apr-1991		O/C			
312001 PILOT	DIGITAL CLOCK	*CF		M877A5V 3370	MTH 09-Apr-1991		O/C			
313001	FLIGHT HOUR RECORDER 85071	ICT		C664503-0104 NSN	MTH 16-Sep-2008 HRS 5233		O/C	0		
313003 NO. 1	ACCELEROMETER AG-222	*CF		7000992 5993	MTH 09-Apr-1991		O/C			
313003 NO. 2	ACCELEROMETER AG-222	*CF		7000992 6058	MTH 09-Apr-1991		O/C			
315001	MASTER WARNING ANNUNCIATOR 9912119-14	*CF		465-1-14 269	MTH 09-Apr-1991		O/C			
321001 LEFT	MAIN LANDING GEAR ASSEMBLY	*CF		6641000-15 25	MTH 09-Apr-1991 LDG 0		12450	0	12450	6737
321002 RIGHT	MAIN LANDING GEAR ASSEMBLY	*CF		6641000-16 25	MTH 09-Apr-1991 LDG 0		12450	0	12450	6737
321003 LEFT MAIN LANDING GEAR	TORQUE LINK BOLT	*CF		5541220-2 SN-UNKNOWN	MTH 09-Apr-1991 LDG 0		10370	0	10370	4657
321003 RIGHT MAIN LANDING GEAR	TORQUE LINK BOLT	*CF		5541220-2 SN-UNKNOWN	MTH 09-Apr-1991 LDG 0		10370	0	10370	4657
322001	NOSE LANDING GEAR ASSEMBLY	*CF		6642000-10 8	MTH 09-Apr-1991 LDG 0		23500	0	23500	17787
322002	NOSE SHIMMY DAMPER	PIT		5543001-8 3878	MTH 15-Nov-1999 HRS 3629 LDG 3890		O/C	0		
322004	NOSE GEAR FORK/PISTON	SMF		6642000-3 SN-UNKNOWN	MTH 19-Mar-2012 HRS 5725.6 LDG 5363		13640	5725.6 5363	13640	7927
323001 LEFT	MAIN LANDING GEAR ACTUATOR 9912111-1	*CF		1523100-3 194	MTH 09-Apr-1991 LDG 0		15000	0	15000	9287
323002 RIGHT	MAIN LANDING GEAR ACTUATOR 9912111-2	TOL		1523100-4 203B	MTH 30-Jun-1999 HRS 3497 LDG 3725		15000	3365	15360	9647

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



# CESCOM 10 - Aircraft Status Report

Owner: **SBM CLEANING COMPANY LLC**

Aircraft Model: **560 - CITATION V**

Aircraft Serial: **560-0096** Unit: **0096** Reg No: **N10TD**

Airworthiness: **09-Apr-1991**

Print Date: **31-Aug-2015 3:12PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>6339.1</b>	<b>5713</b>	<b>25-Aug-2015</b>	<b>.57</b>
<b>ENG 1</b>	<b>6307.4</b>	<b>5661</b>	<b>25-Aug-2015</b>	<b>.57</b>
<b>ENG 2</b>	<b>6307.4</b>	<b>5661</b>	<b>25-Aug-2015</b>	<b>.57</b>

## Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
323003	NOSE LANDING GEAR ACTUATOR 9912120-4	SMF		1523200-9 1773	MTH 06-Feb-2009 HRS 5261 LDG 5111		15000	0	20111	14398
323004 LEFT	MLG UPLOCK ACTUATOR	TOL		5527504-2 WMP1117	MTH 25-Feb-1993 HRS 1203 LDG 1309		O/C	0		
323004 NOSE	UPLOCK ACTUATOR	*CF		5527504-2 772	MTH 09-Apr-1991		O/C			
323004 RIGHT	MLG UPLOCK ACTUATOR	LGB		5527504-2 1567	MTH 28-Aug-1995 HRS 2247 LDG 2402		O/C	0		
323006	PNEUMATIC BLOWDOWN/EMERGENCY BRAKE BOTTLE 9912103-3	SMF		212940-2 8392	MTH 29-Jan-2015 HRS 6147.1 LDG 5586		288		31-Jan-2039	281 m 0 d
Manufacture Date: 27-Jan-2015										
323007	LANDING GEAR CONTROL VALVE *CF			66710 358	MTH 09-Apr-1991		O/C			
323008	DUMP VALVE *CF			AS19400-1 1632	MTH 09-Apr-1991		O/C			
323019	EMERGENCY AIR BOTTLE GAUGE *CF			2341128 20550D	MTH 09-Apr-1991		O/C	0		
324001 LEFT	MLG WHEEL ASSEMBLY 9912222-11	SMF		3-1490-1 1677	MTH 22-May-2015 HRS 6283.9 LDG 5674		O/C		2796	
324001 RIGHT	MLG WHEEL ASSEMBLY 9912222-11	SMF		3-1490-1 1488/3066	MTH 22-May-2015 HRS 6283.9 LDG 5674		O/C			
324002	NOSE WHEEL ASSEMBLY 9914069-2	SMF		3-1418 6630	MTH 22-May-2015 HRS 6283.9 LDG 5674		O/C			
324003 LEFT	MLG BRAKE ASSEMBLY 9912222-17	SMF		2-1529-7 1217	MTH 23-Jul-2007 HRS 4984 LDG 4910		O/C	0		
324004 RIGHT	MLG BRAKE ASSEMBLY 9912222-17	SMF		2-1529-7 3268	MTH 23-Jul-2007 HRS 4984 LDG 4910		O/C	0		
324005 LEFT	MLG TIRE	SMF		220K28-1 41132985	MTH 22-May-2015 HRS 6283.9 LDG 5674		O/C	0	0	0
324005 RIGHT	MLG TIRE	SMF		220K28-1 42843029	MTH 22-May-2015 HRS 6283.9 LDG 5674		O/C	0	0	0
324006	NOSE TIRE 9914070-1	SMF		031-613-8 4343S00457	MTH 22-May-2015 HRS 6283.9 LDG 5674		O/C	0	0	0
324010 LEFT	MLG SHUTTLE VALVE *CF			195-183 328R	MTH 09-Apr-1991		O/C			
324010 RIGHT	MLG SHUTTLE VALVE *CF			195-183 413R	MTH 09-Apr-1991		O/C			



# CESCOM 10 - Aircraft Status Report

Owner: **SBM CLEANING COMPANY LLC**

Aircraft Model: **560 - CITATION V**

Aircraft Serial: **560-0096** Unit: **0096** Reg No: **N10TD**

Airworthiness: **09-Apr-1991**

Print Date: **31-Aug-2015 3:12PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>6339.1</b>	<b>5713</b>	<b>25-Aug-2015</b>	<b>.57</b>
<b>ENG 1</b>	<b>6307.4</b>	<b>5661</b>	<b>25-Aug-2015</b>	<b>.57</b>
<b>ENG 2</b>	<b>6307.4</b>	<b>5661</b>	<b>25-Aug-2015</b>	<b>.57</b>

## Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
324011 LEFT	MLG INBOARD BRAKE MASTER CYLINDER 9912050-11	*CF		95367-9 345	MTH 09-Apr-1991		O/C			
324011 RIGHT	MLG INBOARD BRAKE MASTER CYLINDER 9912050-11	*CF		95367-9 359	MTH 09-Apr-1991		O/C			
324012 LEFT	MLG OUTBOARD MASTER BRAKE CYLINDER 9912050-12	*CF		95367-10 338	MTH 09-Apr-1991		O/C			
324012 RIGHT	MLG OUTBOARD MASTER BRAKE CYLINDER 9912050-12	*CF		95367-10 363	MTH 09-Apr-1991		O/C			
324014	EMERGENCY AIR BRAKE VALVE SMF			895232-0875 V1232	MTH 06-Feb-2009 HRS 5261		O/C	0		
324019	BRAKE PRESS PUMP ASSEMBLY 9912166-2	*CF		634343 202242	MTH 09-Apr-1991		O/C			
324021	POWER BRAKE ANTISKID VALVE 9912305-7	*CF		38-707-1 564	MTH 09-Apr-1991		O/C			
324022	BRAKE CONTROL BOX 9912305-6	TOL		42-707-1 232A	MTH 06-Jul-1997 HRS 2844		O/C	0		
324023	ANTISKID ACCUMULATOR *CF			57C57652 RH0499	MTH 09-Apr-1991		O/C			
324024 LEFT	MLG WHEEL TRANSDUCER 9912305-2	*CF		40-955 2394	MTH 09-Apr-1991		O/C			
324024 RIGHT	MLG WHEEL TRANSDUCER 9912305-2	*CF		40-955 2384	MTH 09-Apr-1991		O/C			
324025	PRESSURE SWITCH 9912163-1	SMF		1206P25 3463	MTH 03-Mar-2013 HRS 5873.7 LDG 5439		O/C	0 0		
324026	POWER BRAKE ASSEMBLY MOTOR *CF			30-2 2022	MTH 09-Apr-1991		O/C			
324101	PARKING BRAKE VALVE 9914263-1	*CF		20800-6 1448	MTH 09-Apr-1991		O/C			
325001	NOSE STEERING BUNGEE ASSEMBLY *CF			5565624-19 SN-UNKNOWN	MTH 09-Apr-1991		O/C			
326003 LEFT	MAIN GEAR DOWN & LOCK SWITCH TOL			1EN118-6 SN-UNKNOWN	MTH 03-Sep-1993 HRS 1503 LDG 1634		O/C	0		
326003 RIGHT	MAIN GEAR DOWN & LOCK SWITCH TOL			1EN118-6 SN-UNKNOWN	MTH 03-Sep-1993 HRS 1503 LDG 1634		O/C	0		
326003	NOSE GEAR DOWN & LOCK SWITCH TOL			1EN118-6 SN-UNKNOWN	MTH 03-Sep-1993 HRS 1503 LDG 1634		O/C	0		
326005 LEFT	MAIN GEAR UP & LOCKED SWITCH *CF			65-430087 SN-UNKNOWN	MTH 09-Apr-1991		O/C			

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



# CESCOM 10 - Aircraft Status Report

Owner: **SBM CLEANING COMPANY LLC**

Aircraft Model: **560 - CITATION V**

Aircraft Serial: **560-0096** Unit: **0096** Reg No: **N10TD**

Airworthiness: **09-Apr-1991**

Print Date: **31-Aug-2015 3:12PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>6339.1</b>	<b>5713</b>	<b>25-Aug-2015</b>	<b>.57</b>
<b>ENG 1</b>	<b>6307.4</b>	<b>5661</b>	<b>25-Aug-2015</b>	<b>.57</b>
<b>ENG 2</b>	<b>6307.4</b>	<b>5661</b>	<b>25-Aug-2015</b>	<b>.57</b>

## Components

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains
Position	Drawing # / Task #	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
326005 RIGHT	MAIN GEAR UP & LOCKED SWITCH *CF	65-430087 SN-UNKNOWN	MTH 09-Apr-1991		O/C			
326005	NOSE GEAR UP & LOCKED SWITCH *CF	65-430087 SN-UNKNOWN	MTH 09-Apr-1991		O/C			
331001 NO. 1	LIGHT PANEL DIMMER *CF	1821-1 1453	MTH 09-Apr-1991		O/C			
331001 NO. 2	LIGHT PANEL DIMMER *CF	1821-1 1391	MTH 09-Apr-1991		O/C			
331001 NO. 3	LIGHT PANEL DIMMER *CF	1821-1 1434	MTH 09-Apr-1991		O/C			
331011	INVT-115V EL PANEL *CF	EM2044-1 1354	MTH 09-Apr-1991		O/C			
332002 AFT	INDIRECT LIGHTING INVERTER *CF	18.996 6516	MTH 09-Apr-1991		O/C			
332002 FORWARD	INDIRECT LIGHTING INVERTER TOL	18.994 2656	MTH 06-Jul-1997 HRS 2844		O/C	0		
334002	ROTATING/FLASHING BEACON SMF	30-2140-5 2539	MTH 22-May-2015 HRS 6283.9 LDG 5674		O/C	0 0 0		
334003 NO. 1	STROBE POWER SUPPLY 9910368-2 *CF	60-2799-1 15587	MTH 09-Apr-1991		O/C			
334003 NO. 2	STROBE POWER SUPPLY 9910368-2 *CF	60-2799-1 15592	MTH 09-Apr-1991		O/C			
335001	EMERGENCY BATTERY PACK LGB	41B0202BA01301 SN-UNKNOWN	MTH 10-Sep-1994 HRS 1953		O/C	0		
341001 NO. 1	AIRSPEED INDICATOR 20240-11323 LGB	C661063-0106 W20628	MTH 23-Nov-1994 HRS 2030		O/C	0		
341001 NO. 2	AIRSPEED INDICATOR 20240-11323 SMF	C661063-0106 W27154H	MTH 29-Aug-2007 HRS 5018		O/C	0		
341005	S262 MACH/AIRSPEED WARNING SWITCH 9912076-13 SMF	D2RA45C-27 249	MTH 07-Jun-2007 HRS 4969		O/C	0		
341006	PITOT PRESSURE SWITCH SMF	D45C31 115	MTH 19-Jul-2009 HRS 5308		O/C	0		
341008 RVSM	ADC ALTIMETER SMF	70251N02D04 04111502D	MTH 20-Apr-2005 HRS 4685		O/C	0		
341010	ANGLE OF ATTACK INDICATOR *CF	C11605-1 178	MTH 09-Apr-1991		O/C			
341011	ANGLE OF ATTACK STALL WARNING COMPUTER TOL	C11606-8 316	MTH 05-Jun-1998 HRS 3159		O/C	0		

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



## CESCOM 10 - Aircraft Status Report

Owner: **SBM CLEANING COMPANY LLC**  
 Aircraft Model: **560 - CITATION V**  
 Aircraft Serial: **560-0096** Unit: **0096** Reg No: **N10TD**  
 Airworthiness: **09-Apr-1991**  
 Print Date: **31-Aug-2015 3:12PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>6339.1</b>	<b>5713</b>	<b>25-Aug-2015</b>	<b>.57</b>
<b>ENG 1</b>	<b>6307.4</b>	<b>5661</b>	<b>25-Aug-2015</b>	<b>.57</b>
<b>ENG 2</b>	<b>6307.4</b>	<b>5661</b>	<b>25-Aug-2015</b>	<b>.57</b>

### Components

Item Code	Description	City	Mod Lvl	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains
Position	Drawing # / Task #			Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
341013	ANGLE OF ATTACK TRANSMITTER	*CF		1703-15 191	MTH 09-Apr-1991		O/C			
341015 PILOT	RADIO ALTIMETER ALT-55B INDICATOR ALI-55	*CF		622-2937-009 2578	MTH 09-Apr-1991		O/C			
341019 LEFT	ALTIMETER BA-141	SMF		4016341-905 90116311	MTH 19-Jul-2009 HRS 5308		O/C	0		
341019 STANDBY	ALTIMETER	SMF		570-24929-013 3555	MTH 20-Apr-2005 HRS 4685		O/C	451		
341020	VNAV CONTROL VN-800	SMF		7000472-901 04031312	MTH 20-Apr-2005 HRS 4685		O/C	0		
341022 341025	OAT INDICATOR 162BL507D	KALN		C668510-0401 296	MTH 23-May-2012 HRS 5743.2 LDG 5371		O/C			
341035	ANGLE OF ATTACK HEAT MONITOR	*CF		1703-147-1 168	MTH 09-Apr-1991		O/C			
342001	MAGNETIC COMPASS	SMF		C660501-0301 NSN	MTH 22-May-2015 HRS 6283.9 LDG 5674		O/C	0 0 0		
342021 NO. 1	VERTICAL SPEED INDICATOR	*CF		C661006-0101 W27796H	MTH 09-Apr-1991		O/C			
342021 NO. 2	VERTICAL SPEED INDICATOR 30260-1117	*CF		C661006-0101 W27800H	MTH 09-Apr-1991		O/C			
342023	RADAR CONTROLLER WC-870	*CF		7008471-801 90061029	MTH 09-Apr-1991		O/C			
342041 NO. 1	FLIGHT DIRECTOR COMPUTER FZ-500	SMF		4018369-905 91016320	MTH 28-Apr-2005 HRS 4685		O/C	2528		
342041 NO. 2	FLIGHT DIRECTOR COMPUTER FZ-500	SMF		4018369-905 90106229	MTH 28-Apr-2005 HRS 4685		O/C	2528		
342042 NO. 1	MODE FLIGHT DIRECTOR SELECTOR MS-205	*CF		4020570-905 90091891	MTH 09-Apr-1991		O/C			
342042 NO. 2	MODE FLIGHT DIRECTOR SELECTOR MS-205	TOL		4020570-905 91102059	MTH 25-Feb-1993 HRS 1203		O/C	0		
342043 NO. 1	VERTICAL FLIGHT DIRECTOR GYRO VG-14A	VNY		7000622-901 81093521	MTH 23-Aug-1996 HRS 2605		O/C	115		
342043 NO. 2	VERTICAL FLIGHT DIRECTOR GYRO VG-14A	LGB		7000622-901 91016765	MTH 29-Jan-1996 HRS 2409		O/C	2409		
342044 NO. 1	RATE OF TURN GYRO RG-204	*CF		7007453-903 90102580	MTH 09-Apr-1991		O/C			
342044 NO. 2	RATE OF TURN GYRO RG-204	LGB		7007453-903 93043349	MTH 06-Apr-1994 HRS 1794		O/C	0		

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



## CESCOM 10 - Aircraft Status Report

Owner: **SBM CLEANING COMPANY LLC**

Aircraft Model: **560 - CITATION V**

Aircraft Serial: **560-0096** Unit: **0096** Reg No: **N10TD**

Airworthiness: **09-Apr-1991**

Print Date: **31-Aug-2015 3:12PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>6339.1</b>	<b>5713</b>	<b>25-Aug-2015</b>	<b>.57</b>
<b>ENG 1</b>	<b>6307.4</b>	<b>5661</b>	<b>25-Aug-2015</b>	<b>.57</b>
<b>ENG 2</b>	<b>6307.4</b>	<b>5661</b>	<b>25-Aug-2015</b>	<b>.57</b>

### Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
342048 NO. 1	AIR DATA COMPUTER AZ-252	SMF		7024900-30302 04060795	MTH 20-Apr-2005 HRS 4685		O/C	0		
342049 NO. 1	DIRECTIONAL GYRO C-14D	ICT		4020577-3 85103701	MTH 21-May-2008 HRS 5163		O/C	4524		
342049 NO. 2	DIRECTIONAL GYRO C-14D	ICT		4020577-3 90084691	MTH 21-May-2008 HRS 5163		O/C	2001		
342050 NO. 1	FLUX DETECTOR FX-220	SMF		2594484 80104102	MTH 22-May-2015 HRS 6283.9 LDG 5674		O/C	5 0 0		
342050 NO. 2	FLUX DETECTOR FX-220	SMF		2594484 98042790	MTH 22-May-2015 HRS 6283.9 LDG 5674		O/C	1 0 0		
342052	REMOTE COMPENSATOR CS-412	*CF		2593379-1 90080224	MTH 09-Apr-1991		O/C			
342063 NO. 1	REMOTE COURSE CONTROL RI-206S	*CF		4026206-974 90114353	MTH 09-Apr-1991		O/C			
342064 STANDBY	GYRO POWER SUPPLY PS-835C	SMF		501-1228-03 1639	MTH 20-Apr-2005 HRS 4685		O/C	0 4685		
342065	STANDBY GYRO AI-804	*CF		501-1197-05 4146	MTH 09-Apr-1991		O/C			
342066 LEFT BOTTOM	EFIS DISPLAY ED-600	*CF		7003430-901 90091932	MTH 09-Apr-1991		O/C			
342066 LEFT TOP	EFIS DISPLAY ED-600	LGB		7003430-901 86040686	MTH 01-Dec-1996 HRS 2692		O/C	0		
342066 MFD 1	EFIS DISPLAY ED-600	MCC		7003430-901 93073157	MTH 24-Feb-2009 HRS 5262		O/C	1537		
342066 RIGHT BOTTOM	EFIS DISPLAY ED-600	SMF		7003430-901 90091940	MTH 22-May-2015 HRS 6283.9 LDG 5674		O/C			
342066 RIGHT TOP	EFIS DISPLAY ED-600	SMF		7003430-901 91012072	MTH 22-May-2015 HRS 6283.9 LDG 5674		O/C	6283.9 5674		
342068 NO. 1	(EFIS) CONTROLLER DISPLAY DC-811	*CF		7012977-753 90090691	MTH 09-Apr-1991		O/C			
342068 NO. 2	(EFIS) CONTROLLER DISPLAY DC-811	*CF		7012977-753 91020850	MTH 09-Apr-1991		O/C			
342069 NO. 1	INCLINOMETER AY-03	*CF		7005400-901 SN-UNKNOWN	MTH 09-Apr-1991		O/C			
342069	MULTIFUNCTION DISPLAY CONTROLLER MC-800	*CF		7007062-933 90110882	MTH 09-Apr-1991		O/C			
342070 NO. 1	EFIS SYMBOL GENERATOR SG-605	LBE		7011672-606 90040415	MTH 18-Dec-1991 HRS 521		O/C	0		

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



## CESCOM 10 - Aircraft Status Report

Owner: **SBM CLEANING COMPANY LLC**  
 Aircraft Model: **560 - CITATION V**  
 Aircraft Serial: **560-0096** Unit: **0096** Reg No: **N10TD**  
 Airworthiness: **09-Apr-1991**  
 Print Date: **31-Aug-2015 3:12PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>6339.1</b>	<b>5713</b>	<b>25-Aug-2015</b>	<b>.57</b>
<b>ENG 1</b>	<b>6307.4</b>	<b>5661</b>	<b>25-Aug-2015</b>	<b>.57</b>
<b>ENG 2</b>	<b>6307.4</b>	<b>5661</b>	<b>25-Aug-2015</b>	<b>.57</b>

### Components

Item Code	Description	City	Mod Lvl	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains
Position	Drawing # / Task #			Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
342070 NO. 2	EFIS SYMBOL GENERATOR SG-605	LBE		7011672-606 90120655	MTH 09-May-1991 HRS 79		O/C		0	
342071	MFD SYMBOL GENERATOR MG-605	PIT		7011673-606 90100264	MTH 03-Nov-1998 HRS 3343		O/C		3343	
342072	STATIC CONVERTER	*CF		501-1318-01 3221	MTH 09-Apr-1991		O/C			
344003	PRIMUS 650 RADAR RECEIVER/TRANSMITTER WU-870	SMF		7012640-921 97021584	MTH 11-Apr-2014 HRS 6043.9 LDG 5528		O/C			
344006	LIGHTING ANTENNA AT-855	*CF		7014062-901 90080204	MTH 09-Apr-1991		O/C			
344007	LIGHTING DETECT PROCESSOR LP-850	*CF		7011822-903 90060423	MTH 09-Apr-1991		O/C			
344021 NO. 1	RADIO MAGNETIC INDICATOR RMI-36	TOL		622-2506-008 1075	MTH 21-Aug-1991 HRS 293		O/C		0	
344021 NO. 2	RADIO MAGNETIC INDICATOR RMI-36	*CF		622-2506-008 7065	MTH 09-Apr-1991		O/C			
344022	RADIO ALT TRANSCEIVER ALT-55B	*CF		622-2855-001 7429	MTH 09-Apr-1991		O/C			
344023 AFT	RECEIVER RADIO ALT ANTENNA	*CF		622-0954-001 4613	MTH 09-Apr-1991		O/C			
344023 FORWARD	TRANSMITTER RADIO ALT ANTENNA	*CF		622-0954-001 4116	MTH 09-Apr-1991		O/C			
345004 AFT	TRANSPONDER ANTENNA 85226	*CF		DMNI50-2-2 44546	MTH 09-Apr-1991		O/C			
345004 FORWARD	TRANSPONDER ANTENNA 85226	*CF		DMNI50-2-2 44537	MTH 09-Apr-1991		O/C			
345007 AFT	DME ANTENNA 85226	*CF		DMNI50-2-2 44512	MTH 09-Apr-1991		O/C			
345007 FORWARD	DME ANTENNA 85226	*CF		DMNI50-2-2 44524	MTH 09-Apr-1991		O/C			
345010 NO. 1	NAVIGATION ANTENNA	*CF		DMN4-17-1B 35038	MTH 09-Apr-1991		O/C			
345013	NAV 2 INDICATOR KI-206	*CF		066-03034-0024 19374	MTH 09-Apr-1991		O/C			
345014 NO. 1	ADF ANTENNA AT-860	SMF		7510300-901 0703C399	MTH 07-Jun-2007 HRS 4969		O/C		0	
345017	MARKER BEACON ANTENNA	*CF		CI164 SN-UNKNOWN	MTH 09-Apr-1991		O/C			

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.





# CESCOM 10 - Aircraft Status Report

Owner: **SBM CLEANING COMPANY LLC**

Aircraft Model: **560 - CITATION V**

Aircraft Serial: **560-0096** Unit: **0096** Reg No: **N10TD**

Airworthiness: **09-Apr-1991**

Print Date: **31-Aug-2015 3:12PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>6339.1</b>	<b>5713</b>	<b>25-Aug-2015</b>	<b>.57</b>
<b>ENG 1</b>	<b>6307.4</b>	<b>5661</b>	<b>25-Aug-2015</b>	<b>.57</b>
<b>ENG 2</b>	<b>6307.4</b>	<b>5661</b>	<b>25-Aug-2015</b>	<b>.57</b>

## Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
345018	GLIDESLOPE ANTENNA	*CF		RGS10-48 A1895	MTH 09-Apr-1991		O/C			
345027 NO. 1	NAV MODULE NV-850	*CF		7510134-901 90070511	MTH 09-Apr-1991		O/C			
345027 NO. 2	NAV MODULE NV-850	*CF		7510134-901 90080542	MTH 09-Apr-1991		O/C			
345028 NO. 1	ADF MODULE DF-850	TOL		7510114-901 92030802	MTH 06-Nov-1992 HRS 1057		O/C	0		
345029 NO. 1	NAV CLUSTER MODULE XN-850	*CF		7510164-902 90020492	MTH 09-Apr-1991		O/C			
345029 NO. 2	NAV CLUSTER MODULE XN-850	*CF		7510164-902 90070585	MTH 09-Apr-1991		O/C			
345030	CLEARANCE DELIVERY CONTROL CD-850	SMF		7513000-811 442	MTH 09-Sep-2013 HRS 5961.8 LDG 5486		O/C			
345031	NAVIGATION(FMS) COMPUTER SAC			1192-00-111101 137	MTH 09-Dec-2002 HRS 4231		O/C	1615		
345034 NO. 1	ATC TRANSPONDER XS-850	KALN		7510774-901 900304483	MTH 23-May-2012 HRS 5743.2 LDG 5371		O/C			
345034 NO. 2	ATC TRANSPONDER XS-850	KALN		7510774-901 91120762	MTH 23-May-2012 HRS 5743.2 LDG 5371		O/C			
345035 NO. 1	DME INDICATOR DI-851	*CF		7513006-911 596	MTH 09-Apr-1991		O/C			
345035 NO. 2	DME INDICATOR DI-851	*CF		7513006-911 571	MTH 09-Apr-1991		O/C			
345036 NO. 1	DME RECEIVER TRANSMITTER DM-850	*CF		7510184-902 90040501	MTH 09-Apr-1991		O/C			
345036 NO. 2	DME RECEIVER TRANSMITTER DM-850	*CF		7510184-902 90080534	MTH 09-Apr-1991		O/C			
345038 NO. 1	INTERGRATED NAV UNIT RNZ-850	SMF		7510100-711 89050311	MTH 09-Sep-2013 HRS 5961.8 LDG 5486		O/C			
345038 NO. 2	INTERGRATED NAV UNIT RNZ-850B	SMF		7510100-713 90090538	MTH 09-Sep-2013 HRS 5961.8 LDG 5486		O/C			
345081 NO. 1	CONFIGURATION MODULE CMU-GNSX	*CF		31990-1 2527	MTH 09-Apr-1991		O/C			
345088 NO. 1	RADIO MANAGEMENT UNIT RM-850	TOL		7012100-983 90030497	MTH 05-Jun-1998 HRS 3159		O/C	405		
345088 NO. 2	RADIO MANAGEMENT UNIT RM-850	TOL		7012100-983 90110677	MTH 06-Nov-1992 HRS 1057		O/C	0		

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



## CESCOM 10 - Aircraft Status Report

Owner: **SBM CLEANING COMPANY LLC**  
 Aircraft Model: **560 - CITATION V**  
 Aircraft Serial: **560-0096** Unit: **0096** Reg No: **N10TD**  
 Airworthiness: **09-Apr-1991**  
 Print Date: **31-Aug-2015 3:12PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>6339.1</b>	<b>5713</b>	<b>25-Aug-2015</b>	<b>.57</b>
<b>ENG 1</b>	<b>6307.4</b>	<b>5661</b>	<b>25-Aug-2015</b>	<b>.57</b>
<b>ENG 2</b>	<b>6307.4</b>	<b>5661</b>	<b>25-Aug-2015</b>	<b>.57</b>

### Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
346003	TAWS COMPUTER	SMF		805-18000-001 80639	MTH 20-Apr-2005 HRS 4685		O/C	0		
346035	TRAFFIC ADVISORY PROCESSOR -- TAS620			71-2420-7 060465	MTH 16-Jun-2006 HRS 4838		O/C	0		
351001	OXYGEN PRESSURE GAUGE MD-97	*CF		C668512-0101 345	MTH 09-Apr-1991		O/C	0		
351002	OXYGEN PRESSURE SWITCH 9912057-5	*CF		P24031 839	MTH 09-Apr-1991		O/C			
351004 COPILOT	OXYGEN MASK	SMF		174045-15 7346	MTH 22-May-2015 HRS 6283.9 LDG 5674		O/C	205 0 0		
351004 PILOT	OXYGEN MASK	SMF		174045-15 50732	MTH 22-May-2015 HRS 6283.9 LDG 5674		O/C	252 0 0		
351005	OXYGEN SUPPLY REGULATOR SMF	SMF		803215-03 C06100331	MTH 06-Feb-2009 HRS 5261		O/C	0		
351006	OXYGEN CYLINDER 9914067-42	SMF		89520077 C06110084	MTH 09-Feb-2007 HRS 4922		180	0	31-Jul-2021	71 m 0 d
Manufacture Date: 01-Jul-2006										
361003	PNEUMATIC REGULATOR 9912043-2	SMF		38E85-5C RF-2203	MTH 04-Mar-2011 HRS 5568.6 LDG 5282		O/C			
361008 NO. 1	VALVE CHECK	LGB		1553-00-18 221	MTH 06-Apr-1994 HRS 1794		O/C	0		
361008 NO. 2	VALVE CHECK	LGB		1553-00-18 144	MTH 06-Apr-1994 HRS 1794		O/C	0		
383002	MOTOR AND PUMP TOILET *CF			17000-102 SN-UNKNOWN	MTH 09-Apr-1991		O/C			
521001	CABIN DOOR SEAL 9912075-4	SMF		S15501-1 -NSN-	MTH 06-Feb-2009 HRS 5261		O/C	0		
521003	SECONDARY DOOR SEAL SMF	SMF		R881515 NSN	MTH 19-Jul-2013 HRS 5941 LDG 5476		O/C	0 0 0		
531001 LEFT	NOSE LANDING GEAR TRUNNION SUPPORT *CF			6613056-3 SN-UNKNOWN	MTH 09-Apr-1991 LDG 0	1398	12050	1398	12050	6337
531001 RIGHT	NOSE LANDING GEAR TRUNNION SUPPORT *CF			6613056-4 SN-UNKNOWN	MTH 09-Apr-1991 LDG 0	1398	12050	1398	12050	6337
531202 NOSE LANDING GEAR	ACTUATOR FITTING *CF			6511105-1 SN-UNKNOWN	MTH 09-Apr-1991 LDG 0	1398	23500	1398	23500	17787
541001 LEFT	INLET ASSEMBLY TOL	TOL		6552500-207 SN-UNKNOWN	MTH 14-Mar-1999 HRS 3430		O/C	0		



# CESCOM 10 - Aircraft Status Report

Owner: **SBM CLEANING COMPANY LLC**

Aircraft Model: **560 - CITATION V**

Aircraft Serial: **560-0096** Unit: **0096** Reg No: **N10TD**

Airworthiness: **09-Apr-1991**

Print Date: **31-Aug-2015 3:12PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>6339.1</b>	<b>5713</b>	<b>25-Aug-2015</b>	<b>.57</b>
<b>ENG 1</b>	<b>6307.4</b>	<b>5661</b>	<b>25-Aug-2015</b>	<b>.57</b>
<b>ENG 2</b>	<b>6307.4</b>	<b>5661</b>	<b>25-Aug-2015</b>	<b>.57</b>

## Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
541001 RIGHT	INLET ASSEMBLY	TOL		6552500-206 SN-UNKNOWN	MTH 14-Mar-1999 HRS 3430		O/C	0		
561001 NO. 1	LEFTHAND MAIN WINDSHIELD 9912064-11	*CF		E149000-9 1665	MTH 09-Apr-1991		O/C			
561002 NO. 2	RIGHTHAND MAIN WINDSHIELD 9912064-12	*CF		E149000-10 1476	MTH 09-Apr-1991		O/C			
561003	FOUL WEATHER WINDOW	*CF		5511275-7 SN-UNKNOWN	MTH 09-Apr-1991		O/C			
561005 LEFT INBOARD	PILOTS INNER WINDOW	*CF		5511285-5 SN-UNKNOWN	MTH 09-Apr-1991		O/C			
561005 LEFT OUTBOARD	PILOTS OUTER WINDOW	*CF		5511285-3 SN-UNKNOWN	MTH 09-Apr-1991		O/C			
561005 RIGHT INBOARD	CO-PILOTS INNER WINDOW			5511285-6 110104	MTH 28-Apr-2005 HRS 4685		O/C	0		
561005 RIGHT OUTBOARD	CO-PILOTS OUTER WINDOW			5511285-78 3705	MTH 28-Apr-2005 HRS 4685		O/C	0		
562001 L1 <i>562002 : L1</i>	CABIN DOOR WINDOW	*CF		5512207-1 SN-UNKNOWN	MTH 09-Apr-1991		O/C			
562001 L2	CABIN WINDOW	*CF		5511260-8 SN-UNKNOWN	MTH 09-Apr-1991		O/C			
562001 L3	CABIN WINDOW	*CF		5511260-8 SN-UNKNOWN	MTH 09-Apr-1991		O/C			
562001 L4	CABIN WINDOW	*CF		5511260-8 SN-UNKNOWN	MTH 09-Apr-1991		O/C			
562001 L5	CABIN WINDOW	*CF		5511260-8 SN-UNKNOWN	MTH 09-Apr-1991		O/C			
562001 L6	CABIN WINDOW	*CF		5511260-8 SN-UNKNOWN	MTH 09-Apr-1991		O/C			
562001 L7	CABIN WINDOW	*CF		5511260-8 SN-UNKNOWN	MTH 09-Apr-1991		O/C			
562001 R1	EMERGENCY DOOR WINDOW	*CF		5511260-8 SN-UNKNOWN	MTH 09-Apr-1991		O/C			
562001 R2	CABIN WINDOW	*CF		5511260-8 SN-UNKNOWN	MTH 09-Apr-1991		O/C			
562001 R3	CABIN WINDOW	*CF		5511260-8 SN-UNKNOWN	MTH 09-Apr-1991		O/C			
562001 R4	CABIN WINDOW	*CF		5511260-8 SN-UNKNOWN	MTH 09-Apr-1991		O/C			

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



# CESCOM 10 - Aircraft Status Report

Owner: **SBM CLEANING COMPANY LLC**  
 Aircraft Model: **560 - CITATION V**  
 Aircraft Serial: **560-0096** Unit: **0096** Reg No: **N10TD**  
 Airworthiness: **09-Apr-1991**  
 Print Date: **31-Aug-2015 3:12PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>6339.1</b>	<b>5713</b>	<b>25-Aug-2015</b>	<b>.57</b>
<b>ENG 1</b>	<b>6307.4</b>	<b>5661</b>	<b>25-Aug-2015</b>	<b>.57</b>
<b>ENG 2</b>	<b>6307.4</b>	<b>5661</b>	<b>25-Aug-2015</b>	<b>.57</b>

## Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
562001 R5	CABIN WINDOW	*CF		5511260-8 SN-UNKNOWN	MTH 09-Apr-1991		O/C			
562001 R6	CABIN WINDOW	*CF		5511260-8 SN-UNKNOWN	MTH 09-Apr-1991		O/C			
562001 R 7	CABIN WINDOW	*CF		5511260-8 SN-UNKNOWN	MTH 09-Apr-1991		O/C			
572001 LEFT AFT <i>572003 : LA</i>	MLG TRUNNION FITTING ASSEMBLY	*CF		5522710-15 SN-UNKNOWN	MTH 09-Apr-1991 LDG 0		25800	0	25800	20087
572001 LEFT FORWARD	MLG TRUNNION FITTING ASSEMBLY	*CF		6522057-5 SN-UNKNOWN	MTH 09-Apr-1991 LDG 0		25800	0	25800	20087
572001 RIGHT AFT <i>572003 : RA</i>	MLG TRUNNION FITTING ASSEMBLY	*CF		5522710-15 SN-UNKNOWN	MTH 09-Apr-1991 LDG 0		25800	0	25800	20087
572001 RIGHT FORWARD <i>572002 : R</i>	MLG TRUNNION FITTING ASSEMBLY	*CF		6522057-6 SN-UNKNOWN	MTH 09-Apr-1991 LDG 0	1398	25800	1398	25800	20087
574003 LEFT	MLG SIDE BRACE SUPPORT FITTING	*CF		6522047-1 SN-UNKNOWN	MTH 09-Apr-1991 LDG 0		25800	0	25800	20087
574004 RIGHT	MLG SIDE BRACE SUPPORT FITTING	*CF		6522047-2 SN-UNKNOWN	MTH 09-Apr-1991 LDG 0		25800	0	25800	20087
575001 LEFT INBOARD	FLAP	ICT		6525130-19 112C	MTH 26-Feb-1992 HRS 591		O/C	0		
575002 RIGHT INBOARD	FLAP	TOL		6525130-20 108C	MTH 11-Feb-1994 HRS 1729		O/C	0		
712001 LEFT	ENGINE AFT ISOLATOR 9912455-2	PIT		LM420SA6-1 R0160	MTH 23-Jul-1999 HRS 3514		3500	0	7014	674.9
712001 RIGHT	ENGINE AFT ISOLATOR 9912455-2	PIT		LM420SA6-1 40161	MTH 23-Jul-1999 HRS 3514		3500	0	7014	674.9
712002 LEFT BOTTOM	FORWARD ENGINE ISOLATOR	PIT		LM420SA-31 R0214	MTH 23-Jul-1999 HRS 3514		3500	0	7014	674.9
712002 LEFT TOP	FORWARD ENGINE ISOLATOR	PIT		LM420SA-30 R0235	MTH 23-Jul-1999 HRS 3514		3500	0	7014	674.9
712002 RIGHT BOTTOM	FORWARD ENGINE ISOLATOR	PIT		LM420SA-31 R0212	MTH 23-Jul-1999 HRS 3514		3500	0	7014	674.9
712002 RIGHT TOP	FORWARD ENGINE ISOLATOR	PIT		LM420SA-30 R0228	MTH 23-Jul-1999 HRS 3514		3500	0	7014	674.9
71EN1 NO. 1 <i>710001 : E1**L</i>	ENGINE 3042000	PIT		JT15D-5A 108220	MTH 23-Jul-1999 HRS 3514		E/C	0		
71EN2 NO. 2 <i>710001 : E2**R</i>	ENGINE 3042000	PIT		JT15D-5A 108198	MTH 23-Jul-1999 HRS 3514		E/C	0		

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



# CESCOM 10 - Aircraft Status Report

Owner: **SBM CLEANING COMPANY LLC**

Aircraft Model: **560 - CITATION V**

Aircraft Serial: **560-0096** Unit: **0096** Reg No: **N10TD**

Airworthiness: **09-Apr-1991**

Print Date: **31-Aug-2015 3:12PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>6339.1</b>	<b>5713</b>	<b>25-Aug-2015</b>	<b>.57</b>
<b>ENG 1</b>	<b>6307.4</b>	<b>5661</b>	<b>25-Aug-2015</b>	<b>.57</b>
<b>ENG 2</b>	<b>6307.4</b>	<b>5661</b>	<b>25-Aug-2015</b>	<b>.57</b>

## Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
724001 E1	COMBUSTOR LINER	PIT		3113170-01 4F110	MTH 23-Jul-1999 HRS 3514		O/C	0		
724001 E2	COMBUSTOR LINER	PIT		3113170-01 1F731	MTH 23-Jul-1999 HRS 3514		O/C	0		
721010 E1	ACESSORY DRIVE GEAR BOX *CF			3031170 SN-UNKNOWN	MTH 09-Apr-1991		O/C			
721010 E2	ACESSORY DRIVE GEAR BOX *CF			3031170 SN-UNKNOWN	MTH 09-Apr-1991		O/C			
722001 E1	OIL PUMP	PIT		3104289-01 4Y603	MTH 23-Jul-1999 HRS 3514		O/C	0		
722001 E2	OIL PUMP	PIT		3104289-01 4Y554	MTH 23-Jul-1999 HRS 3514		O/C	0		
722607 E1	LOW COMPRESSOR HUB 3037911	PIT		3037911 30A521	MTH 23-Jul-1999 HRS 3514 LDG 3747		12000	3698	(11997)12049	6336
722607 E2	LOW COMPRESSOR HUB 3037911	PIT		3037911 28A413	MTH 23-Jul-1999 HRS 3514 LDG 3747		12000	3698	(11997)12049	6336
723001 E1	LP COMPRESSOR ROTOR BALANCE ASSEMBLY	PIT		3102814-01 SN-UNKNOWN	MTH 23-Jul-1999 HRS 3514		O/C	0		
723001 E2	LP COMPRESSOR ROTOR BALANCE ASSEMBLY	PIT		3102814-01 SN-UNKNOWN	MTH 23-Jul-1999 HRS 3514		O/C	0		
723020 E1	LOW BOOST COMPRESSOR HUB 3034112	PIT		3034112 27A524	MTH 23-Jul-1999 HRS 3514 LDG 3747		14000	3698	(13997)14049	8336
723020 E2	LOW BOOST COMPRESSOR HUB 3034112	PIT		3034112 28A941	MTH 23-Jul-1999 HRS 3514 LDG 3747		14000	3698	(13997)14049	8336
723705 E1	2ND-STAGE LOW TURBINE ROTOR DISK	PIT		3022212 32A219	MTH 23-Jul-1999 HRS 3514 LDG 3747		14000	3698	(13997)14049	8336
723705 E2	2ND-STAGE LOW TURBINE ROTOR DISK	PIT		3022212 31A911	MTH 23-Jul-1999 HRS 3514 LDG 3747		14000	3698	(13997)14049	8336
724006 E1	3RD-STAGE LOW TURBINE ROTOR DISK	PIT		3036113 33A480	MTH 23-Jul-1999 HRS 3514 LDG 3747		14000	3698	(13997)14049	8336
724006 E2	3RD-STAGE LOW TURBINE ROTOR DISK	PIT		3036113 30A480	MTH 23-Jul-1999 HRS 3514 LDG 3747		14000	3698	(13997)14049	8336
724706 E1	HIGH TURBINE ROTOR DISK	PIT		3036411 34A253	MTH 23-Jul-1999 HRS 3514 LDG 3747		10526	3698	(10523)10575	4862
724706 E2	HIGH TURBINE ROTOR DISK	PIT		3036411 11A374	MTH 23-Jul-1999 HRS 3514 LDG 3747		10526	3698	(10523)10575	4862
724707 E1	HIGH TURBINE BLADES 3029601	PIT		3029601 SN-UNKNOWN	MTH 23-Jul-1999 HRS 3514		O/C	0		

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



## CESCOM 10 - Aircraft Status Report

Owner: **SBM CLEANING COMPANY LLC**

Aircraft Model: **560 - CITATION V**

Aircraft Serial: **560-0096** Unit: **0096** Reg No: **N10TD**

Airworthiness: **09-Apr-1991**

Print Date: **31-Aug-2015 3:12PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>6339.1</b>	<b>5713</b>	<b>25-Aug-2015</b>	<b>.57</b>
<b>ENG 1</b>	<b>6307.4</b>	<b>5661</b>	<b>25-Aug-2015</b>	<b>.57</b>
<b>ENG 2</b>	<b>6307.4</b>	<b>5661</b>	<b>25-Aug-2015</b>	<b>.57</b>

### Components

Item Code	Description	City	Mod Lvl	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains
Position	Drawing # / Task #			Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
724707 E2	HIGH TURBINE BLADES 3029601	PIT		3029601 SN-UNKNOWN	MTH 23-Jul-1999 HRS 3514		O/C	0		
724825 E1	CENTRIFUGAL IMPELLER 3033682	PIT		3033682 9D744	MTH 23-Jul-1999 HRS 3514 LDG 3747		9000	3698	(8997)9049	3336
724825 E2	CENTRIFUGAL IMPELLER 3033682	PIT		3033682 9D273	MTH 23-Jul-1999 HRS 3514 LDG 3747		9000	3698	(8997)9049	3336
731004 NO. 1	LOW FUEL PRESSURE SWITCH 9912033-1	*CF		1103P92 SN-UNKNOWN	MTH 09-Apr-1991		O/C			
731004 NO. 2	LOW FUEL PRESSURE SWITCH 9912033-2	TOL		1103P0448 3539	MTH 14-Mar-1999 HRS 3430		O/C	0		
733002	FUEL FLOW/QUANTITY INDICATOR 9912147-16	*CF		VSDL-OC208E 659	MTH 09-Apr-1991		O/C			
733003 NO. 1	FUEL FLOW TRANSMITTER 9912031-6	LGB		3268014-0201 1593B	MTH 01-Dec-1996 HRS 2692		O/C	0		
733003 NO. 2	FUEL FLOW TRANSMITTER 9912031-6	LGB		3268014-0201 1604B	MTH 01-Dec-1996 HRS 2692		O/C	0		
731001 E1	FUEL PUMP 3037078	PIT		717101-1 258	MTH 23-Jul-1999 HRS 3514		O/C	0		
731001 E2	FUEL PUMP 3037078	PIT		717100 232S	MTH 23-Jul-1999 HRS 3514		O/C	0		
731002 E1	FLOW DIVIDER VALVE 3119573-01	PIT		26395-2 259	MTH 23-Jul-1999 HRS 3514		O/C	0		
731002 E2	FLOW DIVIDER VALVE 3119573-01	PIT		26395-2 403	MTH 23-Jul-1999 HRS 3514		O/C	0		
731005 E1	BLEED CONTROL VALVE 3118876-01	PIT		800831-1-001-L7 C9510018	MTH 23-Jul-1999 HRS 3514		O/C	0		
731005 E2	BLEED CONTROL VALVE 3118876-01	PIT		800831-1-001-L7 92030005	MTH 23-Jul-1999 HRS 3514		O/C	0		
731006 E1	EFCU WIRING HARNESS	PIT		3112429-01 9W686	MTH 23-Jul-1999 HRS 3514		O/C	0		
731006 E2	EFCU WIRING HARNESS	PIT		3112429-01 9W659	MTH 23-Jul-1999 HRS 3514		O/C	0		
731020 E1	FUEL-OIL COOLER 3033002	PIT		11438-001J 551	MTH 23-Jul-1999 HRS 3514		O/C	0		
731020 E2	FUEL-OIL COOLER 3033002	PIT		11438-001J 513	MTH 23-Jul-1999 HRS 3514		O/C	0		
731030 E1	MOTIVE FLOW VALVE			PN SN-UNKNOWN	MTH 09-Apr-1991		O/C	0		

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



# CESCOM 10 - Aircraft Status Report

Owner: **SBM CLEANING COMPANY LLC**

Aircraft Model: **560 - CITATION V**

Aircraft Serial: **560-0096** Unit: **0096** Reg No: **N10TD**

Airworthiness: **09-Apr-1991**

Print Date: **31-Aug-2015 3:12PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>6339.1</b>	<b>5713</b>	<b>25-Aug-2015</b>	<b>.57</b>
<b>ENG 1</b>	<b>6307.4</b>	<b>5661</b>	<b>25-Aug-2015</b>	<b>.57</b>
<b>ENG 2</b>	<b>6307.4</b>	<b>5661</b>	<b>25-Aug-2015</b>	<b>.57</b>

## Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
731030 E2	MOTIVE FLOW VALVE			PN SN-UNKNOWN	MTH 09-Apr-1991		O/C	0		
731065 E1	BLEED VALVE ACTUATOR			PN SN-UNKNOWN	MTH 09-Apr-1991		O/C	0		
731065 E2	BLEED VALVE ACTUATOR			PN SN-UNKNOWN	MTH 09-Apr-1991		O/C	0		
731085 E1	SCHEDULE MODULATOR			PN SN-UNKNOWN	MTH 09-Apr-1991		O/C	0		
731085 E2	SCHEDULE MODULATOR			PN SN-UNKNOWN	MTH 09-Apr-1991		O/C	0		
732001 E1	FUEL CONTROL UNIT 3119508-05	PIT		3244851-7 B29562	MTH 23-Jul-1999 HRS 3514		O/C	0		
732001 E2	FUEL CONTROL UNIT 3119508-05	PIT		3244851-7 B29262	MTH 23-Jul-1999 HRS 3514		O/C	0		
732005 E1	N1 SPEED SENSOR	*CF		3100335-01 SN-UNKNOWN	MTH 09-Apr-1991		O/C			
732005 E2	N1 SPEED SENSOR	*CF		3100335-01 SN-UNKNOWN	MTH 09-Apr-1991		O/C			
732006 E1 BOTTOM	N2 SPEED SENSOR	*CF		3032997 SN-UNKNOWN	MTH 09-Apr-1991		O/C			
732006 E1 TOP	N2 SPEED SENSOR	*CF		3032997 SN-UNKNOWN	MTH 09-Apr-1991		O/C			
732006 E2 BOTTOM	N2 SPEED SENSOR	*CF		3032997 SN-UNKNOWN	MTH 09-Apr-1991		O/C			
732006 E2 TOP	N2 SPEED SENSOR	*CF		3032997 SN-UNKNOWN	MTH 09-Apr-1991		O/C			
732007 E2	IDLE SOLENOID ASSEMBLY	SMF		3242737 70770	MTH 31-Mar-2000 HRS 3718		O/C	0		
732045 E1	ELECTRONIC BLEED VALVE CONTROL			PN SN-UNKNOWN	MTH 09-Apr-1991		O/C	0		
732045 E2	ELECTRONIC BLEED VALVE CONTROL			PN SN-UNKNOWN	MTH 09-Apr-1991		O/C	0		
732065 E1	MAIN WIRING HARNESS			PN SN-UNKNOWN	MTH 09-Apr-1991		O/C	0		
732065 E2	MAIN WIRING HARNESS			PN SN-UNKNOWN	MTH 09-Apr-1991		O/C	0		
741001 E1 INBOARD	IGNITION EXCITER 3033378	PIT		NB01201 R5948	MTH 23-Jul-1999 HRS 3514		O/C	0		

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.





# CESCOM 10 - Aircraft Status Report

Owner: **SBM CLEANING COMPANY LLC**

Aircraft Model: **560 - CITATION V**

Aircraft Serial: **560-0096** Unit: **0096** Reg No: **N10TD**

Airworthiness: **09-Apr-1991**

Print Date: **31-Aug-2015 3:12PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>6339.1</b>	<b>5713</b>	<b>25-Aug-2015</b>	<b>.57</b>
<b>ENG 1</b>	<b>6307.4</b>	<b>5661</b>	<b>25-Aug-2015</b>	<b>.57</b>
<b>ENG 2</b>	<b>6307.4</b>	<b>5661</b>	<b>25-Aug-2015</b>	<b>.57</b>

## Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
741001 E1 OUTBOARD	IGNITION EXCITER 3033378	PIT		NB01201 R5958	MTH 23-Jul-1999 HRS 3514		O/C	0		
741001 E2 INBOARD	IGNITION EXCITER 3037865	PIT		305013 682	MTH 23-Jul-1999 HRS 3514		O/C	0		
741001 E2 OUTBOARD	IGNITION EXCITER 3041996-01	SMF		CH92028 01030791	MTH 25-Jun-2001 HRS 3926		O/C	0		
742001 E1 INBOARD	IGNITER PLUG 3030595	SMF		FHE-246-4 -NSN-	MTH 29-Jan-2015 HRS 6147.1 LDG 5586		O/C	0		
742001 E1 OUTBOARD	IGNITER PLUG 3030595	SMF		FHE-246-4 -NSN-	MTH 29-Jan-2015 HRS 6147.1 LDG 5586		O/C	0		
742001 E2 INBOARD	IGNITER PLUG 3030595	SMF		FHE-246-4 -NSN-	MTH 29-Jan-2015 HRS 6147.1 LDG 5586		O/C	0		
742001 E2 OUTBOARD	IGNITER PLUG 3030595	SMF		FHE-246-4 -NSN-	MTH 29-Jan-2015 HRS 6147.1 LDG 5586		O/C	0		
742002 E1 INBOARD	IGNITER PLUG CABLE	SMF		10-395428-1 NN08084195	MTH 04-Mar-2011 HRS 5568.6 LDG 5282		O/C	0		
742002 E2 INBOARD	IGNITER PLUG CABLE	PIT		53067-21 SN-UNKNOWN	MTH 23-Jul-1999 HRS 3514		O/C	0		
742003 E1 OUTBOARD	IGNITER PLUG CABLE	SMF		53067-38.5 -NSN-	MTH 28-Apr-2005 HRS 4685		O/C	0		
742003 E2 OUTBOARD	IGNITER PLUG CABLE	SMF		53067-38.5 -NSN-	MTH 29-Jan-2015 HRS 6147.1 LDG 5586		O/C	0		
761002	SYNCHRONIZER CONTROL BOX *CF			213693 2331476	MTH 09-Apr-1991		O/C			
761003	ENGINE SYNC ACTUATOR *CF			5485-066 2168179F	MTH 09-Apr-1991		O/C			
771004	N1 FAN TACHOMETER INDICATOR 9912147-27 *CF			VSDL-OC410AE 225B	MTH 09-Apr-1991		O/C			
771005	N2 TURBINE TACHOMETER INDICATOR 9912147-28 LBE			DDL-OC110B 228B	MTH 31-Jul-1991 HRS 256		O/C	0		
772001	INTERSTAGE TURBINE TEMPERATURE (ITT) INDICATOR 9912147-15 *CF			VSDL-OC419H 559	MTH 09-Apr-1991		O/C			
783001 LEFT ENGINE	THRUST REVERSER ASSEMBLY 9912377-1 *CF			262-0001-501 2412	MTH 09-Apr-1991		O/C			
783001 RIGHT ENGINE	THRUST REVERSER ASSEMBLY 9912377-2 *CF			262-0001-503 2413	MTH 09-Apr-1991		O/C			
783002 LEFT ENGINE	THRUST REVERSER CONTROL VALVE *CF			65680 1497	MTH 09-Apr-1991		O/C			

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



# CESCOM 10 - Aircraft Status Report

Owner: **SBM CLEANING COMPANY LLC**

Aircraft Model: **560 - CITATION V**

Aircraft Serial: **560-0096** Unit: **0096** Reg No: **N10TD**

Airworthiness: **09-Apr-1991**

Print Date: **31-Aug-2015 3:12PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>6339.1</b>	<b>5713</b>	<b>25-Aug-2015</b>	<b>.57</b>
<b>ENG 1</b>	<b>6307.4</b>	<b>5661</b>	<b>25-Aug-2015</b>	<b>.57</b>
<b>ENG 2</b>	<b>6307.4</b>	<b>5661</b>	<b>25-Aug-2015</b>	<b>.57</b>

## Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
783002 RIGHT ENGINE	THRUST REVERSER CONTROL VALVE	SAC		65680 4051	MTH 17-Mar-2003 HRS 4265 LDG 4341		O/C			0
783003 LEFT ENGINE	THRUST REVERSER ISOLATION VALVE	*CF		13027-4 2223	MTH 09-Apr-1991		O/C			
783003 RIGHT ENGINE	THRUST REVERSER ISOLATION VALVE	*CF		13027-4 2231	MTH 09-Apr-1991		O/C			
783005 LEFT	THRUST REVERSER UPPER DOOR ASSEMBLY	*CF		202-0001-503 2412	MTH 09-Apr-1991		O/C			
783005 RIGHT	THRUST REVERSER UPPER DOOR ASSEMBLY	CKB		202-0001-504 2415	MTH 30-Sep-1993 HRS 1537 LDG 1680		O/C		0	
783006 LEFT	THRUST REVERSER LOWER DOOR ASSEMBLY	*CF		202-0002-505 2412	MTH 09-Apr-1991		O/C			
783006 RIGHT	THRUST REVERSER LOWER DOOR ASSEMBLY	*CF		202-0002-506 2415	MTH 09-Apr-1991		O/C			
783007 LEFT	THRUST REVERSER UPPER MECHANISM	*CF		225-0007-513 2412	MTH 09-Apr-1991		O/C			
783007 RIGHT	THRUST REVERSER UPPER MECHANISM	*CF		225-0007-513 2413	MTH 09-Apr-1991		O/C			
783008 LEFT	THRUST REVERSER LOWER MECHANISM	*CF		225-0007-515 2412	MTH 09-Apr-1991		O/C			
783008 RIGHT	THRUST REVERSER LOWER MECHANISM	*CF		225-0007-515 2413	MTH 09-Apr-1991		O/C			
783009 LEFT	THRUST REVERSER FAN DUCT	*CF		225-0014-507 2412	MTH 09-Apr-1991		O/C			
783009 RIGHT	THRUST REVERSER FAN DUCT	*CF		225-0014-508 2413	MTH 09-Apr-1991		O/C			
783010 LEFT INBOARD	THRUST REVERSER ACTUATOR	*CF		62270 2948	MTH 09-Apr-1991		O/C			
783010 LEFT OUTBOARD	THRUST REVERSER ACTUATOR	*CF		62270 2943	MTH 09-Apr-1991		O/C			
783010 RIGHT INBOARD	THRUST REVERSER ACTUATOR	*CF		62270 2949	MTH 09-Apr-1991		O/C			
783010 RIGHT OUTBOARD	THRUST REVERSER ACTUATOR	*CF		62270 2946	MTH 09-Apr-1991		O/C			
783011 RIGHT	EXHAUST NOZZLE CONE	*CF		9912377-3 225-0016-513-V4 SN-UNKNOWN	MTH 09-Apr-1991		O/C			
783012 LEFT ENGINE	EXHAUST NOZZLE	*CF		9912377-4 225-0016-515-V5 SN-UNKNOWN	MTH 09-Apr-1991		O/C			

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



# CESCOM 10 - Aircraft Status Report

Owner: **SBM CLEANING COMPANY LLC**

Aircraft Model: **560 - CITATION V**

Aircraft Serial: **560-0096** Unit: **0096** Reg No: **N10TD**

Airworthiness: **09-Apr-1991**

Print Date: **31-Aug-2015 3:12PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>6339.1</b>	<b>5713</b>	<b>25-Aug-2015</b>	<b>.57</b>
<b>ENG 1</b>	<b>6307.4</b>	<b>5661</b>	<b>25-Aug-2015</b>	<b>.57</b>
<b>ENG 2</b>	<b>6307.4</b>	<b>5661</b>	<b>25-Aug-2015</b>	<b>.57</b>

## Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
793001	OIL TEMP INDICATOR 9912147-11	*CF		VSDL-OC219F 658	MTH 09-Apr-1991		O/C			
793002 LEFT ENGINE	OIL TEMPERATURE TRANSMITTER TOL			102-00083 71	MTH 15-Dec-1993 HRS 1647		O/C	0		
793002 RIGHT ENGINE	OIL TEMPERATURE TRANSMITTER TOL			102-00083 35	MTH 15-Dec-1993 HRS 1647		O/C	0		
793003	OIL PRESSURE INDICATOR 9912147-30	*CF		VSDL-OC204N 213	MTH 09-Apr-1991		O/C			
793004 LEFT ENGINE	OIL PRESSURE TRANSMITTER 9912164-1	*CF		123479 43977	MTH 09-Apr-1991		O/C			
793004 RIGHT ENGINE	OIL PRESSURE TRANSMITTER 9912164-1	*CF		123479 43933	MTH 09-Apr-1991		O/C			
793006 LEFT ENGINE	LOW OIL PRESSURE SWITCH 9912178-3	*CF		1103P89-2 SN-UNKNOWN	MTH 09-Apr-1991		O/C			
793006 RIGHT ENGINE	LOW OIL PRESSURE SWITCH 9912178-3	*CF		1103P89-2 SN-UNKNOWN	MTH 09-Apr-1991		O/C			



# CESCOM 10 - Aircraft Status Report

Owner: **SBM CLEANING COMPANY LLC**  
 Aircraft Model: **560 - CITATION V**  
 Aircraft Serial: **560-0096** Unit: **0096** Reg No: **N10TD**  
 Airworthiness: **09-Apr-1991**  
 Print Date: **31-Aug-2015 3:12PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>6339.1</b>	<b>5713</b>	<b>25-Aug-2015</b>	<b>.57</b>
<b>ENG 1</b>	<b>6307.4</b>	<b>5661</b>	<b>25-Aug-2015</b>	<b>.57</b>
<b>ENG 2</b>	<b>6307.4</b>	<b>5661</b>	<b>25-Aug-2015</b>	<b>.57</b>

## Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SL 560-03-02 R1	SUPPLEMENTAL TYPE CERTIFICATE (STC)			(THIS SL IS REPLACED BY CIL-03-01, DATED JUNE 3, 2013) INFORMATIONAL						
	<b>MOC :</b>									
SB 560-03-06 R1	OPERATIONAL CERTIFICATION REQUIREMENTS - U.S. TO CANADIAN CONVERSION			OPTIONAL						
	<b>MOC :</b>									
SB 560-03-06	OPERATIONAL CERTIFICATION REQUIREMENTS - U.S. TO CANADIAN CONVERSION			OPTIONAL						
	<b>MOC :</b>									
SL CIL-03-01	SUPPLEMENTAL TYPE CERTIFICATE (STC)			INFORMATIONAL						
	<b>MOC :</b>									
SL CIL-99-01 R1	USE OF CORROSION INHIBITING COMPOUNDS			INFORMATIONAL						
	<b>MOC :</b>									
SL CIL-99-01	USE OF CORROSION INHIBITING COMPOUNDS			INFORMATIONAL						
	<b>MOC :</b>									
SL CIL-99-02	AVOID OPERATIONS ON RUNWAYS TREATED WITH RUNWAY DE-ICE (RDI) FLUIDS. AIRCRAFT WASHING RECOMMENDED AFTER EXPOSURE TO RDI FLUIDS			RECOMMENDED	MTH					
	<b>MOC :</b>									
SL CIL-99-03 R1	CORROSION PREVENTION AND CONTROL PROGRAM (CPCP)			RECOMMENDED						
	<b>MOC :</b>									
SL CIL-99-03	CORROSION PREVENTION AND CONTROL PROGRAM (CPCP)			RECOMMENDED	MTH					
	<b>MOC :</b>									
SL 560-99-02 R6	CESCOM PRICES (THIS SL CANCELS SL560-99-02 R5 AND PREVIOUS)			INFORMATIONAL						
	<b>MOC :</b>									
SL 560-99-04	MISCELLANEOUS - CESSNA PART NUMBER SUFFIXES FOR REMANUFACTURED PARTS			INFORMATIONAL			A/R			
	<b>MOC :</b>									
SL 560-99-05	MISCELLANEOUS - CESSNA SERVICE DOCUMENT CHANGE NOTIFICATION			INFORMATIONAL			A/R			
	<b>MOC :</b>									
SB 560-11-02 <i>11SB-02</i>	FLAP NO STEP PLACARD INSTALLATION			TOL RECOMMENDED	MTH 25-Feb-1993 HRS 1203					Complete
	<b>MOC : COMPLIED WITH</b>									
SB 560-11-04 <i>11SB-04</i>	FIRE EXTINGUISHER PLACARD INSTALLATION			OPTIONAL	MTH					
	<b>MOC :</b>									



# CESCOM 10 - Aircraft Status Report

Owner: **SBM CLEANING COMPANY LLC**  
 Aircraft Model: **560 - CITATION V**  
 Aircraft Serial: **560-0096** Unit: **0096** Reg No: **N10TD**  
 Airworthiness: **09-Apr-1991**  
 Print Date: **31-Aug-2015 3:12PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>6339.1</b>	<b>5713</b>	<b>25-Aug-2015</b>	<b>.57</b>
<b>ENG 1</b>	<b>6307.4</b>	<b>5661</b>	<b>25-Aug-2015</b>	<b>.57</b>
<b>ENG 2</b>	<b>6307.4</b>	<b>5661</b>	<b>25-Aug-2015</b>	<b>.57</b>

## Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB 560-12-01	ADDITIONAL APPROVED FUEL ANTI-ICE ADDITIVES			INFORMATIONAL			-			
	<b>MOC :</b>									
SL CIL-99-01 R2	USE OF CORROSION INHIBITING COMPOUNDS			INFORMATIONAL			-			
	<b>MOC :</b>									
SL CIL-20-01 R2	STANDARD PRACTICES - CESSNA CERTIFICATION OF NONDESTRUCTIVE TESTING FACILITIES/PERSONNEL			INFORMATIONAL			-			
	<b>MOC :</b>									
SL CIL-20-01	CESSNA CERTIFICATION OF NONDESTRUCTIVE TESTING FACILITIES/PERSONNEL			INFORMATIONAL			-			
	<b>MOC :</b>									
SL 560-20-01 R25	STANDARD PRACTICES - CESSNA CERTIFICATION OF NONDESTRUCTIVE TESTING FACILITIES/PERSONNEL			INFORMATIONAL			A/R			
	<b>MOC :</b>									
SB 560-21-06 <i>21SB-06</i>	TAILCONE PRESSURE VALVE ACTUATOR WIRING MODIFICATION			OPTIONAL	MTH		-			
	<b>MOC :</b>									
SB 560-21-08 R1 <i>21SB-08 : 560R1</i>	P-10 PANEL ACCESS AIR DUCT MODIFICATION			OPTIONAL	MTH		-			
	<b>MOC :</b>									
SB 560-21-10 <i>21SB-10</i>	ADDITIONAL OUTFLOW VALVE REPLACEMENT	LGB		SUPERSEDED	MTH 28-Aug-1995 HRS 2247		A/R			Complete
	<b>MOC : COMPLIED WITH</b>									
SB 560-21-12 R1 <i>21SB-12 : 560R1</i>	RAM AIR DUCT IMPROVEMENT			OPTIONAL	MTH		-			
	<b>MOC :</b>									
SB 560-21-12 R2	RAM AIR DUCT IMPROVEMENT			OPTIONAL			A/R			
	<b>MOC :</b>									
SB 560-21-15 <i>21SB-15</i>	COCKPIT SIDE WINDOW DEFOG SYSTEM MODIFICATION			OPTIONAL	MTH		-			
	<b>MOC :</b>									
SB 560-21-16 R1 <i>21SB-16 : 560R1</i>	CABIN FAN AND DEFOT BLOWER WIRING IMPROVEMENT			DISCRETIONARY	MTH		-			
	<b>MOC :</b>									
SB 560-21-30 <i>21SB-30</i>	CABIN ALTITUDE BAROMETRIC SWITCH IMPROVEMENT			OPTIONAL	MTH		A/R			
	<b>MOC :</b>									
SB 560-21-35	TEMPERATURE CONTROLLER IMPROVEMENT			OPTIONAL	MTH		A/R			
	<b>MOC :</b>									
SL CIL-21-01	COMPRESSOR MOTOR BRUSH LIFE LIMIT			INFORMATIONAL			-			
	<b>MOC :</b>									



# CESCOM 10 - Aircraft Status Report

Owner: **SBM CLEANING COMPANY LLC**  
 Aircraft Model: **560 - CITATION V**  
 Aircraft Serial: **560-0096** Unit: **0096** Reg No: **N10TD**  
 Airworthiness: **09-Apr-1991**  
 Print Date: **31-Aug-2015 3:12PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>6339.1</b>	<b>5713</b>	<b>25-Aug-2015</b>	<b>.57</b>
<b>ENG 1</b>	<b>6307.4</b>	<b>5661</b>	<b>25-Aug-2015</b>	<b>.57</b>
<b>ENG 2</b>	<b>6307.4</b>	<b>5661</b>	<b>25-Aug-2015</b>	<b>.57</b>

## Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SL CIL-21-02 R1	ENVIRONMENTAL HOUR METER INSTALLATION	SMF		MANDATORY	MTH 29-Jan-2015 HRS 6147.1 LDG 5586		-			Complete
<b>MOC : COMPLIED WITH - COMPLIED WITH CIL-21-02 REVISION 1 BY INSTALLING AN HOUR METER FOR THE COMPRESSOR MOTOR.</b>										
SL CIL-21-02	ENVIRONMENTAL HOUR METER INSTALLATION	SMF		OPTIONAL	MTH 11-Apr-2014 HRS 6043.9 LDG 5528		-			Complete
<b>MOC : COMPLIED WITH - COMPLIED WITH CIL-21-02 BY INSTALLING AN AC HOUR METER PER THE ACCOMPLISHMENT INSTRUCTIONS.</b>										
SL 560-21-02	AIR CONDITIONING - COMPRESSOR DRIVE MOTOR BRUSH INSPECTION/REPLACEMENT (FORT WORTH AIRWORKS INC. - ZEPHYR AIR CONDITIONING)									
<i>21SL-02</i>		TOL		RECOMMENDED	MTH 29-May-1992 HRS 759		-			Complete
<b>MOC : COMPLIED WITH</b>										
SL 560-21-03	EMERGENCY PRESSURIZATION SUPPLY LINE INSPECTION/MODIFICATION									
<i>21SL-03</i>		TOL		RECOMMENDED	MTH 29-May-1992 HRS 759		-			Complete
<b>MOC : COMPLIED WITH</b>										
SL 560-21-05	COUPLING INSPECTION AND TORQUE REQUIREMENTS									
<i>21SL-05</i>		TOL		RECOMMENDED	MTH 25-May-1993 HRS 1346		-			Complete
<b>MOC : COMPLIED WITH</b>										
SL 560-21-06 R1	VENTILATION BOX ASSEMBLY FORWARD FLANGE INSPECTION/REPAIR									
<i>21SL-06 : 560R1</i>		LGB		RECOMMENDED	MTH 28-Aug-1995 HRS 2247			A/R		Complete
<b>MOC : COMPLIED WITH</b>										
SL 560-21-06 R2	VENTILATION BOX ASSEMBLY FORWARD FLANGE INSPECTION/REPAIR									
<i>21SL-06 : 560R2</i>		TOL		RECOMMENDED	MTH 08-Jan-1998 HRS 2999			A/R		Complete
<b>MOC : COMPLIED WITH</b>										
SL 560-21-06 R3	VENTILATION BOX ASSEMBLY FORWARD FLANGE INSPECTION/REPAIR									
<i>21SL-06 : 560R3</i>		TOL		RECOMMENDED	MTH 14-Mar-1999 HRS 3430			-		Complete
<b>MOC : COMPLIED WITH</b>										
SL 560-21-06	VENTILATION BOX ASSEMBLY FORWARD FLANGE INSPECTION/REPAIR									
<i>21SL-06</i>		TOL		RECOMMENDED	MTH 15-Dec-1993 HRS 1647			A/R		Complete
<b>MOC : COMPLIED WITH</b>										
SL 560-21-09	EVAPORATOR MODULE INSTALLATION 1250240 AND 1134240 SERIES									
<i>21SL-09</i>				RECOMMENDED	MTH			-		
<b>MOC :</b>										
SL 560-21-10	OUTFLOW VALVE STATIC PRESSURE LINE INSPECTION/REPLACEMENT									
<i>21SL-10</i>				RECOMMENDED	MTH			-		
<b>MOC :</b>										
SL 560-21-11 R1	RAM AIR INLET DRAIN LINE INSPECTION									
<i>21SL-11 : 560R1</i>		SAC		RECOMMENDED	MTH 28-Jun-2004 HRS 4560			-		Complete
<b>MOC : COMPLIED WITH - NOT APPLICABLE</b>										



# CESCOM 10 - Aircraft Status Report

Owner: **SBM CLEANING COMPANY LLC**  
 Aircraft Model: **560 - CITATION V**  
 Aircraft Serial: **560-0096** Unit: **0096** Reg No: **N10TD**  
 Airworthiness: **09-Apr-1991**  
 Print Date: **31-Aug-2015 3:12PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>6339.1</b>	<b>5713</b>	<b>25-Aug-2015</b>	<b>.57</b>
<b>ENG 1</b>	<b>6307.4</b>	<b>5661</b>	<b>25-Aug-2015</b>	<b>.57</b>
<b>ENG 2</b>	<b>6307.4</b>	<b>5661</b>	<b>25-Aug-2015</b>	<b>.57</b>

## Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SL 560-21-16 21SL-16	AIR CONDITIONING - AIR CONDITIONING EXHAUST DOOR SHAFT SPACER INSPECTION			DISCRETIONARY	MTH		A/R			
<b>MOC :</b>										
SB 560-23-09 R1 23SB-09 : 560R1	HONEYWELL EFIS SYMBOL GENERATOR INTERPOSER FILTER INSTALLATION	ICT		OPTIONAL	MTH 26-Feb-1992 HRS 591		A/R			Complete
<b>MOC : COMPLIED WITH</b>										
SB 560-23-10 23SB-10	CABIN PASSENGER ADDRESS MODIFICATION	TOL		RECOMMENDED	MTH 25-Feb-1993 HRS 1203		A/R			Complete
<b>MOC : COMPLIED WITH</b>										
SB 560-23-12 23SB-12	PRIMUS II SIMULCOM WIRING ADDITION	TOL		RECOMMENDED	MTH 25-May-1993 HRS 1346		-			Complete
<b>MOC : COMPLIED WITH</b>										
SB 560-23-14 23SB-14	FLITEPHONE VI ANTENNA CABLE REPLACEMENT	TOL		RECOMMENDED	MTH 03-Sep-1993 HRS 1503		A/R			Complete
<b>MOC : COMPLIED WITH</b>										
SB 560-23-16 23SB-16	STATIC WICK REPLACEMENT	*CF		OPTIONAL	MTH		-			
<b>MOC :</b>										
SB 560-23-19 R1 23SB-19 : 560R1	ELECTRICAL BONDING FLAP AND SPEED BRAKE PUSHRODS	TOL		RECOMMENDED	MTH 14-Mar-1999 HRS 3430		A/R			Complete
<b>MOC : COMPLIED WITH</b>										
SB 560-23-19 R2 23SB-19 : 560R2	ELECTRICAL BONDING FLAP AND SPEED BRAKE PUSHRODS	SAC		RECOMMENDED	MTH 28-Jun-2004 HRS 4560		-			Complete
<b>MOC : COMPLIED WITH</b>										
SB 560-23-19 23SB-19	ELECTRICAL BONDING FLAP AND SPEED BRAKE PUSHRODS	TOL		RECOMMENDED	MTH 08-Jan-1998 HRS 2999		A/R			Complete
<b>MOC : COMPLIED WITH</b>										
SB 560-23-25 R1 23SB-25 : 560R1	HONEYWELL 8.33 KHZ COMMUNICATION RADIO INSTALLATION			OPTIONAL	MTH		-			
<b>MOC :</b>										
SB 560-23-26 R1 23SB-26 : 560R1	COLLINS 8.33 KHZ COMMUNICATION RADIO INSTALLATION			OPTIONAL	MTH		-			
<b>MOC :</b>										
SB 560-23-30 R1 23SB-30 : 560R1	VLF NOISE FILTER CAPACITOR REMOVAL/REPLACEMENT	SMF		MANDATORY	MTH 31-Mar-2000 HRS 3718		A/R			Complete
<b>MOC : COMPLIED WITH</b>										
SB 560-23-32 R1 23SB-32 : 560R1	RNZ-850 NAVIGATION RADIO UPGRADE	SAC		MANDATORY	MTH 28-Jun-2004 HRS 4531		-			Complete
<b>MOC : COMPLIED WITH</b>										
SB 560-23-38 R2	COMMUNICATIONS - RADIO MANAGEMENT UNIT (RM855) INSTALLATION			OPTIONAL			-			
<b>MOC :</b>										
SB 560-23-38	COMMUNICATIONS - RADIO MANAGEMENT UNIT (RM855) INSTALLATION			OPTIONAL	MTH		A/R			
<b>MOC :</b>										

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.





# CESCOM 10 - Aircraft Status Report

Owner: **SBM CLEANING COMPANY LLC**  
 Aircraft Model: **560 - CITATION V**  
 Aircraft Serial: **560-0096** Unit: **0096** Reg No: **N10TD**  
 Airworthiness: **09-Apr-1991**  
 Print Date: **31-Aug-2015 3:12PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>6339.1</b>	<b>5713</b>	<b>25-Aug-2015</b>	<b>.57</b>
<b>ENG 1</b>	<b>6307.4</b>	<b>5661</b>	<b>25-Aug-2015</b>	<b>.57</b>
<b>ENG 2</b>	<b>6307.4</b>	<b>5661</b>	<b>25-Aug-2015</b>	<b>.57</b>

## Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SL 560-23-15 23SL-15	TRANSMITTAL OF AIRSHOW SERVICE BULLETIN 920720-1 AIRSHOW 400 DIGITAL INTERFACE UNIT			RECOMMENDED	DAYS	55	-			
<b>MOC :</b>										
SL 560-23-16 R1 23SL-16 : 560R1	AIRSHOW RELIABILITY IMPROVEMENTS AND SERVICE PACK SOFTWARE UPGRADE			RECOMMENDED	MTH		A/R			
<b>MOC :</b>										
SB 560-24-03 R1 24SB-03 : 560R1	MAIN LANDING GEAR AXLE ANTISKID WIRE BUNDLE PROTECTION	TOL		RECOMMENDED	MTH 29-May-1992 HRS 759		-			Complete
<b>MOC : COMPLIED WITH</b>										
SB 560-24-03 24SB-03	MAIN LANDING GEAR AXLE ANTISKID WIRE BUNDLE PROTECTION	TOL		RECOMMENDED	MTH 29-May-1992 HRS 759		A/R			Complete
<b>MOC : COMPLIED WITH</b>										
SB 560-24-04 R3 24SB-04 : 560R3	LIGHT DIMMING AND TEST PRINTED CIRCUIT BOARD MODIFICATION	LGB		RECOMMENDED	MTH 28-Aug-1995 HRS 2247		-			Complete
<b>MOC : COMPLIED WITH</b>										
SB 560-24-04 24SB-04	LIGHT DIMMING AND TEST PRINTED CIRCUIT BOARD MODIFICATION	TOL		RECOMMENDED	MTH 06-Nov-1992 HRS 1057		A/R			Complete
<b>MOC : COMPLIED WITH</b>										
SB 560-24-05 24SB-05	DUAL FLIGHT DIRECTORS CIRCUIT BREAKER BUSSING INSPECTION/MODIFICATION	TOL		MANDATORY	MTH 21-Aug-1991 HRS 293		A/R			Complete
<b>MOC : COMPLIED WITH</b>										
SB 560-24-08 24SB-08	WING WIRE BUNDLE ROUTING MODIFICATION	TOL		RECOMMENDED	MTH 29-May-1992 HRS 759		A/R			Complete
<b>MOC : COMPLIED WITH</b>										
SB 560-24-10 24SB-10	NOSE AVIONICS GROUND BLOCK MODIFICATION	LGB		RECOMMENDED	MTH 12-Nov-1994 HRS 2020		A/R			Complete
<b>MOC : COMPLIED WITH</b>										
SB 560-24-11 24SB-11	LIGHT DIMMING CIRCUIT J-BOX SCREW AND DIODE MODIFICATION			OPTIONAL	MTH		A/R			
<b>MOC :</b>										
SB 560-24-12 R3 24SB-12 : 560R3	AVIONICS POWER RELAYS REPLACEMENT			OPTIONAL	MTH		-			
<b>MOC :</b>										
SB 560-24-14 24SB-14	WING TIP WIRE BUNDLE PROTECTIVE COVER INSTALLATION	LGB		RECOMMENDED	MTH 10-Sep-1994 HRS 1953		-			Complete
<b>MOC : COMPLIED WITH</b>										
SB 560-24-15 R1 24SB-15 : 560R1	ELECTRICAL CABLE CHAFING PROTECTION INSTALLATION WS 44.0 AND 54.07	LGB		RECOMMENDED	MTH 18-Mar-1996 HRS 2448		-			Complete
<b>MOC : COMPLIED WITH</b>										



# CESCOM 10 - Aircraft Status Report

Owner: **SBM CLEANING COMPANY LLC**  
 Aircraft Model: **560 - CITATION V**  
 Aircraft Serial: **560-0096** Unit: **0096** Reg No: **N10TD**  
 Airworthiness: **09-Apr-1991**  
 Print Date: **31-Aug-2015 3:12PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>6339.1</b>	<b>5713</b>	<b>25-Aug-2015</b>	<b>.57</b>
<b>ENG 1</b>	<b>6307.4</b>	<b>5661</b>	<b>25-Aug-2015</b>	<b>.57</b>
<b>ENG 2</b>	<b>6307.4</b>	<b>5661</b>	<b>25-Aug-2015</b>	<b>.57</b>

## Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB 560-24-15 <i>24SB-15</i>	ELECTRICAL CABLE CHAFING PROTECTION INSTALLATION	VNY		WS 44.0 AND 54.07 RECOMMENDED	MTH 02-Mar-1995 HRS 2104		A/R			Complete
<b>MOC : COMPLIED WITH</b>										
SB 560-24-16 <i>24SB-16</i>	TRIM PC BOARD MODIFICATION AND ELEVATOR ELECTRIC TRIM MOTOR MODIFICATION	TOL		SUPERSEDED	MTH 08-Jan-1998 HRS 2999		-			Complete
<b>MOC : COMPLIED WITH</b>										
SB 560-24-19 R1 <i>24SB-19 : 560R1</i>	OVERVOLTAGE MONITOR SYSTEM INSTALLATION			OPTIONAL	MTH		-			
<b>MOC :</b>										
SB 560-24-20 <i>24SB-20</i>	BATTERY DISCONNECT RELAY ACCESS IMPROVEMENT			OPTIONAL	MTH		-			
<b>MOC : - OPERATOR DOES NOT WISH TO COMPLY AT THIS TIME</b>										
SB 560-24-22 <i>24SB-22</i>	CIRCUIT BREAKER TERMINAL SCREW LENGTH INSPECTION/REPLACEMENT			RECOMMENDED	MTH		-			
<b>MOC :</b>										
SB 560-24-27 R1 <i>24SB-27 : 560R1</i>	WING WIRE ROUTING IMPROVEMENT/FLAP HYDRAULIC LINE INSPECTION			RECOMMENDED	MTH		-			
<b>MOC :</b>										
SB 560-24-29 <i>24SB-29</i>	NO SMOKING LIGHT WIRING MODIFICATION			OPTIONAL	MTH		-			
<b>MOC :</b>										
SB 560-24-37 R3 <i>24SB-37 : 560R3</i>	MAIN POWER WIRE ANCHOR IMPROVEMENT			RECOMMENDED	MTH		-			
<b>MOC :</b>										
SB 560-24-39 <i>24SB-39</i>	SEALED LEAD ACID BATTERY INSTALLATION			OPTIONAL	MTH		-			
<b>MOC :</b>										
SB 560-24-42 <i>24SB-42</i>	RELAY SHIELD INSTALLATION	SMF		MANDATORY	MTH 17-Nov-2005 HRS 4766		-			Complete
<b>MOC : COMPLIED WITH</b>										
SB 560-24-45	ELECTRICAL POWER - MAGNETIC CIRCUIT BREAKER REPLACEMENT			OPTIONAL			A/R			
<b>MOC :</b>										
SL 560-24-05 <i>24SL-05</i>	ANTI-ICE RELAY BASE ORIENTATION MODIFICATION	TOL		RECOMMENDED	MTH 30-Oct-1991 HRS 451		A/R			Complete
<b>MOC : COMPLIED WITH</b>										
SL 560-24-06 <i>24SL-06</i>	MFD SYMBOL GENERATOR WIRE BUNDLE SUPPORT INSTALLATION	TOL		OPTIONAL	MTH 29-May-1992 HRS 759		-			Complete
<b>MOC : COMPLIED WITH</b>										
SL 560-24-07 <i>24SL-07</i>	HARTMAN BATTERY DISCONNECT RELAY PART NUMBER A876K INSPECTION/REPLACE	TOL		RECOMMENDED	MTH 06-Nov-1992 HRS 1057		A/R			Complete
<b>MOC : COMPLIED WITH</b>										



# CESCOM 10 - Aircraft Status Report

Owner: **SBM CLEANING COMPANY LLC**  
 Aircraft Model: **560 - CITATION V**  
 Aircraft Serial: **560-0096** Unit: **0096** Reg No: **N10TD**  
 Airworthiness: **09-Apr-1991**  
 Print Date: **31-Aug-2015 3:12PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>6339.1</b>	<b>5713</b>	<b>25-Aug-2015</b>	<b>.57</b>
<b>ENG 1</b>	<b>6307.4</b>	<b>5661</b>	<b>25-Aug-2015</b>	<b>.57</b>
<b>ENG 2</b>	<b>6307.4</b>	<b>5661</b>	<b>25-Aug-2015</b>	<b>.57</b>

## Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB 560-25-09 25SB-09	PASSENGER SEAT BACK PIVOT PLATE ASSEMBLY INSPECTION/REPLACEMENT	TOL		RECOMMENDED	MTH 15-Dec-1993 HRS 1647		A/R			Complete
<b>MOC : COMPLIED WITH</b>										
SB 560-25-16 R1 25SB-16 : 560R1	WINDOW TRIM INSULATION IMPROVEMENTS	TOL		RECOMMENDED	MTH 05-Jun-1998 HRS 3159		-			Complete
<b>MOC : COMPLIED WITH</b>										
SB 560-25-16 25SB-16	WINDOW TRIM INSULATION IMPROVEMENTS	LGB		RECOMMENDED	MTH 18-Mar-1996 HRS 2448		A/R			Complete
<b>MOC : COMPLIED WITH</b>										
SB 560-25-19 25SB-19	TSO C91A EMERGENCY LOCATOR TRANSMITTER INSTALLATION			CANCELLED	MTH		A/R			
<b>MOC :</b>										
SB 560-25-23 25SB-23	FLIGHT CREW SEAT PAN REINFORCEMENT			OPTIONAL	MTH		-			
<b>MOC :</b>										
SB 560-25-26 R1 25SB-26 : 560R1	EQUIPMENT/FURNISHINGS - ARTEX C406-2 THREE-FREQUENCY EMERGENCY LOCATOR TRANSMITTER (ELT)			SUPERSEDED			A/R			
<b>MOC : - SERVICE BULLETIN ON HOLD.</b>										
SB 560-25-26 R3	ARTEX C406-2 THREE-FREQUENCY EMERGENCY LOCATOR TRANSMITTER (ELT)			OPTIONAL			A/R			
<b>MOC :</b>										
SB 560-25-29 R1 25SB-29 : 560R1	GLARESHIELD LEATHER STRIP INSTALLATION			OPTIONAL	MTH		-			
<b>MOC :</b>										
SB 560-25-32 R1 25SB-32 : 560R1	EQUIPMENT/FURNISHINGS - TOILET TRAY AND PAD INSTALLATION			OPTIONAL	MTH		A/R			
<b>MOC :</b>										
SL 560-25-03 25SL-03	LIFE PRESERVERS AND INDIVIDUAL FLOTATION DEVICES REPLACEMENT	PIT		MANDATORY	MTH 27-Sep-1997 HRS 2912		A/R			Complete
<b>MOC : COMPLIED WITH - NOT APPLICABLE BY DATE OF MANUFACTURE</b>										
SL 560-25-04 25SL-04	GLARESHIELD ATTACHMENT SCREW(S) INSPECTION/REPLACEMENT			RECOMMENDED	MTH		-			
<b>MOC :</b>										
SL 560-25-09 25SL-09	EQUIPMENT/FURNISHINGS - TRANSMITTAL OF PACIFIC SCIENTIFIC AEROSPACE SERVICE BULLETIN SB 25-1111432, INFORMATION REGARDING THE POTENTIAL FAILURE OF THE GUARDED ROTARYBUCKLE PLASTIC HANDLE	SMF		MANDATORY	MTH 25-Jun-2008 HRS 5180		A/R			Complete
<b>MOC : COMPLIED WITH</b>										
SB 560-26-01 26SB-01	FIRE BOTTLE WIRE IDENTIFICATION SLEEVE INSTALLATION	SMF		MANDATORY	DAYS 17-Nov-2005 HRS 4766		A/R			Complete
<b>MOC : COMPLIED WITH</b>										



# CESCOM 10 - Aircraft Status Report

Owner: **SBM CLEANING COMPANY LLC**  
 Aircraft Model: **560 - CITATION V**  
 Aircraft Serial: **560-0096** Unit: **0096** Reg No: **N10TD**  
 Airworthiness: **09-Apr-1991**  
 Print Date: **31-Aug-2015 3:12PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>6339.1</b>	<b>5713</b>	<b>25-Aug-2015</b>	<b>.57</b>
<b>ENG 1</b>	<b>6307.4</b>	<b>5661</b>	<b>25-Aug-2015</b>	<b>.57</b>
<b>ENG 2</b>	<b>6307.4</b>	<b>5661</b>	<b>25-Aug-2015</b>	<b>.57</b>

## Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
ASL 560-26-01 26ASL-01	FIRE PROTECTION - TRANSMITTAL OF MEGGITT SAFETY SYSTEMS SERVICE BULLETIN 26-36 - THERMISTORS DETECTORS	SMF		MANDATORY	MTH 25-Jun-2008 HRS 5180		A/R			Complete
<b>MOC : COMPLIED WITH</b>										
SB 560-27-05 R1 27SB-05 : 560R1	FLIGHT CONTROLS - EXTENDED PEDESTAL AILERON PULLEY BRACKET MODIFICATION	ICT		SUPERSEDED	MTH 26-Feb-1992 HRS 591		A/R			Complete
<b>MOC : COMPLIED WITH</b>										
SB 560-27-07 R1 27SB-07 : 560R1	ELEVATOR SERVO CABLE INSTALLATION MODIFICATION	LGB		SUPERSEDED	MTH 06-Apr-1994 HRS 1794		A/R			Complete
<b>MOC : COMPLIED WITH</b>										
SB 560-27-07 R4 27SB-07 : 560R4	ELEVATOR SERVO CABLE INSTALLATION MODIFICATION			OPTIONAL	MTH		-			
<b>MOC :</b>										
SB 560-27-09 27SB-09	IMPROVED ELEVATOR TRIM SECTOR INSTALLATION	LGB		SUPERSEDED	MTH 18-Mar-1996 HRS 2448		A/R			Complete
<b>MOC : COMPLIED WITH</b>										
SB 560-27-11 27SB-11	AILERON/RUDDER INTERCONNECT CLAMP MODIFICATION	TOL		RECOMMENDED	MTH 05-Jun-1998 HRS 3159		-			Complete
<b>MOC : COMPLIED WITH</b>										
SB 560-27-13 27SB-13	TRIM TAB ACTUATOR GREASE FITTING INSTALLATION			OPTIONAL	MTH		-			
<b>MOC :</b>										
SB 560-27-22 27SB-22	FLIGHT CONTROLS - RUDDER PEDAL SUPPORT IMPROVEMENT			DISCRETIONARY	MTH		A/R			
<b>MOC :</b>										
SB 560-27-23	FLIGHT CONTROLS - ELEVATOR BELLCRANK SUPPORT BRACKET INSPECTION AND REPAIR			MANDATORY	MTH		A/R			N/A
<b>MOC : NOT APPLICABLE - BY SERIAL NUMBER APPLICABLE TO SERIAL NUMBERS -0539 THRU -0815.</b>										
SL 560-27-03 27SL-03	FLAP HYDRAULIC HOSE FITTING CLOCKING INSPECTION/ADJUSTMENT	TOL		RECOMMENDED	MTH 15-Dec-1993 HRS 1647		-			Complete
<b>MOC : COMPLIED WITH</b>										
SL 560-27-05 27SL-05	AILERON/RUDDER INTERCONNECT RIGGING INSPECTION	TOL		RECOMMENDED	MTH 08-Jan-1998 HRS 2999		A/R			Complete
<b>MOC : COMPLIED WITH</b>										
SL 560-27-06 27SL-06	RUDDER/AILERON INTERCONNECT BOLT INSPECTION	TOL		SUPERSEDED	MTH 08-Jan-1998 HRS 2999		A/R			Complete
<b>MOC : COMPLIED WITH</b>										
SL 560-27-08 27SL-08	LOWER CABLE GUARD INSPECTION			RECOMMENDED	MTH		-			
<b>MOC :</b>										
SB 560-28-02 28SB-02	WING LEADING EDGE RIB FLAPPER VALVES INSTALLATION	LBE		OPTIONAL	MTH		-			
<b>MOC : - OPERATOR DOES NOT WISH TO COMPLY AT THIS TIME</b>										



# CESCOM 10 - Aircraft Status Report

Owner: **SBM CLEANING COMPANY LLC**  
 Aircraft Model: **560 - CITATION V**  
 Aircraft Serial: **560-0096** Unit: **0096** Reg No: **N10TD**  
 Airworthiness: **09-Apr-1991**  
 Print Date: **31-Aug-2015 3:12PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>6339.1</b>	<b>5713</b>	<b>25-Aug-2015</b>	<b>.57</b>
<b>ENG 1</b>	<b>6307.4</b>	<b>5661</b>	<b>25-Aug-2015</b>	<b>.57</b>
<b>ENG 2</b>	<b>6307.4</b>	<b>5661</b>	<b>25-Aug-2015</b>	<b>.57</b>

## Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB 560-28-03 28SB-03	MOTIVE FLOW FUEL LINE INSPECTION AND SUPPORT INSTALLATION	TOL		RECOMMENDED	MTH 25-May-1993 HRS 1346		-			Complete
	<b>MOC : COMPLIED WITH</b>									
SB 560-28-04 28SB-04	FUEL SYS PLUMBING CLAMP ADDITIONS	LGB		RECOMMENDED	MTH 18-Mar-1996 HRS 2448		-			Complete
	<b>MOC : COMPLIED WITH</b>									
SB 560-28-05 28SB-05	IMPROVED FUEL CROSSFEED SELECT KNOB AVAILABILITY			OPTIONAL	MTH		-			
	<b>MOC :</b>									
SB 560-28-07 28SB-07	FUEL LINE SUPPORT INSTALLATION	TOL		RECOMMENDED	MTH 26-Oct-1999 HRS 3608		-			Complete
	<b>MOC : COMPLIED WITH</b>									
SB 560-28-10 28SB-10	WING FUEL BOOST PUMP WIRE ROUTING IMPROVEMENT	SAC		MANDATORY	MTH 28-Jun-2004 HRS 4560		-			Complete
	<b>MOC : COMPLIED WITH</b>									
SB 560-28-14 R1	FUEL - FUEL CHECK VALVE MODIFICATION			RECOMMENDED	MTH		-			
	<b>MOC :</b>									
SB 560-28-14 28SB-14	FUEL - FUEL CHECK VALVE MODIFICATION			RECOMMENDED	MTH	4	A/R			
	<b>MOC :</b>									
SL 560-28-01 R1 28SL-01 : 560R1	FUEL COMPENSATOR INSTALLATION ATTACHMENT INSPECTION	TOL		SUPERSEDED	MTH 06-Nov-1992 HRS 1057			A/R		Complete
	<b>MOC : COMPLIED WITH</b>									
SL 560-28-01 28SL-01	FUEL QUANTITY COMPENSATOR INSTALLATION ATTACHMENT INSPECTION	ICT		RECOMMENDED	MTH 26-Feb-1992 HRS 591		-			Complete
	<b>MOC : COMPLIED WITH</b>									
SLA 560-28-03 28SLA03	TRANSMITTAL OF PARKER HANNIFIN CORPORATION - AIRBORNE AIR & FUEL PRODUCTS NO. 41, RAPCO FLEET SUPPORT INC. OVERHAUL OF AIRBORNE FUEL PUMPS	LGB		SUPERSEDED	MTH 01-Dec-1996 HRS 2692			A/R		Complete
	<b>MOC : COMPLIED WITH</b>									
SB 560-29-01 29SB-01	ECOLOGY (OVERFLOW) BOTTLE INSTALLATION			OPTIONAL	MTH		-			
	<b>MOC :</b>									
SB 560-29-02 29SB-02	IMPROVED HYDRAULIC PUMP PRESSURE HOSE INSTALLATION	LGB		RECOMMENDED	MTH 01-Dec-1996 HRS 2692		-			Complete
	<b>MOC : COMPLIED WITH</b>									
SB 560-29-04 R1 29SB-04 : 560R1	HYDRAULIC TUBE REPLACEMENT	SMF		MANDATORY	MTH 17-Nov-2005 HRS 4766		-			Complete
	<b>MOC : COMPLIED WITH</b>									
SB 560-29-08 R1	HYDRAULIC PRESSURE LINE ROUTING IMPROVEMENT			RECOMMENDED				A/R		
	<b>MOC :</b>									



# CESCOM 10 - Aircraft Status Report

Owner: **SBM CLEANING COMPANY LLC**  
 Aircraft Model: **560 - CITATION V**  
 Aircraft Serial: **560-0096** Unit: **0096** Reg No: **N10TD**  
 Airworthiness: **09-Apr-1991**  
 Print Date: **31-Aug-2015 3:12PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>6339.1</b>	<b>5713</b>	<b>25-Aug-2015</b>	<b>.57</b>
<b>ENG 1</b>	<b>6307.4</b>	<b>5661</b>	<b>25-Aug-2015</b>	<b>.57</b>
<b>ENG 2</b>	<b>6307.4</b>	<b>5661</b>	<b>25-Aug-2015</b>	<b>.57</b>

## Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB 560-29-08	HYDRAULIC PRESSURE LINE ROUTING IMPROVEMENT			RECOMMENDED			A/R			
	<b>MOC :</b>									
SB 560-30-02 30SB-02	ANTI-ICE TEMPERATURE SENSOR SUPPORT ANGLE MODIFICATION	TOL		SUPERSEDED	MTH 29-May-1992 HRS 759		A/R			Complete
	<b>MOC : COMPLIED WITH</b>									
SB 560-30-03 30SB-03	ENGINE BLEED AIR ANTI-ICE TEMPERATURE SENSORS REPLACEMENT	TOL		RECOMMENDED	MTH 29-May-1992 HRS 759		-			Complete
	<b>MOC : COMPLIED WITH</b>									
SB 560-30-04 30SB-04	TAILCONE DEICE LINES SUPPORT INSPECTION/INSTALLATION	TOL		RECOMMENDED	MTH 03-Sep-1993 HRS 1503		-			Complete
	<b>MOC : COMPLIED WITH</b>									
SB 560-30-06 30SB-06	PICCOLO TUBE INSTALLATION INSPECTION AND MODIFICATION	LGB		SUPERSEDED	MTH 10-Sep-1994 HRS 1953		A/R			Complete
	<b>MOC : COMPLIED WITH</b>									
SB 560-30-10 30SB-10	WINDSHIELD ANTI-ICE BLEED AIR SWITCH INSPECTION/REPLACEMENT	SAC		MANDATORY	MTH 28-Jun-2004 HRS 4560		-			Complete
	<b>MOC : COMPLIED WITH - NOT APPLICABLE</b>									
SB 560-30-15 30SB-15	ICE AND RAIN PROTECTION - ENGINE INLET ANTI-ICE VALVE SUPPORT BRACKET INSTALLATION			RECOMMENDED	MTH		A/R			
	<b>MOC :</b>									
SL CIL-30-01 R1	APPROVED DEICING PROGRAM UPDATES			INFORMATIONAL			-			
	<b>MOC :</b>									
SL 560-30-05 R1 30SL-05 : 560R1	ENGINE ANTI-ICE VALVE INSPECTION	LGB		RECOMMENDED	MTH 10-Sep-1994 HRS 1953		A/R			Complete
	<b>MOC : COMPLIED WITH</b>									
SL 560-30-05 30SL-05	ENGINE ANTI-ICE VALVE INSPECTION	LGB		SUPERSEDED	MTH 06-Apr-1994 HRS 1794		A/R			Complete
	<b>MOC : COMPLIED WITH</b>									
SB 560-31-09 31SB-09	INADVERTENT POWER BRAKE LOW PRESSURE ANNUNCIATION			RECOMMENDED	MTH		-			
	<b>MOC :</b>									
SB 560-31-15 31SB-15	INDICATING/RECORDING SYSTEMS - INSTRUMENT PANEL MODIFICATION FOR AOA TEST SWITCH			OPTIONAL	MTH		A/R			
	<b>MOC :</b>									
SB 560-32-03 R5 32SB-03 : 560R5	GRAVEL RUNWAY PROTECTION			OPTIONAL	MTH		-			
	<b>MOC :</b>									
SB 560-32-06 32SB-06	BFGOODRICH BRAKE BLEEDER BLOCK INSTALLATION AND HOSE REPLACEMENT	VNY		OPTIONAL	MTH 02-Mar-1995 HRS 2104		-			Complete
	<b>MOC : COMPLIED WITH</b>									



# CESCOM 10 - Aircraft Status Report

Owner: **SBM CLEANING COMPANY LLC**  
 Aircraft Model: **560 - CITATION V**  
 Aircraft Serial: **560-0096** Unit: **0096** Reg No: **N10TD**  
 Airworthiness: **09-Apr-1991**  
 Print Date: **31-Aug-2015 3:12PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>6339.1</b>	<b>5713</b>	<b>25-Aug-2015</b>	<b>.57</b>
<b>ENG 1</b>	<b>6307.4</b>	<b>5661</b>	<b>25-Aug-2015</b>	<b>.57</b>
<b>ENG 2</b>	<b>6307.4</b>	<b>5661</b>	<b>25-Aug-2015</b>	<b>.57</b>

## Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB 560-32-07 32SB-07	NOSE GEAR DOORS TORQUE TUBE INSTALLATION INSP/MOD TOL			RECOMMENDED	MTH 25-Feb-1993 HRS 1203		-			Complete
<b>MOC : COMPLIED WITH</b>										
SB 560-32-09 32SB-09	MLG WHEEL WELL AFT SPAR BOX HYDRAULIC/PNEUMATIC LINES GROMMET REPLACEMENT TOL			RECOMMENDED	MTH 25-Feb-1993 HRS 1203		-			Complete
<b>MOC : COMPLIED WITH</b>										
SB 560-32-10 32SB-10	ANTI-SKID WIRING MODIFICATION LGB			SUPERSEDED	MTH 18-Mar-1996 HRS 2448		A/R			Complete
<b>MOC : COMPLIED WITH</b>										
SB 560-32-11 32SB-11	UPLOCK SWITCH COVER MOD LGB			RECOMMENDED	MTH 28-Aug-1995 HRS 2247		-			Complete
<b>MOC : COMPLIED WITH</b>										
SB 560-32-15 32SB-15	ANTI-SKID DRIVE CLIP REPLACEMENT LGB			RECOMMENDED	MTH 01-Dec-1996 HRS 2692		-			Complete
<b>MOC : COMPLIED WITH</b>										
SB 560-32-16 32SB-16	TRANSMITTAL OF BFGOODRICH SB195-183-32-1, MAIN BRAKE SHUTTLE VALVE IMPROVEMENTS TOL			RECOMMENDED	MTH 08-Jan-1998 HRS 2999		-			Complete
<b>MOC : COMPLIED WITH</b>										
SB 560-32-17 32SB-17	POWER BRAKE HYDRAULIC PUMP SCREW REPLACEMENT TOL			SUPERSEDED	MTH 08-Jan-1998 HRS 2999		A/R			Complete
<b>MOC : COMPLIED WITH</b>										
SB 560-32-18 32SB-18	ANTI-SKID SYSTEM DIODE REMOVAL TOL			RECOMMENDED	MTH 05-Jun-1998 HRS 3159		-			Complete
<b>MOC : COMPLIED WITH</b>										
SB 560-32-19 32SB-19	BRAKE MOTOR COUPLING REPLACEMENT TOL			RECOMMENDED	MTH 05-Jun-1998 HRS 3159		-			Complete
<b>MOC : COMPLIED WITH</b>										
SB 560-32-20 R1 32SB-20 : 560R1	BRAKE LINE REPLACEMENT			RECOMMENDED	MTH		-			
<b>MOC :</b>										
SB 560-32-22 R3 32SB-22 : 560R3	LANDING GEAR ON GROUND OPERATION AND MODIFICATION			RECOMMENDED	MTH		-			
<b>MOC :</b>										
SB 560-32-31 R1 32SB-31 : 560R1	PARKING BRAKE CABLE REPLACEMENT			OPTIONAL	MTH		A/R			
<b>MOC :</b>										
SB 560-32-39 32SB-39	LANDING GEAR - NLG ACTUATOR REPLACEMENT SMF			MANDATORY	MTH 19-Jul-2009 HRS 5308		A/R			Complete
<b>MOC : COMPLIED WITH</b>										
SB 560-32-42 R1	REPLACEMENT OF BLEEDER SCREWS AND FITTINGS WITH BLEEDER PLUGS RECOMMENDED				HRS		300		6264.27	-74.83
<b>MOC :</b>										
SB 560-32-42	REPLACEMENT OF BLEEDER SCREWS AND FITTINGS WITH BLEEDER PLUGS RECOMMENDED						-			<b>Over Due</b>
<b>MOC :</b>										

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.





# CESCOM 10 - Aircraft Status Report

Owner: **SBM CLEANING COMPANY LLC**  
 Aircraft Model: **560 - CITATION V**  
 Aircraft Serial: **560-0096** Unit: **0096** Reg No: **N10TD**  
 Airworthiness: **09-Apr-1991**  
 Print Date: **31-Aug-2015 3:12PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>6339.1</b>	<b>5713</b>	<b>25-Aug-2015</b>	<b>.57</b>
<b>ENG 1</b>	<b>6307.4</b>	<b>5661</b>	<b>25-Aug-2015</b>	<b>.57</b>
<b>ENG 2</b>	<b>6307.4</b>	<b>5661</b>	<b>25-Aug-2015</b>	<b>.57</b>

## Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SL CIL-32-01	IMPROVED NOSE WHEEL GREASE SEAL			INFORMATIONAL			-			
	<b>MOC :</b>									
SL CIL-32-03	NLG UPLOCK ROLLER BRACKET INSPECTION			RECOMMENDED	MTH HRS		300		6459.05	119.95
	<b>MOC :</b>									
SL CIL-32-04	WIRELESS TIRE PRESSURE MONITORING SYSTEM INSTALLATION			INFORMATIONAL			-			
	<b>MOC :</b>									
SL 560-32-08 R1 32SL-08 : 560R1	STRUT EXTENSION INSPECTION AND PISTON UPPER BEARING RETENTION IMPROVEMENT	TOL		RECOMMENDED	MTH 06-Nov-1992 HRS 1057		A/R			Complete
	<b>MOC : COMPLIED WITH</b>									
SL 560-32-17 32SL-17	BRAKE AND SPOILER/SPEEDBRAKE EXTEND HYDRAULIC LINES(S) ROUTING INSPECTION/MODIFICATION	TOL		RECOMMENDED	MTH 29-May-1992 HRS 759		-			Complete
	<b>MOC : COMPLIED WITH</b>									
SL 560-32-18 32SL-18	NOSE GEAR TRUNNION FINISH INSPECTION/REFINISH	TOL		RECOMMENDED	MTH 06-Nov-1992 HRS 1057		-			Complete
	<b>MOC : COMPLIED WITH</b>									
SL 560-32-24 32SL-24	MAIN LANDING GEAR WHEEL WELL BRAKE LINE INSPECTION	LBE		MANDATORY	MTH 13-Jan-1993 HRS 1150		A/R			Complete
	<b>MOC : COMPLIED WITH</b>									
SL 560-32-25 R1 32SL-25 : 560R1	TEIJIN SEIKI MAIN AND NOSE LANDING GEAR ACTUATOR DOWN AND LOCKED SWITCH INSPECTION/REPLACEMENT	TOL		SUPERSEDED	MTH 03-Sep-1993 HRS 1503		A/R			Complete
	<b>MOC : COMPLIED WITH</b>									
SL 560-32-29 32SL-29	NOSE LANDING GEAR WHEEL WELL AND TIRE ASSEMBLY AND WIDE DOOR ATTACH HARDWARE INSPECTION/REPLACEMENT	LGB		RECOMMENDED	MTH 12-Nov-1994 HRS 2020		-			Complete
	<b>MOC : COMPLIED WITH</b>									
SL 560-32-31 32SL-31	MAIN LANDING GEAR EXTEND PNEUMATIC LINE CLEARANCE INSPECTION	LGB		SUPERSEDED	MTH 28-Aug-1995 HRS 2247		A/R			Complete
	<b>MOC : COMPLIED WITH</b>									
SL 560-32-34 32SL-34	NOSE GEAR STEERING BUNGEE INSPECTION	TOL		RECOMMENDED	MTH 14-Mar-1999 HRS 3430		-			Complete
	<b>MOC : COMPLIED WITH</b>									
SL 560-32-40 R1 32SL-40 : 560R1	NOSE LANDING GEAR ICE PROTECTION BOOT INSTALLATION			OPTIONAL	MTH		-			
	<b>MOC :</b>									
SL 560-32-41 32SL-41	GOODRICH NOSE WHEEL INSPECTION/REPLACEMENT	SMF		MANDATORY	MTH 09-Feb-2007 HRS 4922		A/R			Complete
	<b>MOC : COMPLIED WITH</b>									
SL 560-32-50 32SL-50	LANDING GEAR - EMERGENCY GEAR RELEASE INSPECTION	SMF		MANDATORY	MTH 19-Jul-2009 HRS 5308		A/R			Complete
	<b>MOC : COMPLIED WITH</b>									

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



# CESCOM 10 - Aircraft Status Report

Owner: **SBM CLEANING COMPANY LLC**  
 Aircraft Model: **560 - CITATION V**  
 Aircraft Serial: **560-0096** Unit: **0096** Reg No: **N10TD**  
 Airworthiness: **09-Apr-1991**  
 Print Date: **31-Aug-2015 3:12PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>6339.1</b>	<b>5713</b>	<b>25-Aug-2015</b>	<b>.57</b>
<b>ENG 1</b>	<b>6307.4</b>	<b>5661</b>	<b>25-Aug-2015</b>	<b>.57</b>
<b>ENG 2</b>	<b>6307.4</b>	<b>5661</b>	<b>25-Aug-2015</b>	<b>.57</b>

## Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SL 560-32-51	LANDING GEAR - UNAPPROVED NOSE LANDING GEAR TIRE INSPECTION			RECOMMENDED			A/R			
	<b>MOC :</b>									
SB 560-33-04 R1 33SB-04 : 560R1	LANDING LIGHT BULB PROTECTION LBE			OPTIONAL	MTH 18-Apr-1991 HRS 29		-			Complete
	<b>MOC : COMPLIED WITH</b>									
SB 560-33-06 R1 33SB-06 : 560R1	EXIT SIGN REPLACEMENT *CF			OPTIONAL	MTH		-			
	<b>MOC :</b>									
SB 560-33-07 33SB-07	TAIL FLOODLIGHT INSTALLATION			OPTIONAL	MTH		A/R			
	<b>MOC :</b>									
SB 560-33-08 R1 33SB-08 : 560R1	WINGTIP NAV/COLLISION LIGHT MODIFICATION LGB			OPTIONAL	MTH 12-Nov-1994 HRS 2020		-			Complete
	<b>MOC : COMPLIED WITH</b>									
SB 560-33-09 33SB-09	WING TIP LANDING LIGHT INSTALLATION *CF			SUPERSEDED	MTH		A/R			
	<b>MOC :</b>									
SB 560-33-11 33SB-11	LANDING LIGHT CIRCUIT SWITCH MODULE INSTALLATION			OPTIONAL	MTH		-			
	<b>MOC :</b>									
SB 560-33-14 33SB-14	TAIL NAVIGATION LIGHT SOCKET MODIFICATION LGB			SUPERSEDED	MTH 28-Aug-1995 HRS 2247		A/R			Complete
	<b>MOC : COMPLIED WITH</b>									
SB 560-33-15 33SB-15	INDIRECT LIGHTING LAMP AND CONNECTOR UPGRADE			OPTIONAL	MTH		-			
	<b>MOC :</b>									
SB 560-33-16 R3 33SB-16 : 560R3	EMERGENCY LIGHTING BATTERY PACK UPGRADE			OPTIONAL	MTH		A/R			
	<b>MOC :</b>									
SB 560-33-16 R4	EMERGENCY LIGHTING BATTERY PACK UPGRADE			OPTIONAL			-			
	<b>MOC :</b>									
SB 560-33-22 33SB-22	LIGHTS - LED TAIL POSITION LIGHT INSTALLATION			OPTIONAL	MTH		A/R			
	<b>MOC :</b>									
SB 560-33-31 33SB-31	LED TAIL FLOODLIGHT UPGRADE			OPTIONAL	MTH		A/R			
	<b>MOC :</b>									
SB 560-33-32	LED REPLACEMENT LIGHT FOR THE BAGGAGE COMPARTMENT			OPTIONAL			A/R			
	<b>MOC :</b>									
SB 560-33-33 R1	LED REPLACEMENT LIGHT FOR THE WING LANDING/TAXI LIGHT ASSEMBLY			OPTIONAL			-			
	<b>MOC :</b>									
SB 560-33-35	LED LANDING GEAR INDICATION LIGHT INSTALLATION			OPTIONAL			A/R			
	<b>MOC :</b>									

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



# CESCOM 10 - Aircraft Status Report

Owner: **SBM CLEANING COMPANY LLC**  
 Aircraft Model: **560 - CITATION V**  
 Aircraft Serial: **560-0096** Unit: **0096** Reg No: **N10TD**  
 Airworthiness: **09-Apr-1991**  
 Print Date: **31-Aug-2015 3:12PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>6339.1</b>	<b>5713</b>	<b>25-Aug-2015</b>	<b>.57</b>
<b>ENG 1</b>	<b>6307.4</b>	<b>5661</b>	<b>25-Aug-2015</b>	<b>.57</b>
<b>ENG 2</b>	<b>6307.4</b>	<b>5661</b>	<b>25-Aug-2015</b>	<b>.57</b>

## Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 (ENG) DUE 1 TSO 2 (ENG) DUE 2	Remains Remains
SL CIL-33-01	TRANSMITTAL OF RADIANT POWER CORP. SB-RPC-001, PROCEDURE TO REPLACE OBSOLETE CONNECTOR ASSEMBLY FOR CBS28 EMERGENCY BATTERY			INFORMATIONAL			-		
<b>MOC :</b>									
SL 560-33-02 R1 33SL-02 : 560R1	CABIN INDIRECT LIGHTING SYSTEM INSPECTION LGB			SUPERSEDED	MTH 27-Jan-1996 HRS 2409		A/R		Complete
<b>MOC : COMPLIED WITH</b>									
SL 560-33-02 R2 33SL-02 : 560R2	CABIN INDIRECT LIGHTING SYSTEM INSPECTION TOL			RECOMMENDED	MTH 06-Jul-1997 HRS 2844		-		Complete
<b>MOC : COMPLIED WITH</b>									
SL 560-33-05 R1 33SL-05 : 560R1	LANDING LIGHT SWITCH INSPECTION/REPLACEMENT TOL			MANDATORY	MTH 15-Dec-1993 HRS 1647		-		Complete
<b>MOC : COMPLIED WITH</b>									
SB 560-34-109 34SB-109	5 AMP-HOUR STANDBY GYRO BATTERY INSTALLATION OPTIONAL				MTH		-		
<b>MOC :</b>									
SB 560-34-112 R3 34SB-112 : 560R3	MARK VIII ENHANCED GROUND PROXIMITY WARNING SYSTEM (EGPWS) INSTALLATION OPTIONAL				MTH		-		
<b>MOC :</b>									
SB 560-34-113 R1 34SB-113 : 560R1	NAVIGATION - TRAFFIC COLLISION AVOIDANCE SYSTEM (TCAS) II AND HONEYWELL TRANSPONDER UPGRADE FOR ELEMENTARY SURVEILLANCE OPTIONAL				MTH		A/R		
<b>MOC :</b>									
SB 560-34-116 34SB-116	TRAFFIC COLLISION AVOIDANCE SYSTEM (TCAS) II AND MST-67A TRANSPONDER FOR ELEMENTARY SURVEILLANCE SUPERSEDED				MTH		A/R		
<b>MOC :</b>									
SB 560-34-121 34SB-121	SANDEL ST3400 TAWS INSTALLATION OPTIONAL				MTH		-		
<b>MOC :</b>									
SB 560-34-143 R1 34SB-143 : 560R1	NAVIGATION - SPEED LIMITATION PLACARD INSTALLATION MCC			MANDATORY	MTH 15-Jan-2008 HRS 5071		A/R		Complete
<b>MOC : COMPLIED WITH</b>									
SB 560-34-156	NAVIGATION - UNIVERSAL SOLID STATE DATA TRANSFER UNIT (SSDTU) UPGRADE OPTIONAL						A/R		
<b>MOC :</b>									
SB 560-34-23 34SB-23	VN212 SIGNAL GROUND WIRING MODIFICATION OPTIONAL				MTH		-		
<b>MOC :</b>									
SB 560-34-27 34SB-27	FMS/COMM2 NOISE REDUCTION IMPROVEMENTS LGB			SUPERSEDED	MTH 06-Apr-1994 HRS 1794		A/R		Complete
<b>MOC : COMPLIED WITH</b>									
SB 560-34-28 34SB-28	GLOBAL NAVIGATION MANAGEMENT UNIT UPGRADE OPTIONAL				MTH		-		
<b>MOC : - NOT APPLICABLE-EQUIPMENT NOT INSTALLED</b>									



# CESCOM 10 - Aircraft Status Report

Owner: **SBM CLEANING COMPANY LLC**  
 Aircraft Model: **560 - CITATION V**  
 Aircraft Serial: **560-0096** Unit: **0096** Reg No: **N10TD**  
 Airworthiness: **09-Apr-1991**  
 Print Date: **31-Aug-2015 3:12PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>6339.1</b>	<b>5713</b>	<b>25-Aug-2015</b>	<b>.57</b>
<b>ENG 1</b>	<b>6307.4</b>	<b>5661</b>	<b>25-Aug-2015</b>	<b>.57</b>
<b>ENG 2</b>	<b>6307.4</b>	<b>5661</b>	<b>25-Aug-2015</b>	<b>.57</b>

## Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB 560-34-32 <i>34SB-32</i>	GNS-X OFFSET WAYPOINT S/W UPGRADE	TOL		RECOMMENDED	MTH 06-Nov-1992 HRS 1057		-			Complete
<b>MOC : COMPLIED WITH</b>										
SB 560-34-34 <i>34SB-34</i>	MULTIFUNCTION DISPLAY SYMBOL GENERATOR WIRE BUNDLE ROUTING MODIFICATION	PCT		OPTIONAL	MTH 17-Sep-1998 HRS 3288		-			Complete
<b>MOC : COMPLIED WITH</b>										
SB 560-34-36 <i>34SB-36</i>	HONEYWELL PRIMUS RADIO RACK COAX CONNECTOR REPLACEMENT	LGB		SUPERSEDED	MTH 12-Nov-1994 HRS 2020		A/R			Complete
<b>MOC : COMPLIED WITH</b>										
SB 560-34-37 <i>34SB-37</i>	HONEYWELL PRIMUS RADIO ADF SYSTEM IMPROVEMENTS	LGB		RECOMMENDED	MTH 12-Nov-1994 HRS 2020		-			Complete
<b>MOC : COMPLIED WITH</b>										
SB 560-34-40 R1 <i>34SB-40 : 560R1</i>	P870 RADAR RECEIVER/TRANSMITTER REPLACEMENT (FOR REDUCED COMM RADIO INTERFERENCE)	VNY		OPTIONAL	MTH 07-Dec-1994 HRS 2043		-			Complete
<b>MOC : COMPLIED WITH</b>										
SB 560-34-44 <i>34SB-44</i>	KOLLSMAN AIRSPEED INDICATOR SERVICE TEST			OPTIONAL	MTH		-			
<b>MOC :</b>										
SB 560-34-46 <i>34SB-46</i>	HONEYWELL RMU SOFTWARE UPDATE			SUPERSEDED	MTH		A/R			
<b>MOC :</b>										
SB 560-34-50 R1 <i>34SB-50 : 560R1</i>	INTERMITTENT RUDDER KICK CORRECTION MODIFICATION	LGB		RECOMMENDED	MTH 28-Aug-1995 HRS 2247		-			Complete
<b>MOC : COMPLIED WITH</b>										
SB 560-34-54 <i>34SB-54</i>	AIRSPEED INDICATOR WITH OVERSPEED/LOW SPEED WARNING SWITCHES INSTALLATION			OPTIONAL	MTH		-			
<b>MOC :</b>										
SB 560-34-59 <i>34SB-59</i>	COPILOT ALTIMETER INSTALLATION - KOLLSMAN			OPTIONAL	MTH		-			
<b>MOC :</b>										
SB 560-34-60 <i>34SB-60</i>	PRIMUS 870 RADAR GERMAN CERTIFICATION UPGRADE			OPTIONAL	MTH		-			
<b>MOC :</b>										
SB 560-34-69 R1 <i>34SB-69 : 560R1</i>	SAFE FLIGHT ANGLE-OF-ATTACK COMPUTER MODIFICATION	TOL		SUPERSEDED	MTH 05-Jun-1998 HRS 3159		A/R			Complete
<b>MOC : COMPLIED WITH</b>										
SB 560-34-70 <i>34SB-70</i>	TELEDYNE ANGLE-OF-ATTACK COMPUTER MODIFICATION	PIT		SUPERSEDED	MTH 05-Oct-1998 HRS 3296		A/R			Complete
<b>MOC : COMPLIED WITH - NOT APPLICABLE-EQUIPMENT NOT INSTALLED</b>										
SB 560-34-75 R1 <i>34SB-75 : 560R1</i>	STATIC PORT INSPECTION/MODIFICATION	SMF		OPTIONAL	MTH 20-Apr-2005 HRS 4685		-			Complete
<b>MOC : COMPLIED WITH</b>										
SB 560-34-89 <i>34SB-89</i>	UNS-1K 603.4 SOFTWARE UPGRADE			RECOMMENDED	MTH		-			
<b>MOC :</b>										



# CESCOM 10 - Aircraft Status Report

Owner: **SBM CLEANING COMPANY LLC**  
 Aircraft Model: **560 - CITATION V**  
 Aircraft Serial: **560-0096** Unit: **0096** Reg No: **N10TD**  
 Airworthiness: **09-Apr-1991**  
 Print Date: **31-Aug-2015 3:12PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>6339.1</b>	<b>5713</b>	<b>25-Aug-2015</b>	<b>.57</b>
<b>ENG 1</b>	<b>6307.4</b>	<b>5661</b>	<b>25-Aug-2015</b>	<b>.57</b>
<b>ENG 2</b>	<b>6307.4</b>	<b>5661</b>	<b>25-Aug-2015</b>	<b>.57</b>

## Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB 560-34-97 R1 <i>34SB-97 : 560R1</i>	REDUCED VERTICAL SEPARATION MINIMUM (RVSM) MODIFICATION	SMF		OPTIONAL	MTH 20-Apr-2005 HRS 4685		-			Complete
<b>MOC : COMPLIED WITH</b>										
ASL 560-34-21 <i>34ASL21</i>	TRANSMITTAL OF HONEYWELL TECHNICAL NEWSLETTER A23-3850-001	SMF		MANDATORY	MTH 17-Nov-2005 HRS 4766		A/R			Complete
<b>MOC : COMPLIED WITH</b>										
ASL 560-34-34 R3 <i>34ASL-34 : 560R3</i>	NAVIGATION - STALL WARNING SYSTEM CALIBRATION ADJUSTMENT AND IN-FLIGHT TEST PROCEDURES	SMF		SUPERSEDED	MTH 25-Jun-2008 HRS 5180		A/R			Complete
<b>MOC : COMPLIED WITH</b>										
ASL 560-34-35 R3 <i>34ASL-35 : 560R3</i>	NAVIGATION - STALL WARNING SYSTEM CALIBRATION, ADJUSTMENT, AND IN-FLIGHT TEST PROCEDURES	SMF		SUPERSEDED	MTH 25-Jun-2008 HRS 5180		A/R			N/A
<b>MOC : NOT APPLICABLE</b>										
SL CIL-34-02	TRANSMITTAL OF HONEYWELL SIL D201301000032, PRIMUS II INTEGRATED RADIO SYSTEM	SMF		MANDATORY	MTH 09-Sep-2013 HRS 5961.8 LDG 5486		-			Complete
<b>MOC : COMPLIED WITH - COMPLIED WITH CIL-34-02, BY COMPLYING WITH A MORE COMPREHENSIVE INSPECTION CRITERIA TO ASSURE COMPLIANCE WITH AD2010-07-02.</b>										
SL 560-34-06 <i>34SL-06</i>	GNS-X NAV MANAGEMENT UNIT COVER REPLACEMENT	50L		RECOMMENDED	MTH 25-Feb-1993 HRS 1203		-			Complete
<b>MOC : COMPLIED WITH</b>										
SL 560-34-23 R1	GNS-XL FLIGHT MANAGEMENT SYSTEM (FMS) MOD 4 UPGRADE			RECOMMENDED			-			
<b>MOC :</b>										
SL 560-34-28 <i>34SL-28</i>	HONEYWELL SOFTWARE BULLETIN SWB TPU 67A-SW8			DISCRETIONARY	MTH		-			
<b>MOC :</b>										
SL 560-34-36 <i>34SL-36</i>	NAVIGATION - TRANSMITTAL OF HONEYWELL SWB MST 67A-SW5			RECOMMENDED	MTH		A/R			
<b>MOC :</b>										
SB 560-35-01 R4 <i>35SB-01 : 560R4</i>	EROS OXYGEN MASK INSTALLATION	LBE		OPTIONAL	MTH		-			
<b>MOC : - OPERATOR DOES NOT WISH TO COMPLY AT THIS TIME</b>										
SB 560-35-04 <i>35SB-04</i>	CHAFING PROTECTION INSTALLATION OF TAILCONE LINES AND WIRE BUNDLES	LGB		RECOMMENDED	MTH 18-Mar-1996 HRS 2448		-			Complete
<b>MOC : COMPLIED WITH</b>										
SB 560-35-09 R1 <i>35SB-09 : 560R1</i>	EROS MLD20-506 OXYGEN MASK INSTALLATION			OPTIONAL	MTH		-			
<b>MOC :</b>										
SB 560-35-12 <i>35SB-12</i>	EROS MLD20-510 OXYGEN MASK INSTALLATION			OPTIONAL	MTH		-			
<b>MOC :</b>										



## CESCOM 10 - Aircraft Status Report

Owner: **SBM CLEANING COMPANY LLC**  
 Aircraft Model: **560 - CITATION V**  
 Aircraft Serial: **560-0096** Unit: **0096** Reg No: **N10TD**  
 Airworthiness: **09-Apr-1991**  
 Print Date: **31-Aug-2015 3:12PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>6339.1</b>	<b>5713</b>	<b>25-Aug-2015</b>	<b>.57</b>
<b>ENG 1</b>	<b>6307.4</b>	<b>5661</b>	<b>25-Aug-2015</b>	<b>.57</b>
<b>ENG 2</b>	<b>6307.4</b>	<b>5661</b>	<b>25-Aug-2015</b>	<b>.57</b>

### Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SL 560-35-04 <i>35SL-04</i>	PORTABLE OXYGEN CYLINDER MASK INSPECTION/REPLACEMENT			RECOMMENDED	MTH		-			
<b>MOC :</b>										
SL 560-35-06	OXYGEN - OXYGEN BOTTLE INSPECTION			INFORMATIONAL	MTH		A/R			
<b>MOC :</b>										
SL 560-35-07 R1	TRANSMITTAL OF INTERTECHNIQUE SERVICE BULLETIN MXH-35-240	KALN		MANDATORY	MTH 23-May-2012 HRS 5743.2 LDG 5371		-			Complete
<b>MOC : COMPLIED WITH - ACCOMPLISHED THE SL560-35-07REV1 PER THE SL INSTRUCTIONS. THE INSTALLED CREW O2 MASKS DO NOT APPLY TO THIS SL.</b>										
SL 560-35-07 R2	OXYGEN - TRANSMITTAL OF INTERTECHNIQUE SERVICE BULLETIN MXH-35-240			MANDATORY			-			
<b>MOC :</b>										
SL 560-35-07	OXYGEN - TRANSMITTAL OF INTERTECHNIQUE SERVICE BULLETIN MXH-35-240			MANDATORY			-			
<b>MOC :</b>										
SB 560-36-01 <i>36SB-01</i>	TAILCONE BLEED AIR CHECK VALVE REPLACEMENT	LGB		RECOMMENDED	MTH 06-Apr-1994 HRS 1794		-			Complete
<b>MOC : COMPLIED WITH</b>										
SB 560-36-02 R1 <i>36SB-02 : 560R1</i>	DOOR SEAL VALVE REPLACEMENT AND WATER TRAP INSTALLATION			OPTIONAL	MTH		-			
<b>MOC :</b>										
SB 560-36-03 R3 <i>36SB-03 : 560R3</i>	PNEUMATIC - WIDE CARGO DOOR SEAL LINE WATER TRAP INSTALLATION			OPTIONAL	MTH		A/R			
<b>MOC :</b>										
SB 560-52-02 <i>52SB-02</i>	ENTRY DOOR STEP CATCH COVER (W/STD DOOR & STEP INSTL)	TOL		RECOMMENDED	MTH 03-Sep-1993 HRS 1503		-			Complete
<b>MOC : COMPLIED WITH</b>										
SB 560-52-04 R1 <i>52SB-04 : 560R1</i>	WIDE DOOR MODIFICATION INSTALLATION			OPTIONAL	MTH		-			
<b>MOC :</b>										
SB 560-52-04 R2	WIDE DOOR MODIFICATION INSTALLATION			OPTIONAL			-			
<b>MOC :</b>										
SB 560-52-08 R4	COMPOSITE DOOR STEP INSTALLATION			OPTIONAL			-			
<b>MOC :</b>										
SB 560-52-18 <i>52SB-18</i>	INSTALLATION OF NOSE LANDING GEAR DOOR DEFLECTORS			OPTIONAL	MTH		-			
<b>MOC :</b>										



# CESCOM 10 - Aircraft Status Report

Owner: **SBM CLEANING COMPANY LLC**  
 Aircraft Model: **560 - CITATION V**  
 Aircraft Serial: **560-0096** Unit: **0096** Reg No: **N10TD**  
 Airworthiness: **09-Apr-1991**  
 Print Date: **31-Aug-2015 3:12PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>6339.1</b>	<b>5713</b>	<b>25-Aug-2015</b>	<b>.57</b>
<b>ENG 1</b>	<b>6307.4</b>	<b>5661</b>	<b>25-Aug-2015</b>	<b>.57</b>
<b>ENG 2</b>	<b>6307.4</b>	<b>5661</b>	<b>25-Aug-2015</b>	<b>.57</b>

## Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
ASL 560-52-05	DOORS - EMERGENCY EXIT INSPECTION SMF			MANDATORY	DAYS 04-Mar-2011 HRS 5568.6 LDG 5282		A/R			Complete
<b>MOC : COMPLIED WITH - COMPLIED WITH ASL560-52-05 BY INSPECTING THE EMERGENCY EXIT SEAL PER ACCOMPLISHMENT INSTRUCTIONS. NO DEFECTS NOTED.</b>										
SL 560-52-01 52SL-01	CABIN DOOR SECONDARY SEAL FUNCTIONAL CHECK TOL			RECOMMENDED	MTH 29-May-1992 HRS 759		A/R			Complete
<b>MOC : COMPLIED WITH</b>										
SL 560-52-02 52SL-02	EMERGENCY EXIT INNER HANDLE ATTACH SCREW INSPECTION/REPLACEMENT LBE			MANDATORY	MTH 14-Apr-1992 HRS 683		-			Complete
<b>MOC : COMPLIED WITH</b>										
SB 560-53-07 R1 53SB-07 : 560R1	TAILCONE BALLAST INSTALLATION			SUPERSEDED	MTH		A/R			
<b>MOC :</b>										
SB 560-53-11 53SB-11	FRAME BRACE INSPECTION/INSTALLATION TOL			SUPERSEDED	MTH 25-Feb-1993 HRS 1203		A/R			Complete
<b>MOC : COMPLIED WITH</b>										
SB 560-53-12 53SB-12	W/S CANTED FRAME & UPPER STRINGER INSP/MOD TOL			MANDATORY	MTH 25-Feb-1993 HRS 1203		-			Complete
<b>MOC : COMPLIED WITH</b>										
SB 560-53-14 53SB-14	CABIN INTERIOR ATTACH/CONTACT POINT CORROSION PROTECTION 50L			SUPERSEDED	MTH 25-Feb-1993 HRS 1203		A/R			Complete
<b>MOC : COMPLIED WITH</b>										
SB 560-53-15 53SB-15	FLIGHT CREW SEAT RAIL AND BEAM RIVET INSPECTION/INSTALLATION LGB			SUPERSEDED	MTH 06-Apr-1994 HRS 1794		A/R			Complete
<b>MOC : COMPLIED WITH</b>										
SB 560-53-16 53SB-16	MAP COMPARTMENT ASSEMBLY INSPECTION/REPLACEMENT VNY			RECOMMENDED	MTH 02-Mar-1995 HRS 2104		-			Complete
<b>MOC : COMPLIED WITH</b>										
SB 560-53-18 53SB-18	DORSAL FIN INSTALLATION AND MATERIAL IMPROVEMENT OPTIONAL				MTH		-			
<b>MOC :</b>										
SB 560-53-20 53SB-20	AN3-5A BOLT INSPECTION/REPLACEMENT TOL			RECOMMENDED	MTH 14-Mar-1999 HRS 3430		A/R			Complete
<b>MOC : COMPLIED WITH</b>										
SB 560-53-21 R1 53SB-21 : 560R1	COCKPIT LEFT SIDE WINDOW RIVET INSPECTION TOL			SUPERSEDED	MTH 05-Jun-1998 HRS 3159		A/R			Complete
<b>MOC : COMPLIED WITH</b>										
SB 560-53-21 R2 53SB-21 : 560R2	COCKPIT LEFT SIDE WINDOW RIVET INSPECTION TOL			RECOMMENDED	MTH 14-Mar-1999 HRS 3430		-			Complete
<b>MOC : COMPLIED WITH</b>										
SB 560-53-23 R1 53SB-23 : 560R1	WING MAIN SPAR CARRY THRU LUGS INSPECTION/REPAIR TOL			RECOMMENDED	MTH 14-Mar-1999 HRS 3430		-			Complete
<b>MOC : COMPLIED WITH</b>										
SB 560-53-25 53SB-25	TAILCONE BAGGAGE COMPARTMENT SUPPORT IMPROVEMENT TOL			SUPERSEDED	MTH 05-Jun-1998 HRS 3159		A/R			Complete
<b>MOC : COMPLIED WITH</b>										





# CESCOM 10 - Aircraft Status Report

Owner: **SBM CLEANING COMPANY LLC**  
 Aircraft Model: **560 - CITATION V**  
 Aircraft Serial: **560-0096** Unit: **0096** Reg No: **N10TD**  
 Airworthiness: **09-Apr-1991**  
 Print Date: **31-Aug-2015 3:12PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>6339.1</b>	<b>5713</b>	<b>25-Aug-2015</b>	<b>.57</b>
<b>ENG 1</b>	<b>6307.4</b>	<b>5661</b>	<b>25-Aug-2015</b>	<b>.57</b>
<b>ENG 2</b>	<b>6307.4</b>	<b>5661</b>	<b>25-Aug-2015</b>	<b>.57</b>

## Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB 560-53-26 R1 53SB-26 : 560R1	LOWER STUB WING SKIN INSPECTION/REPAIR TOL			SUPERSEDED	MTH 26-Oct-1999 HRS 3608		A/R			Complete
	<b>MOC : COMPLIED WITH</b>									
SB 560-53-26 R2 53SB-26 : 560R2	LOWER STUB WING SKIN INSPECTION/REPAIR			RECOMMENDED	MTH		-			
	<b>MOC :</b>									
SB 560-53-27 53SB-27	CABIN ENTRANCE AFT DOORPOST INSPECTION/REPAIR MHR			RECOMMENDED	MTH 16-Apr-2002 HRS 4056		-			Complete
	<b>MOC : COMPLIED WITH</b>									
SB 560-53-28 53SB-28	FUSELAGE MOISTURE DRAIN INSTALLATION			OPTIONAL	MTH		-			
	<b>MOC :</b>									
SB 560-53-29 R2 53SB-29 : 560R2	NOSE WHEEL STEERING BRACKET REPLACEMENT MHR			MANDATORY	MTH 16-Apr-2002 HRS 4056		-			Complete
	<b>MOC : COMPLIED WITH</b>									
SB 560-53-29 53SB-29	NOSE WHEEL STEERING BRACKET REPLACEMENT SMF			SUPERSEDED	MTH 31-Mar-2000 HRS 3718		A/R			Complete
	<b>MOC : COMPLIED WITH</b>									
SB 560-53-34 53SB-34	WHEEL WELL BOX/SKIN GAP IMPROVEMENT			OPTIONAL	MTH		-			
	<b>MOC :</b>									
SL 560-53-05 53SL-05	DORSAL FIN VANE INSPECTION			RECOMMENDED	MTH		-			
	<b>MOC :</b>									
SL 560-53-06 R1 53SL-06 : 560R1	INTERCOSTAL DRAINAGE PATH INSPECTION			RECOMMENDED	MTH		A/R			
	<b>MOC :</b>									
SB 560-54-01 R1 54SB-01 : 560R1	NEW DESIGN INLET INSTALLATION TOL			SUPERSEDED	MTH 14-Mar-1999 HRS 3430		A/R			Complete
	<b>MOC : COMPLIED WITH</b>									
SB 560-54-03 R2 54SB-03 : 560R2	ENGINE INLET DOUBLER INSTALLATION			RECOMMENDED	MTH		-			
	<b>MOC :</b>									
SB 560-55-04 55SB-04	STABILIZERS - ELEVATOR TIP BONDING STRIP INSTALLATION			DISCRETIONARY	MTH		A/R			
	<b>MOC :</b>									
SL 560-55-02 55SL-02	HORIZONTAL STABILIZER ATTACH BOLT/NUT TORQUE VERIFICATION TOL			RECOMMENDED	MTH 05-Jun-1998 HRS 3159		A/R			Complete
	<b>MOC : COMPLIED WITH</b>									
SL 560-55-03 R1	STABILIZERS - HORIZONTAL STABILIZER RIB BORESCOPE INSPECTION SMF			MANDATORY	MTH 22-May-2015 HRS 6283.9 LDG 5674		-			Complete
	<b>MOC : COMPLIED WITH - COMPLIED WITH SL560-55-03 R1, ACCOMPLISHMENT OF TASK 55-10-01-290 PER INSTRUCTIONS</b>									
SL 560-55-03 R2	HORIZONTAL STABILIZER RIB BORESCOPE INSPECTION MANDATORY				MTH		-			
	<b>MOC :</b>									



## CESCOM 10 - Aircraft Status Report

Owner: **SBM CLEANING COMPANY LLC**  
 Aircraft Model: **560 - CITATION V**  
 Aircraft Serial: **560-0096** Unit: **0096** Reg No: **N10TD**  
 Airworthiness: **09-Apr-1991**  
 Print Date: **31-Aug-2015 3:12PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>6339.1</b>	<b>5713</b>	<b>25-Aug-2015</b>	<b>.57</b>
<b>ENG 1</b>	<b>6307.4</b>	<b>5661</b>	<b>25-Aug-2015</b>	<b>.57</b>
<b>ENG 2</b>	<b>6307.4</b>	<b>5661</b>	<b>25-Aug-2015</b>	<b>.57</b>

### Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SL 560-55-03	HORIZONTAL STABILIZER RIB BORESCOPE INSPECTION			MANDATORY	MTH		-			
	<b>MOC :</b>									
SB 560-57-02 R1 57SB-02 : 560R1	WINGS - STUB WING FASTENER INSPECTION/INSTALLATION	TOL		SUPERSEDED	MTH 29-May-1992 HRS 759		A/R			Complete
	<b>MOC : COMPLIED WITH</b>									
SB 560-57-03 R1 57SB-03 : 560R1	OUTBOARD FLAP ISLAND DOUBLER INSTALLATION	LGB		SUPERSEDED	MTH 12-Nov-1994 HRS 2020		A/R			Complete
	<b>MOC : COMPLIED WITH</b>									
SB 560-57-07 57SB-07	FLAP VENT HOLES INSTALL	LNK		RECOMMENDED	MTH 19-Jul-1996 HRS 2553		-			Complete
	<b>MOC : COMPLIED WITH</b>									
SL 560-57-01 R1	NOTIFICATION OF LEADING EDGE SKIN REWORK REQUIREMENT WHEN A DEICE BOOT IS REMOVED	KALN		MANDATORY	MTH 23-May-2012 HRS 5743.2 LDG 5371		-			Complete
	<b>MOC : COMPLIED WITH - ACCOMPLISHED THE SL560-57-01REV1 TO THE LH &amp; RH WING STATION 91 PER THE SRM INSTRUCTIONS.</b>									
ASL 560-30-07 30SLA07	APPROACH AND LANDING IN ICING CONDITIONS ADDITION TO FLIGHT MANUAL	PIT		SUPERSEDED	MTH 22-Aug-1997 HRS 2879		A/R			Complete
	<b>MOC : COMPLIED WITH</b>									
SB 560-71-03 71SB-03	LOWER COWL DOOR FIRESEAL INSPECTION/INSTALLATION	LGB		SUPERSEDED	MTH 01-Dec-1996 HRS 2692		A/R			Complete
	<b>MOC : COMPLIED WITH</b>									
SL 560-71-03 71SL-03	REPLACEMENT OF FUEL CONTROL UNIT IDLE SOLENOID	BTV		SUPERSEDED	MTH 14-Aug-1992 HRS 898		A/R			Complete
	<b>MOC : COMPLIED WITH</b>									
SB 560-72-01 R3 72SB-01 : 560R3	ENGINE COWLING MODIFICATION TO ACCOMMODATE PRATT & WHITNEY CANADA ENGINE FUEL ACCUMULATOR INSTALLATION	TOL		RECOMMENDED	MTH 14-Mar-1999 HRS 3430		-			Complete
	<b>MOC : COMPLIED WITH</b>									
SL 560-72-05 R1 72SL-05 : 560R1	TRANSMITTAL OF P&WC SB JT15D-72-7458, REVISION 3, INSPECTION OF FCU - MINIMUM FUEL FLOW, AND SERVICE LETTER 7077 JT15D-012, FCU METERING VALVE (SB7458) CLARIFICATION	TOL		SUPERSEDED	MTH 06-Jul-1997 HRS 2844		A/R			Complete
	<b>MOC : COMPLIED WITH</b>									
SL 560-72-11 72SL-11	TRANSMITTAL OF P&WC SB JT15D-72-7495 TURBOFAN ENGINE - FUEL CONTROL UNIT - INSPECTION OF DECEL SCHEDULE	TOL		INFORMATIONAL	MTH 05-Jun-1998 HRS 3159		A/R			Complete
	<b>MOC : COMPLIED WITH</b>									
SL 560-72-16 72SL-16	TRANSMITTAL OF P&WC SERVICE LETTER JT15D-023	PIT		RECOMMENDED	MTH 09-Aug-1999 HRS 3514		A/R			Complete
	<b>MOC : COMPLIED WITH</b>									
SB JT15D-72-7001 R25 E1	APPROVED LISTING OF (SYNTHETIC) LUBRICATING OILS			RECOMMENDED			-			
	<b>MOC :</b>									



# CESCOM 10 - Aircraft Status Report

Owner: **SBM CLEANING COMPANY LLC**  
 Aircraft Model: **560 - CITATION V**  
 Aircraft Serial: **560-0096** Unit: **0096** Reg No: **N10TD**  
 Airworthiness: **09-Apr-1991**  
 Print Date: **31-Aug-2015 3:12PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>6339.1</b>	<b>5713</b>	<b>25-Aug-2015</b>	<b>.57</b>
<b>ENG 1</b>	<b>6307.4</b>	<b>5661</b>	<b>25-Aug-2015</b>	<b>.57</b>
<b>ENG 2</b>	<b>6307.4</b>	<b>5661</b>	<b>25-Aug-2015</b>	<b>.57</b>

## Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB JT15D-72-7001 R25 E2	APPROVED LISTING OF (SYNTHETIC) LUBRICATING OILS RECOMMENDED						-			
<b>MOC :</b>										
SB JT15D-72-7002 R42 E1	SERVICE LIVES - ROTOR COMPONENTS						A/R			
<b>MOC :</b>										
SB JT15D-72-7002 R42 E2	SERVICE LIVES - ROTOR COMPONENTS						A/R			
<b>MOC :</b>										
SB JT15D-72-7003 R35	ENGINE OPERATING TIME BETWEEN OVERHAULS AND HOT SECTION INSPECTION FREQUENCY RECOMMENDED						-			
E1	<b>MOC :</b>									
SB JT15D-72-7003 R35	ENGINE OPERATING TIME BETWEEN OVERHAULS AND HOT SECTION INSPECTION FREQUENCY RECOMMENDED						-			
E2	<b>MOC :</b>									
SB JT15D-72-7003 R36	ENGINE OPERATING TIME BETWEEN OVERHAULS AND HOT SECTION INSPECTION FREQUENCY RECOMMENDED						-			
E1	<b>MOC :</b>									
SB JT15D-72-7003 R36	ENGINE OPERATING TIME BETWEEN OVERHAULS AND HOT SECTION INSPECTION FREQUENCY RECOMMENDED						-			
E2	<b>MOC :</b>									
SB JT15D-72-7003 R37	ENGINE OPERATING TIME BETWEEN OVERHAULS AND HOT SECTION INSPECTION FREQUENCY RECOMMENDED						-			
E1	<b>MOC :</b>									
SB JT15D-72-7003 R37	ENGINE OPERATING TIME BETWEEN OVERHAULS AND HOT SECTION INSPECTION FREQUENCY RECOMMENDED						-			
E2	<b>MOC :</b>									
SB JT15D-72-7003 R38	ENGINE OPERATING TIME BETWEEN OVERHAULS AND HOT SECTION INSPECTION FREQUENCY RECOMMENDED						-			
E1	<b>MOC :</b>									



# CESCOM 10 - Aircraft Status Report

Owner: **SBM CLEANING COMPANY LLC**  
 Aircraft Model: **560 - CITATION V**  
 Aircraft Serial: **560-0096** Unit: **0096** Reg No: **N10TD**  
 Airworthiness: **09-Apr-1991**  
 Print Date: **31-Aug-2015 3:12PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>6339.1</b>	<b>5713</b>	<b>25-Aug-2015</b>	<b>.57</b>
<b>ENG 1</b>	<b>6307.4</b>	<b>5661</b>	<b>25-Aug-2015</b>	<b>.57</b>
<b>ENG 2</b>	<b>6307.4</b>	<b>5661</b>	<b>25-Aug-2015</b>	<b>.57</b>

## Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB JT15D-72-7003 R38	ENGINE OPERATING TIME BETWEEN OVERHAULS AND HOT SECTION INSPECTION FREQUENCY									
				RECOMMENDED			-			
E2	<b>MOC :</b>									
SB JT15D-72-7144 R20	ENGINE FUELS AND ADDITIVES - REQUIREMENTS AND APPROVED LISTING									
				RECOMMENDED			-			
E1	<b>MOC :</b>									
SB JT15D-72-7144 R20	ENGINE FUELS AND ADDITIVES - REQUIREMENTS AND APPROVED LISTING									
				RECOMMENDED			-			
E2	<b>MOC :</b>									
SB JT15D-72-7315 R1	TURBINE SHAFT LOCKING BOLT - REPLACEMENT/MODIFICATION OF									
				RECOMMENDED			A/R			
E1	<b>MOC :</b>									
SB JT15D-72-7315 R1	TURBINE SHAFT LOCKING BOLT - REPLACEMENT/MODIFICATION OF									
				RECOMMENDED			A/R			
E2	<b>MOC :</b>									
SB JT15D-72-7369 R2	LOW COMPRESSOR STATOR/CASE ASSEMBLY - IMPROVED RETENTION									
				RECOMMENDED			A/R			
E1	<b>MOC :</b>									
SB JT15D-72-7369 R2	LOW COMPRESSOR STATOR/CASE ASSEMBLY - IMPROVED RETENTION									
				RECOMMENDED			A/R			
E2	<b>MOC :</b>									
SB JT15D-72-7459 R1 E1	REPLACEMENT OF IGNITER									
				OPTIONAL			A/R			
	<b>MOC :</b>									
SB JT15D-72-7459 R1 E2	REPLACEMENT OF IGNITER									
				OPTIONAL			A/R			
	<b>MOC :</b>									



# CESCOM 10 - Aircraft Status Report

Owner: **SBM CLEANING COMPANY LLC**  
 Aircraft Model: **560 - CITATION V**  
 Aircraft Serial: **560-0096** Unit: **0096** Reg No: **N10TD**  
 Airworthiness: **09-Apr-1991**  
 Print Date: **31-Aug-2015 3:12PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>6339.1</b>	<b>5713</b>	<b>25-Aug-2015</b>	<b>.57</b>
<b>ENG 1</b>	<b>6307.4</b>	<b>5661</b>	<b>25-Aug-2015</b>	<b>.57</b>
<b>ENG 2</b>	<b>6307.4</b>	<b>5661</b>	<b>25-Aug-2015</b>	<b>.57</b>

## Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB JT15D-72-7493 R4	MODIFICATION/REPLACEMENT OF FUEL NOZZLE (SUPERSEDED BY SB JT15D-72-7526 R3)									
				CATEGORY 8						-
E1	<b>MOC :</b>									
SB JT15D-72-7493 R4	MODIFICATION/REPLACEMENT OF FUEL NOZZLE (SUPERSEDED BY SB JT15D-72-7526 R3)									
				CATEGORY 8						-
E2	<b>MOC :</b>									
SB JT15D-72-7493 R5	MODIFICATION / REPLACEMENT OF FUEL NOZZLE (SUPERSEDED BY SB JT15D-72-7526 R3)									
				CATEGORY 8						-
E1	<b>MOC :</b>									
SB JT15D-72-7493 R5	MODIFICATION / REPLACEMENT OF FUEL NOZZLE (SUPERSEDED BY SB JT15D-72-7526 R3)									
				CATEGORY 8						-
E2	<b>MOC :</b>									
SB JT15D-72-7526 R2 E1	MODIFICATION/REPLACEMENT OF FUEL NOZZLES									
				CATEGORY 7						-
E1	<b>MOC :</b>									
SB JT15D-72-7526 R2 E2	MODIFICATION/REPLACEMENT OF FUEL NOZZLES									
				CATEGORY 7						-
E2	<b>MOC :</b>									
SB JT15D-72-7526 R3 E1	MODIFICATION / REPLACEMENT OF FUEL NOZZLES									
				CATEGORY 7						-
E1	<b>MOC :</b>									
SB JT15D-72-7526 R3 E2	MODIFICATION / REPLACEMENT OF FUEL NOZZLES									
				CATEGORY 7						-
E2	<b>MOC :</b>									
SB JT15D-72-7571 R2 E1	NEW LOW TURBINE DISC ASSEMBLY - INTRODUCTION OF INFORMATIONAL									
										A/R
E1	<b>MOC :</b>									
SB JT15D-72-7571 R2 E2	NEW LOW TURBINE DISC ASSEMBLY - INTRODUCTION OF INFORMATIONAL									
										A/R
E2	<b>MOC :</b>									
SB JT15D-72-7588 R2	REPLACEMENT/MODIFICATION OF ACCESSORY GEARBOX INPUT DRIVE GEAR									
				OPTIONAL						-
E1	<b>MOC :</b>									



# CESCOM 10 - Aircraft Status Report

Owner: **SBM CLEANING COMPANY LLC**  
 Aircraft Model: **560 - CITATION V**  
 Aircraft Serial: **560-0096** Unit: **0096** Reg No: **N10TD**  
 Airworthiness: **09-Apr-1991**  
 Print Date: **31-Aug-2015 3:12PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>6339.1</b>	<b>5713</b>	<b>25-Aug-2015</b>	<b>.57</b>
<b>ENG 1</b>	<b>6307.4</b>	<b>5661</b>	<b>25-Aug-2015</b>	<b>.57</b>
<b>ENG 2</b>	<b>6307.4</b>	<b>5661</b>	<b>25-Aug-2015</b>	<b>.57</b>

## Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB JT15D-72-7588 R2	REPLACEMENT/MODIFICATION OF ACCESSORY GEARBOX INPUT DRIVE GEAR			OPTIONAL			-			
E2	<b>MOC :</b>									
SB JT15D-72-7625 R1 E1	REPLACEMENT OF GASKET			RECOMMENDED			A/R			
E1	<b>MOC :</b>									
SB JT15D-72-7625 R1 E2	REPLACEMENT OF GASKET			RECOMMENDED			A/R			
E2	<b>MOC :</b>									
SB JT15D-72-7625 E1	REPLACEMENT OF GASKET			RECOMMENDED			A/R			
E1	<b>MOC :</b>									
SB JT15D-72-7625 E2	REPLACEMENT OF GASKET			RECOMMENDED			A/R			
E2	<b>MOC :</b>									
SB JT15D-72-7627 E1	REPLACEMENT OF LOW PRESSURE TURBINE INTERSTAGE ROTOR AIR SEAL AND ROTOR AIR SEAL			RECOMMENDED			-			
E1	<b>MOC :</b>									
SB JT15D-72-7627 E2	REPLACEMENT OF LOW PRESSURE TURBINE INTERSTAGE ROTOR AIR SEAL AND ROTOR AIR SEAL			RECOMMENDED			-			
E2	<b>MOC :</b>									
SB JT15D-72-7628 R1	REPLACEMENT/MODIFICATION OF GAS GENERATOR CASE ASSEMBLY			CATEGORY 6			-			
E1	<b>MOC :</b>									
SB JT15D-72-7628 R1	REPLACEMENT/MODIFICATION OF GAS GENERATOR CASE ASSEMBLY			CATEGORY 6			-			
E2	<b>MOC :</b>									
SB JT15D-72-7628 R2	REPLACEMENT/MODIFICATION OF GAS GENERATOR CASE ASSEMBLY			CATEGORY 6			-			
E1	<b>MOC :</b>									
SB JT15D-72-7628 R2	REPLACEMENT/MODIFICATION OF GAS GENERATOR CASE ASSEMBLY			CATEGORY 6			-			
E2	<b>MOC :</b>									



# CESCOM 10 - Aircraft Status Report

Owner: **SBM CLEANING COMPANY LLC**  
 Aircraft Model: **560 - CITATION V**  
 Aircraft Serial: **560-0096** Unit: **0096** Reg No: **N10TD**  
 Airworthiness: **09-Apr-1991**  
 Print Date: **31-Aug-2015 3:12PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>6339.1</b>	<b>5713</b>	<b>25-Aug-2015</b>	<b>.57</b>
<b>ENG 1</b>	<b>6307.4</b>	<b>5661</b>	<b>25-Aug-2015</b>	<b>.57</b>
<b>ENG 2</b>	<b>6307.4</b>	<b>5661</b>	<b>25-Aug-2015</b>	<b>.57</b>

## Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB JT15D-72-7628 R3	REPLACEMENT/MODIFICATION OF GAS GENERATOR CASE ASSEMBLY									
CATEGORY 6										
E1	<b>MOC :</b>									
SB JT15D-72-7628 R3	REPLACEMENT/MODIFICATION OF GAS GENERATOR CASE ASSEMBLY									
CATEGORY 6										
E2	<b>MOC :</b>									
SB JT15D-72-7628 E1	REPLACEMENT/MODIFICATION OF GAS GENERATOR CASE ASSEMBLY									
CATEGORY 6										
E1	<b>MOC :</b>									
SB JT15D-72-7628 E2	REPLACEMENT/MODIFICATION OF GAS GENERATOR CASE ASSEMBLY									
CATEGORY 6										
E2	<b>MOC :</b>									
SB JT15D-72-7630 E1	INSPECTION/REPLACEMENT OF FUEL COOLED OIL COOLER				MTH 09-Oct-2014 HRS 6147.1 LDG 5586					N/A
SMF										
<b>MOC : NOT APPLICABLE - COMPLIED WITH PWCSB72-7630 FUEL COOLED OIL COOLER INSPECTION AND FOUND TO NOT BE APPLICABLE BY PART NUMBER.</b>										
SB JT15D-72-7630 E2	INSPECTION/REPLACEMENT OF FUEL COOLED OIL COOLER				MTH 09-Oct-2014 HRS 6147.1 LDG 5586					N/A
SMF										
<b>MOC : NOT APPLICABLE - COMPLIED WITH PWCSB72-7630 FUEL COOLED OIL COOLER INSPECTION AND FOUND TO NOT BE APPLICABLE BY PART NUMBER.</b>										
SB JT15D-72-7634 E1	REPLACEMENT OF SHIPPING CAPS FOR SHIPPING CONTAINERS									
CATEGORY 3										
E1	<b>MOC :</b>									
SB JT15D-72-7634 E2	REPLACEMENT OF SHIPPING CAPS FOR SHIPPING CONTAINERS									
CATEGORY 3										
E2	<b>MOC :</b>									
SL 560-73-03 73SL-03	FLOW DIVIDER START VALVE REPLACEMENT				MTH 15-Jan-1993 HRS 1150		A/R			Complete
LBE RECOMMENDED										
<b>MOC : COMPLIED WITH</b>										
SL 560-73-04 73SL-04	TRANSMITTAL OF PRATT & WHITNEY CANADA SERVICE INFORMATION LETTER SIL 7067 FLOW DIVIDER VALVE				MTH 22-Jun-1994 HRS 1871		A/R			Complete
VNY RECOMMENDED										
<b>MOC : COMPLIED WITH</b>										
SL 560-73-05 73SL-05	TRANSMITTAL OF PRATT & WHITNEY CANADA SERVICE BULLETIN JT15D-72-7467 FLOW DIVIDER VALVE - REPLACEMENT/MODIFICATION OF				MTH 05-Jun-1996 HRS 2540		A/R			Complete
LGB RECOMMENDED										
<b>MOC : COMPLIED WITH</b>										
SL 560-73-06 73SL-06	SIL JT15D-021 AND SB JT15D-72-7561				MTH 09-Aug-1999 HRS 3514					Complete
PIT RECOMMENDED										
<b>MOC : COMPLIED WITH</b>										

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.





# CESCOM 10 - Aircraft Status Report

Owner: **SBM CLEANING COMPANY LLC**  
 Aircraft Model: **560 - CITATION V**  
 Aircraft Serial: **560-0096** Unit: **0096** Reg No: **N10TD**  
 Airworthiness: **09-Apr-1991**  
 Print Date: **31-Aug-2015 3:12PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>6339.1</b>	<b>5713</b>	<b>25-Aug-2015</b>	<b>.57</b>
<b>ENG 1</b>	<b>6307.4</b>	<b>5661</b>	<b>25-Aug-2015</b>	<b>.57</b>
<b>ENG 2</b>	<b>6307.4</b>	<b>5661</b>	<b>25-Aug-2015</b>	<b>.57</b>

## Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SLA 560-73-02 R1 73SLA02 : 560R1	FLOW DIVIDER DIAPHRAGM LBE			MANDATORY	MTH 17-Nov-1992 HRS 1067		A/R			Complete
<b>MOC : COMPLIED WITH</b>										
SL CIL-74-01 R1	INSPECTION OF IGNITION CABLE AND THROTTLE LINKAGE SMF			MANDATORY	DAYS 09-Sep-2013 HRS 5961.8 LDG 5486		-			Complete
<b>MOC : COMPLIED WITH - COMPLIED WITH SL CIL-74-01 R1, BY VISUAL INSPECTION OF THE IGNITION LEAD ELBOW POSITION AND MAKE CORRECTION AS NECESSARY PER ACCOMPLISHMENT INSTRUCTIONS. OPERATIONAL CHECK NORMAL.</b>										
SL CIL-74-01	INSPECTION OF IGNITION CABLE AND THROTTLE LINKAGE MANDATORY				DAYS		-			
<b>MOC :</b>										
SL 560-74-02 74SL-02	P&W SB 7567R1			RECOMMENDED	MTH		-			
<b>MOC :</b>										
SB JT15D-72-7459 R2 E1	REPLACEMENT OF IGNITER			OPTIONAL				A/R		
<b>MOC :</b>										
SB JT15D-72-7459 R2 E2	REPLACEMENT OF IGNITER			OPTIONAL				A/R		
<b>MOC :</b>										
SB 560-76-01 R2 76SB-01 : 560R2	ENGINE SYNCHRONIZER CONTROLLER MODIFICATION			RECOMMENDED	MTH		-			
<b>MOC :</b>										
SB 560-78-02 78SB-02	THRUST REVERSER THROTTLE LOAD LIMITER MODIFICATION TOL			RECOMMENDED	MTH 30-Oct-1991 HRS 451		-			Complete
<b>MOC : COMPLIED WITH</b>										
SB 560-78-03 78SB-03	UPPER THRUST REVERSER DOOR MODIFICATION VNY			RECOMMENDED	MTH 02-Mar-1995 HRS 2104		-			Complete
<b>MOC : COMPLIED WITH</b>										
SB 560-78-04 78SB-04	THRUST REVERSER THROTTLE STOP SOLENOID GROUND IMPROVEMENT			OPTIONAL	MTH		-			
<b>MOC :</b>										
SL 560-78-01 R2 78SL-01 : 560R2	THRUST REVERSER SYSTEM OPERATIONAL TEST LGB			RECOMMENDED	MTH 27-Jan-1996 HRS 2409			A/R		Complete
<b>MOC : COMPLIED WITH</b>										
SL 560-78-03 78SL-03	THRUST REVERSER STANG FAIRING SUPPORT FORMER REPLACEMENT TOL			RECOMMENDED	MTH 15-Dec-1993 HRS 1647			A/R		Complete
<b>MOC : COMPLIED WITH</b>										
SL 560-78-04 78SL-04	EXHAUST NOZZLE I. D. INSPECTION/REPLACEMENT LGB			SUPERSEDED	MTH 12-Nov-1994 HRS 2020			A/R		Complete
<b>MOC : COMPLIED WITH</b>										



# CESCOM 10 - Aircraft Status Report

Owner: **SBM CLEANING COMPANY LLC**  
 Aircraft Model: **560 - CITATION V**  
 Aircraft Serial: **560-0096** Unit: **0096** Reg No: **N10TD**  
 Airworthiness: **09-Apr-1991**  
 Print Date: **31-Aug-2015 3:12PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>6339.1</b>	<b>5713</b>	<b>25-Aug-2015</b>	<b>.57</b>
<b>ENG 1</b>	<b>6307.4</b>	<b>5661</b>	<b>25-Aug-2015</b>	<b>.57</b>
<b>ENG 2</b>	<b>6307.4</b>	<b>5661</b>	<b>25-Aug-2015</b>	<b>.57</b>

## Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SL 560-78-06	TRANSMITTAL OF NORDAM CITY 78-2, EXHAUST - THRUST REVERSER - REPLACEMENT OF THRUST REVERSER STANG FAIRING SUPPORT FORMER									
<i>78SL-06</i>		SMF		SUPERSEDED	MTH 25-Jun-2001 HRS 3926		A/R			Complete
	<b>MOC : COMPLIED WITH</b>									
SB 560-79-01	OIL TEMPERATURE PROBE REPLACEMENT									
<i>79SB-01</i>		TOL		SUPERSEDED	MTH 15-Dec-1993 HRS 1647		A/R			Complete
	<b>MOC : COMPLIED WITH</b>									
SB 560-80-03 R2	APC P/N 9912125-2 STARTER/GENERATOR INSPECTION/REPLACEMENT									
<i>80SB-03 : 560R2</i>		TOL		RECOMMENDED	MTH 05-Jun-1998 HRS 3159		-			Complete
	<b>MOC : COMPLIED WITH</b>									
SB 560-80-04	REPLACEMENT OF SUPPRESSION DIODE WITH TRANSZORB									
<i>80SB-04</i>				OPTIONAL	MTH		-			
	<b>MOC :</b>									



## CESCOM 10 - Aircraft Status Report

Owner: **SBM CLEANING COMPANY LLC**  
 Aircraft Model: **560 - CITATION V**  
 Aircraft Serial: **560-0096** Unit: **0096** Reg No: **N10TD**  
 Airworthiness: **09-Apr-1991**  
 Print Date: **31-Aug-2015 3:12PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>6339.1</b>	<b>5713</b>	<b>25-Aug-2015</b>	<b>.57</b>
<b>ENG 1</b>	<b>6307.4</b>	<b>5661</b>	<b>25-Aug-2015</b>	<b>.57</b>
<b>ENG 2</b>	<b>6307.4</b>	<b>5661</b>	<b>25-Aug-2015</b>	<b>.57</b>

### Airworthiness Directives

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
FAA 1996-24-06 30AD-01	ICING COND ADDITION TO FM PIT	PIT		SUPERSEDED	MTH 22-Aug-1997 HRS 2879		-			Complete
	<b>MOC : COMPLIED WITH</b>									
FAA 1997-05-03 34AD-07	APPLIANCE AD - GNS-XLS AND GNS-XL GPS TOL	TOL		SUPERSEDED	MTH 06-Jul-1997 HRS 2844		-			Complete
	<b>MOC : COMPLIED WITH - NOT APPLICABLE-EQUIPMENT NOT INSTALLED</b>									
FAA 1998-04-38 30AD-02	SEVERE ICING PROCEDURES PIT	PIT		MANDATORY	MTH 14-Apr-1998 HRS 3086		-			Complete
	<b>MOC : COMPLIED WITH</b>									
FAA 1998-25-10 25AD-02	APPLIANCE AD - AIRCRAFT BELTS, INC. TOL	TOL		SUPERSEDED	MTH 14-Mar-1999 HRS 3430		-			Complete
	<b>MOC : COMPLIED WITH</b>									
FAA 1999-08-21 35AD-03	APPLIANCE AD - PURITAN-BENNETT AERO SYSTEM CO PIT	PIT		MANDATORY	MTH 09-Aug-1999 HRS 3514		-			Complete
	<b>MOC : COMPLIED WITH - NOT APPLICABLE BY TYPE MANUFACTURER</b>									
FAA 2000-03-09 34AD-09	ICING COND FM INFORMATION MHR	MHR		MANDATORY	MTH 15-Dec-2000 HRS 3836		-			Complete
	<b>MOC : COMPLIED WITH</b>									
FAA 2006-04-10 26AD-02	THIS AD REQUIRES INSTALLING IDENTIFICATION SLEEVES ON THE WIRES FOR THE POSITIVE AND NEGATIVE STUDS OF THE ENGINE AND/ OR (APU) FIRE EXTINGUISHING BOTTLES, AS APPICABLE, AND RECONNECTING THE WIRES TO THE CORRECT TERMINAL STUDS. SMF	SMF		MANDATORY	MTH 09-Feb-2007 HRS 4922		-			Complete
	<b>MOC : COMPLIED WITH</b>									
FAA 2006-06-03 28AD-01	PREVENT FUEL VAPOR IGNITION SMF	SMF		MANDATORY	MTH 09-Feb-2007 HRS 4922		-			Complete
	<b>MOC : COMPLIED WITH</b>									
FAA 2006-16-18 34AD-16	APPLIANCE AD - SANDEL AVIONICS INCORPORATED MODEL ST3400 TERRAIN AWARENESS WARNING SYSTEM/RADIO MAGNETIC INDICATOR(TAWS/RMI) SMF	SMF		MANDATORY	MTH 09-Feb-2007 HRS 4922		A/R			N/A
	<b>MOC : NOT APPLICABLE</b>									
FAA 2006-19-04 PARA(F) 34AD-17	REVISE HONEYWELL RCZ-833J/K, -851J/K AND 854J COMMUNICATION (COM) UNITS, EQUIPPED WITH XS-852E/F MODE S TRANSPONDERS; AND HONEYWELL XS-856A/B AND -857A MODE S TRANSPONDERS AIRPLANE FLIGHT MANUAL (AFM) MANDATORY			MANDATORY	MTH 09-Feb-2007 HRS 4922		A/R			N/A
	<b>MOC : NOT APPLICABLE</b>									
FAA 1995-25-10 21AD-01	OUTFLOW AND SAFETY VALUES LNK	LNK		MANDATORY	MTH 19-Jul-1996 HRS 2553		-			Complete
	<b>MOC : COMPLIED WITH - NOT APPLICABLE BY COMPONENT SERIAL NUMBER.</b>									
FAA 2013-09-11 (G)	AIR CONDITIONING - REPLACEMENT OF THE BRUSHES ON A/C COMPRESSOR MOTORS, PART NOS. 1134104-1/1134104-5, OR DEACTIVATION OF THE A/C SYSTEM INSPECTION FOR PART NUMBER (P/N) SMF	SMF		MANDATORY	DAYS 09-Sep-2013 HRS 5961.8 LDG 5486		-			N/A
	<b>MOC : NOT APPLICABLE - COMPLIED WITH AD2013-09-11, EFFECTIVE DATE JULY 5, 2013, BY INSPECTION OF THE A/C COMPRESSOR MOTOR AND DETERMINED PART NUMBER INSTALLED IS NOT APPLICABLE AS PER PARAGRAPH (G) OF THIS AD. NO FURTHER ACTION REQUIRED</b>									



# CESCOM 10 - Aircraft Status Report

Owner: **SBM CLEANING COMPANY LLC**  
 Aircraft Model: **560 - CITATION V**  
 Aircraft Serial: **560-0096** Unit: **0096** Reg No: **N10TD**  
 Airworthiness: **09-Apr-1991**  
 Print Date: **31-Aug-2015 3:12PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>6339.1</b>	<b>5713</b>	<b>25-Aug-2015</b>	<b>.57</b>
<b>ENG 1</b>	<b>6307.4</b>	<b>5661</b>	<b>25-Aug-2015</b>	<b>.57</b>
<b>ENG 2</b>	<b>6307.4</b>	<b>5661</b>	<b>25-Aug-2015</b>	<b>.57</b>

## Airworthiness Directives

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
FAA 2013-09-11 (H)	AIR CONDITIONING - REPLACEMENT OF THE BRUSHES ON A/C COMPRESSOR MOTORS, PART NOS. 1134104-1/1134104-5, OR DEACTIVATION OF THE A/C SYSTEM INSPECTION A/C COMPRESSOR HOUR METER AND MAINTENANCE RECORDS	SMF		MANDATORY	DAYS 09-Sep-2013 HRS 5961.8 LDG 5486		-			N/A
	<b>MOC : NOT APPLICABLE - COMPLIED WITH AD2013-09-11, EFFECTIVE DATE JULY 5, 2013, BY INSPECTION OF THE A/C COMPRESSOR MOTOR AND DETERMINED PART NUMBER INSTALLED IS NOT APPLICABLE AS PER PARAGRAPH (G) OF THIS AD. NO FURTHER ACTION REQUIRED</b>									
FAA 2013-09-11 (I) & (J)	AIR CONDITIONING - REPLACEMENT OF THE BRUSHES ON A/C COMPRESSOR MOTORS, PART NOS. 1134104-1/1134104-5, OR DEACTIVATION OF THE A/C SYSTEM REPLACEMENT OF A/C COMPRESSOR MOTOR BRUSHES AND RELATED MAINTENANCE MANUAL INFORMATION	SMF		MANDATORY	MTH 09-Sep-2013 HRS 5961.8 LDG 5486		-			N/A
	<b>MOC : NOT APPLICABLE</b>									
FAA 2013-09-11 (K)	AIR CONDITIONING - REPLACEMENT OF THE BRUSHES ON A/C COMPRESSOR MOTORS, PART NOS. 1134104-1/1134104-5, OR DEACTIVATION OF THE A/C SYSTEM DEACTIVATION OF A/C SYSTEM	SMF		MANDATORY	MTH 09-Sep-2013 HRS 5961.8 LDG 5486		A/R			N/A
	<b>MOC : NOT APPLICABLE</b>									
FAA 2013-09-11 (L)	AIR CONDITIONING - REPLACEMENT OF THE BRUSHES ON A/C COMPRESSOR MOTORS, PART NOS. 1134104-1/1134104-5, OR DEACTIVATION OF THE A/C SYSTEM REACTIVATION OF A/C SYSTEM	SMF		MANDATORY	MTH 09-Sep-2013 HRS 5961.8 LDG 5486		A/R			N/A
	<b>MOC : NOT APPLICABLE</b>									
FAA 2013-09-11 (M)	AIR CONDITIONING - REPLACEMENT OF THE BRUSHES ON A/C COMPRESSOR MOTORS, PART NOS. 1134104-1/1134104-5, OR DEACTIVATION OF THE A/C SYSTEM PARTS RETURN AND REPORTING REQUIREMENTS	SMF		MANDATORY	DAYS 09-Sep-2013 HRS 5961.8 LDG 5486		-			N/A
	<b>MOC : NOT APPLICABLE</b>									
FAA 2013-09-11	AIR CONDITIONING - REPLACEMENT OF THE BRUSHES ON A/C COMPRESSOR MOTORS, PART NOS. 1134104-1/1134104-5, OR DEACTIVATION OF THE A/C SYSTEM	SMF		MANDATORY	MTH 09-Sep-2013 HRS 5961.8 LDG 5486		-			N/A
	<b>MOC : NOT APPLICABLE - COMPLIED WITH AD2013-09-11, EFFECTIVE DATE JULY 5, 2013, BY INSPECTION OF THE A/C COMPRESSOR MOTOR AND DETERMINED PART NUMBER INSTALLED IS NOT APPLICABLE AS PER PARAGRAPH (G) OF THIS AD. NO FURTHER ACTION REQUIRED</b>									
FAA 2015-17-12 PARA (G)	INSPECT THE A/C COMPRESSOR MOTOR TO DETERMINE WHETHER P/N FWA1134104-1 OR P/N FWA1134104-5 IS INSTALLED			MANDATORY	DAYS HRS		30 10		29-Oct-2015 6361.4	New Req
	<b>MOC :</b>									
FAA 2015-17-12 PARA (H)	DETERMINE THE HOUR READING ON THE A/C COMPRESSOR HOUR METER (IF, DURING THE INSPECTION REQUIRED BY PARA (G) OF THIS AD, ANY A/C COMPRESSOR MOTOR HAVING P/N FWA1134104-1 OR P/N FWA1134104-5 IS FOUND			MANDATORY	DAYS HRS		30 10		29-Oct-2015 6361.4	New Req
	<b>MOC :</b>									



# CESCOM 10 - Aircraft Status Report

Owner: **SBM CLEANING COMPANY LLC**  
 Aircraft Model: **560 - CITATION V**  
 Aircraft Serial: **560-0096** Unit: **0096** Reg No: **N10TD**  
 Airworthiness: **09-Apr-1991**  
 Print Date: **31-Aug-2015 3:12PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>6339.1</b>	<b>5713</b>	<b>25-Aug-2015</b>	<b>.57</b>
<b>ENG 1</b>	<b>6307.4</b>	<b>5661</b>	<b>25-Aug-2015</b>	<b>.57</b>
<b>ENG 2</b>	<b>6307.4</b>	<b>5661</b>	<b>25-Aug-2015</b>	<b>.57</b>

## Airworthiness Directives

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
FAA 2015-17-12 PARA (I)	REPLACE THE A/C COMPRESSOR MOTOR BRUSHES WITH NEW BRUSHES (USING THE HOUR READING ON THE A/C COMPRESSOR HOUR METER DETERMINED IN PARA (H) OF THIS AD)			MANDATORY	MTH		BF/F BF/F			New Req
<b>MOC :</b>										
FAA 2015-17-12 PARA (K)	DEACTIVATE THE A/C SYSTEM (IN LIEU OF REPLACING THE A/C COMPRESSOR MOTOR BRUSHES AS REQUIRED BY THIS AD)			MANDATORY			-			
<b>MOC :</b>										
FAA 2015-17-12 PARA (L)	IF THE A/C SYSTEM IS DEACTIVATED, AS SPECIFIED IN PARA (K), PRIOR TO THE A/C SYSTEM BEING REACTIVATED: PERFORM THE INSPECTION SPECIFIED IN PARA (H), AND DO THE REPLACEMENTS SPECIFIED IN PARA (I), AT THE TIMES SPECIFIED IN PARA (I). RETURN THE A/C SYSTEM TO SERVICE			MANDATORY			-			
<b>MOC :</b>										
FAA 2015-17-12 PARA (M)	SEND THE REMOVED BRUSHES TO CESSNA AIRCRAFT COMPANY			MANDATORY	DAYS		30		29-Oct-2015	New Req
<b>MOC :</b>										
FAA 2015-17-12	AIR CONDITIONING - INSPECTIONS TO DETERMINE IF CERTAIN A/C COMPRESSOR MOTORS ARE INSTALLED AND TO DETERMINE THE ACCUMULATED HOURS ON CERTAIN A/C COMPRESSOR MOTOR ASSEMBLIES; AND REPETITIVE REPLACEMENT OF THE BRUSHES IN THE A/C COMPRESSOR MOTOR ASSEMBLY, OR, AS AN OPTION TO THE BRUSH REPLACEMENT, DEACTIVATION OF THE A/C SYSTEM AND PLACARD INSTALLATION; AND RETURN OF REPLACED BRUSHES TO CESSNA			MANDATORY	MTH		-			New Req
<b>MOC :</b>										
FAA 1995-22-01 33AD-03	APPLIANCE AD - TO PREVENT SMOKE, FIRE, ELECTRICAL SHOCK AND POSSIBLE ELECTROMAGNETIC INTERFERENCE CAUSED BY HIGH VOLTAGE ARCING	SMF		MANDATORY	MTH	17-Nov-2005 HRS 4766	A/R			Complete
<b>MOC : COMPLIED WITH</b>										
FAA 1974-08-09 R3	LAVATORY PAPER OR LINEN WASTE RECEPTACLE FIRE PREVENTION			MANDATORY			-			
<b>MOC :</b>										
FAA 2015-10-02 (G)	GENERAL VISUAL INSPECTION FOR CRACKING OF SEAT BACKREST LINKS HAVING PART NUMBER (P/N) 90-000200-104-1, P/N 90-000200-104-2, P/N 90-000202-104-1 AND P/N 90-000202-104-2			MANDATORY			-			
<b>MOC :</b>										
FAA 2015-10-02 (H)	CORRECTIVE ACTIONS - CRACKING IS FOUND ON THE LINK			MANDATORY			-			
<b>MOC :</b>										
FAA 2015-10-02 (I)	REPLACE ALL SEAT BACKREST LINKS, HAVING P/N 90-000200-104-1, P/N 90-000200-104-2, P/N 90-000202-104-1 AND P/N 90-000202-104-2, WITH NEW LINKS			MANDATORY			-			
<b>MOC :</b>										



# CESCOM 10 - Aircraft Status Report

Owner: **SBM CLEANING COMPANY LLC**  
 Aircraft Model: **560 - CITATION V**  
 Aircraft Serial: **560-0096** Unit: **0096** Reg No: **N10TD**  
 Airworthiness: **09-Apr-1991**  
 Print Date: **31-Aug-2015 3:12PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>6339.1</b>	<b>5713</b>	<b>25-Aug-2015</b>	<b>.57</b>
<b>ENG 1</b>	<b>6307.4</b>	<b>5661</b>	<b>25-Aug-2015</b>	<b>.57</b>
<b>ENG 2</b>	<b>6307.4</b>	<b>5661</b>	<b>25-Aug-2015</b>	<b>.57</b>

## Airworthiness Directives

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
FAA 2015-10-02	APPLIANCE AD - EQUIPMENT/FURNISHINGS - ZODIAC SEATS FRANCE - INSPECTION/REPLACEMENT			MANDATORY	MTH					
	<b>MOC :</b>									
FAA 2007-11-17 26AD-03	IDENTIFY WIRES FOR FIRE EXTINGUISHING BOTTLES	SMF		MANDATORY	MTH 25-Jun-2008 HRS 5180		A/R			Complete
	<b>MOC : COMPLIED WITH</b>									
FAA 2010-04-16 (G) 26AD-07	REPLACE TYPE H1-10 AIR HALON 1211 (BCF) PORTABLE FIRE EXTINGUISHERSMANUFACTURED BY SICLI WITH SERVICABLE UNIT			MANDATORY	DAYS 09-Jul-2010 HRS 5437.2 LDG 5216		A/R			N/A
	<b>MOC : NOT APPLICABLE - COMMENTS: COMPLIED WITH AD2010-01-16, EFFECTIVE DATE MARCH 8, 2010 BY INSPECTION. PORTABLE FIRE EXTINGUISHERS ON BOARD AIRCRAFT NOT AFFECTED BY THIS AD DUE TO MANUFACTURE AND MODEL TYPE. NO FURTHER ACTION REQUIRED.</b>									
FAA 2010-04-16 26AD-07	APPLIANCE AD - TYPE H1-10 AIR HALON 1211 (BCF) PORTABLE FIRE EXTINGUISHERSMANUFACTURED BY SICLI	SMF		MANDATORY	DAYS 09-Jul-2010 HRS 5437.2 LDG 5216		A/R			N/A
	<b>MOC : NOT APPLICABLE - COMMENTS: COMPLIED WITH AD2010-01-16, EFFECTIVE DATE MARCH 8, 2010 BY INSPECTION. PORTABLE FIRE EXTINGUISHERS ON BOARD AIRCRAFT NOT AFFECTED BY THIS AD DUE TO MANUFACTURE AND MODEL TYPE. NO FURTHER ACTION REQUIRED.</b>									
FAA 2007-23-13 34AD-19	INSPECT - ADJUSTMENT OF STALL WARNING SYSTEM	SMF		SUPERSEDED	MTH 25-Jun-2008 HRS 5180		A/R			Complete
	<b>MOC : COMPLIED WITH</b>									
FAA 2008-26-04 34AD-24	INSTALL WARNING PLACARDS, PERFORM FUNCTIONAL TEST OF ANGLE OF ATTACK SYSTEM AND ADJUST CALIBRATION SETTINGS OF AOA SYSTEM AS REQUIRED.	SMF		AIRWORTHINESS	MTH 06-Feb-2009 HRS 5261		A/R			Complete
	<b>MOC : COMPLIED WITH</b>									
FAA 1994-01-04 34AD-03	APPLIANCE AD - TO PREVENT COLLISIONS OR NEAR MISSES	LGB		MANDATORY	MTH 10-Sep-1994 HRS 1953		A/R			Complete
	<b>MOC : COMPLIED WITH</b>									
FAA 1998-25-02 34AD-08	APPLIANCE AD - TO PREVENT THE DISPLAY OF TARGET INDICATORS ON THE WRONG SIDE OF THE AIRCRAFT CAUSED BY AN INTERNAL COMPONENT FAILURE IN THE SKY497 INSTALLATIONS	TOL		MANDATORY	MTH 14-Mar-1999 HRS 3430		A/R			Complete
	<b>MOC : COMPLIED WITH</b>									
FAA 2001-23-17 34AD-10	APPLIANCE AD - TO PREVENT INACCURATE COURSE DEVIATION DISPLAYS IN THE GNS 430 UNIT	SAC		MANDATORY	MTH 28-Jun-2004 HRS 4560		A/R			Complete
	<b>MOC : COMPLIED WITH - NOT APPLICABLE</b>									
FAA 2003-04-06 34AD-13	APPLIANCE AD - HONEYWELL PRIMUS RNZ-850/851 NM	SAC		SUPERSEDED	MTH 28-Jun-2004 HRS 4531		A/R			Complete
	<b>MOC : COMPLIED WITH</b>									



# CESCOM 10 - Aircraft Status Report

Owner: **SBM CLEANING COMPANY LLC**  
 Aircraft Model: **560 - CITATION V**  
 Aircraft Serial: **560-0096** Unit: **0096** Reg No: **N10TD**  
 Airworthiness: **09-Apr-1991**  
 Print Date: **31-Aug-2015 3:12PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>6339.1</b>	<b>5713</b>	<b>25-Aug-2015</b>	<b>.57</b>
<b>ENG 1</b>	<b>6307.4</b>	<b>5661</b>	<b>25-Aug-2015</b>	<b>.57</b>
<b>ENG 2</b>	<b>6307.4</b>	<b>5661</b>	<b>25-Aug-2015</b>	<b>.57</b>

## Airworthiness Directives

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
FAA 2006-22-08 34AD-18	APPLIANCE AD - HONEYWELL PRIMUS RNZ-850/851 NM	SMF		MANDATORY	MTH 09-Sep-2013 HRS 5961.8 LDG 5486		A/R			Complete
<p><b>MOC :</b> COMPLIED WITH - COMPLIED WITH AD-2010-07-02 EFFECTIVE DATE 05/03/2010 BY COMPLIANCE OF CESSNA CIL-34-02, UNIT UPGRADE AS PER SECTION (I) OF AD. OPERATIONAL CHECK NORMAL. SEE SECTION 3 FOR COMPONENT INFORMATION.</p>										
FAA 2010-07-02	APPLIANCE AD - PERFORM A ONE-TIME GENERAL VISUAL INSPECTION OF THE MODIFICATION PLATE FOR THE HONEYWELL PRIMUS II NV-850 NAVIGATION RECEIVER MODULE (NRM)			MANDATORY	MTH 09-Jul-2010 HRS 5437.2 LDG 5216		A/R			Complete
<p><b>MOC :</b> COMPLIED WITH - COMPLIED WITH STEPS (H), (L) AND (L)(2) OF AD2010-07-02 DATED MAY 3, 2010. #1 NAV RECEIVER MODULE (NRM); P/N 7510134-701 AND #2 (NRM); P/N 7510134-701 DOES NOT HAVE MOD L OR T INSTALLED PER AD. OPERATOR WILL COMPLY WITH HONEYWELL SERVICE BULLETIN 7510100-34-0037 WITHIN 30 MONTHS FROM THE DATE OF THIS AD. INCORPORATED FLIGHT LIMITATIONS INTO THE AFM.</p>										
FAA 2012-02-08	APPLIANCE AD - AVIATION COMMUNICATION AND SURVEILLANCE SYSTEMS (ACSS) TRAFFICALERT AND COLLISION AVOIDANCE SYSTEM (TCAS) UNITS	SMF		MANDATORY	MTH 29-Jan-2015 HRS 6147.1 LDG 5586		-			N/A
<p><b>MOC :</b> NOT APPLICABLE - COMPLIED WITH AD 2012-02-08 EFFECTIVE ON MARCH 13, 2012 BY INSPECTING AIRCRAFT. FOUND AFFECTED ACSS EQUIPMENT NOT INSTALLED IN THIS AIRCRAFT.</p>										
FAA 2014-18-01	APPLIANCE AD - NAVIGATION - ROCKWELL COLLINS, INC. MODE S TRANSPONDERS - INSPECTION / MODIFICATION			MANDATORY	MTH		-			
<p><b>MOC :</b></p>										
FAA 2015-10-51-E	APPLIANCE AD - AVIDYNE INTEGRATED FLIGHT DISPLAY (IFD)- INCORPORATE OPERATIONAL LIMITATIONS INTO LIMITATIONS SECTION OF THE AFM OR AFMS.			MANDATORY	MTH		-			
<p><b>MOC :</b></p>										
FAA 2015-10-51	APPLIANCE AD - AVIDYNE INTEGRATED FLIGHT DISPLAY (IFD)- INCORPORATE OPERATIONAL LIMITATIONS INTO LIMITATIONS SECTION OF THE AFM OR AFMS			MANDATORY			-			
<p><b>MOC :</b></p>										
FAA 1994-19-06 35AD-01	APPLIANCE AD - TO PREVENT THE FLIGHT CREW FROM EXPERIENCING DIFFICULTY IN EXHALING	VNY		MANDATORY	MTH 23-Nov-1994 HRS 2030		A/R			Complete
<p><b>MOC :</b> COMPLIED WITH</p>										
FAA 2015-08-07 PARA (G)	INSPECT THE INFLATABLE HARNESS FITTED TO EACH FLIGHTCREW OXYGEN MASK REGULATOR TO DETERMINE IF THE INFLATABLE HARNESS IS INSTALLED WITH A PART NUMBER AND A BATCH NUMBER IDENTIFIED IN APPENDIX I OF ZODIAC AEROSPACE SERVICE BULLETIN MXH-35-240, REVISION 7, DATED SEPTEMBER 1, 2011			MANDATORY	MTH		24		16-Jun-2017	21 m 16 d
<p><b>MOC :</b></p>										
FAA 2015-08-07 PARA (H)	REPLACE THE INFLATABLE HARNESS IDENTIFIED IN PAPRGRAPH G WITH A NEW OR RE-IDENTIFIED HARNESSES			MANDATORY	MTH		24		16-Jun-2017	21 m 16 d
<p><b>MOC :</b></p>										





# CESCOM 10 - Aircraft Status Report

Owner: **SBM CLEANING COMPANY LLC**  
 Aircraft Model: **560 - CITATION V**  
 Aircraft Serial: **560-0096** Unit: **0096** Reg No: **N10TD**  
 Airworthiness: **09-Apr-1991**  
 Print Date: **31-Aug-2015 3:12PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>6339.1</b>	<b>5713</b>	<b>25-Aug-2015</b>	<b>.57</b>
<b>ENG 1</b>	<b>6307.4</b>	<b>5661</b>	<b>25-Aug-2015</b>	<b>.57</b>
<b>ENG 2</b>	<b>6307.4</b>	<b>5661</b>	<b>25-Aug-2015</b>	<b>.57</b>

## Airworthiness Directives

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
FAA 2015-08-07	APPLIANCE AD - OXYGEN - ZODIAC AEROTECHNICS (FORMERLY INTERTECHNIQUE AIRCRAFT SYSTEMS) FLIGHTCREW OXYGEN MASK REGULATORS - INSPECTION / REPLACEMENT OF INFLATABLE HARNESES MANDATORY									
<b>MOC :</b>										
FAA 1992-22-15 73AD-01	SUPERSEDED BY AD 93-19-03 LBE			SUPERSEDED	MTH 17-Nov-1992 HRS 1067		A/R			Complete
<b>MOC : COMPLIED WITH</b>										
FAA 1993-19-03 73AD-02	TO PREVENT DETERIORATION OF THE FLOW DIVIDER START VALVE DIAPHRAGM DUE TO HIGHT TEMPERATURE									
	LBE		MANDATORY	MTH 19-Nov-1993 HRS 1615		A/R			Complete	
<b>MOC : COMPLIED WITH</b>										
FAA 1993-05-15 78AD-01	THRUST REVERSERS LBE			MANDATORY	MTH 05-May-1993 HRS 1332		-			Complete
<b>MOC : COMPLIED WITH</b>										



# CESCOM 10 - Aircraft Status Report

Owner: **SBM CLEANING COMPANY LLC**  
 Aircraft Model: **560 - CITATION V**  
 Aircraft Serial: **560-0096** Unit: **0096** Reg No: **N10TD**  
 Airworthiness: **09-Apr-1991**  
 Print Date: **31-Aug-2015 3:12PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>6339.1</b>	<b>5713</b>	<b>25-Aug-2015</b>	<b>.57</b>
<b>ENG 1</b>	<b>6307.4</b>	<b>5661</b>	<b>25-Aug-2015</b>	<b>.57</b>
<b>ENG 2</b>	<b>6307.4</b>	<b>5661</b>	<b>25-Aug-2015</b>	<b>.57</b>

## Factory Installed

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
21FO-02 560 <i>21FO-02 : 560</i>	COOLING/FREON SUPPLEMENTAL FACTORY OPTION	*CF		15A FO	MTH 09-Apr-1991		-			
25FO-01 560 <i>25FO-01 : 560</i>	LOCATOR BEACON-EMERG FACTORY OPTION	*CF		175 FO	MTH 09-Apr-1991		-			
31FO-01 560 <i>31FO-01 : 560</i>	CLOCK/DIGITAL RH FACTORY OPTION	*CF		182A FO	MTH 09-Apr-1991		-			
34FO-06 560/C <i>34FO-06 : 560/C</i>	FMS DATA LOADER(PORTABLE) GLOBAL GNS-X FACTORY OPTION	PIT		695C FO	MTH 09-Apr-1991		-			
EQUIPMENT REMOVED BY OPERATOR SUBSEQUENT TO DELIVERY.										
34FO-07 560 <i>34FO-07 : 560</i>	ALTITUDE REPORTING DUAL W/DC ENCODING FACTORY OPTION	*CF		625 FO	MTH 09-Apr-1991		-			
34FO-08 560/R <i>34FO-08 : 560/R</i>	DME 2-HNYWL DM-850 ONLY W/OPT PACKAGE FACTORY OPTION	*CF		681R FO	MTH 09-Apr-1991		-			
34FO-09 560/X <i>34FO-09 : 560/X</i>	FM SYS-5TUBE HONEYWL EFIS FACTORY OPTION	*CF		685X FO	MTH 09-Apr-1991		-			
34FO-10 560 <i>34FO-10 : 560</i>	PRIMUS II RADIO PKG HONEYWELL SRZ-850 FACTORY OPTION	*CF		607D FO	MTH 09-Apr-1991		-			
34FO-12 560/K <i>34FO-12 : 560/K</i>	RADAR-PRIMUS 870 W/MFD FACTORY OPTION	*CF		627K FO	MTH 09-Apr-1991		-			
34FO-14 560 <i>34FO-14 : 560</i>	VLf/OMEGA GLOBAL GNS-X FACTORY OPTION	PIT		693G FO	MTH 09-Apr-1991		-			
EQUIPMENT REMOVED BY OPERATOR SUBSEQUENT TO DELIVERY.										