

**OWNER: AEROSERVICIOS LA FLORIDA
ASF S.A.**

**OPERATOR: AEROSERVICIOS LA FLORIDA
ASF S.A.**

ADDRESS: EDIF. CORP. FLORIDA BEBIDAS
HEREDIA 4046-3000

ADDRESS: EDIF. CORP. FLORIDA BEBIDAS
HEREDIA 4046-3000

OFFICE: 506-2437-6756

OFFICE: 506-2437-6756

FAX:

FAX:

ANALYST: SEAN WELLS
EMAIL: SWELLS@CAMPSYSTEMS.COM

1-866-581-2267 (OFFICE)
316-462-2442 (FAX)
WWW.CAMPSYSTEMS.COM

800-787-9749 (EFAX-CARDS)
631-980-4222 (EFAX-CARDS)

PLEASE REACH OUT TO YOUR ANALYST TO
RECORD CHANGES TO ADDRESS, LAST ACTUALS
(IF ANY).

AIRCRAFT **SERIAL/ REGNO:** 45-416/N450FC **MODEL:** LEARJET 45 **MANUFACTURER:** BOMBARDIER AVIATION

CERTIFICATION DATE: 20-JAN-2011

LAST ACTUALS:

1675	A/C HRS	as of 20-JAN-2023
1330	AFL	as of 20-JAN-2023
873.4	APH	as of 20-JAN-2023

APU **SERIAL/ PART:** P-454/3800726-1 **MODEL:** RE100 (CIMMS) **MANUFACTURER:** HONEYWELL

INSTALLED ON: 20-JAN-2011

LAST ACTUALS:

0	APU HRS	0 A/C HRS	873.4	APU HRS	as of 20-JAN-2023
0	APUS		1496	APUS	as of 20-JAN-2023

ENGINE NO. 1 **SERIAL/ PART:** P-132199C/3060084-2 **MODEL:** TFE731-20BR-1B **MANUFACTURER:** HONEYWELL

INSTALLED ON: 14-APR-2010

LAST ACTUALS:

0	ENG. HRS	0 A/C HRS	1675	ENG. HRS	as of 20-JAN-2023
0	ENC		1335	ENC	as of 20-JAN-2023

ENGINE NO. 2 **SERIAL/ PART:** P-132200C/3060084-2 **MODEL:** TFE731-20BR-1B **MANUFACTURER:** HONEYWELL

INSTALLED ON: 14-APR-2010

LAST ACTUALS:

0	ENG. HRS	0 A/C HRS	1675	ENG. HRS	as of 20-JAN-2023
0	ENC		1333	ENC	as of 20-JAN-2023

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty
---------	------	------	----------	-----------	--------------------------	-----------	-----------	-------------	-----	----------

ATA GENERAL

14CFR PART 47	PERFORM RECURRENT AIRCRAFT REGISTRATION								Service	ATA:--
MOS	20-Jan-23	36	31-Dec-24 (M)		692 d					
HRS	1675									
AFL	1330									
PROC. REF: CFR 14 CFR PART 47										

ATA 00 - INFORMATION

CI45-150721	REVIEW CONCORDE EMERGENCY BATTERY CMM 5-0167 REV E								Service	ATA:00
MOS/MSC	EFF	-					REQUIREMENT CHANGE FORMS			
HRS										
AFL										
PROC. REF: RCF CI45										

CI45-160527	REVIEW LEARJET AMM REVISION 66								Service	ATA:00
MOS/MSC	EFF	-					REQUIREMENT CHANGE FORMS			
HRS										
AFL										
PROC. REF: RCF CI45										

CI45-160603	REVIEW LEARJET 45 AMM TR 4-40								Service	ATA:00
MOS/MSC	EFF	-					REQUIREMENT CHANGE FORMS			
HRS										
AFL										
PROC. REF: RCF CI45										

CI45-160613	REVIEW LEARJET 45 AMM TR 5-110								Service	ATA:00
MOS/MSC	EFF	-					REQUIREMENT CHANGE FORMS			
HRS										
AFL										
PROC. REF: RCF CI45										

CI45-161207B	REVIEW LEARJET 45 AMM REVISION 67								Service	ATA:00
MOS/MSC	EFF	-					REQUIREMENT CHANGE FORMS			
HRS										
AFL										
PROC. REF: RCF CI45										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 00 - INFORMATION										
CI45-181109B					REVIEW LEARJET 45/45XR AMM REVISION 71					Service ATA:00
	MOS/MSC	EFF	-					REQUIREMENT CHANGE FORMS		
	HRS									
	AFL									
					PROC. REF: RCF CI45					
CI45-190429A					REVIEW LEARJET 45/45XR AMM REV 72					Service ATA:00
	MOS/MSC	EFF	-					REQUIREMENT CHANGE FORMS		
	HRS									
	AFL									
					PROC. REF: RCF CI45					
CI45-200529					REVIEW AUDIT SUMMARY CHANGE FORM					Service ATA:00
	MOS/MSC	EFF	-					AUDIT SUMMARY CHANGE FORM		
	HRS									
	AFL									
					PROC. REF: RCF CI45					
CI45-210120					REVIEW LEARJET 45/45XR AUDIT SUMMARY CHANGE FORM					Service ATA:00
	MOS/MSC	EFF	-					AUDIT SUMMARY CHANGE FORM		
	HRS									
	AFL									
					PROC. REF: RCF CI45					
EC04-180802					NO. 1 ENGINE - REVIEW TFE731-20/-40/-60 (CIMMS) LMM TR 5-17					Service ATA:00
	MOS/MSC	EFF	-					REQUIREMENT CHANGE FORMS		
	HRS									
	ENC									
					PROC. REF: RCF EC04-180802					
EC04-180802					NO. 2 ENGINE - REVIEW TFE731-20/-40/-60 (CIMMS) LMM TR 5-17					Service ATA:00
	MOS/MSC	EFF	-					REQUIREMENT CHANGE FORMS		
	HRS									
	ENC									
					PROC. REF: RCF EC04-180802					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 05 - TIME LIMITS/ MAINTENANCE CHECKS											
051101	PHASE A1-300 HOUR CHECKS									Package ATA:05	
	MOS	20-Jan-23	12 (+ 14d/-14d)		20-Jan-24	03-Feb-24	346 d (+ 14)				
	HRS	1675	300 (+ 25/-25)		1975	2000	300 (+ 25)				
WC# : 05.110	AFL	1330									
PROC. REF: AMM 05-10-00, AMM 05-11-01										PKG:1	
051102	PHASE A2-300 HOUR CHECKS									Package ATA:05	
	MOS	20-Jan-23	12 (+ 14d/-14d)		20-Jan-24	03-Feb-24	346 d (+ 14)				
	HRS	1675	300 (+ 25/-25)		1975	2000	300 (+ 25)				
WC# : 05.130	AFL	1330									
PROC. REF: AMM 05-10-00, AMM 05-11-02										PKG:2	
051103	PHASE A3-300 HOUR CHECKS									Package ATA:05	
	MOS	20-Jan-23	12 (+ 14d/-14d)		20-Jan-24	03-Feb-24	346 d (+ 14)				
	HRS	1675	300 (+ 25/-25)		1975	2000	300 (+ 25)				
	AFL	1330									
PROC. REF: AMM 05-10-00, AMM 05-11-03										PKG:3	
051104	PHASE A4-300 HOUR CHECKS									Package ATA:05	
	MOS	20-Jan-23	12 (+ 14d/-14d)		20-Jan-24	03-Feb-24	346 d (+ 14)				
	HRS	1675	300 (+ 25/-25)		1975	2000	300 (+ 25)				
	AFL	1330									
PROC. REF: AMM 05-10-00, AMM 05-11-04										PKG:4	
051105	PHASE A5-300 HOUR CHECKS									Package ATA:05	
	MOS	20-Jan-23	12 (+ 14d/-14d)	Adj -131d	11-Sep-23	25-Sep-23	215 d (+ 14)				
	HRS	1675	300 (+ 25/-25)		1975	2000	300 (+ 25)				
	AFL	1330									
PROC. REF: AMM 05-10-00, AMM 05-11-05										PKG:5	
051106	PHASE A6-300 HOUR CHECKS									Package ATA:05	
	MOS	20-Jan-23	12 (+ 14d/-14d)		20-Jan-24	03-Feb-24	346 d (+ 14)				
	HRS	1675	300 (+ 25/-25)		1975	2000	300 (+ 25)				
	AFL	1330									
PROC. REF: AMM 05-10-00, AMM 05-11-06										PKG:6	

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 05 - TIME LIMITS/ MAINTENANCE CHECKS										
051201	PHASE B1 600 HOUR CHECKS									Package ATA:05
	MOS	20-Jan-23	24 (+ 14d/-14d)		20-Jan-25	03-Feb-25	712 d (+ 14)			
	HRS	1675	600 (+ 25/-25)		2275	2300	600 (+ 25)			
	AFL	1330								
	PROC. REF: AMM 05-10-00, AMM 05-12-01									PKG:7
051202	PHASE B2 600 HOUR CHECKS									Package ATA:05
	MOS	20-Jan-23	24 (+ 14d/-14d)		20-Jan-25	03-Feb-25	712 d (+ 14)			
	HRS	1675	600 (+ 25/-25)		2275	2300	600 (+ 25)			
	AFL	1330								
	PROC. REF: AMM 05-10-00, AMM 05-12-02									PKG:8
051203	PHASE B3 600 HOUR CHECKS									Package ATA:05
	MOS	20-Jan-23	24 (+ 14d/-14d)		20-Jan-25	03-Feb-25	712 d (+ 14)			
	HRS	1675	600 (+ 25/-25)		2275	2300	600 (+ 25)			
	AFL	1330								
	PROC. REF: AMM 05-10-00, AMM 05-12-03									PKG:9
051204	PHASE B4 600 HOUR CHECKS									Package ATA:05
	MOS	20-Jan-23	24 (+ 14d/-14d)		20-Jan-25	03-Feb-25	712 d (+ 14)			
	HRS	1675	600 (+ 25/-25)		2275	2300	600 (+ 25)			
	AFL	1330								
	PROC. REF: AMM 05-10-00, AMM 05-12-04									PKG:10
051205	PHASE B5 600 HOUR CHECKS									Package ATA:05
	MOS	20-Jan-23	24 (+ 14d/-14d)		20-Jan-25	03-Feb-25	712 d (+ 14)			
	HRS	1675	600 (+ 25/-25)		2275	2300	600 (+ 25)			
	AFL	1330								
	PROC. REF: AMM 05-10-00, AMM 05-12-05									PKG:11
051206	PHASE B6 600 HOUR CHECKS									Package ATA:05
	MOS	20-Jan-23	24 (+ 14d/-14d)		20-Jan-25	03-Feb-25	712 d (+ 14)			
	HRS	1675	600 (+ 25/-25)		2275	2300	600 (+ 25)			
	AFL	1330								
	PROC. REF: AMM 05-10-00, AMM 05-12-06									PKG:12

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 05 - TIME LIMITS/ MAINTENANCE CHECKS										
051301	PHASE C1 1200 HOUR CHECKS									Package ATA:05
	MOS	20-Jan-23	48 (+ 14d/-14d)		20-Jan-27	03-Feb-27	1442 d (+ 14)			
	HRS	1675	1200 (+ 25/-25)		2875	2900	1200 (+ 25)			
	AFL	1330								
PROC. REF: AMM 05-10-00, AMM 05-13-01										PKG:13
051302	PHASE C2 1200 HOUR CHECKS									Package ATA:05
	MOS	20-Jan-23	48 (+ 14d/-14d)		20-Jan-27	03-Feb-27	1442 d (+ 14)			
	HRS	1675	1200 (+ 25/-25)		2875	2900	1200 (+ 25)			
	AFL	1330								
PROC. REF: AMM 05-10-00, AMM 05-13-02										PKG:14
051303	PHASE C3 1200 HOUR CHECKS									Package ATA:05
	MOS	20-Jan-23	48 (+ 14d/-14d)		20-Jan-27	03-Feb-27	1442 d (+ 14)			
	HRS	1675	1200 (+ 25/-25)		2875	2900	1200 (+ 25)			
	AFL	1330								
PROC. REF: AMM 05-10-00, AMM 05-13-03										PKG:15
051304	PHASE C4 1200 HOUR CHECKS									Package ATA:05
	MOS	20-Jan-23	48 (+ 14d/-14d)		20-Jan-27	03-Feb-27	1442 d (+ 14)			
	HRS	1675	1200 (+ 25/-25)		2875	2900	1200 (+ 25)			
	AFL	1330								
PROC. REF: AMM 05-10-00, AMM 05-13-04										PKG:16
051305	PHASE C5 1200 HOUR CHECKS									Package ATA:05
	MOS	20-Jan-23	48 (+ 14d/-14d)		20-Jan-27	03-Feb-27	1442 d (+ 14)			
	HRS	1675	1200 (+ 25/-25)		2875	2900	1200 (+ 25)			
	AFL	1330								
PROC. REF: AMM 05-10-00, AMM 05-13-05										PKG:17
051306	PHASE C6 1200 HOUR CHECKS									Package ATA:05
	MOS	20-Jan-23	48 (+ 14d/-14d)		20-Jan-27	03-Feb-27	1442 d (+ 14)			
	HRS	1675	1200 (+ 25/-25)		2875	2900	1200 (+ 25)			
	AFL	1330								
PROC. REF: AMM 05-10-00, AMM 05-13-06										PKG:18

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 05 - TIME LIMITS/ MAINTENANCE CHECKS										
051401			PHASE D1 2400 HOUR CHECKS						Package	ATA:05
	MOS	11-Sep-18	96		11-Sep-26		1311 d			
	HRS	1387.4	2400		3787.4		2112.4			
	AFL	1114								
					PROC. REF: AMM 05-10-00, AMM 05-14-01					PKG:19
051402			PHASE D2 2400 HOUR CHECKS						Package	ATA:05
	MOS	11-Sep-18	96		11-Sep-26		1311 d			
	HRS	1387.4	2400		3787.4		2112.4			
	AFL	1114								
					PROC. REF: AMM 05-10-00, AMM 05-14-02					PKG:20
051403			PHASE D3 2400 HOUR CHECKS						Package	ATA:05
	MOS	11-Sep-18	96 (+ 14d/-14d)		11-Sep-26	25-Sep-26	1311 d (+ 14)			
	HRS	1387.4	2400 (+ 25/-25)		3787.4	3812.4	2112.4 (+ 25)			
	AFL	1114								
					PROC. REF: AMM 05-10-00, AMM 05-14-03					PKG:21
051404			PHASE D4 2400 HOUR CHECKS						Package	ATA:05
	MOS	11-Sep-18	96 (+ 14d/-14d)		11-Sep-26	25-Sep-26	1311 d (+ 14)			
	HRS	1387.4	2400 (+ 25/-25)		3787.4	3812.4	2112.4 (+ 25)			
	AFL	1114								
					PROC. REF: AMM 05-10-00, AMM 05-14-04					PKG:22
051405			PHASE D5 2400 HOUR CHECKS						Package	ATA:05
	MOS	11-Sep-18	96 (+ 14d/-14d)		11-Sep-26	25-Sep-26	1311 d (+ 14)			
	HRS	1387.4	2400 (+ 25/-25)		3787.4	3812.4	2112.4 (+ 25)			
	AFL	1114								
					PROC. REF: AMM 05-10-00, AMM 05-14-05					PKG:23
051406			PHASE D6 2400 HOUR CHECKS						Package	ATA:05
	MOS	11-Sep-18	96 (+ 14d/-14d)		11-Sep-26	25-Sep-26	1311 d (+ 14)			
	HRS	1387.4	2400 (+ 25/-25)		3787.4	3812.4	2112.4 (+ 25)			
	AFL	1114								
					PROC. REF: AMM 05-10-00, AMM 05-14-06					PKG:24

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 05 - TIME LIMITS/ MAINTENANCE CHECKS											
051500		4800 HOUR CHECKS								Package	ATA:05
	MOS	20-Jan-11									
	HRS	0	4800		4800		3125				
	AFL	0									
PROC. REF: AMM 05-10-00, AMM 05-15-00										PKG:25	
051600		9600 HOUR CHECKS								Package	ATA:05
	MOS	20-Jan-11									
	HRS	0	9600		9600		7925				
	AFL	0									
PROC. REF: AMM 05-10-00, AMM 05-16-00										PKG:26	
051700		MAJOR LANDING GEAR INSPECTION								Package	ATA:05
	MOS	20-Jan-11									
	HRS	0									
	AFL	0	10000		10000		8670				
PROC. REF: AMM 05-10-00, AMM 05-17-00										PKG:27	
057110		NO. 1 ENGINE - 150 TO 250 HR ROUTINE PERIODIC INSP PER MANUFACTURERS INSTRUCTIONS								Package	ATA:05
	MOS	20-Jan-23									
	HRS	1675	200 (+ 50/-50)		(1875) 1875	1925	200 (+ 50)				
	ENC	1335									
PROC. REF: LMM 72-00-00											
057110		NO. 2 ENGINE - 150 TO 250 HR ROUTINE PERIODIC INSP PER MANUFACTURERS INSTRUCTIONS								Package	ATA:05
	MOS	20-Jan-23									
	HRS	1675	200 (+ 50/-50)		(1875) 1875	1925	200 (+ 50)				
	ENC	1333									
PROC. REF: LMM 72-00-00											
057120		NO. 1 ENGINE - 300 TO 440 HR ROUTINE PERIODIC INSP PER MANUFACTURERS INSTRUCTIONS								Package	ATA:05
	MOS/MSC	01-Apr-10	N/A								
	HRS	0									
	ENC	0									
PROC. REF: LMM 72-00-00											

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty		
ATA 05 - TIME LIMITS/ MAINTENANCE CHECKS												
057120			NO. 2 ENGINE - 300 TO 440 HR ROUTINE PERIODIC INSP PER MANUFACTURERS INSTRUCTIONS								Package	ATA:05
	MOS/MSC	02-Apr-10	N/A									
	HRS	0										
	ENC	0										
PROC. REF: LMM 72-00-00												
057130			NO. 1 ENGINE - 500 TO 650 HR ROUTINE PERIODIC INSP PER MANUFACTURERS INSTRUCTIONS								Package	ATA:05
	MOS	11-Sep-18										
	HRS	1387.4	600 (+ 50/-100)		(1987.4) 1987.4	2037.4	312.4 (+ 50)					
	ENC	1119										
PROC. REF: LMM 72-00-00												
057130			NO. 2 ENGINE - 500 TO 650 HR ROUTINE PERIODIC INSP PER MANUFACTURERS INSTRUCTIONS								Package	ATA:05
	MOS	11-Sep-18										
	HRS	1387.4	600 (+ 50/-100)		(1987.4) 1987.4	2037.4	312.4 (+ 50)					
	ENC	1117										
PROC. REF: LMM 72-00-00												
057140			NO. 1 ENGINE - 500 TO 850 HOUR ROUTINE PERIODIC INSP PER MANUFACTURERS INSTRUCTIONS								Package	ATA:05
	MOS	10-Oct-19										
	HRS	1509.8	850 (-350)		(2359.8) 2359.8		684.8					
	ENC	1206										
PROC. REF: LMM 72-00-00												
057140			NO. 2 ENGINE - 500 TO 850 HOUR ROUTINE PERIODIC INSP PER MANUFACTURERS INSTRUCTIONS								Package	ATA:05
	MOS	10-Oct-19										
	HRS	1509.8	850 (-350)		(2359.8) 2359.8		684.8					
	ENC	1204										
PROC. REF: LMM 72-00-00												
057150			NO. 1 ENGINE - 1000 TO 1300 HR ROUTINE PERIODIC INSP PER MANUFACTURERS INSTRUCTIONS								Package	ATA:05
	MOS	16-Dec-16										
	HRS	1162	1200 (+ 100/-200) Adj 38		(2400) 2400	2500	725 (+ 100)					
	ENC	971										
PROC. REF: LMM 72-00-00												

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 05 - TIME LIMITS/ MAINTENANCE CHECKS											
057150			NO. 2 ENGINE - 1000 TO 1300 HR ROUTINE PERIODIC INSP PER MANUFACTURERS INSTRUCTIONS							Package	ATA:05
	MOS	16-Dec-16									
	HRS	1162	1200 (+ 100/-200)	Adj 38	(2400) 2400	2500	725 (+ 100)				
	ENC	969									
PROC. REF: LMM 72-00-00											
057160			NO. 1 ENGINE - 1500 TO 1650 HOUR ROUTINE PERIODIC INSP PER MANUFACTURERS INSTRUCTIONS							Package	ATA:05
	MOS	10-Oct-19									
	HRS	1509.8	1600 (+ 50/-100)		(3109.8) 3109.8	3159.8	1434.8 (+ 50)				
	ENC	1206									
PROC. REF: LMM 72-00-00											
057160			NO. 2 ENGINE - 1500 TO 1650 HOUR ROUTINE PERIODIC INSP PER MANUFACTURERS INSTRUCTIONS							Package	ATA:05
	MOS	10-Oct-19									
	HRS	1509.8	1600 (+ 50/-100)		(3109.8) 3109.8	3159.8	1434.8 (+ 50)				
	ENC	1204									
PROC. REF: LMM 72-00-00											
5-50-00-BS			INSPECTION BIRD STRIKE							Service	ATA:05
	MOS/MSC		A/R					INSPECT			
	HRS										
	AFL										
PROC. REF: GENERIC NO REF											
5-50-00-CS			INSPECTION PRESSURE CABIN SKIN THICKNESS MEASUREMENT (P-STATIC TEST)							Service	ATA:05
	MOS/MSC	20-Jan-11	A/R					INSPECT			
	HRS	0									
	AFL	0									
PROC. REF: AMM 05-50-00											
5-50-00-ED			INSPECTION ELEVATOR DISCONNECT							Service	ATA:05
	MOS/MSC	20-Jan-11	O/C								
	HRS	0									
	AFL	0									
PROC. REF: AMM 05-50-00											

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 05 - TIME LIMITS/ MAINTENANCE CHECKS										
5-50-00-EV	PERFORM ENGINE VIBRATION TEST AND INSPECTION									Service ATA:05
	MOS/MSC		A/R							
	HRS									
	AFL									
	PROC. REF: AMM 05-50-00									
5-50-00-FD	INSPECTION FOREIGN OBJECT DAMAGE									Service ATA:05
	MOS/MSC		O/C							
	HRS									
	AFL									
	PROC. REF: AMM 05-50-00									
5-50-00-GW	INSPECTION HIGH GROUND WIND GUST									Service ATA:05
	MOS/MSC	20-Jan-11	A/R					INSPECT		
	HRS	0								
	AFL	0								
	PROC. REF: AMM 05-50-00									
5-50-00-HD	INSPECTION HEAT DAMAGE									Service ATA:05
	MOS/MSC	20-Jan-11	O/C							
	HRS	0								
	AFL	0								
	PROC. REF: AMM 05-50-00									
5-50-00-HE	INSPECTION HIGH ENERGY STOP									Service ATA:05
	MOS/MSC	20-Jan-11	A/R					INSPECT		
	HRS	0								
	AFL	0								
	PROC. REF: AMM 05-50-00									
5-50-00-HL	INSPECTION HARD LANDING									Service ATA:05
	MOS/MSC		A/R					INSPECT		
	HRS									
	AFL									
	PROC. REF: AMM 05-50-00									
5-50-00-LS	INSPECTION LIGHTNING STRIKE									Service ATA:05
	MOS/MSC	20-Jan-11	A/R					INSPECT		
	HRS	0								
	AFL	0								
	PROC. REF: AMM 05-50-00									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 05 - TIME LIMITS/ MAINTENANCE CHECKS										
5-50-00-NH	INSPECTION NACELLE HEAT FAIL MESSGE									Service ATA:05
	MOS/MSC	20-Jan-11	O/C							
	HRS	0								
	AFL	0								
PROC. REF: AMM 05-50-00										
5-50-00-OS	INSPECTION OVERSPEED RECOVERY LANDING GEAR									Service ATA:05
	MOS/MSC	20-Jan-11	A/R					INSPECT		
	HRS	0								
	AFL	0								
PROC. REF: AMM 05-50-00										
5-50-00-OW	INSPECTION OVERWEIGHT LANDING (WEIGHT IN EXCESS OF MAXIMUM LANDING WEIGHT)									Service ATA:05
	MOS/MSC		A/R					INSPECT		
	HRS									
	AFL									
PROC. REF: AMM 05-50-00										
5-50-00-ST	INSPECTION SEVERE TURBULANCE AND OR MANEUVERS									Service ATA:05
	MOS/MSC	20-Jan-11	A/R					INSPECT		
	HRS	0								
	AFL	0								
PROC. REF: AMM 05-50-00										
5-50-00-TR	INSPECTION THRUST REVERSER SYSTEM									Service ATA:05
	MOS/MSC	20-Jan-11	O/C							
	HRS	0								
	AFL	0								
PROC. REF: AMM 05-50-00										
5-50-00-UE	PERFORM UNSCHEDULED ENGINE CHANGE/REMOVAL INSPECTION									Service ATA:05
	MOS/MSC	20-Jan-11	O/C							
	HRS	0								
	AFL	0								
PROC. REF: AMM 05-50-00										
5-50-00-VA	INSPECTION VOLCANIC ASH									Service ATA:05
	MOS/MSC	20-Jan-11	A/R					INSPECT		
	HRS	0								
	AFL	0								
PROC. REF: AMM 05-50-00										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty
---------	------	------	----------	-----------	--------------------------	-----------	-----------	-------------	-----	----------

ATA 05 - TIME LIMITS/ MAINTENANCE CHECKS

5-50-00-WF	INSPECTION WING FLAP SYSTEM OVERSPEED CHECK								Service	ATA:05
	MOS/MSC	20-Jan-11	O/C							
	HRS	0								
	AFL	0								
PROC. REF: AMM 05-50-00										

ATA 08 - LEVELING AND WEIGHING

082000	REWEIGH AIRCRAFT								Service	ATA:08
	MOS/MSC	28-Nov-15	A/R							
	HRS	954.7								
	AFL	842								
PROC. REF: AMM 08-10-00, FAR FAR 135.185										

ATA 11 - PLACARDS AND MARKINGS

G1130000 ^S	CHECK CHECK BRIGHTNESS LEVEL OF ALL SELF-LUMINOUS PLACARDS								Service	ATA:11
	MOS	20-Jan-23	48 (+ 14d/-14d)							
	HRS	1675	1200 (+ 25/-25)							
	AFL	1330								
PROC. REF: AMM 11-30-00										PKG:13

ATA 12 - SERVICING

5-19-00-Q1221064	FLAP ACTUATOR JOINT (P/N 145673-1) - APPLY CORROSION PREVENTIVE COMPOUND (CPC). (REFER TO 12-21-03.)								Service	ATA:12
	MOS/MSC	06-Apr-11	N/A					NOT APPLICABLE		
	HRS	68.8								
	AFL	47								
PROC. REF: AMM 12-21-03										

5-19-00-U1210004	LUBRICATE FLAP FLEXIBLE TRANSMISSION SHAFTS - BY HAND (U1210004)								Service	ATA:12
	MOS	20-Jan-11								
	HRS	0	4800 (+ 25/-25)	4800	4825	3125 (+ 25)				
	AFL	0								
PROC. REF: GENERIC NO REF										

AB1210060 ^S	MAIN LANDING GEAR UP-LOCK ACTUATOR - LUBRICATE								Service	ATA:12
	MOS	20-Jan-23	12 (+ 14d/-14d)							
	HRS	1675	300 (+ 25/-25)							
	AFL	1330								
PROC. REF: AMM 12-21-01										PKG:5

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 12 - SERVICING											
O1210002 ^S			FLAP ACTUATORS - CHECK OIL LEVEL.						Service	ATA:12	
	MOS	20-Jan-23	24 (+ 14d/-14d)								
	HRS	1675	600 (+ 25/-25)								
	AFL	1330									
					PROC. REF: AMM 12-21-03					PKG:10	
Y1210000 ^S			NOSE LANDING GEAR SHOCK STRUT - CHECK FOR PROPER FLUID LEVEL AND INFLATION PRESSURE.						Service	ATA:12	
	MOS	20-Jan-23	12 (+ 14d/-14d)								
	HRS	1675	300 (+ 25/-25)								
	AFL	1330									
					PROC. REF: AMM 12-10-02					PKG:5	
Y1210001 ^S			MAIN LANDING GEAR SHOCK STRUTS - CHECK FOR PROPER FLUID LEVEL AND INFLATION PRESSURE.						Service	ATA:12	
	MOS	20-Jan-23	12 (+ 14d/-14d)								
	HRS	1675	300 (+ 25/-25)								
	AFL	1330									
					PROC. REF: AMM 12-10-03					PKG:5	
Y1210003 ^S			FLAP ACTUATOR BALLNUT - LUBRICATE.						Service	ATA:12	
	MOS	20-Jan-23	12 (+ 14d/-14d)								
	HRS	1675	300 (+ 25/-25)								
	AFL	1330									
					PROC. REF: AMM 12-21-03					PKG:4	
Y1210005 ^S			NOSE LANDING GEAR TRUNNION PIN - LUBRICATE.						Service	ATA:12	
	MOS	20-Jan-23	12 (+ 14d/-14d)								
	HRS	1675	300 (+ 25/-25)								
	AFL	1330									
					PROC. REF: AMM 12-21-01					PKG:5	
Y1210006 ^S			NOSE LANDING GEAR ACTUATOR ATTACH FITTING - LUBRICATE.						Service	ATA:12	
	MOS	20-Jan-23	12 (+ 14d/-14d)								
	HRS	1675	300 (+ 25/-25)								
	AFL	1330									
					PROC. REF: AMM 12-21-01					PKG:5	
Y1210007 ^S			NOSE AND MAIN TIRES - CHECK FOR PROPER INFLATION.						Service	ATA:12	
	MOS	20-Jan-23	12 (+ 14d/-14d)								
	HRS	1675	300 (+ 25/-25)								
	AFL	1330									
					PROC. REF: AMM 12-10-04					PKG:5	

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 12 - SERVICING											
Y1210009 ^S			NOSE GEAR DOOR HINGE - LUBRICATE.								Service ATA:12
	MOS	20-Jan-23	12 (+ 14d/-14d)								
	HRS	1675	300 (+ 25/-25)								
	AFL	1330									
										PROC. REF: AMM 12-21-02	
										PKG:1	
Y1210011 ^S			MAIN LANDING GEAR ACTUATOR JOINTS - LUBRICATE.								Service ATA:12
	MOS	20-Jan-23	12 (+ 14d/-14d)								
	HRS	1675	300 (+ 25/-25)								
	AFL	1330									
										PROC. REF: AMM 12-21-01	
										PKG:5	
Y1210012 ^S			MAIN LANDING GEAR AXLE BEAM/PISTON JOINTS - LUBRICATE.								Service ATA:12
	MOS	20-Jan-23	12 (+ 14d/-14d)								
	HRS	1675	300 (+ 25/-25)								
	AFL	1330									
										PROC. REF: AMM 12-21-01	
										PKG:5	
Y1210013 ^S			MAIN LANDING GEAR TORQUE LINKS - LUBRICATE.								Service ATA:12
	MOS	20-Jan-23	12 (+ 14d/-14d)								
	HRS	1675	300 (+ 25/-25)								
	AFL	1330									
										PROC. REF: AMM 12-21-01	
										PKG:5	
Y1210014 ^S			MAIN GEAR DOOR HINGE - LUBRICATE								Service ATA:12
	MOS	08-Nov-21	12 (+ 14d/-14d)								
	HRS	1605.6	300 (+ 25/-25)								
	AFL	1281									
										PROC. REF: AMM 12-21-02	
										PKG:5	
Y1210016 ^S			PASSENGER/CREW DOOR HINGE - LUBRICATE								Service ATA:12
	MOS	20-Jan-23	12 (+ 14d/-14d)								
	HRS	1675	300 (+ 25/-25)								
	AFL	1330									
										PROC. REF: AMM 12-21-02	
										PKG:6	
Y1210017 ^S			PASSENGER/CREW DOOR PINS - LUBRICATE								Service ATA:12
	MOS	20-Jan-23	12 (+ 14d/-14d)								
	HRS	1675	300 (+ 25/-25)								
	AFL	1330									
										PROC. REF: AMM 12-21-02	
										PKG:6	

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 12 - SERVICING											
Y1210018 ^S			PASSENGER/CREW DOOR TENSION BOLTS - LUBRICATE.						Service	ATA:12	
	MOS	20-Jan-23	12 (+ 14d/-14d)								
	HRS	1675	300 (+ 25/-25)								
	AFL	1330									
					PROC. REF: AMM 12-21-02					PKG:6	
Y1210019 ^S			EMERGENCY EXIT DOOR LATCHING MECHANISM - LUBRICATE.						Service	ATA:12	
	MOS	20-Jan-23	12 (+ 14d/-14d)								
	HRS	1675	300 (+ 25/-25)								
	AFL	1330									
					PROC. REF: AMM 12-21-02					PKG:6	
Y1210020 ^S			EMERGENCY EXIT DOOR PINS - LUBRICATE.						Service	ATA:12	
	MOS	20-Jan-23	12 (+ 14d/-14d)								
	HRS	1675	300 (+ 25/-25)								
	AFL	1330									
					PROC. REF: AMM 12-21-02					PKG:6	
Y1210021 ^S			BAGGAGE COMPARTMENT DOOR LATCH PINS - LUBRICATE.						Service	ATA:12	
	MOS	20-Jan-23	12 (+ 14d/-14d)								
	HRS	1675	300 (+ 25/-25)								
	AFL	1330									
					PROC. REF: AMM 12-21-02					PKG:6	
Y1210022 ^S			BAGGAGE COMPARTMENT DOOR HINGE - LUBRICATE						Service	ATA:12	
	MOS	20-Jan-23	12 (+ 14d/-14d)								
	HRS	1675	300 (+ 25/-25)								
	AFL	1330									
					PROC. REF: AMM 12-21-02					PKG:6	
Y1210023 ^S			OXYGEN SYSTEM SERVICING DOOR HINGE - LUBRICATE						Service	ATA:12	
	MOS	20-Jan-23	12 (+ 14d/-14d)								
	HRS	1675	300 (+ 25/-25)								
	AFL	1330									
					PROC. REF: AMM 12-21-02					PKG:1	
Y1210024 ^S			TOILET SERVICING DOOR HINGE - LUBRICATE.						Service	ATA:12	
	MOS	20-Jan-23	12 (+ 14d/-14d)								
	HRS	1675	300 (+ 25/-25)								
	AFL	1330									
					PROC. REF: AMM 12-21-02					PKG:4	

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 12 - SERVICING											
Y1210025 ^S			PRESSURE REFUELING DOOR HINGE - LUBRICATE.								Service ATA:12
	MOS	20-Jan-23	12 (+ 14d/-14d)								
	HRS	1675	300 (+ 25/-25)								
	AFL	1330									
			PROC. REF: AMM 12-21-02								PKG:2
Y1210026 ^S			FUSELAGE FUEL FILLER DOOR HINGE - LUBRICATE								Service ATA:12
	MOS	20-Jan-23	12 (+ 14d/-14d)								
	HRS	1675	300 (+ 25/-25)								
	AFL	1330									
			PROC. REF: AMM 12-21-02								PKG:2
Y1210027 ^S			TAILCONE ACCESS DOOR PINS - LUBRICATE								Service ATA:12
	MOS	20-Jan-23	12 (+ 14d/-14d)								
	HRS	1675	300 (+ 25/-25)								
	AFL	1330									
			PROC. REF: AMM 12-21-02								PKG:6
Y1210028 ^S			TAILCONE ACCESS DOOR HINGE - LUBRICATE.								Service ATA:12
	MOS	20-Jan-23	12 (+ 14d/-14d)								
	HRS	1675	300 (+ 25/-25)								
	AFL	1330									
			PROC. REF: AMM 12-21-02								PKG:6
Y1210029 ^S			MAIN LANDING GEAR TRUNNION PIN - LUBRICATE								Service ATA:12
	MOS	20-Jan-23	12 (+ 14d/-14d)								
	HRS	1675	300 (+ 25/-25)								
	AFL	1330									
			PROC. REF: AMM 12-21-01								PKG:5
Y1221037 ^S			FLAPS - LUBRICATE ROLLING SURFACES OF MAIN AND NOSE ROLLER TRACKS								Service ATA:12
	MOS	20-Jan-23	12 (+ 14d/-14d)								
	HRS	1675	300 (+ 25/-25)								
	AFL	1330									
			PROC. REF: AMM 12-21-03								PKG:4
Y1221042 ^S			HORIZONTAL STABILIZER UPPER AND LOWER TORQUE LINKS - LUBRICATE								Service ATA:12
	MOS	20-Jan-23	24 (+ 14d/-14d)								
	HRS	1675	600 (+ 25/-25)								
	AFL	1330									
			PROC. REF: AMM 12-21-03								PKG:9

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty
---------	------	------	----------	-----------	--------------------------	-----------	-----------	-------------	-----	----------

ATA 12 - SERVICING

Y1227000 ^S		EMERGENCY PARK BRAKE HANDLE SHAFT - LUBRICATE							Service	ATA:12
	MOS	20-Jan-23	12 (+ 14d/-14d)							
	HRS	1675	300 (+ 25/-25)							
	AFL	1330								
PROC. REF: AMM 12-27-00										
PKG:1										

ATA 21 - AIR CONDITIONING

211001		SERVO AIR PRESSURE REGULATING VALVE							Component	ATA:21
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN	0					
SN:UNKNOWN	HRS	0		TSN	0					
	AFL	0		TSN	0					
PROC. REF: AMM 36-15-01										

211011		LEFT PLENUM CHECK VALVE							Component	ATA:21
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN	0					
SN:UNKNOWN	HRS	0		TSN	0					
	AFL	0		TSN	0					
PROC. REF: AMM 21-20-09										

211012		RIGHT PLENUM CHECK VALVE							Component	ATA:21
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN	0					
SN:UNKNOWN	HRS	0		TSN	0					
	AFL	0		TSN	0					
PROC. REF: AMM 21-20-09										

211017		LEFT EMERGENCY PRESSURIZATION ISOLATION CHECK VALVE							Component	ATA:21
PN:3202744-1	MOS/MSC	20-Jan-11	O/C	TSN	0					
SN:3096	HRS	0		TSN	0					
	AFL	0		TSN	0					
PROC. REF: AMM 21-20-03										

211018		RIGHT EMERGENCY PRESSURIZATION ISOLATION CHECK VALVE							Component	ATA:21
PN:3202744-1	MOS/MSC	20-Jan-11	O/C	TSN	0					
SN:3102	HRS	0		TSN	0					
	AFL	0		TSN	0					
PROC. REF: AMM 21-20-03										

212001		COCKPIT AIR CHECK VALVE							Component	ATA:21
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN	0					
SN:UNKNOWN	HRS	0		TSN	0					
	AFL	0		TSN	0					
PROC. REF: AMM 21-20-01										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 21 - AIR CONDITIONING											
212007		AFT BLOWER MOTOR								Component	ATA:21
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 21-51-09											
212008		FWD BLOWER MOTOR								Component	ATA:21
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: GENERIC NO REF											
212011		LINEAR ELECTRO-MECHANICAL ACTUATOR								Component	ATA:21
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: GENERIC NO REF											
212041		LEFT ENGINE OZONE CONVERTER								Component	ATA:21
PN:53A405-4	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:1374/2878	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 21-20-12											
212041A		TEST LEFT ENGINE OZONE CONVERTER EFFICIENCY. (Y2140001)								Service	ATA:21
PN:53A405-4	MOS	20-Jan-11									
SN:1374/2878	HRS	0	3600 (+25/-25)		3600	3625	1925 (+25)				
	AFL	0									
PROC. REF: GENERIC NO REF											
212042		RIGHT ENGINE OZONE CONVERTER								Component	ATA:21
PN:53A405-4	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:1362/2866	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 21-20-12											
212042A		TEST RIGHT ENGINE OZONE CONVERTER EFFICIENCY (Y2140001)								Service	ATA:21
PN:53A405-4	MOS	20-Jan-11									
SN:1362/2866	HRS	0	3600 (+25/-25)		3600	3625	1925 (+25)				
	AFL	0									
PROC. REF: GENERIC NO REF											

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 21 - AIR CONDITIONING											
212101		NO. 1 THERMAL CONTROL ACTUATOR								Component	ATA:21
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: GENERIC NO REF											
212102		NO. 2 THERMAL CONTROL ACTUATOR								Component	ATA:21
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: GENERIC NO REF											
212105		LEFT ECS TRANSITION DUCT								Component	ATA:21
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: GENERIC NO REF											
212106		RIGHT ECS TRANSITION DUCT								Component	ATA:21
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: GENERIC NO REF											
212201		LEFT GASPER AIR CHECK VALVE								Component	ATA:21
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 21-20-07											
212202		RIGHT GASPER AIR CHECK VALVE								Component	ATA:21
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 21-20-07											
212213		LEFT CABIN AIR CHECK VALVE								Component	ATA:21
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 21-20-02											

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 21 - AIR CONDITIONING											
212214		RIGHT CABIN AIR CHECK VALVE								Component	ATA:21
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 21-20-02											
212801		AVIONICS COOLING B13 FAN								Component	ATA:21
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 21-21-01											
213000		CABIN PRESSURE CONTROLLER								Component	ATA:21
PN:2119858-10	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:69-K0095	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 21-30-03											
213001		LEFT EMERGENCY PRESSURE SHUTOFF VALVE								Component	ATA:21
PN:3291224-1	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:1207	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 21-31-01											
213002		RIGHT EMERGENCY PRESSURE SHUTOFF VALVE								Component	ATA:21
PN:3291224-1	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:1231	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 21-31-01											
213021		JET PUMP EJECTOR								Component	ATA:21
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 21-30-06											
213031		PRIMARY OUTFLOW VALVE								Component	ATA:21
PN:6621300000-019	MOS/MSC	25-Jan-11	O/C								
SN:30-A0188	HRS	10									
	AFL	7									
PROC. REF: AMM 21-30-01											

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 21 - AIR CONDITIONING										
213032	SECONDARY OUTFLOW VALVE									Component ATA:21
PN:6621300000-021	MOS/MSC	25-Jan-11	O/C							
SN:98-C0355	HRS	10								
	AFL	7								
PROC. REF: AMM 21-30-02										
213055	EMERGENCY PRESSURE ANEROID SWITCH									Component ATA:21
PN:E45C-47	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:5838	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
213056	ABSOLUTE PRESSURE SWITCH									Component ATA:21
PN:E45C-47	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:5891	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
213101	TAILCONE CHECK VALVE									Component ATA:21
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
213110	CABIN PRESSURIZATION CHECK VALVE									Component ATA:21
PN:130158-3-1	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:118-A1235	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 21-30-07										
214301	FOOT WARMER (S167) THERMOSTAT									Component ATA:21
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 21-41-02										
214302	PILOT HEEL PLATE ASSEMBLY, FOOT WARMER CHANGE									Component ATA:21
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 21-41-01										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 21 - AIR CONDITIONING											
214303		CO-PILOT HEEL PLATE ASSEMBLY, FOOT WARMER CHANGE								Component	ATA:21
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 21-41-01											
214925		LEFT CHECK, ECS (3.0 DIAMETER) VALVE								Component	ATA:21
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 36-10-04											
214926		RIGHT CHECK, ECS (3.0 DIAMETER) VALVE								Component	ATA:21
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 36-10-04											
215001		WATER SEPARATOR ASSEMBLY								Component	ATA:21
PN:2341168-1	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:663	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 21-50-03											
215002		WATER SEPARATOR BYPASS VALVE								Component	ATA:21
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: GENERIC NO REF											
215010		ACM PRECOOLER ASSEMBLY								Component	ATA:21
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 21-50-08											
215013		BI-LEVEL PRESSURE REGULATING & SHUTOFF (L19) VALVE								Component	ATA:21
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 21-50-02											

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 21 - AIR CONDITIONING											
215015		ACM BYPASS CHECK VALVE								Component	ATA:21
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 21-50-07											
215019		CABIN REFRIGERATION CONDENSER								Component	ATA:21
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 21-51-04											
215030		ENVIRONMENTAL CONTROL UNIT								Component	ATA:21
PN:2215150-3	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:688	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 21-50-01											
215033		AIR CYCLE MACHINE								Component	ATA:21
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 21-50-04											
215036		HEAT, PRIMARY, SECONDARY EXCHANGER								Component	ATA:21
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: GENERIC NO REF											
215039		AIR CYCLE MACHINE TURBINE								Component	ATA:21
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 21-50-04											
215043		AFT EVAPORATOR								Component	ATA:21
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 21-51-09											

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 21 - AIR CONDITIONING											
215044		FORWARD EVAPORATOR								Component	ATA:21
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 21-51-07											
215100		AIR CONDITIONING COMPRESSOR								Component	ATA:21
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 21-51-01											
215101		AIR CONDITIONING COMPRESSOR DRIVE MOTOR								Component	ATA:21
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 21-51-02											
215101A		PERFORM AIR CONDITIONING COMPRESSOR DRIVE MOTOR BRUSH WEAR INSPECTION - IRN L2150054								Service	ATA:21
PN:PN	MOS/MSC	20-Jan-11	O/C								
SN:UNKNOWN	HRS	0									
	AFL	0									
PROC. REF: GENERIC NO REF											
215101B		OVERHAUL AIR CONDITIONING COMPRESSOR DRIVE MOTOR								Service	ATA:21
PN:PN	MOS/MSC	20-Jan-11	O/C								
SN:UNKNOWN	HRS	0									
	AFL	0									
PROC. REF: GENERIC NO REF											
216001		INTEGRATED ECS TEMPERATURE CONTROLLER								Component	ATA:21
PN:1151831-3	MOS/MSC	10-Feb-15	O/C								
SN:1151830-00779	HRS	883.5									
	AFL	792									
PROC. REF: AMM 21-60-10											
216013		COCKPIT TEMPERATURE CONTROL VALVE								Component	ATA:21
PN:3291222-1	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:1214	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 21-60-05											

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty
---------	------	------	----------	-----------	--------------------------	-----------	-----------	-------------	-----	----------

ATA 21 - AIR CONDITIONING

216014 CABIN TEMPERATURE CONTROL VALVE Component ATA:21										
PN:3291222-1	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:1226	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 21-60-04										
216025 COCKPIT TEMPERATURE CONTROL SELECTOR Component ATA:21										
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 21-60-01										
216026 CABIN TEMPERATURE CONTROL SELECTOR Component ATA:21										
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 21-60-01										
216036 OVERHEAT, COCKPIT DUCT THERMOSTAT Component ATA:21										
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 21-60-09										
216037 OVERHEAT, CABIN DUCT THERMOSTAT Component ATA:21										
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 21-60-08										
216040 CABIN TEMP 28VDC SENSOR/FAN ASSEMBLY Component ATA:21										
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 21-60-03										
216049 CABIN DUCT OVERTEMP LIMITER Component ATA:21										
PN:627962-2	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:627962-23269	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 21-60-06										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 21 - AIR CONDITIONING											
216071		LOW LIMIT TEMPERATURE CONTROL VALVE								Component	ATA:21
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: GENERIC NO REF											
216074		REGULATING, SERVO AIR PRESSURE VALVE								Component	ATA:21
PN:60810-1	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:1435	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 36-15-01											
216081		TEMPERATURE, COCKPIT DUCT SENSOR								Component	ATA:21
PN:627962-2	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:627962-23274	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 21-60-07											
216083		COCKPIT TEMPERATURE SENSOR								Component	ATA:21
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 21-60-02											
216084		CABIN TEMPERATURE, LOW LIMIT SENSOR								Component	ATA:21
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 21-50-09											
5-19-00-L2150054		WEAR INSPECTION - AIR CONDITIONING COMPRESSOR DRIVE MOTOR BRUSHES - PERFORM WEAR INSPECTION (RETURN DRIVE MOTOR TO AUTHORIZED SERVICE FACILITY FOR OVERHAUL)								Service	ATA:21
	MOS/MSC	20-Jan-11	N/A					N/A BY SERIAL NUMBER			
	HRS	0									
	AFL	0									
PROC. REF: GENERIC NO REF											

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 21 - AIR CONDITIONING										
5-19-00-L2150055	OVERHAUL - AIR CONDITIONING COMPRESSOR MOTOR - PERFORM OVERHAUL (RETURN DRIVE MOTOR TO AUTHORIZED SERVICE FACILITY FOR OVERHAUL)								Service	ATA:21
	MOS/MSC	20-Jan-11	N/A					N/A BY SERIAL NUMBER		
	HRS	0								
	AFL	0								
PROC. REF: GENERIC NO REF										
5-19-00-Y2130065	LEAK TEST CABIN PRESSURIZATION SYSTEM. (IRN # Y2130065).								Service	ATA:21
	MOS	16-Dec-16								
	HRS	1162	1200 (+25/-25)		2362	2387	687 (+25)			
	AFL	966								
PROC. REF: AMM 21-30-00										
5-19-01-Y2141002	REPLACE WATER SEPARATOR COALESCER BAG. (ZONE/ACCESS 310HL, 310RR IRN # W2141002)								Service	ATA:21
	MOS/MSC	20-Mar-15	O/C							
	HRS	905.6								
	AFL	802								
PROC. REF: GENERIC NO REF										
J2160007 ^S	TEMPERATURE CONTROL SYSTEM - INSPECT AND CLEAN CABIN AND COCKPIT TEMPERATURE CONTROL VALVE SERVO AIR FILTERS. (EFFECTIVE ON AIRCRAFT 45-005 THRU 45-232 POST SB 45-21-16, AND AIRCRAFT 45-233 THRU 45-2000.)								Service	ATA:21
	MOS	20-Jan-23	24 (+14d/-14d)							
	HRS	1675	600 (+25/-25)							
	AFL	1330								
PROC. REF: AMM 21-60-11										
L2150056 ^S	** AUXILIARY HEAT SYSTEM - PERFORM FUNCTIONAL TEST. (EFFECTIVE ON AIRCRAFT 45-250 AND SUBSEQUENT EQUIPPED WITH KEITH PRODUCTS VAPOR CYCLE AIR CONDITIONING SYSTEM USING REFRIGERANT R-134.)								Service	ATA:21
	MOS	20-Jan-23	24 (+14d/-14d)					AIRWORTHINESS		
	HRS	1675	600 (+25/-25)							
	AFL	1330								
PROC. REF: AMM 21-51-00										
L2150057 ^S	PERFORM ** AUXILIARY HEAT SYSTEM - AUXILIARY HEATER ELECTRICAL AND TEMPERATURE SWITCH TEST. (EFFECTIVE ON AIRCRAFT 45-250 AND SUBSEQUENT EQUIPPED WITH KEITH PRODUCTS VAPOR CYCLE AIR CONDITIONING SYSTEM USING REFRIGERANT R-134.)								Service	ATA:21
	MOS	20-Jan-23	48 (+14d/-14d)					AIRWORTHINESS		
	HRS	1675	1200 (+25/-25)							
	AFL	1330								
PROC. REF: AMM 21-51-00										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 21 - AIR CONDITIONING											
O2130000 ^S			PERFORM PRIMARY AND SECONDARY OUTFLOW VALVES - INSPECTION.							Service	ATA:21
	MOS	20-Jan-23	48 (+ 14d/-14d)								
	HRS	1675	1200 (+ 25/-25)								
	AFL	1330									
			PROC. REF: AMM 21-30-01, AMM 21-30-02								PKG:13
O2130001 ^S			REPLACE OUTFLOW VALVE AIR FILTER - REMOVE AND REPLACE.							Service	ATA:21
	MOS	11-Sep-18	96 (+ 14d/-14d)								
	HRS	1387.4	2400 (+ 25/-25)								
	AFL	1114									
			PROC. REF: AMM 21-30-04								PKG:19
O2130002 ^S			PERFORM ** PRESSURIZATION CONTROL SYSTEM - FUNCTIONAL TEST.							Service	ATA:21
	MOS	20-Jan-23	48 (+ 14d/-14d)					AIRWORTHINESS			
	HRS	1675	1200 (+ 25/-25)								
	AFL	1330									
			PROC. REF: AMM 21-30-00								PKG:13
Y2130003 ^S			PRESSURIZATION CONTROL SYSTEM - PERFORM OPERATIONAL CHECK							Service	ATA:21
	MOS	20-Jan-23	24 (+ 14d/-14d)								
	HRS	1675	600 (+ 25/-25)								
	AFL	1330									
			PROC. REF: AMM 21-30-00								PKG:7
Y2140000 ^S			PERFORM AIR CYCLE MACHINE HEAT EXCHANGER INLET - VISUAL INSPECTION							Service	ATA:21
	MOS	20-Jan-23	48 (+ 14d/-14d)								
	HRS	1675	1200 (+ 25/-25)								
	AFL	1330									
			PROC. REF: AMM 05-10-00								PKG:14
Y2141000 ^S			PERFORM ENVIRONMENTAL CONTROL UNIT - VISUAL INSPECTION							Service	ATA:21
	MOS	20-Jan-23	48 (+ 14d/-14d)								
	HRS	1675	1200 (+ 25/-25)								
	AFL	1330									
			PROC. REF: AMM 05-10-00								PKG:14

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 21 - AIR CONDITIONING										
Y2141001 ^S	WATER SEPARATOR COALESCER BAG - PERFORM VISUAL INSPECTION. CLEAN IF NECESSARY. (NOTE: THE SERVICING ACTIVITY MAY REQUIRE A MORE FREQUENT INTERVAL, DEPENDING ON ENVIRONMENTAL AND OPERATIONAL REQUIREMENTS, AND SHOULD BE ADJUSTED BY INDIVIDUAL OPERATORS)								Service	ATA:21
	MOS	20-Jan-23	12 (+ 14d/-14d)							
	HRS	1675	300 (+ 25/-25)							
	AFL	1330								
PROC. REF: AMM 05-10-00										PKG:2
Y2142000 ^S	PERFORM BAGGAGE COMPARTMENT HEATING SYSTEM - FUNCTIONAL TEST								Service	ATA:21
	MOS	11-Sep-18	96 (+ 14d/-14d)							
	HRS	1387.4	2400 (+ 25/-25)							
	AFL	1114								
PROC. REF: AMM 21-40-00										PKG:20
Y2145000 ^S	PERFORM ECS PLENUM ASSEMBLY CHECK VALVES - VISUAL INSPECTION. VERIFY FREEDOM OF MOVEMENT OF BUTTERFLY ASSEMBLY								Service	ATA:21
	MOS	20-Jan-23	48 (+ 14d/-14d)							
	HRS	1675	1200 (+ 25/-25)							
	AFL	1330								
PROC. REF: AMM 21-20-03, AMM 21-20-09										PKG:14
Y2150058 ^S	PERFORM VISUAL INSPECTION OF THE AIR CONDITIONING SYSTEM COMPONENTS, INCLUDING COMPRESSOR MOTORBELT FOR WEAR AND PROPER V-BELT TENSION, CONDENSER COILS FOR CLEANLINESS AND HOSES FOR CHAFING AND WEAR. IF OIL LEAKS ARE VISIBLE AND/OR REFRIGERANT DUMPED, CHECK COMPRESSOR OIL LEVEL (SOME LEAKAGE IS ALLOWABLE AROUND THE SHAFT.)								Service	ATA:21
	MOS	20-Jan-23	48 (+ 14d/-14d)							
	HRS	1675	1200 (+ 25/-25)							
	AFL	1330								
PROC. REF: AMM 05-10-00										PKG:14
Y2150059 ^S	PERFORM AIR CONDITIONING SYSTEM - LOAD SHED ASSEMBLY CHECK								Service	ATA:21
	MOS	20-Jan-23	48 (+ 14d/-14d)							
	HRS	1675	1200 (+ 25/-25)							
	AFL	1330								
PROC. REF: AMM 21-51-00										PKG:14
ATA 22 - AUTO FLIGHT										
2210-RVSM	FLIGHT CHECK AUTOMATIC ALTITUDE HOLD FUNCTIONAL. RVSM COMPLIANT AIRCRAFT.								Service	ATA:22
	MOS/MS	20-Jan-11	N/R							
	HRS	0								
	AFL	0								
PROC. REF: GENERIC NO REF										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 22 - AUTO FLIGHT										
221001	FLIGHT GUIDANCE, AUTOPILOT CONTROLLER									Component ATA:22
PN:2210001-001	MOS/MSC	06-Jun-12	O/C							
SN:07091833	HRS	392								
	AFL	321								
PROC. REF: AMM 22-10-01										
221041	AUTOPILOT, ROLL SERVO									Component ATA:22
PN:4006719-949	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:0811J625	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 22-10-04										
221045	SERVO, ROLL BRACKET									Component ATA:22
PN:4005842	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:0803J360	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 22-10-05										
221051	AUTOPILOT, PITCH SERVO									Component ATA:22
PN:4006719-923	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:0809J575	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 22-10-02										
221055	SERVO, PITCH BRACKET									Component ATA:22
PN:4005842	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:0809J555	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 22-10-03										
221061	AUTOPILOT, YAW SERVO									Component ATA:22
PN:7012919-904	MOS/MSC	11-Sep-18	O/C							
SN:0510H011	HRS	1387.4								
	AFL	1114								
PROC. REF: AMM 22-10-06										
221065	SERVO, YAW BRACKET									Component ATA:22
PN:7012098-902	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:0809H149	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 22-10-07										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 22 - AUTO FLIGHT										
225001	YAW INTERFACE UNIT									Component ATA:22
PN:4522108501-013	MOS/MSC	10-Oct-19	O/C							
SN:A00494625	HRS	1509.8								
	AFL	1201								
PROC. REF: AMM 22-50-01										
225031	PILOT YAW FORCE, RUDDER BOOST SYSTEM SENSOR									Component ATA:22
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 22-50-02										
225032	COPILOT YAW FORCE, RUDDER BOOST SYSTEM. SENSOR									Component ATA:22
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 22-50-02										
A2210033 ^S	** AUTOPILOT SYSTEM - PERFORM AUTOPILOT DISCONNECT TONE TEST									Service ATA:22
	MOS	20-Jan-23	24 (+14d/-14d)					AIRWORTHINESS		
	HRS	1675	600 (+25/-25)							
	AFL	1330								
PROC. REF: AMM 22-10-00										
G2210030 ^S	PERFORM PITCH SERVO CABLES - CABLE TENSION CHECK									Service ATA:22
	MOS	20-Jan-23	48 (+14d/-14d)							
	HRS	1675	1200 (+25/-25)							
	AFL	1330								
PROC. REF: AMM 22-10-03										
G2210031 ^S	PERFORM ROLL SERVO CABLES - CABLE TENSION CHECK									Service ATA:22
	MOS	20-Jan-23	48 (+14d/-14d)							
	HRS	1675	1200 (+25/-25)							
	AFL	1330								
PROC. REF: AMM 22-10-05										
G2210032 ^S	PERFORM YAW SERVO CABLES - CABLE TENSION CHECK.									Service ATA:22
	MOS	20-Jan-23	48 (+14d/-14d)							
	HRS	1675	1200 (+25/-25)							
	AFL	1330								
PROC. REF: AMM 22-10-07										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty
---------	------	------	----------	-----------	--------------------------	-----------	-----------	-------------	-----	----------

ATA 23 - COMMUNICATIONS

230001		UNILINK PROCESSER								Component	ATA:23
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: GENERIC NO REF											
230002		CONFIGURATION MODULE								Component	ATA:23
PN:31990-1	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:11249	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: GENERIC NO REF											
231011		NO. 1 POWER AMPLIFIER/HF ANTENNA COUPLER								Component	ATA:23
PN:064-1017-01	MOS/MSC	06-Nov-17	O/C								
SN:KAC1052-3024	HRS	1300.2									
	AFL	1056									
PROC. REF: GENERIC NO REF											
231012		NO. 2 POWER AMPLIFIER/HF ANTENNA COUPLER								Component	ATA:23
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: GENERIC NO REF											
231021		NO. 1 VHF COMMUNICATIONS TRANSCEIVER UNIT								Component	ATA:23
PN:7510733-666	MOS/MSC	11-Sep-18	O/C								
SN:1101C916	HRS	1387.4									
	AFL	1114									
PROC. REF: AMM 23-11-01											
231021A		TEST/INSPECT NO. 1 VHF COMMUNICATIONS TRANSCEIVER UNIT ATC TRANSPONDER								Service	ATA:23
PN:7510733-666	MOS	20-Jan-23	24 (+14d/-14d)		20-Jan-25		03-Feb-25	712 d (+14)			
SN:1101C916	HRS										
	AFL										
PROC. REF: AMM 23-11-00, FAR FAR 91.413											
231022		NO. 2 VHF COMMUNICATIONS TRANSCEIVER UNIT								Component	ATA:23
PN:7510733-666	MOS/MSC	11-Sep-18	O/C								
SN:0612B143	HRS	1387.4									
	AFL	1114									
PROC. REF: AMM 23-11-01, FAR FAR 91.413											

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 23 - COMMUNICATIONS											
231022A		TEST/INSPECT NO. 2 VHF COMMUNICATIONS TRANSCEIVER UNIT ATC TRANSPONDER								Service	ATA:23
PN:7510733-666	MOS	20-Jan-23	24 (+ 14d/-14d)		20-Jan-25	03-Feb-25	712 d (+ 14)				
SN:0612B143	HRS										
	AFL										
PROC. REF: AMM 23-11-00, FAR FAR 91.413											
231025		NO. 1 COMM. CIRCUIT CARD ASSEM. REPLACE								Component	ATA:23
PN:PN	MOS/MSC	20-Jan-11	O/C		TSN 0						
SN:UNKNOWN	HRS	0			TSN 0						
	AFL	0			TSN 0						
PROC. REF: GENERIC NO REF											
231026		NO. 2 COMM. CIRCUIT CARD ASSEM. REPLACE								Component	ATA:23
PN:PN	MOS/MSC	20-Jan-11	O/C		TSN 0						
SN:UNKNOWN	HRS	0			TSN 0						
	AFL	0			TSN 0						
PROC. REF: GENERIC NO REF											
231030		NO. 1 HF SELCAL RECEIVER/EXCITER								Component	ATA:23
PN:064-01073-0102	MOS/MSC	20-Jan-11	O/C		TSN 0						
SN:4507	HRS	0			TSN 0						
	AFL	0			TSN 0						
PROC. REF: GENERIC NO REF											
231031		NO. 2 HF SELCAL RECEIVER/EXCITER								Component	ATA:23
PN:PN	MOS/MSC	20-Jan-11	O/C		TSN 0						
SN:UNKNOWN	HRS	0			TSN 0						
	AFL	0			TSN 0						
PROC. REF: GENERIC NO REF											
231032		HF SELCAL ANTENNA								Component	ATA:23
PN:PN	MOS/MSC	20-Jan-11	O/C		TSN 0						
SN:UNKNOWN	HRS	0			TSN 0						
	AFL	0			TSN 0						
PROC. REF: GENERIC NO REF											
231033		UPPER VHF ANTENNA								Component	ATA:23
PN:DMC60-17-1	MOS/MSC	20-Jan-11	O/C		TSN 0						
SN:15474	HRS	0			TSN 0						
	AFL	0			TSN 0						
PROC. REF: AMM 23-11-02											

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 23 - COMMUNICATIONS											
231034		LOWER VHF ANTENNA								Component	ATA:23
PN:DMC60-17-1	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:15578	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 23-11-02											
231045		NO. 1 HF (KCU-951) CONTROL								Component	ATA:23
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: GENERIC NO REF											
231046		NO. 2 HF (KCU-951) CONTROL								Component	ATA:23
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: GENERIC NO REF											
231051		NO. 1 BRIDGING, HF AMPLIFIER								Component	ATA:23
PN:064-01072-0101	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:4290	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: GENERIC NO REF											
231052		NO. 2 BRIDGING, HF AMPLIFIER								Component	ATA:23
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: GENERIC NO REF											
231090		PILOT HEADSET								Component	ATA:23
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: GENERIC NO REF											
231091		COPILOT HEADSET								Component	ATA:23
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: GENERIC NO REF											

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty
---------	------	------	----------	-----------	--------------------------	-----------	-----------	-------------	-----	----------

ATA 23 - COMMUNICATIONS

231200	KHF-1050 HIGH FREQUENCY COMMUNICATION SYSTEM								Component	ATA:23
--------	--	--	--	--	--	--	--	--	-----------	--------

PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										

231200A	GENERAL VISUAL INSPECTION KHF-1050 HIGH FREQUENCY COMMUNICATION SYSTEM OF THE SYSTEM COMPONENTS AND WIRING								Service	ATA:23
---------	--	--	--	--	--	--	--	--	---------	--------

PN:PN	MOS	20-Jan-11								
SN:UNKNOWN	HRS	0	4800 (+25/-25)		4800	4825	3125 (+25)			
	AFL	0								
PROC. REF: AMM 23-12-04										

231200B	CHECK KHF-1050 HIGH FREQUENCY COMMUNICATION SYSTEM NITROGEN PRESSURE OF THE ANTENNA COUPLER. THE PRESSURE SHOULD BE MEASURED AT THE VALVE ADJACENT TO P10522. WHEN MEASURED AT ROOM TEMPERATURE, IT SHOULD BE BETWEEN 8 AND 10 PSIG (55 TO 69 KPA GAUGE). IF BELOW 8 PSIG, ADD NITROGEN TO BRING THE PRESSURE UP TO 8 TO 10 PSIG.								Service	ATA:23
---------	---	--	--	--	--	--	--	--	---------	--------

PN:PN	MOS	20-Jan-23	12 (+14d/-14d)	Adj -131d	11-Sep-23	25-Sep-23	215 d (+14)			
SN:UNKNOWN	HRS	1675								
	AFL	1330								
PROC. REF: GENERIC NO REF										

231300	PHONE MAGNASTAR TRANSCEIVER								Component	ATA:23
--------	-----------------------------	--	--	--	--	--	--	--	-----------	--------

PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										

231305	MAGNASTAR ANTENNA								Component	ATA:23
--------	-------------------	--	--	--	--	--	--	--	-----------	--------

PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										

231307	COCKPIT ASSEMBLY PHONE								Component	ATA:23
--------	------------------------	--	--	--	--	--	--	--	-----------	--------

PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty
---------	------	------	----------	-----------	--------------------------	-----------	-----------	-------------	-----	----------

ATA 23 - COMMUNICATIONS

231308 CABIN ASSEMBLY PHONE Component ATA:23										
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
231310 ARTU TRAY Component ATA:23										
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
231313 NO. 1 CABIN DISTRIBUTION BUS REPEATER Component ATA:23										
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
231314 NO. 2 CABIN DISTRIBUTION BUS REPEATER Component ATA:23										
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
231315 CALL ALERTER (CAS) SWITCH Component ATA:23										
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
231320 CABIN IRIDIUM SATCOM HANDSET Component ATA:23										
PN:P12192-001	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:1210214455	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
231321 CABIN IRIDIUM SATCOM PHONE CRADLE Component ATA:23										
PN:P12192-001	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:1219214778	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 23 - COMMUNICATIONS										
231322 CABIN IRIDIUM SATCOM HANDSET Component ATA:23										
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
231323 AFT LAVATORY IRIDIUM SATCOM TRANSCEIVER Component ATA:23										
PN:500617-2	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:5900	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
231325 IRIDIUM SATCOM SONALERT Component ATA:23										
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
231327 COCKPIT IRIDIUM SATCOM PHONE CRADLE Component ATA:23										
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
231328 COCKPIT IRIDIUM SATCOM HANDSET Component ATA:23										
PN:PN	MOS/MSC	28-Nov-15	O/C							
SN:NOT INSTALLED	HRS	954.7								
	AFL	842								
PROC. REF: GENERIC NO REF										
231330 FWD IRIDIUM SATCOM ANTENNA Component ATA:23										
PN:CI 490-1 / 500644-1	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:282152	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 23 - COMMUNICATIONS											
231335		COCKPIT IRIDIUM SATCOM BASE UNIT								Component	ATA:23
PN:463092-230	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:3004416	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: GENERIC NO REF											
231336		AFT IRIDIUM PHONE SYSTEM BASE UNIT								Component	ATA:23
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: GENERIC NO REF											
231351		SATELLITE DATA (SDU) UNIT								Component	ATA:23
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: GENERIC NO REF											
232120		UNILINK ANTENNA								Component	ATA:23
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: GENERIC NO REF											
232200		SELCAL SYSTEM CHANGE								Component	ATA:23
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: GENERIC NO REF											
232200A		GENERAL VISUAL INSPECTION SELCAL SYSTEM CHANGE OF THE SELCAL DECODER AND WIRING.								Service	ATA:23
PN:PN	MOS	20-Jan-11									
SN:UNKNOWN	HRS	0	4800 (+25/-25)		4800	4825	3125 (+25)				
	AFL	0									
PROC. REF: GENERIC NO REF											
233001		FORWARD CABIN VIDEO MONITOR-								Component	ATA:23
PN:LCD-9121-101-1	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:061000033	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: GENERIC NO REF											

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 23 - COMMUNICATIONS											
233002		AFT CABIN VIDEO MONITOR-								Component	ATA:23
PN:LCD-9121-101-1	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:061000034	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: GENERIC NO REF											
233003		AUDIO DISTRIBUTION MODULE								Component	ATA:23
PN:AV-4589-01-1	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:061000199	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: GENERIC NO REF											
233005		PA SYSTEM AMPLIFER								Component	ATA:23
PN:30300548	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:011000268	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 23-30-02											
233010		INFRARED REMOTE MODULE RECEIVER								Component	ATA:23
PN:IFR-485-05-1	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:051000125	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: GENERIC NO REF											
233015		AUDIO/VIDEO CONTROLLER								Component	ATA:23
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: GENERIC NO REF											
233053		DVD PLAYER								Component	ATA:23
PN:DVD-511-01-1	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:051000359	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: GENERIC NO REF											
233054-1		CD PLAYER CHANGER								Component	ATA:23
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: GENERIC NO REF											

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 23 - COMMUNICATIONS											
233054-2		CD PLAYER CONTROL UNIT								Component	ATA:23
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: GENERIC NO REF											
233055		CASSETTE TAPE PLAYER								Component	ATA:23
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: GENERIC NO REF											
233101		LEFT FORWARD CABIN SPEAKER								Component	ATA:23
PN:EN-MT-45A	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:091000080	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 23-30-01											
233102		RIGHT FORWARD CABIN SPEAKER								Component	ATA:23
PN:EN-MT-45A	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:091000086	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 23-30-01											
233103		LEFT AFT CABIN SPEAKER								Component	ATA:23
PN:EN-MT-45A	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:091000085	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 23-30-01											
233104		RIGHT AFT CABIN SPEAKER								Component	ATA:23
PN:EN-MT-45A	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:091000079	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 23-30-01											
233105		SUBWOOFER SPEAKER								Component	ATA:23
PN:EN-646-W	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:101000275	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: GENERIC NO REF											

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 23 - COMMUNICATIONS											
233201		PASSENGER INTERFACE UNIT								Component	ATA:23
PN:PIU-45-04-1	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:051000128	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: GENERIC NO REF											
234000		INTERPHONE JACK BOX ASSEMBLY								Component	ATA:23
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: GENERIC NO REF											
235001		# 1 AUDIO CONTROL UNIT								Component	ATA:23
PN:7511001-037	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:0904D622	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 23-50-01											
235002		# 2 AUDIO CONTROL UNIT								Component	ATA:23
PN:7511001-037	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:0903D556	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 23-50-01											
235013		LEFT COCKPIT SPEAKER								Component	ATA:23
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 23-50-03											
235014		RIGHT COCKPIT SPEAKER								Component	ATA:23
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 23-50-03											
236001		STATIC INVERTER								Component	ATA:23
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: GENERIC NO REF											

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 23 - COMMUNICATIONS											
236005		WEATHER XM RADIO RECEIVER								Component	ATA:23
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: GENERIC NO REF											
236010		WEATHER XM DATA PORT								Component	ATA:23
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: GENERIC NO REF											
236015		XM RADIO ANTENNA								Component	ATA:23
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: GENERIC NO REF											
236020		GDC34 CONVERTER REPLACE								Component	ATA:23
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: GENERIC NO REF											
236025		AIRSERV TRANSMITTER REPLACE								Component	ATA:23
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: GENERIC NO REF											
236096		NO. 1 NAVIGATION STRAP BOARD								Component	ATA:23
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 34-51-05											
236097		NO. 2 NAVIGATION STRAP BOARD								Component	ATA:23
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 34-51-05											

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 23 - COMMUNICATIONS											
236098		NO. 1 COMMUNICATION STRAP BOARD								Component	ATA:23
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 23-11-03											
236099		NO. 2 COMMUNICATION STRAP BOARD								Component	ATA:23
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 23-11-03											
237001		COCKPIT VOICE (CVR) RECORDER								Component	ATA:23
PN:980-6022-011	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:CVR120-08727	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 23-70-01											
237001A		INTELLIGIBILITY CHECK COCKPIT VOICE (CVR) RECORDER CVR								Service	ATA:23
PN:980-6022-011	MOS/MSC	07-Jan-14	A/R	Adj -26d							
SN:CVR120-08727	HRS	805.1									
	AFL	733									
PROC. REF: GENERIC NO REF											
237005		CVR UNDERWATER LOCATOR (ULB) BEACON								Component	ATA:23
PN:DK120	MOS/MSC	07-Jan-14	O/C	TSN 36							
SN:DU37684	HRS	805.1		TSN 805.1							
	AFL	733		TSN 733							
PROC. REF: AMM 25-61-01											
237005A		FUNCTIONAL TEST CVR UNDERWATER LOCATOR (ULB) BEACON / CLEAN BEACON SWITCH AND PERFORM TEST OF ULB BATTERY (IRN AA2560000)								Service	ATA:23
PN:DK120	MOS	20-Jan-23	12 (+ 14d/-14d)	Adj -318d	08-Mar-23	22-Mar-23	28 d (+ 14)				
SN:DU37684	HRS	1675									
	AFL	1330									
PROC. REF: GENERIC NO REF											

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty
---------	------	------	----------	-----------	--------------------------	-----------	-----------	-------------	-----	----------

ATA 23 - COMMUNICATIONS

237005B		REPLACE CVR UNDERWATER LOCATOR (ULB) BEACON BATTERY ON OR BEFORE ULB BATTERY REPLACEMENT DATE. (ZONE/ACCESS 300 IRN # D2566001)							Service	ATA:23
PN:DK120	MOS/MSC	11-Sep-18	DUE		01-Jan-24 (M)		327 d			
SN:DU37684	HRS	1387.4								
	AFL	1114								
PROC. REF: GENERIC NO REF										

237018		CVR INERTIA SWITCH							Component	ATA:23
PN:3LO-453/8	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:91872	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 23-70-05										

237019		COCKPIT AREA MICROPHONE							Component	ATA:23
PN:980-6113-001	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:06354	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										

237030		PANEL SWITCH							Component	ATA:23
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										

237031		COCKPIT VOICE RECORDER PRE-AMPLIFIER							Component	ATA:23
PN:980-6118-001	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 23-70-03										

238001		NO. 1 RADIO MANAGEMENT (RMU) UNIT							Component	ATA:23
PN:7013270-977	MOS/MSC	11-Sep-18	O/C	TSR 56						
SN:07035711	HRS	1387.4		TSR 582.3						
	AFL	1114		TSR 381						
PROC. REF: AMM 23-80-01										

238002		NO. 2 RADIO MANAGEMENT (RMU) UNIT							Component	ATA:23
PN:7013270-977	MOS/MSC	11-Sep-18	O/C							
SN:09036689	HRS	1387.4								
	AFL	1114								
PROC. REF: AMM 23-80-01										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 23 - COMMUNICATIONS										
238025	CLEARANCE DELIVERY UNIT									Component ATA:23
PN:7513000-835	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:09013855	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 23-82-01										
239004	MASTER CONTROL SWITCH									Component ATA:23
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
239011	LAVATORY MASTER CONTROL SWITCH									Component ATA:23
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
A2300000 ^S	** COMMUNICATIONS SYSTEMS - PERFORM OPERATIONAL CHECK									Service ATA:23
	MOS	20-Jan-23	24 (+14d/-14d)					AIRWORTHINESS		
	HRS	1675	600 (+25/-25)							
	AFL	1330								
PROC. REF: AMM 23-00-00										
ST01374WI-D-1 ^{U S}	PERFORM A GENERAL VISUAL INSPECTION OF THE AIRSHOW 4000 SYSTEM COMPONENTS.									Service ATA:23
	MOS							ICA		
	HRS		4800							
	AFL									
ST01428WI-D-1 ^{U S}	PERFORM A GENERAL VISUAL INSPECTION OF THE IRIDIUM PHONE SYSTEM COMPONENTS									Service ATA:23
	MOS		48					ICA		
	HRS		1200							
	AFL									
V2312003 ^S	HF ANTENNA- PERFORM VISUAL INSPECTION. CHECK FOR PROPER TENSION ON HF ANTENNA WIRE									Service ATA:23
	MOS	20-Jan-23	48 (+14d/-14d)							
	HRS	1675	1200 (+25/-25)							
	AFL	1330								
PROC. REF: AMM 23-12-04										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty
---------	------	------	----------	-----------	--------------------------	-----------	-----------	-------------	-----	----------

ATA 23 - COMMUNICATIONS

Y2360020 ^S		PERFORM AIRCRAFT STATIC DISCHARGERS - FUNCTIONAL TEST							Service	ATA:23
	MOS	11-Sep-18	96 (+ 14d/-14d)							
	HRS	1387.4	2400 (+ 25/-25)							
	AFL	1114								
PROC. REF: AMM 23-60-00										
PKG:20										

Y2360023 ^S		PERFORM AIRCRAFT STATIC DISCHARGERS - FUNCTIONAL TEST							Service	ATA:23
	MOS	11-Sep-18	96 (+ 14d/-14d)							
	HRS	1387.4	2400 (+ 25/-25)							
	AFL	1114								
PROC. REF: AMM 23-60-00										
PKG:22										

ATA 24 - ELECTRICAL POWER

240109		AFT CIRCUIT BREAKER PANEL ASSY							Component	ATA:24
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	AFL	0	TSN 0							
PROC. REF: AMM 24-60-04										

242001		NO. 1 AC 5KVA ALTERNATOR							Component	ATA:24
PN:90278-2	MOS/MSC	16-Dec-16	O/C	TSN 71, TSO 0						
SN:1224	HRS	1162	TSN 1162, TSO 0							
	AFL	966	TSN 966, TSO 0							
PROC. REF: AMM 24-20-01										

242001A		REPLACE NO. 1 AC 5KVA ALTERNATOR ** BEARING. (F2420000)							Service	ATA:24
PN:90278-2	MOS	16-Dec-16						AIRWORTHINESS		
SN:1224	HRS	1162	1200 (+ 25/-25)	2362	2387	687 (+ 25)				
	AFL	966								
PROC. REF: GENERIC NO REF										

242002		NO. 2 AC 5KVA ALTERNATOR							Component	ATA:24
PN:90278-2	MOS/MSC	16-Dec-16	O/C	TSN 71, TSO 0						
SN:1234	HRS	1162	TSN 1162, TSO 0							
	AFL	966	TSN 966, TSO 0							
PROC. REF: AMM 24-20-01										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 24 - ELECTRICAL POWER											
242002A		REPLACE NO. 2 AC 5KVA ALTERNATOR ** BEARING. (F2420000)								Service	ATA:24
PN:90278-2	MOS	16-Dec-16						AIRWORTHINESS			
SN:1234	HRS	1162	1200 (+25/-25)		2362	2387	687 (+25)				
	AFL	966									
PROC. REF: GENERIC NO REF											
242008		AC/DC VOLT INDICATOR								Component	ATA:24
PN:PN	MOS/MSC	20-Jan-11	O/C		TSN 0						
SN:UNKNOWN	HRS	0			TSN 0						
	AFL	0			TSN 0						
PROC. REF: GENERIC NO REF											
242050		REMOTE CONTROL CIRCUIT BREAKER								Component	ATA:24
PN:M83383/01-01	MOS/MSC	20-Jan-11	O/C		TSN 0						
SN:95138	HRS	0			TSN 0						
	AFL	0			TSN 0						
PROC. REF: AMM 24-60-01											
242052		REMOTE CONTROL CIRCUIT BREAKER								Component	ATA:24
PN:SM600BA75N1	MOS/MSC	20-Jan-11	O/C		TSN 0						
SN:95410	HRS	0			TSN 0						
	AFL	0			TSN 0						
PROC. REF: AMM 24-60-01											
242054		REMOTE CONTROL CIRCUIT BREAKER								Component	ATA:24
PN:PN	MOS/MSC	20-Jan-11	O/C		TSN 0						
SN:UNKNOWN	HRS	0			TSN 0						
	AFL	0			TSN 0						
PROC. REF: AMM 24-60-01											
242081		CABIN AC INVERTER								Component	ATA:24
PN:2D1200-1A-1011	MOS/MSC	12-Jul-16	O/C								
SN:GB001314	HRS	1064.4									
	AFL	913									
PROC. REF: GENERIC NO REF											
242082		TAILCONE AC INVERTER								Component	ATA:24
PN:LT-45(J)	MOS/MSC	20-Jan-11	A/R		TSN 0						
SN:725	HRS	0			TSN 0						
	AFL	0			TSN 0						
PROC. REF: GENERIC NO REF											

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 24 - ELECTRICAL POWER											
242083		AC INVERTER								Component	ATA:24
PN:LT-45(J)	MOS/MSC	20-Jan-11	A/R	TSN 0							
SN:723	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: GENERIC NO REF											
243001		NO. 1 STARTER/GENERATOR								Component	ATA:24
PN:6608458-012	MOS/MSC	16-Dec-16	O/C	TSO 0							
SN:P1161	HRS	1162		TSO 0							
	AFL	966		TSO 0							
PROC. REF: AMM 24-30-01											
243001A		OVERHAUL NO. 1 STARTER/GENERATOR IRN P2430003. (ZONE/ACCESS 410)								Service	ATA:24
PN:6608458-012	MOS	16-Dec-16						OVERHAUL			
SN:P1161	HRS	1162	1200 (+ 25/-25)		2362	2387	687 (+ 25)				
	AFL	966									
PROC. REF: GENERIC NO REF											
243001B		REPLACE NO. 1 STARTER/GENERATOR BEARING								Service	ATA:24
PN:6608458-012	MOS/MSC		N/A								
SN:P1161	HRS										
	AFL										
PROC. REF: GENERIC NO REF											
243002		NO. 2 STARTER/GENERATOR								Component	ATA:24
PN:6608458-012	MOS/MSC	16-Dec-16	O/C	TSO 0							
SN:Y20407	HRS	1162		TSO 0							
	AFL	966		TSO 0							
PROC. REF: AMM 24-30-01											
243002A		OVERHAUL NO. 2 STARTER/GENERATOR IRN P2430003. (ZONE/ACCESS 410)								Service	ATA:24
PN:6608458-012	MOS	16-Dec-16						OVERHAUL			
SN:Y20407	HRS	1162	1200 (+ 25/-25)		2362	2387	687 (+ 25)				
	AFL	966									
PROC. REF: GENERIC NO REF											
243002B		REPLACE NO. 2 STARTER/GENERATOR BEARING								Service	ATA:24
PN:6608458-012	MOS/MSC		N/A								
SN:Y20407	HRS										
	AFL										
PROC. REF: GENERIC NO REF											

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 24 - ELECTRICAL POWER											
243003		APU STARTER/GENERATOR								Component	ATA:24
PN:6608458-010	MOS/MSC	21-Jul-17	O/C	TSO 2							
SN:Y01101	HRS	1258.2		TSO 0							
	AFL	1031		TSO 0							
PROC. REF: AMM 49-40-01											
243003A		OVERHAUL APU STARTER/GENERATOR AND BRUSH REPLACEMENT. (IRN # V4900021, V4900003)								Service	ATA:24
PN:6608458-010	MOS	21-Jul-17						OVERHAUL			
SN:Y01101	HRS	1258.2									
	AFL	1031									
	APH	615.97	600 (+ 25/-25)		1215.97	1240.97	342.6 (+ 25)				
PROC. REF: AMM 49-40-01											
243003B		VISUALLY INSPECT APU STARTER/GENERATOR GEAR BOX DRIVE SPLINE. (IRN # O4900006)								Service	ATA:24
PN:6608458-010	MOS	21-Jul-17									
SN:Y01101	HRS	1258.2									
	AFL	1031									
	APH	615.97	600 (+ 25/-25)		1215.97	1240.97	342.6 (+ 25)				
PROC. REF: AMM 05-10-00											
243005		LEFT (GCU) GENERATOR CONTROL UNIT								Component	ATA:24
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: GENERIC NO REF											
243006		RIGHT (GCU) GENERATOR CONTROL UNIT								Component	ATA:24
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: GENERIC NO REF											
243019		NO. 1 MAIN SHIP BATTERY								Component	ATA:24
PN:RG-380E/40L	MOS/MSC	20-Jan-23	O/C	TSN 1							
SN:41250355	HRS	1675		TSN 0							
	AFL	1330		TSN 0							
PROC. REF: AMM 24-31-01, AMM 24-31-06, CMM 24-30-71											

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 24 - ELECTRICAL POWER											
243019A		CHECK/SERVICE NO. 1 MAIN SHIP BATTERY (IRN O1222000 NI-CAD) - CAPACITY CHECK (IRN T1222004 38 AMP HOUR LEAD- ACID) - CAPACITY CHECK (IRN T1222007 28 AMP HOUR LEAD ACID)							Service	ATA:24	
PN:RG-380E/40L	MOS	20-Jan-23	T:12 (+ 1m /-1m)		20-Jan-24	20-Feb-24	346 d (+ 31)				
SN:41250355	HRS	1675	T:1000 (+ 100/- 100)		2675	2775	1000 (+ 100)				
	AFL	1330									
PROC. REF: AMM 12-22-00, CMM 24-30-71											
243019B		OVERHAUL NO. 1 MAIN SHIP BATTERY NI-CAD BATTERY PER RECOMMENDED MFG'S INSTRUCTIONS.							Service	ATA:24	
PN:RG-380E/40L	MOS/MSC		N/A								
SN:41250355	HRS										
	AFL										
PROC. REF: AMM 24-31-01											
243019C		NO. 1 BATTERY TEMPERATURE SWITCH							Component	ATA:24	
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: GENERIC NO REF											
243020		NO. 2 MAIN SHIP BATTERY							Component	ATA:24	
PN:RG-380E/40L	MOS/MSC	20-Jan-23	O/C	TSN 1							
SN:41250356	HRS	1675		TSN 0							
	AFL	1330		TSN 0							
PROC. REF: AMM 24-31-01, AMM 24-31-06, CMM 24-30-71											
243020A		CHECK/SERVICE NO. 2 MAIN SHIP BATTERY (IRN O1222000 NI-CAD) - CAPACITY CHECK (IRN T1222004 38 AMP HOUR LEAD- ACID) - CAPACITY CHECK (IRN T1222007 28 AMP HOUR LEAD ACID)							Service	ATA:24	
PN:RG-380E/40L	MOS	20-Jan-23	T:12 (+ 1m /-1m)		20-Jan-24	20-Feb-24	346 d (+ 31)				
SN:41250356	HRS	1675	T:1000 (+ 100/- 100)		2675	2775	1000 (+ 100)				
	AFL	1330									
PROC. REF: AMM 12-22-00, CMM 24-30-71											
243020B		OVERHAUL NO. 2 MAIN SHIP BATTERY NI-CAD BATTERY PER RECOMMENDED MFG'S INSTRUCTIONS.							Service	ATA:24	
PN:RG-380E/40L	MOS/MSC		N/A								
SN:41250356	HRS										
	AFL										
PROC. REF: AMM 24-31-01											

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 24 - ELECTRICAL POWER											
243020C		NO. 2 BATTERY TEMPERATURE SWITCH								Component	ATA:24
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: GENERIC NO REF											
243037		EMERGENCY (IRN AB2431063 FOR RG-443) BATTERY								Component	ATA:24
PN:RG-443	MOS	08-Nov-21	60 (+14d/-14d)	TSN 0	08-Nov-26	22-Nov-26	1369 d (+14)	REPLACE			
SN:41142533	HRS	1605.6	5000 (+25/-25)	TSN 0	6605.6	6630.6	4930.6 (+25)				
	AFL	1281		TSN 0							
PROC. REF: AMM 24-32-01, CMM 24-30-71											
243037A		PERFORM EMERGENCY (IRN AB2431063 FOR RG-443) BATTERY CAPACITY CHECK (P/N 7624308001, IRN O2431002), (P/N RG-443, IRN AB2431062)								Service	ATA:24
PN:RG-443	MOS	08-Nov-21	12 (+14d/-14d)		08-Nov-22	22-Nov-22	OVD				
SN:41142533	HRS	1605.6	1000 (+25/-25)		2605.6	2630.6	930.6 (+25)				
	AFL	1281									
PROC. REF: CMM 24-30-71											
246001		LEFT FORWARD POWER DISTRIBUTION PANEL								Component	ATA:24
PN:650GC02Y03	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:592	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 24-60-02											
246002		RIGHT FORWARD POWER DISTRIBUTION PANEL								Component	ATA:24
PN:655GC02Y03	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:610	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 24-60-02											
246003		LEFT AFT POWER DISTRIBUTION PANEL								Component	ATA:24
PN:660GC02Y07	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:673	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 24-60-03											

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 24 - ELECTRICAL POWER										
246004	RIGHT AFT POWER DISTRIBUTION PANEL									Component ATA:24
PN:665GC02Y07	MOS/MSC	21-Jul-17	O/C	TSN 78						
SN:707	HRS	1258.2		TSN 1258.2						
	AFL	1031		TSN 1031						
PROC. REF: AMM 24-60-03										
246101	LEFT GENERATOR CONTROL UNIT PRINTED CIRCUIT BOARD									Component ATA:24
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
246102	LEFT LOGIC PRINTED CIRCUIT BOARD									Component ATA:24
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
246104	RIGHT GENERATOR CONTROL UNIT PRINTED CIRCUIT BOARD									Component ATA:24
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
246105	RIGHT LOGIC PRINTED CIRCUIT BOARD									Component ATA:24
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
246106	APU GENERATOR CONTROL UNIT PRINTED CIRCUIT BOARD									Component ATA:24
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
5-19-00-Y2431005	BATTERY CABLES AND RECEPTACLES - PERFORM BATTERY CONNECTOR TOLERANCE CHECK. (REFER TO 24-31-00.). IRN Y2431005									Service ATA:24
	MOS	08-Nov-21								
	HRS	1605.6	300 (+ 25/- 25)		1905.6	1930.6	230.6 (+ 25)			
	AFL	1281								
PROC. REF: AMM 24-31-00										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 24 - ELECTRICAL POWER											
AC2460002 ^S			REMOVE ATTACHING PARTS SECURING CIRCUIT BREAKER PANEL TO STRUCTURE. CHECK FOR LOOSE CIRCUIT BREAKER TERMINALS, LOOSE WIRE TERMINALS, CORRODED TERMINALS OR BUSS BARS, AND EVIDENCE OF WIRE INSULATION DAMAGE.							Service	ATA:24
	MOS	20-Jan-11	96 (+ 14d/-14d)								
	HRS	0	2400 (+ 25/-25)								
	AFL	0									
PROC. REF: GENERIC NO REF										PKG:19	
B2450002 ^S			PERFORM ** ELECTRICAL SYSTEM CONTROL - OPERATIONAL CHECK							Service	ATA:24
	MOS	20-Jan-23	48 (+ 14d/-14d)					AIRWORTHINESS			
	HRS	1675	1200 (+ 25/-25)								
	AFL	1330									
PROC. REF: AMM 24-00-00										PKG:13	
H2450001 ^S			** AUXILIARY POWER SUPPLIES - PERFORM FUNCTIONAL TEST							Service	ATA:24
	MOS	20-Jan-23	24 (+ 14d/-14d)					AIRWORTHINESS			
	HRS	1675	600 (+ 25/-25)								
	AFL	1330									
PROC. REF: AMM 24-00-00										PKG:7	
H2450023 ^S			** EMER BATT LOW AND GEN AMPS HIGH INDICATION - PERFORM OPERATIONAL CHECK.							Service	ATA:24
	MOS	20-Jan-23	24 (+ 14d/-14d)					AIRWORTHINESS			
	HRS	1675	600 (+ 25/-25)								
	AFL	1330									
PROC. REF: AMM 24-00-00										PKG:7	
Q2460001 ^S			PERFORM ** POWER DISTRIBUTION SYSTEM - SQUAT SWITCH CHECK.							Service	ATA:24
	MOS	20-Jan-23	48 (+ 14d/-14d)					AIRWORTHINESS			
	HRS	1675	1200 (+ 25/-25)								
	AFL	1330									
PROC. REF: AMM 24-60-00										PKG:17	
R2431003 ^S			PERFORM ** BATTERY WARNING SYSTEM - FUNCTIONAL TEST. (EFFECTIVE ON AIRCRAFT WITH NI-CAD BATTERIES INSTALLED)							Service	ATA:24
	MOS	11-Sep-18	96 (+ 14d/-14d)					AIRWORTHINESS			
	HRS	1387.4	2400 (+ 25/-25)								
	AFL	1114									
PROC. REF: AMM 24-31-00										PKG:19	
W2450000 ^S			** GENERATOR FAIL INDICATION - PERFORM OPERATIONAL CHECK							Service	ATA:24
	MOS	20-Jan-23	24 (+ 14d/-14d)					AIRWORTHINESS			
	HRS	1675	600 (+ 25/-25)								
	AFL	1330									
PROC. REF: AMM 24-00-00										PKG:7	

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 24 - ELECTRICAL POWER											
Y2400001 ^S			PERFORM SWITCH AND CIRCUIT BREAKER PANELS - VISUAL INSPECTION						Service	ATA:24	
	MOS	20-Jan-23	48 (+ 14d/-14d)								
	HRS	1675	1200 (+ 25/-25)								
	AFL	1330									
			PROC. REF: AMM 05-10-00								PKG:13
Y2400002 ^S			ELECTRICAL WIRING - PERFORM VISUAL INSPECTION FOR ROUTING, SECURITY, CLEARANCES, CHAFING, AND ELECTRICAL COMPONENTS FOR SECURITY AND GENERAL CONDITION						Service	ATA:24	
	MOS	20-Jan-23	24 (+ 14d/-14d)								
	HRS	1675	600 (+ 25/-25)								
	AFL	1330									
			PROC. REF: AMM 05-10-00								PKG:7
Y2400025 ^S			ELECTRICAL WIRING - PERFORM VISUAL INSPECTION FOR ROUTING, SECURITY, CLEARANCES, CHAFING, AND ELECTRICAL COMPONENTS FOR SECURITY AND GENERAL CONDITION						Service	ATA:24	
	MOS	20-Jan-23	24 (+ 14d/-14d)								
	HRS	1675	600 (+ 25/-25)								
	AFL	1330									
			PROC. REF: AMM 05-10-00								PKG:8
Y2430005 ^S			STARTER/GENERATOR - PERFORM GROUNDING LUG BONDING CHECK						Service	ATA:24	
	MOS	20-Jan-23	24 (+ 14d/-14d)								
	HRS	1675	600 (+ 25/-25)								
	AFL	1330									
			PROC. REF: AMM 24-30-01								PKG:9
Y2430006 ^S			STARTER/GENERATOR - PERFORM VISUAL INSPECTION OF GROUNDING LUGS						Service	ATA:24	
	MOS	20-Jan-23	24 (+ 14d/-14d)								
	HRS	1675	600 (+ 25/-25)								
	AFL	1330									
			PROC. REF: AMM 05-10-00								PKG:9
Y2431000 ^S			PERFORM BATTERY, GENERATOR, AND BUS-TIE CABLES - VISUAL INSPECTION.						Service	ATA:24	
	MOS	11-Sep-18	96 (+ 14d/-14d)								
	HRS	1387.4	2400 (+ 25/-25)								
	AFL	1114									
			PROC. REF: AMM 05-10-00								PKG:20

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty
---------	------	------	----------	-----------	--------------------------	-----------	-----------	-------------	-----	----------

ATA 24 - ELECTRICAL POWER

Y2431001 ^S	EMERGENCY BATTERY CABLES - PERFORM VISUAL INSPECTION								Service	ATA:24
	MOS	20-Jan-23	24 (+ 14d/-14d)							
	HRS	1675	600 (+ 25/-25)							
	AFL	1330								
					PROC. REF: AMM 05-10-00					PKG:7

Y2460000 ^S	PERFORM DC BUS ISOLATION - OPERATIONAL CHECK								Service	ATA:24
	MOS	20-Jan-23	48 (+ 14d/-14d)							
	HRS	1675	1200 (+ 25/-25)							
	AFL	1330								
					PROC. REF: AMM 24-60-00					PKG:13

ATA 25 - EQUIPMENT/ FURNISHINGS

250010	RELAY MODULE								Component	ATA:25
PN:MSM9646-01-1	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:051000326	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: GENERIC NO REF					

252000-1	# 1 PASSENGER SEAT								Component	ATA:25
PN:M6613100-001	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:100927-41	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 25-20-45					

252000-2	# 2 PASSENGER SEAT								Component	ATA:25
PN:M6613100-002	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:101101-15	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 25-20-45					

252000-3	# 3 PASSENGER SEAT								Component	ATA:25
PN:M6613100-001	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:100927-42	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 25-20-45					

252000-4	# 4 PASSENGER SEAT								Component	ATA:25
PN:M6613100-002	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:100927-43	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 25-20-45					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 25 - EQUIPMENT/ FURNISHINGS											
252000-5		# 5 PASSENGER SEAT								Component	ATA:25
PN:M6613100-001	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:101101-14	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 25-20-45											
252000-6		# 6 PASSENGER SEAT								Component	ATA:25
PN:M6613100-002	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:100927-44	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 25-20-45											
252000-7		# 7 PASSENGER SEAT								Component	ATA:25
PN:M6613100-001	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:101101-13	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 25-20-45											
252000-8		# 8 PASSENGER SEAT								Component	ATA:25
PN:M6613100-002	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:101101-16	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 25-20-45											
252000-9		JUMP SEAT								Component	ATA:25
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: GENERIC NO REF											
252001-1		# 1 PASSENGER SEAT PCU								Component	ATA:25
PN:SP-45-54	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:030900326	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 25-20-45											
252001-2		# 2 PASSENGER SEAT PCU								Component	ATA:25
PN:SP-45-54	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:110800273	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 25-20-45											

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 25 - EQUIPMENT/ FURNISHINGS											
252001-3		# 3 PASSENGER SEAT PCU								Component	ATA:25
PN:SP-45-54	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:080601263	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 25-20-45											
252001-4		# 4 PASSENGER SEAT PCU								Component	ATA:25
PN:SP-45-54	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:020800511	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 25-20-45											
252001-5		# 5 PASSENGER SEAT PCU								Component	ATA:25
PN:SP-45-54	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:030900328	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 25-20-45											
252001-6		# 6 PASSENGER SEAT PCU								Component	ATA:25
PN:SP-45-54	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:020800463	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 25-20-45											
252001-7		# 7 PASSENGER SEAT PCU								Component	ATA:25
PN:SP-45-54	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:030701032	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 25-20-45											
252001-8		# 8 PASSENGER SEAT PCU								Component	ATA:25
PN:SP-45-54	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:070900040	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 25-20-45											
252001-9		LAVATORY PASSENGER CONTROL UNIT PCU								Component	ATA:25
PN:SP-45-55	MOS/MSC	20-Jan-11	A/R	TSN 0							
SN:030900071	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: GENERIC NO REF											

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 25 - EQUIPMENT/ FURNISHINGS											
252003-1		BOX ASSEM, STORAGE RH FWD (# 1) CHANGE								Component	ATA:25
PN:B4525402005-055A	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:6706175/001	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 25-20-32											
252003-2		BOX ASSEM, STORAGE, RH FWD MID (# 2) CHANGE								Component	ATA:25
PN:B4525402005-057A	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:6706180/001	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 25-20-32											
252003-3		BOX ASSEM, STORAGE, RH AFT FWD (# 3) CHANGE								Component	ATA:25
PN:B4525402005-056A	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:6706177/001	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 25-20-32											
252003-4		BOX ASSEM, STORAGE, RH AFT (# 4) CHANGE								Component	ATA:25
PN:B4525402005-056A	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:6706178/001	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 25-20-32											
252003-5		BOX ASSEM, STORAGE, LH AFT (# 5) CHANGE								Component	ATA:25
PN:B4525402005-056A	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:6706176/001	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 25-20-32											
252003-6		BOX ASSEM, STORAGE, LH AFT MID (# 6) CHANGE								Component	ATA:25
PN:B4525402005-056A	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:6706179/001	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 25-20-32											

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 25 - EQUIPMENT/ FURNISHINGS											
252003-7		BOX ASSEM, STORAGE LH FWD MID (# 7) CHANGE								Component	ATA:25
PN:B4525402036-005AC	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:6706822/001	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 25-20-32											
252003-8		BOX ASSEM, STORAGE, LH FWD (# 8) CHANGE								Component	ATA:25
PN:B4525402036-005AC	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:6706821/001	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 25-20-32											
252010		AIRSHOW COMPUTER								Component	ATA:25
PN:925000-100	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:NG3LF	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: GENERIC NO REF											
252012		AIRSHOW SWITCH CHANGE								Component	ATA:25
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: GENERIC NO REF											
252015		IR SENSOR CHANGE								Component	ATA:25
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: GENERIC NO REF											
252020		CLOSET SWITCH PANEL ASSEMBLY								Component	ATA:25
PN:SP-45-21	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:061000025	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: GENERIC NO REF											

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 25 - EQUIPMENT/ FURNISHINGS											
252090		POWER PORT 110 VOLT OUTLET								Component	ATA:25
PN:SP-45-26	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:030900060	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: GENERIC NO REF											
252091		POWER PORT 110 VOLT OUTLET								Component	ATA:25
PN:SP-45-26	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:070800737	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: GENERIC NO REF											
252092		POWER PORT 110 VOLT OUTLET								Component	ATA:25
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: GENERIC NO REF											
252095		POWER PORT 110 VOLT OUTLET								Component	ATA:25
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: GENERIC NO REF											
252097		NO. 1 AC OUTLET								Component	ATA:25
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: GENERIC NO REF											
252098		NO. 2 AC OUTLET								Component	ATA:25
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: GENERIC NO REF											
252099		NO. 3 AC OUTLET								Component	ATA:25
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: GENERIC NO REF											

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 25 - EQUIPMENT/ FURNISHINGS										
253001	MICROWAVE OVEN									Component ATA:25
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
253075	NO. 1 HEATED WATER CONTAINER									Component ATA:25
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
253076	NO. 2 HEATED WATER CONTAINER									Component ATA:25
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
253077	HEATED WATER SWITCH									Component ATA:25
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
253080	GALLEY DRAIN VALVE SOLENOID									Component ATA:25
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
256001	PILOT CREW SEAT									Component ATA:25
PN:0820-0-L	MOS/MSC	28-Nov-15	O/C							
SN:0123	HRS	954.7								
	AFL	842								
PROC. REF: AMM 25-10-50										
256002	COPILOT CREW SEAT									Component ATA:25
PN:0820-0-R	MOS/MSC	28-Nov-15	O/C							
SN:0125	HRS	954.7								
	AFL	842								
PROC. REF: AMM 25-10-50										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 25 - EQUIPMENT/ FURNISHINGS											
256030		PILOT PROTECTIVE BREATHING (PBE), (IRN A3510008) EQUIPMENT UNIT								Component	ATA:25
PN:PN	MOS/MSC	20-Jan-11	N/A	TSN 0				NOT INSTALLED			
SN:UNKNOWN	HRS										
	AFL										
PROC. REF: GENERIC NO REF											
256032		COPILOT PROTECTIVE BREATHING (PBE), (IRN A3510008) EQUIPMENT UNIT								Component	ATA:25
PN:PN	MOS/MSC	20-Jan-11	N/A	TSN 0				NOT INSTALLED			
SN:UNKNOWN	HRS										
	AFL										
PROC. REF: GENERIC NO REF											
256061		PILOT LIFE VEST								Component	ATA:25
PN:63600-101	MOS/MSC	23-Oct-20	O/C	TSN 4							
SN:L5052601	HRS	1570.8		TSN 0							
	AFL	1243		TSN 0							
PROC. REF: CMM 25-60-05, AMM 25-60-01											
256061A		INSPECT PILOT LIFE VEST (IRN # E2561002)								Service	ATA:25
PN:63600-101	MOS	10-Jun-20	120		10-Jun-30		2679 d				
SN:L5052601	HRS										
	AFL										
PROC. REF: CMM 25-60-05, AMM 25-60-01											
256062		COPILOT LIFE VEST								Component	ATA:25
PN:63600-101	MOS/MSC	23-Oct-20	O/C	TSN 4							
SN:L5052604	HRS	1570.8		TSN 0							
	AFL	1243		TSN 0							
PROC. REF: CMM 25-60-05, AMM 25-60-01											
256062A		INSPECT COPILOT LIFE VEST (IRN # E2561002)								Service	ATA:25
PN:63600-101	MOS	10-Jun-20	120		10-Jun-30		2679 d				
SN:L5052604	HRS										
	AFL										
PROC. REF: CMM 25-60-05, AMM 25-60-01											
256063		NO. 1 LIFE VEST								Component	ATA:25
PN:63600-101	MOS/MSC	23-Oct-20	O/C	TSN 13							
SN:L4864170	HRS	1570.8		TSN 0							
	AFL	1243		TSN 0							
PROC. REF: CMM 25-60-05, AMM 25-60-01											

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 25 - EQUIPMENT/ FURNISHINGS											
256063A		INSPECT NO. 1 LIFE VEST (IRN # E2561002)								Service	ATA:25
PN:63600-101	MOS	16-Sep-19	120		16-Sep-29		2412 d				
SN:L4864170	HRS										
	AFL										
PROC. REF: CMM 25-60-05, AMM 25-60-01											
256064		NO. 2 LIFE VEST								Component	ATA:25
PN:63600-101	MOS/MSC	23-Oct-20	O/C	TSN 13							
SN:L4864174	HRS	1570.8		TSN 0							
	AFL	1243		TSN 0							
PROC. REF: CMM 25-60-05, AMM 25-60-01											
256064A		INSPECT NO. 2 LIFE VEST (IRN # E2561002)								Service	ATA:25
PN:63600-101	MOS	16-Sep-19	120		16-Sep-29		2412 d				
SN:L4864174	HRS										
	AFL										
PROC. REF: CMM 25-60-05, AMM 25-60-01											
256065		NO. 3 LIFE VEST								Component	ATA:25
PN:63600-101	MOS/MSC	23-Oct-20	O/C	TSN 13							
SN:L4864175	HRS	1570.8		TSN 0							
	AFL	1243		TSN 0							
PROC. REF: CMM 25-60-05, AMM 25-60-01											
256065A		INSPECT NO. 3 LIFE VEST (IRN # E2561002)								Service	ATA:25
PN:63600-101	MOS	16-Sep-19	120		16-Sep-29		2412 d				
SN:L4864175	HRS										
	AFL										
PROC. REF: CMM 25-60-05, AMM 25-60-01											
256066		NO. 4 LIFE VEST								Component	ATA:25
PN:63600-101	MOS/MSC	23-Oct-20	O/C	TSN 13							
SN:L4864177	HRS	1570.8		TSN 0							
	AFL	1243		TSN 0							
PROC. REF: CMM 25-60-05, AMM 25-60-01											
256066A		INSPECT NO. 4 LIFE VEST (IRN # E2561002)								Service	ATA:25
PN:63600-101	MOS	16-Sep-19	120		16-Sep-29		2412 d				
SN:L4864177	HRS										
	AFL										
PROC. REF: CMM 25-60-05, AMM 25-60-01											

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 25 - EQUIPMENT/ FURNISHINGS										
256067	NO. 5 LIFE VEST									Component ATA:25
PN:63600-101	MOS/MSC	23-Oct-20	O/C	TSN 13						
SN:L4864178	HRS	1570.8		TSN 0						
	AFL	1243		TSN 0						
PROC. REF: CMM 25-60-05, AMM 25-60-01										
256067A	INSPECT NO. 5 LIFE VEST (IRN # E2561002)									Service ATA:25
PN:63600-101	MOS	16-Sep-19	120		16-Sep-29		2412 d			
SN:L4864178	HRS									
	AFL									
PROC. REF: CMM 25-60-05, AMM 25-60-01										
256068	NO. 6 LIFE VEST									Component ATA:25
PN:63600-101	MOS/MSC	23-Oct-20	O/C	TSN 13						
SN:L4864191	HRS	1570.8		TSN 0						
	AFL	1243		TSN 0						
PROC. REF: CMM 25-60-05, AMM 25-60-01										
256068A	INSPECT NO. 6 LIFE VEST (IRN # E2561002)									Service ATA:25
PN:63600-101	MOS	16-Sep-19	120		16-Sep-29		2412 d			
SN:L4864191	HRS									
	AFL									
PROC. REF: CMM 25-60-05, AMM 25-60-01										
256069	NO. 7 LIFE VEST									Component ATA:25
PN:63600-101	MOS/MSC	23-Oct-20	O/C	TSN 13						
SN:L4864195	HRS	1570.8		TSN 0						
	AFL	1243		TSN 0						
PROC. REF: CMM 25-60-05, AMM 25-60-01										
256069A	INSPECT NO. 7 LIFE VEST (IRN # E2561002)									Service ATA:25
PN:63600-101	MOS	16-Sep-19	120		16-Sep-29		2412 d			
SN:L4864195	HRS									
	AFL									
PROC. REF: CMM 25-60-05, AMM 25-60-01										
256070	NO. 8 LIFE VEST									Component ATA:25
PN:63600-101	MOS/MSC	23-Oct-20	O/C	TSN 4						
SN:L5052606	HRS	1570.8		TSN 0						
	AFL	1243		TSN 0						
PROC. REF: CMM 25-60-05, AMM 25-60-01										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 25 - EQUIPMENT/ FURNISHINGS										
256070A	INSPECT NO. 8 LIFE VEST (IRN # E2561002)									Service ATA:25
PN:63600-101	MOS	10-Jun-20	120		10-Jun-30		2679 d			
SN:L5052606	HRS									
	AFL									
PROC. REF: CMM 25-60-05, AMM 25-60-01										
256071	LAVATORY LIFE VEST									Component ATA:25
PN:63600-101	MOS/MSC	23-Oct-20	O/C	TSN 4						
SN:L5052608	HRS	1570.8		TSN 0						
	AFL	1243		TSN 0						
PROC. REF: GENERIC NO REF, CMM 25-60-05										
256071A	INSPECT LAVATORY LIFE VEST (IRN # E2561002)									Service ATA:25
PN:63600-101	MOS	10-Jun-20	120		10-Jun-30		2679 d			
SN:L5052608	HRS									
	AFL									
PROC. REF: CMM 25-60-05, AMM 25-60-01										
256076	FIRST AID KIT									Component ATA:25
PN:AFK 1.0	MOS/MSC	20-Jan-23	O/C	TSN 0	30-Apr-24 (M)		447 d			
SN:121322025	HRS	1675		TSN 0						
	AFL	1330		TSN 0						
PROC. REF: GENERIC NO REF										
256076A	VISUALLY INSPECT FIRST AID KIT PER MANUFACTURER INSTRUCTIONS									Service ATA:25
PN:AFK 1.0	MOS	20-Jan-23	12		20-Jan-24		346 d			
SN:121322025	HRS	1675								
	AFL	1330								
PROC. REF: GENERIC NO REF										
256080	INSPECT LIFE VESTS 05-19-00-E2561002									Service ATA:25
	MOS/MSC	20-Jan-11	A/R							
	HRS	0								
	AFL	0								
PROC. REF: GENERIC NO REF, CMM 25-60-05										
256080A	RECERTIFY LIFE VEST FOR CONTINUED SERVICE PER MANUFACTURER'S INSTRUCTIONS									Service ATA:25
	MOS/MSC	20-Jan-11	A/R							
	HRS	0								
	AFL	0								
PROC. REF: CMM 25-60-05										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 25 - EQUIPMENT/ FURNISHINGS										
256109	(ELT) EMERGENCY LOCATOR TRANSMITTER									Component ATA:25
PN:453-5000-(366)	MOS/MSC	11-Mar-14	O/C							
SN:210-04705	HRS	815.4								
	AFL	741								
PROC. REF: AMM 25-62-01										
256109A	FUNCTIONAL TEST (ELT) EMERGENCY LOCATOR TRANSMITTER									Service ATA:25
PN:453-5000-(366)	MOS	20-Jan-23	12 (+ 14d/-14d)	20-Jan-24	03-Feb-24	346 d (+ 14)				
SN:210-04705	HRS	1675								
	AFL	1330								
PROC. REF: AMM 25-62-00, FAR FAR 91.207										
256109B	INSPECT ELT BATTERIES (IF INSTALLED)									Service ATA:25
PN:453-5000-(366)	MOS	20-Jan-23	12 (+ 14d/-14d)	20-Jan-24	03-Feb-24	346 d (+ 14)				
SN:210-04705	HRS	1675								
	AFL	1330								
PROC. REF: AMM 25-62-00, FAR FAR 91.207										
256109C	REPLACE (ELT) EMERGENCY LOCATOR TRANSMITTER ELT BATTERY									Service ATA:25
PN:453-5000-(366)	MOS/MSC	10-Oct-19	DUE	01-Jun-23 (M)	113 d					
SN:210-04705	HRS	1509.8								
	AFL	1201								
PROC. REF: AMM 25-62-01, FAR FAR 91.207										
256109D	REPLACE (ELT) EMERGENCY LOCATOR TRANSMITTER REMOTE SWITCH BATTERY ARTEX 110 SYSTEMS WITHOUT 406 MHZ CAPABILITIES.									Service ATA:25
PN:453-5000-(366)	MOS/MSC	23-Oct-20	N/A	N/A EQUIPMENT NOT INSTALLED						
SN:210-04705	HRS	1570.8								
	AFL	1243								
PROC. REF: GENERIC NO REF, FAR FAR 91.207										
256109E	REPLACE (ELT) EMERGENCY LOCATOR TRANSMITTER REMOTE SWITCH BATTERY (DORNE AND MARGOLIN ELT REMOTE CONTROL BATTERY (P/N U264-1). (ZONE/ACCESS 200 IRN # N2561004)									Service ATA:25
PN:453-5000-(366)	MOS/MSC	23-Oct-20	N/A	NOT INSTALLED						
SN:210-04705	HRS	1570.8								
	AFL	1243								
PROC. REF: GENERIC NO REF										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 25 - EQUIPMENT/ FURNISHINGS											
256110		ELT NAV INTERFACE UNIT								Component	ATA:25
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: GENERIC NO REF											
256115		ELT ANTENNA								Component	ATA:25
PN:110-337	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:287585	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 25-62-03											
256116		ELT REMOTE SWITCH								Component	ATA:25
PN:455-0030	MOS/MSC	20-Jan-23	O/C	TSN 0							
SN:394327-004	HRS	1675		TSN 0							
	AFL	1330		TSN 0							
PROC. REF: AMM 25-62-04											
258001		CABIN AIRSHOW DISPLAY COMPUTER UNIT								Component	ATA:25
PN:922000-2	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:NG3MH	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: GENERIC NO REF											
259072		AUTOMATIC ELECTRONIC DEFIBRILLATOR								Component	ATA:25
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM NO REF											
259073		AUTOMATIC ELECTRONIC DEFIBRILLATOR BATTERIES								Component	ATA:25
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: GENERIC NO REF											
259074		AUTOMATIC ELECTRONIC DEFIBRILLATOR PADS								Component	ATA:25
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: GENERIC NO REF											

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 25 - EQUIPMENT/ FURNISHINGS										
ST00909SE	INSPECT LIFEPORT INSTALLATION									Service ATA:25
	MOS/MSC	20-Jan-11	O/C					STC-SUPPLEMENTAL TYPE CERTIFICATE		
	HRS	0								
	AFL	0								
PROC. REF: GENERIC NO REF										
ST01527WI-D-1 ^{U S}	GENERAL VISUAL INSPECTION OF THE MICROWAVE OVEN									Service ATA:25
	MOS							ICA		
	HRS		4800							
	AFL									
ST01527WI-D-2 ^{U S}	CHECK THE MICROWAVE OVEN AND BAROMETRIC SWITCH									Service ATA:25
	MOS							ICA		
	HRS		600							
	AFL									
ST01527WI-D-3 ^{U S}	GENERAL VISUAL INSPECTION OF THE MICROWAVE OVEN DOOR GASKET									Service ATA:25
	MOS		12					ICA		
	HRS									
	AFL									
ST01527WI-D-4 ^{U S}	GENERAL VISUAL INSPECTION OF THE MICROWAVE OVEN WAVEGUIDE MOISTURE COVER									Service ATA:25
	MOS		12					ICA		
	HRS									
	AFL									
Y2510000 ^S	GLARESHIELD, HEADLINER, AND TRIM STRIPS - PERFORM VISUAL INSPECTION									Service ATA:25
	MOS	20-Jan-23	12 (+ 14d/-14d)							
	HRS	1675	300 (+ 25/-25)							
	AFL	1330								
PROC. REF: AMM 05-10-00										
Y2510001 ^S	CREW SEATS AND SEAT BELTS - PERFORM VISUAL INSPECTION									Service ATA:25
	MOS	20-Jan-23	12 (+ 14d/-14d)							
	HRS	1675	300 (+ 25/-25)							
	AFL	1330								
PROC. REF: AMM 05-10-00										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty
---------	------	------	----------	-----------	--------------------------	-----------	-----------	-------------	-----	----------

ATA 25 - EQUIPMENT/ FURNISHINGS

Y2520000 ^S			CABIN - PERFORM VISUAL INSPECTION OF THE FOLLOWING: A. CABIN SEATS AND SEAT BELTS. ENSURE THAT THE SEATS FUNCTION CORRECTLY AND LOCK IN PLACE. B. STOWAGE CABINETS. C. HEADLINER. D. SIDE PANELS. E. RUG.						Service	ATA:25
	MOS	20-Jan-23	12 (+ 14d/-14d)							
	HRS	1675	300 (+ 25/-25)							
	AFL	1330								
PROC. REF: AMM 05-10-00									PKG:1	

Y2540000 ^S			ALL LAVATORY PAPER AND LINEN WASTE RECEPTACLE ACCESS DOORS AND DISPOSAL DOORS FOR PROPER OPERATION, FIT, SEALING, LATCHING, AND LEGIBILITY OF PLACARD.						Service	ATA:25
	MOS	20-Jan-23	24 (+ 14d/-14d)							
	HRS	1675	600 (+ 25/-25)							
	AFL	1330								
PROC. REF: GENERIC NO REF									PKG:7	

Y2540009 ^S			PERFORM AVIONICS EQUIPMENT AND WIRING LOCATED IN LAVATORY AREA - GENERAL VISUAL INSPECTION						Service	ATA:25
	MOS	20-Jan-11								
	HRS	0	4800 (+ 25/-25)							
	AFL	0								
PROC. REF: AMM 05-10-00									PKG:25	

ATA 26 - FIRE PROTECTION

261012			NO. 1 ENGINE FIREWALL FIRE DETECT ELEMENT						Component	ATA:26
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN	0					
SN:UNKNOWN	HRS	0		TSN	0					
	AFL	0		TSN	0					
PROC. REF: AMM 26-11-02										

261013			NO. 2 ENGINE FIREWALL FIRE DETECT ELEMENT						Component	ATA:26
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN	0					
SN:UNKNOWN	HRS	0		TSN	0					
	AFL	0		TSN	0					
PROC. REF: AMM 26-11-02										

261014			NO. 1 ENGINE ACCESSORY GEARBOX FIRE DETECT ELEMENT						Component	ATA:26
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN	0					
SN:UNKNOWN	HRS	0		TSN	0					
	AFL	0		TSN	0					
PROC. REF: AMM 26-11-02										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty
---------	------	------	----------	-----------	--------------------------	-----------	-----------	-------------	-----	----------

ATA 26 - FIRE PROTECTION

261015		NO. 2 ENGINE ACCESSORY GEARBOX FIRE DETECT ELEMENT								Component	ATA:26
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 26-11-02											
261016		NO. 1 ENGINE HOT SECTION FIRE DETECT ELEMENT								Component	ATA:26
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 26-11-02											
261017		NO. 2 ENGINE HOT SECTION FIRE DETECT ELEMENT								Component	ATA:26
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 26-11-02											
261057		NO. 1 FIRE DETECT CONTROL UNIT								Component	ATA:26
PN:877-01032	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:0907-549	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 26-11-01											
261058		NO. 2 FIRE DETECT CONTROL UNIT								Component	ATA:26
PN:877-01032	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:0907-547	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 26-11-01											
261069		NO. 1 BLEED AIR LEAK(A76) DETECTION UNIT								Component	ATA:26
PN:35009-39	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:2464	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 26-12-01											
261070		NO. 2 BLEED AIR LEAK(A78) DETECTION UNIT								Component	ATA:26
PN:35009-39	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:2427	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 26-12-01											

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 26 - FIRE PROTECTION											
261071		ANTI-ICE BLEED AIR LEAK(A77) DETECTION UNIT								Component	ATA:26
PN:35009-39	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:2424	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 26-12-01											
261075		APU FIRE/OVERHEAT DETECTOR								Component	ATA:26
PN:10-1093	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:09-0392	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 26-13-01											
262001		NO. 1/LEFT/LOWER FIRE EXTINGUISHER BOTTLE								Component	ATA:26
PN:33100021-1	MOS/MSC	10-Oct-19	O/C	TSN 63, TSO 1							
SN:71183B1	HRS	1509.8		TSO 0							
	AFL	1201		TSO 0							
PROC. REF: AMM 26-21-01											
262001A		NO. 1/LEFT/LOWER FIRE EXTINGUISHER BOTTLE - HYDROSTATIC TEST (Q2620006)								Service	ATA:26
PN:33100021-1	MOS	01-Sep-19	60 (+ 14d/-14d)		01-Sep-24	15-Sep-24	571 d (+ 14)	SCHEDULED MAINTENANCE TASKS AND INTERVALS			
SN:71183B1	HRS										
	AFL										
PROC. REF: GENERIC NO REF											
262002		NO. 2/RIGHT/UPPER FIRE EXTINGUISHER BOTTLE								Component	ATA:26
PN:33100021-1	MOS/MSC	10-Oct-19	O/C	TSN 64, TSO 4							
SN:71037B1	HRS	1509.8		TSO 0							
	AFL	1201		TSO 0							
PROC. REF: AMM 26-21-01											
262002A		NO. 2/RIGHT/UPPER FIRE EXTINGUISHER BOTTLE - HYDROSTATIC TEST (Q2620006)								Service	ATA:26
PN:33100021-1	MOS	01-Jun-19	60 (+ 14d/-14d)		01-Jun-24	15-Jun-24	479 d (+ 14)				
SN:71037B1	HRS										
	AFL										
PROC. REF: GENERIC NO REF											

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 26 - FIRE PROTECTION										
262013	NO. 1/LEFT/LOWER FIRE EXTINGUISHER, LEFT SQUIB									Component ATA:26
PN:30903856	MOS	10-Oct-19	120 (+ 14d/-14d)	TSN 62	10-Aug-24	24-Aug-24	549 d (+ 14)	REPLACE		
SN:UNKNOWN	HRS	1509.8								
	AFL	1201								
PROC. REF: GENERIC NO REF										
262014	NO. 1/LEFT/LOWER FIRE EXTINGUISHER, RIGHT SQUIB									Component ATA:26
PN:30903859	MOS	10-Oct-19	120 (+ 14d/-14d)	TSN 62	10-Aug-24	24-Aug-24	549 d (+ 14)	REPLACE		
SN:UNKNOWN	HRS	1509.8								
	AFL	1201								
PROC. REF: GENERIC NO REF										
262015	NO. 2/RIGHT/UPPER FIRE EXTINGUISHER, LEFT SQUIB									Component ATA:26
PN:30903856	MOS	10-Oct-19	120 (+ 14d/-14d)	TSN 4	10-Jun-29	24-Jun-29	2314 d (+ 14)	REPLACE		
SN:UNKNOWN	HRS	1509.8								
	AFL	1201								
PROC. REF: GENERIC NO REF										
262016	NO. 2/RIGHT/UPPER FIRE EXTINGUISHER, RIGHT SQUIB									Component ATA:26
PN:30903859	MOS	10-Oct-19	120 (+ 14d/-14d)	TSN 4	10-Jun-29	24-Jun-29	2314 d (+ 14)	REPLACE		
SN:UNKNOWN	HRS	1509.8								
	AFL	1201								
PROC. REF: GENERIC NO REF										
262040	APU FIRE WARNING HORN									Component ATA:26
PN:430-M1	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:23596	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 26-13-02										
262041	PILOT PORTABLE FIRE EXTINGUISHER									Component ATA:26
PN:A-344T	MOS/MSC	08-Nov-21	O/C	TSN 0						
SN:G-42446521	HRS	1605.6		TSN 0						
	AFL	1281		TSN 0						
PROC. REF: GENERIC NO REF										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 26 - FIRE PROTECTION											
262041A ^S		VISUAL INSPECTION AND WEIGHT CHECK PILOT PORTABLE FIRE EXTINGUISHER PILOTS PORTABLE FIRE EXTINGUISHER IRN (Y2620009)							Service	ATA:26	
PN:A-344T	MOS	08-Nov-21	12 (+ 14d/-14d)								
SN:G-42446521	HRS	1605.6	300 (+ 25/-25)								
	AFL	1281									
PROC. REF: GENERIC NO REF						PKG:1					
262041B		HYDROSTATIC TEST PILOT PORTABLE FIRE EXTINGUISHER (IRN # Q2510003).							Service	ATA:26	
PN:A-344T	MOS		144 (+ 14d/-14d)		?		?	SCHEDULED MAINTENANCE TASKS AND INTERVALS			
SN:G-42446521	HRS										
	AFL										
PROC. REF: AMM 26-23-00											
262042		COPILOT PORTABLE FIRE EXTINGUISHER							Component	ATA:26	
PN:A-344T	MOS/MSC	08-Nov-21	O/C	TSN 0							
SN:G42446527	HRS	1605.6		TSN 0							
	AFL	1281		TSN 0							
PROC. REF: GENERIC NO REF											
262042A ^S		VISUAL INSPECTION AND WEIGHT CHECK COPILOT PORTABLE FIRE EXTINGUISHER CO-PILOT'S PORTABLE FIRE EXTINGUISHER (IRN Y2620009)							Service	ATA:26	
PN:A-344T	MOS	08-Nov-21	12 (+ 14d/-14d)								
SN:G42446527	HRS	1605.6	300 (+ 25/-25)								
	AFL	1281									
PROC. REF: GENERIC NO REF						PKG:1					
262042B		HYDROSTATIC TEST COPILOT PORTABLE FIRE EXTINGUISHER (IRN # Q2510003).							Service	ATA:26	
PN:A-344T	MOS		144 (+ 14d/-14d)		?		?	SCHEDULED MAINTENANCE TASKS AND INTERVALS			
SN:G42446527	HRS										
	AFL										
PROC. REF: AMM 26-23-00											
262051		CABIN PORTABLE FIRE EXTINGUISHER							Component	ATA:26	
PN:C-352TS	MOS/MSC	08-Nov-21	O/C	TSN 0							
SN:G-45678393	HRS	1605.6		TSN 0							
	AFL	1281		TSN 0							
PROC. REF: GENERIC NO REF											

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 26 - FIRE PROTECTION											
262051A ^S		VISUAL INSPECTION AND WEIGHT CHECK CABIN PORTABLE FIRE EXTINGUISHER (IRN Y2620009)								Service	ATA:26
PN:C-352TS	MOS	08-Nov-21	12 (+ 14d/-14d)								
SN:G-45678393	HRS	1605.6	300 (+ 25/-25)								
	AFL	1281									
PROC. REF: AMM 26-23-00										PKG:1	
262051B		HYDROSTATIC TEST CABIN PORTABLE FIRE EXTINGUISHER (IRN # Q2510003).								Service	ATA:26
PN:C-352TS	MOS		144 (+ 14d/-14d)		?		?	SCHEDULED MAINTENANCE TASKS AND INTERVALS			
SN:G-45678393	HRS										
	AFL										
PROC. REF: AMM 26-23-00											
262075		APU FIRE EXTINGUISHER								Component	ATA:26
PN:51600-2	MOS/MSC	20-Jan-23	O/C	TSN 4							
SN:0995	HRS	1675		TSN 0							
	AFL	1330		TSN 0							
PROC. REF: AMM 26-22-01											
262075A		PERFORM APU FIRE EXTINGUISHER CONTAINER - ICC HYDROSTATIC TEST. (ZONE/ACCESS 310JL, 310QR) (IRN # Q4900014)								Service	ATA:26
PN:51600-2	MOS	01-Sep-22	60 (+ 14d/-14d)		01-Sep-27	15-Sep-27	1666 d (+ 14)				
SN:0995	HRS										
	AFL										
PROC. REF: GENERIC NO REF											
262076		REPLACE APU ENGINE FIRE EXTINGUISHER CONTAINER CARTRIDGE								Component	ATA:26
PN:PN-UNKNOWN	MOS	20-Jan-23	180 (+ 14d/-14d)		01-Sep-37	15-Sep-37	5319 d (+ 14)	LIFE LIMIT			
SN:UNKNOWN	HRS	1675		TSN 0							
	AFL	1330		TSN 0							
Manufacture Date:: 01-Sep-22 PROC. REF: AMM 26-21-02											
5-19-00-O2610001-LEFT		VISUALLY INSPECT NO. 1 ENGINE HOT SECTION FIRE DETECTOR ELEMENT. (ZONE/ACCESS 410 IRN O2610001) DURING MAJOR ENGINE INSPECTION/UNSCHEDULED ENGINE CHANGE								Service	ATA:26
	MOS	20-Jan-11									
	HRS	0	3000 (+ 100/-100)		3000	3100	1325 (+ 100)				
	AFL	0									
PROC. REF: AMM 05-10-00											

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 26 - FIRE PROTECTION										
5-19-00-O2610001-RIGHT	VISUALLY INSPECT NO. 2 ENGINE HOT SECTION FIRE DETECTOR ELEMENT. (ZONE/ACCESS 410 IRN O2610001) DURING MAJOR ENGINE INSPECTION/UNSCHEDULED ENGINE CHANGE								Service	ATA:26
MOS	20-Jan-11									
HRS	0		3000 (+ 100/-100)		3000	3100	1325 (+ 100)			
AFL	0									
PROC. REF: AMM 05-10-00										
J2620000 ^S	PERFORM ** ENGINE FIRE EXTINGUISHING SYSTEM FIRE SWITCH - FUNCTIONAL TEST								Service	ATA:26
MOS	20-Jan-11							AIRWORTHINESS		
HRS	0		4800 (+ 25/-25)							
AFL	0									
PROC. REF: AMM 26-21-00										
T2620001 ^S	PERFORM ** FIREWALL SHUTOFF VALVES - OPERATIONAL CHECK.								Service	ATA:26
MOS	20-Jan-23		48 (+ 14d/-14d)					AIRWORTHINESS		
HRS	1675		1200 (+ 25/-25)							
AFL	1330									
PROC. REF: AMM 26-21-00										
Y2610000 ^S	FIREWALL AND ACCESSORY COMPARTMENT FIRE DETECTOR ELEMENTS - PERFORM VISUAL INSPECTION								Service	ATA:26
MOS	20-Jan-23		24 (+ 14d/-14d)							
HRS	1675		600 (+ 14/-14)							
AFL	1330									
PROC. REF: AMM 05-10-00										
Y2620002 ^S	ENGINE FIRE EXTINGUISHER CONTAINERS - PERFORM VISUAL INSPECTION. CHECK CONTAINERS FOR CONDITION,CARTRIDGES AND CARTRIDGE WIRING FOR SECURITY AND CONDITION, CONTAINER PRESSURE GAUGE FOR PROPER PRESSURES, AND PLUMBING FOR SECURITY AND CONDITION								Service	ATA:26
MOS	20-Jan-23		12 (+ 14d/-14d)							
HRS	1675		300 (+ 25/-25)							
AFL	1330									
PROC. REF: AMM 05-10-00										
Y2620005 ^S	PERFORM ENGINE FIRE EXTINGUISHING SYSTEM - OPERATIONAL CHECK								Service	ATA:26
MOS	11-Sep-18		96 (+ 14d/-14d)							
HRS	1387.4		2400 (+ 25/-25)							
AFL	1114									
PROC. REF: AMM 26-21-00										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty
---------	------	------	----------	-----------	--------------------------	-----------	-----------	-------------	-----	----------

ATA 26 - FIRE PROTECTION

Y2620009 ^S			INSPECT PORTABLE HAND HELD FIRE EXTINGUISHERS FOR CONDITION AND DATE OF MANUFACTURE. CHECK OPERATING PRESSURE AND WEIGHT PER MAINTENANCE INSTRUCTIONS ON FIRE EXTINGUISHER BOTTLE.					Service	ATA:26
	MOS	20-Jan-23	12 (+ 14d/-14d)						
	HRS	1675	300 (+ 25/-25)						
	AFL	1330							
PROC. REF: GENERIC NO REF									
PKG:1									

Z2620021 ^S			NO. 1 ENGINE FIRE EXTINGUISHER CONTAINER PLUMBING - PERFORM DETAILED INSPECTION					Service	ATA:26
	MOS	20-Jan-23	12						
	HRS	1675	300						
	AFL	1330							
PROC. REF: AMM 26-21-00									
PKG:2									

Z2620021 ^S			NO. 2 ENGINE FIRE EXTINGUISHER CONTAINER PLUMBING - PERFORM DETAILED INSPECTION					Service	ATA:26
	MOS	20-Jan-23	12						
	HRS	1675	300						
	AFL	1330							
PROC. REF: AMM 26-21-00									
PKG:2									

ATA 27 - FLIGHT CONTROLS

270301			TRIM SWITCH PANEL ASSY					Component	ATA:27
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN	0				
SN:UNKNOWN	HRS	0		TSN	0				
	AFL	0		TSN	0				
PROC. REF: AMM 27-00-01									

271001			LEFTAILERON CONTROL SYSTEM CROSSOVER CABLE					Component	ATA:27
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN	0				
SN:UNKNOWN	HRS	0		TSN	0				
	AFL	0		TSN	0				
PROC. REF: AMM 27-10-05									

271002			RIGHTAILERON CONTROL SYSTEM CROSSOVER CABLE					Component	ATA:27
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN	0				
SN:UNKNOWN	HRS	0		TSN	0				
	AFL	0		TSN	0				
PROC. REF: AMM 27-10-05									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 27 - FLIGHT CONTROLS										
271003 LEFT AILERON CONTROL SYSTEM CABLE Component ATA:27										
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 27-10-05										
271004 RIGHT AILERON CONTROL SYSTEM CABLE Component ATA:27										
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 27-10-05										
271005 AILERON CONTROL SYSTEM AFT CABLE ASSEMBLY Component ATA:27										
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 27-10-05										
271045 ASSEMBLY, AILERON CONTROL INBOARD LEFT CABLE Component ATA:27										
PN:4527103077-011	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:1110096-2	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 27-10-05										
271046 ASSEMBLY, AILERON CONTROL INBOARD RIGHT CABLE Component ATA:27										
PN:4527103076-015	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:1110104-1	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 27-10-05										
271051 LEFT AILERON FORWARD OUTBOARD CONTROL CABLE Component ATA:27										
PN:4527103078-009	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:1110085-11	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 27-10-05										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 27 - FLIGHT CONTROLS										
271052	RIGHT AILERON FORWARD OUTBOARD CONTROL CABLE									Component ATA:27
PN:4527103078-009	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:1110085-20	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 27-10-05										
271053	LEFT AILERON OUTBOARD AFT CONTROL CABLE									Component ATA:27
PN:4527103079-009	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:1110091-9	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 27-10-05										
271054	RIGHT AILERON AFT OUTBOARD CONTROL CABLE									Component ATA:27
PN:4527103079-009	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:1110092-12	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 27-10-05										
271083	AILERON TRIM TAB ACTUATOR									Component ATA:27
PN:6627108000-001	MOS/MSC	06-Nov-17	O/C							
SN:0314	HRS	1300.2								
	AFL	1056								
PROC. REF: AMM 27-10-09										
271095	PILOT ANGLE OF ATTACK (AOA) INDICATOR									Component ATA:27
PN:C-38805-1	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:85096	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
271096	COPILOT ANGLE OF ATTACK (AOA) INDICATOR									Component ATA:27
PN:C-38805-1	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:85097	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty
---------	------	------	----------	-----------	--------------------------	-----------	-----------	-------------	-----	----------

ATA 27 - FLIGHT CONTROLS

271220 TRIM, TOGGLE, AND PUSH BUTTON SWITCH Component ATA:27										
PN:403-4300	MOS/MSC	06-Nov-17	O/C	TSN 0						
SN:UNKNOWN	HRS	1300.2		TSN 0						
	AFL	1056		TSN 0						
PROC. REF: AMM 27-10-06										
272001 FORWARD UPPER RUDDER CONTROL SYSTEM CABLE Component ATA:27										
PN:7627202001-005	MOS/MSC	11-Mar-14	O/C	TSN 0						
SN:UNKNOWN	HRS	815.4		TSN 0						
	AFL	741		TSN 0						
PROC. REF: AMM 27-20-08										
272002 FORWARD LOWER RUDDER CONTROL SYSTEM CABLE Component ATA:27										
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 27-20-08										
272003 LEFT AFT UPPER RUDDER CONTROL SYSTEM CABLE Component ATA:27										
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 27-20-08										
272004 RIGHT AFT UPPER RUDDER CONTROL SYSTEM CABLE Component ATA:27										
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 27-20-08										
272005 LEFT AFT LOWER RUDDER CONTROL SYSTEM CABLE Component ATA:27										
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 27-20-08										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 27 - FLIGHT CONTROLS										
272006 RIGHT AFT LOWER RUDDER CONTROL SYSTEM CABLE Component ATA:27										
PN:7627202006-005	MOS/MSC	11-Mar-14	O/C	TSN 0						
SN:UNKNOWN	HRS	815.4		TSN 0						
	AFL	741		TSN 0						
PROC. REF: AMM 27-20-08										
272021 RUDDER TRIM TAB ACTUATOR Component ATA:27										
PN:4323322A	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:0579	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 27-20-03										
272031 PILOT RUDDER PEDAL ADJUST ACTUATOR Component ATA:27										
PN:4389596	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:1295	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 27-20-05										
272032 COPILOT RUDDER PEDAL ADJUST ACTUATOR Component ATA:27										
PN:4389596	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:1296	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 27-20-05										
273001 FORWARD PILOT ELEVATOR CONTROL SYSTEM CABLE Component ATA:27										
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 27-30-05										
273002 FORWARD COPILOT ELEVATOR CONTROL SYSTEM CABLE Component ATA:27										
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 27-30-05										
273003 LEFT AFT UPPER ELEVATOR CONTROL SYSTEM CABLE Component ATA:27										
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 27-30-05										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty
---------	------	------	----------	-----------	--------------------------	-----------	-----------	-------------	-----	----------

ATA 27 - FLIGHT CONTROLS

273004 RIGHT AFT UPPER ELEVATOR CONTROL SYSTEM CABLE Component ATA:27										
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 27-30-05										
273005 LEFT AFT LOWER ELEVATOR CONTROL SYSTEM CABLE Component ATA:27										
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 27-30-05										
273006 RIGHT AFT LOWER ELEVATOR CONTROL SYSTEM CABLE Component ATA:27										
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 27-30-05										
273015 LEFT ANGLE OF ATTACK (AOA) VANE Component ATA:27										
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 27-31-04										
273016 RIGHT ANGLE OF ATTACK (AOA) VANE Component ATA:27										
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 27-31-04										
273051 ELEVATOR DISCONNECT ACTUATOR Component ATA:27										
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 27-30-09										
273063 PILOT STICK SHAKER Component ATA:27										
PN:C-38802-01	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:1896	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 27-31-03										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty
---------	------	------	----------	-----------	--------------------------	-----------	-----------	-------------	-----	----------

ATA 27 - FLIGHT CONTROLS

273064 COPILOT STICK SHAKER Component ATA:27										
PN:C-38802-01	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:1921	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 27-31-03										
273075 LEFT ANGLE OF ATTACK (AOA) TRANSMITTER Component ATA:27										
PN:C-38817-1	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:1391	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 27-31-01										
273076 RIGHT ANGLE OF ATTACK (AOA) TRANSMITTER Component ATA:27										
PN:C-38817-1	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:1388	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 27-31-01										
273087 STALL WARNING COMPUTER Component ATA:27										
PN:C-38806-2	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:681	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 27-31-02										
273201 ELEVATOR DISCONNECT (A83) CURRENT LIMITER Component ATA:27										
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 27-30-13										
273220 DISCONNECT ASSEM, ELEVATOR AFT CHANGE Component ATA:27										
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 27-30-07										
273420 ELEVATOR OVERRIDE (L45) ACTUATOR Component ATA:27										
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 27-30-14										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 27 - FLIGHT CONTROLS											
274011		HORIZONTAL STABILIZER ACTUATOR								Component	ATA:27
PN:6627401000-009	MOS/MSC	11-Sep-18	O/C	TSO 0							
SN:B0216	HRS	1387.4		TSN 4761.42, TSO 0							
	AFL	1114		TSO 0							
PROC. REF: AMM 27-40-02											
274011A		INSPECT HORIZONTAL STABILIZER ACTUATOR * (6627401000-009 - IRN P2740032). (6627401000-007 - IRN T2740002)								Service	ATA:27
PN:6627401000-009	MOS	11-Sep-18									
SN:B0216	HRS	1387.4	1200		2587.4		912.4				
	AFL	1114									
PROC. REF: AMM 27-40-00											
274011B		* HORIZONTAL STABILIZER ACTUATOR - PERFORM DETAILED STRUCTURAL INSPECTION (6627401000-009 - IRN P2740033). (6627401000-007 - IRN N2740025)								Service	ATA:27
PN:6627401000-009	MOS	11-Sep-18									
SN:B0216	HRS	1387.4	2400		3787.4		2112.4				
	AFL	1114									
PROC. REF: GENERIC NO REF											
274011C		REPLACE HORIZONTAL STABILIZER ACTUATOR * ACME SCREW (P/N 2A94568008). EFFECTIVE ON AIRCRAFT EQUIPPED WITH (6627401000-007 - IRN N2740023)								Service	ATA:27
PN:6627401000-009	MOS/MSC	11-Sep-18	N/A								
SN:B0216	HRS	1387.4									
	AFL	1114									
PROC. REF: GENERIC NO REF											
274011D		REPLACE HORIZONTAL STABILIZER ACTUATOR * ACME NUT (P/N 2A94567005). (EFFECTIVE ON AIRCRAFT EQUIPPED WITH (6627401000-007 - IRN N2740024)								Service	ATA:27
PN:6627401000-009	MOS/MSC	11-Sep-18	N/A								
SN:B0216	HRS	1387.4									
	AFL	1114									
PROC. REF: GENERIC NO REF											

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty
---------	------	------	----------	-----------	--------------------------	-----------	-----------	-------------	-----	----------

ATA 27 - FLIGHT CONTROLS

274031		TRIM-IN-MOTION DETECTOR								Component	ATA:27
PN:1625-1-1	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:3D67B	HRS	0	TSN 0								
	AFL	0	TSN 0								
PROC. REF: AMM 27-41-00											

274041		FORWARD INTERFACE UNIT								Component	ATA:27
PN:4527408503-027	MOS/MSC	04-Jan-15	O/C								
SN:A00343443-01	HRS	877.1									
	AFL	786									
PROC. REF: AMM 27-40-04											

274051		HORIZONTAL STABILIZER ACTUATOR CONTROL BOX ASSEMBLY								Component	ATA:27
PN:E6D201C	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:0528	HRS	0	TSN 0								
	AFL	0	TSN 0								
PROC. REF: AMM 27-40-02, AMM 27-40-03											

275000		FLAP HYDRAULIC MOTOR								Component	ATA:27
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:UNKNOWN	HRS	0	TSN 0								
	AFL	0	TSN 0								
PROC. REF: GENERIC NO REF											

275020		LEFT FLAP, OUTBOARD ACTUATOR								Component	ATA:27
PN:6627503000-033	MOS/MSC	04-Feb-13	O/C								
SN:1953	HRS	528.7									
	AFL	457									
PROC. REF: AMM 27-50-06											

275021		LEFT FLAP, INBOARD ACTUATOR								Component	ATA:27
PN:6627503000-031	MOS/MSC	04-Feb-13	O/C	TSR 0							
SN:1645	HRS	528.7	TSR 0								
	AFL	457	TSR 0								
PROC. REF: AMM 27-50-06											

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty
---------	------	------	----------	-----------	--------------------------	-----------	-----------	-------------	-----	----------

ATA 27 - FLIGHT CONTROLS

275022		RIGHT FLAP, INBOARD ACTUATOR								Component	ATA:27
PN:6627503000-031	MOS/MSC	04-Feb-13	O/C								
SN:1330	HRS	528.7									
	AFL	457									
PROC. REF: AMM 27-50-06											

275023		RIGHT FLAP, OUTBOARD ACTUATOR								Component	ATA:27
PN:6627503000-033	MOS/MSC	04-Feb-13	O/C								
SN:2156	HRS	528.7									
	AFL	457									
PROC. REF: AMM 27-50-06											

275030 ^S		LEFT * INBOARD FLAP ACTUATOR JOINT REPLACE								Component	ATA:27
PN:PN	MOS	20-Jan-11	24	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 27-50-06											

275031 ^S		LEFT * OUTBOARD FLAP ACTUATOR JOINT REPLACE								Component	ATA:27
PN:PN	MOS	20-Jan-11	24	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 27-50-06											

275032 ^S		RIGHT * INBOARD FLAP ACTUATOR JOINT REPLACE								Component	ATA:27
PN:PN	MOS	20-Jan-11	24	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 27-50-06											

275033 ^S		RIGHT * OUTBOARD FLAP ACTUATOR JOINT REPLACE								Component	ATA:27
PN:PN	MOS	20-Jan-11	24	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 27-50-06											

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 27 - FLIGHT CONTROLS										
275057 FLAP DRIVE POWER UNIT Component ATA:27										
PN:C144483-3	MOS/MSC	18-Apr-11	O/C							
SN:1437	HRS	68.8								
	AFL	47								
PROC. REF: AMM 27-50-08										
275058 FLAP CONTROL UNIT Component ATA:27										
PN:C144486-3-003	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:1615	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 27-50-05										
275069 FLAP POSITION INDICATOR Component ATA:27										
PN:C145159-1	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:1671	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 27-50-07										
275080 FLAP CONTROL MODULE Component ATA:27										
PN:69013-17	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:543	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 27-50-02										
275081 LEFT FLAP DRIVE RVDT Component ATA:27										
PN:C144489-2	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:A1184	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 27-50-03										
275082 RIGHT FLAP DRIVE RVDT Component ATA:27										
PN:C144489-2	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:A1203	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 27-50-03										
275110 LH IB FLAP TRACK ASSEMBLY REPLACE Component ATA:27										
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 27 - FLIGHT CONTROLS											
275112		RH IB FLAP TRACK ASSEMBLY REPLACE								Component	ATA:27
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: GENERIC NO REF											
275114		LH OB FLAP TRACK ASSEMBLY REPLACE								Component	ATA:27
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: GENERIC NO REF											
275116		RH OB FLAP TRACK ASSEMBLY REPLACE								Component	ATA:27
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: GENERIC NO REF											
275120		CENTER LEFT FLAP TRACK ASSEMBLY REPLACE								Component	ATA:27
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: GENERIC NO REF											
275122		CENTER RIGHT FLAP TRACK ASSEMBLY REPLACE								Component	ATA:27
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: GENERIC NO REF											
275201		SHAFT, LH INBD FLAP DRIVE								Component	ATA:27
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 27-50-04											
275202		SHAFT, RH INBD FLAP DRIVE								Component	ATA:27
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 27-50-04											

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty
---------	------	------	----------	-----------	--------------------------	-----------	-----------	-------------	-----	----------

ATA 27 - FLIGHT CONTROLS

275203		SHAFT, LH OUTBD FLAP DRIVE								Component	ATA:27
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 27-50-04											
275204		SHAFT, RH OUTBD FLAP DRIVE								Component	ATA:27
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 27-50-04											
276001		LEFT SPOILER ACTUATOR								Component	ATA:27
PN:P455A0001-04	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:AAA292P455	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 27-60-04											
276002		RIGHT SPOILER ACTUATOR								Component	ATA:27
PN:P455A0001-04	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:AAA314P455	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 27-60-04											
276005		SPOILER CONTROL MODULE								Component	ATA:27
PN:69014-9	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:590	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 27-60-03											
276010		SPOILERON CONTROLLER RESISTOR BOX ASSEMBLY								Component	ATA:27
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 27-60-10											
276013		SPOILER SHUTOFF VALVE								Component	ATA:27
PN:100291000-003	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:0312TK	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 27-60-07											

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty
---------	------	------	----------	-----------	--------------------------	-----------	-----------	-------------	-----	----------

ATA 27 - FLIGHT CONTROLS

276020 SPOILER LOW PRESSURE ASSEMBLY (L41) SWITCH										Component	ATA:27	
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0								
SN:UNKNOWN	HRS	0		TSN 0								
	AFL	0		TSN 0								
PROC. REF: AMM 27-60-08												

276031 LEFT SPOILER RVDT										Component	ATA:27	
PN:3A2-249A	MOS/MSC	20-Jan-11	O/C	TSN 0								
SN:A1142	HRS	0		TSN 0								
	AFL	0		TSN 0								
PROC. REF: AMM 27-60-05												

276032 RIGHT SPOILER RVDT										Component	ATA:27	
PN:3A2-249A	MOS/MSC	20-Jan-11	O/C	TSN 0								
SN:A1174	HRS	0		TSN 0								
	AFL	0		TSN 0								
PROC. REF: AMM 27-60-05												

276073 SPOILERON COMPUTER										Component	ATA:27	
PN:402800-06-03	MOS/MSC	20-Jan-11	O/C	TSN 0								
SN:00921	HRS	0		TSN 0								
	AFL	0		TSN 0								
PROC. REF: AMM 27-60-02												

276076 CONTROL WHEEL RVDT										Component	ATA:27	
PN:3G4-211A	MOS/MSC	20-Jan-11	O/C	TSN 0								
SN:0056/0819	HRS	0		TSN 0								
	AFL	0		TSN 0								
PROC. REF: AMM 27-60-06												

5-19-00-D2740003 ** HORIZONTAL STABILIZER ACTUATOR SECONDARY TRIM - PERFORM FUNCTIONAL TEST (IRN D2740003)										Service	ATA:27	
	MOS	10-Oct-19										
	HRS	1509.8	600 (+ 25/-25)		2109.8		2134.8		434.8 (+ 25)			
	AFL	1201										
PROC. REF: AMM 27-40-02												

5-19-00-D2740004 ** HORIZONTAL STABILIZER ACTUATOR PRIMARY TRIM - PERFORM FUNCTIONAL TEST (IRN D2740004)										Service	ATA:27	
	MOS	10-Oct-19										
	HRS	1509.8	600 (+ 25/-25)		2109.8		2134.8		434.8 (+ 25)			
	AFL	1201										
PROC. REF: AMM 27-40-02												

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 27 - FLIGHT CONTROLS										
5-19-00-K2700007	* AILERON CONTROL SYSTEM PRIMARY CABLES - REMOVE FROM AIRCRAFT AND PERFORM DETAILED VISUAL INSPECTION (IRN K2700007)									Service ATA:27
MOS	20-Jan-11							AIRWORTHINESS		
HRS	0	4800			4800		3125			
AFL	0									
PROC. REF: AMM 27-00-00										
5-19-00-K2700008	* ELEVATOR CONTROL SYSTEM PRIMARY CABLES - REMOVE FROM AIRCRAFT AND PERFORM DETAILED VISUAL INSPECTION (IRN K2700008)									Service ATA:27
MOS	20-Jan-11							AIRWORTHINESS		
HRS	0	4800			4800		3125			
AFL	0									
PROC. REF: AMM 27-00-00										
5-19-00-K2700009	* RUDDER CONTROL SYSTEM PRIMARY CABLES - REMOVE FROM AIRCRAFT AND PERFORM DETAILED VISUAL INSPECTION (IRN K2700009)									Service ATA:27
MOS	20-Jan-11							AIRWORTHINESS		
HRS	0	4800			4800		3125			
AFL	0									
PROC. REF: AMM 27-00-00										
5-19-00-K2700010	* ELEVATOR CONTROL SYSTEM PRIMARY CABLES - REMOVE FROM AIRCRAFT AND PERFORM DETAILED VISUAL INSPECTION (IRN K2700010)									Service ATA:27
MOS	20-Jan-11							AIRWORTHINESS		
HRS	0	4800			4800		3125			
AFL	0									
PROC. REF: AMM 27-00-00										
5-19-00-K2700012	* RUDDER CONTROL SYSTEM PRIMARY CABLES - REMOVE FROM AIRCRAFT AND PERFORM DETAILED VISUAL INSPECTION (IRN K2700012)									Service ATA:27
MOS	20-Jan-11							AIRWORTHINESS		
HRS	0	4800			4800		3125			
AFL	0									
PROC. REF: AMM 27-00-00										
5-19-00-K2700014	DETAILED VISUAL INSPECTION * AILERON CONTROL SYSTEM PRIMARY CABLES (IRN K2700014)									Service ATA:27
MOS	20-Jan-11							AIRWORTHINESS		
HRS	0	4800			4800		3125			
AFL	0									
PROC. REF: AMM 27-00-00										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 27 - FLIGHT CONTROLS											
5-19-00-M5540022	RUDDER TORQUE TUBE - PERFORM BORESCOPE INSPECTION									Service ATA:27	
	MOS/MSC	20-Jan-11	N/A								
	HRS	0									
	AFL	0									
PROC. REF: GENERIC NO REF											
5-19-00-N2720030	RUDDER TORQUE TUBE AND SPINDLE - PERFORM DETAILED VISUAL INSPECTION									Service ATA:27	
	MOS	20-Jan-23	72 (+14d/-14d)	Adj -35d	16-Dec-28	30-Dec-28	2138 d (+14)	AIRWORTHINESS			
	HRS	1675									
	AFL	1330									
PROC. REF: AMM 27-20-01											
5-19-00-S2750057	* FLAP ACTUATOR BALLNUT SLEEVE (FLAP ACTUATOR ASSEMBLY LEARJET P/N 6627503000-009, 6627503000-011, 6627503000-021, 6627503000-023, 6627503000-025, AND 6627503000-027, FLAP ACTUATOR ASSEMBLY MICROTECNICA P/N C144487-1, C144488-1, C144487-2, C144488-2, C144487-3, AND C144488-3) - PERFORM FLUORESCENT PENETRANT INSPECTION									Service ATA:27	
	MOS/MSC	30-Nov-12	N/A						NOT APPLICABLE		
	HRS	509.4									
	AFL	434									
PROC. REF: NDT PART 8/27-50-01, NDT PART 8/27-50-02											
5-19-00-W2750056	PERFORM * FLAP ACTUATOR JOINT (P/N 145673-1) - PERFORM DETAILED VISUAL INSPECTION. (REFER TO 27-50-06.) APPLY CORROSION PREVENTIVE COMPOUND (CPC) TO JOINT. (REFER TO 12-21-03.). IRN W2750056									Service ATA:27	
	MOS/MSC	03-Apr-12	N/A						N/A BY PART NUMBER		
	HRS	338.5									
	AFL	277									
PROC. REF: AMM 12-21-03, AMM 27-50-06											
5-19-01-AA2760021-LEFT	LEFT SPOILER HYDRAULIC PRESSURE SWIVEL - REPLACE									Service ATA:27	
	MOS	10-Oct-19	TSN 0								
	HRS	1509.8	1200 (+25/-25)	TSN 0	2709.8	2734.8	1034.8 (+25)				
	AFL	1201	TSN 0								
PROC. REF: GENERIC NO REF											
5-19-01-AA2760021-LEFT	LEFT SPOILER HYDRAULIC RETURN SWIVEL - REPLACE									Service ATA:27	
	MOS	10-Oct-19	TSN 0								
	HRS	1509.8	1200 (+25/-25)	TSN 0	2709.8	2734.8	1034.8 (+25)				
	AFL	1201	TSN 0								
PROC. REF: GENERIC NO REF											

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 27 - FLIGHT CONTROLS											
5-19-01-AA2760021- RIGHT		RIGHT SPOILER HYDRAULIC PRESSURE SWIVEL - REPLACE								Service	ATA:27
	MOS	10-Oct-19		TSN 0							
	HRS	1509.8	1200 (+ 25/-25)	TSN 0	2709.8	2734.8	1034.8 (+ 25)				
	AFL	1201		TSN 0							
PROC. REF: GENERIC NO REF											
5-19-01-AA2760021- RIGHT		RIGHT SPOILER HYDRAULIC RETURN SWIVEL - REPLACE								Service	ATA:27
	MOS	10-Oct-19		TSN 0							
	HRS	1509.8	1200 (+ 25/-25)	TSN 0	2709.8	2734.8	1034.8 (+ 25)				
	AFL	1201		TSN 0							
PROC. REF: GENERIC NO REF											
5-19-01-R2710041		REPLACE * AILERON SPINDLE (P/N 4527102103-001). (IRN R2710041)								Service	ATA:27
	MOS/MSC	20-Jan-11	N/A					NOT APPLICABLE			
	HRS	0									
	AFL	0									
PROC. REF: AMM 27-10-07											
5-19-01-W2750055		* FLAP ACTUATOR JOINT (P/N 145673-1) (IRN W2750055) REPLACEMENT								Component	ATA:27
PN:159174-1	MOS/MSC	20-Jan-11	N/A	TSN 0				NOT APPLICABLE			
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 27-50-06											
A2711001 ^S		** AILERON TRIM TAB CONTROL SYSTEM - PERFORM OPERATIONAL CHECK								Service	ATA:27
	MOS	20-Jan-23	24 (+ 14d/-14d)					AIRWORTHINESS			
	HRS	1675	600 (+ 25/-25)								
	AFL	1330									
PROC. REF: AMM 27-10-04											
A2721001 ^S		** RUDDER TRIM SYSTEM - PERFORM OPERATIONAL CHECK								Service	ATA:27
	MOS	20-Jan-23	24 (+ 14d/-14d)					AIRWORTHINESS			
	HRS	1675	600 (+ 25/-25)								
	AFL	1330									
PROC. REF: AMM 27-20-00											

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 27 - FLIGHT CONTROLS											
A2731002 ^S			** ELEVATOR DISCONNECT SYSTEM - PERFORM OPERATIONAL CHECK							Service	ATA:27
	MOS	20-Jan-23	24 (+ 14d/-14d)					AIRWORTHINESS			
	HRS	1675	600 (+ 25/-25)								
	AFL	1330									
					PROC. REF: AMM 27-30-00					PKG:8	
A2760001 ^S			** SPOILER ACTUATOR CHECK VALVE - PERFORM OPERATIONAL CHECK							Service	ATA:27
	MOS	20-Jan-23	24 (+ 14d/-14d)					AIRWORTHINESS			
	HRS	1675	600 (+ 25/-25)								
	AFL	1330									
					PROC. REF: AMM 27-60-04					PKG:10	
A2760002 ^S			** SPOILER SYSTEM - PERFORM SPOILER AUTHORITY WITH FLAPS CHECK							Service	ATA:27
	MOS	20-Jan-23	24 (+ 14d/-14d)					AIRWORTHINESS			
	HRS	1675	600 (+ 25/-25)								
	AFL	1330									
					PROC. REF: AMM 27-60-00					PKG:10	
AA2700000 ^S			AILERON CONTROL CABLE SYSTEM - WITH COCKPIT AND CABIN FLOORBOARDS REMOVED, PERFORM VISUAL INSPECTION OF ACCESSIBLE CABLES							Service	ATA:27
	MOS	20-Jan-23	24 (+ 14d/-14d)								
	HRS	1675	600 (+ 25/-25)								
	AFL	1330									
					PROC. REF: AMM 27-00-00					PKG:7	
AA2700001 ^S			RUDDER CONTROL CABLE SYSTEM - WITH COCKPIT AND CABIN FLOORBOARDS REMOVED, PERFORM VISUAL INSPECTION OF ACCESSIBLE CABLES							Service	ATA:27
	MOS	20-Jan-23	24 (+ 14d/-14d)								
	HRS	1675	600 (+ 25/-25)								
	AFL	1330									
					PROC. REF: AMM 27-00-00					PKG:7	
AA2700002 ^S			ELEVATOR CONTROL CABLE SYSTEM - WITH COCKPIT AND CABIN FLOORBOARDS REMOVED, PERFORM VISUAL INSPECTION OF ACCESSIBLE CABLES							Service	ATA:27
	MOS	20-Jan-23	24 (+ 14d/-14d)								
	HRS	1675	600 (+ 25/-25)								
	AFL	1330									
					PROC. REF: AMM 27-00-00					PKG:7	

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 27 - FLIGHT CONTROLS											
G2710003 ^S			PERFORM AILERON CONTROL SYSTEM CABLES (LOCATED IN WING AREA) - CABLE TENSION CHECK.							Service	ATA:27
	MOS	20-Jan-23	48 (+ 14d/-14d)								
	HRS	1675	1200 (+ 25/-25)								
	AFL	1330									
					PROC. REF: AMM 27-10-00					PKG:16	
G2710004 ^S			PERFORM AILERON CONTROL SYSTEM CABLES (LOCATED IN FUSELAGE AREA) - CABLE TENSION CHECK.							Service	ATA:27
	MOS	20-Jan-23	48 (+ 14d/-14d)								
	HRS	1675	1200 (+ 25/-25)								
	AFL	1330									
					PROC. REF: AMM 27-10-00					PKG:13	
G2720003 ^S			PERFORM RUDDER CONTROL CABLES - TENSION CHECK.							Service	ATA:27
	MOS	20-Jan-23	48 (+ 14d/-14d)								
	HRS	1675	1200 (+ 25/-25)								
	AFL	1330									
					PROC. REF: AMM 27-20-00					PKG:14	
G2720004 ^S			PERFORM RUDDER PEDALS, PEDAL PUSHRODS, ADJUSTMENT ACTUATOR, AND SECTORS - VISUAL INSPECTION. CHECK DURING FULL TRAVEL OF RUDDER.							Service	ATA:27
	MOS	20-Jan-23	48 (+ 14d/-14d)								
	HRS	1675	1200 (+ 25/-25)								
	AFL	1330									
					PROC. REF: AMM 05-10-00					PKG:13	
G2730003 ^S			PERFORM ELEVATOR CONTROL CABLES - TENSION CHECK.							Service	ATA:27
	MOS	20-Jan-23	48 (+ 14d/-14d)								
	HRS	1675	1200 (+ 25/-25)								
	AFL	1330									
					PROC. REF: AMM 27-30-00					PKG:14	
V2712000 ^S			** ROLL DISCONNECT SWITCHES - PERFORM OPERATIONAL CHECK.							Service	ATA:27
	MOS	20-Jan-23	24 (+ 25d/-25d)					AIRWORTHINESS			
	HRS	1675	600 (+ 14/-14)								
	AFL	1330									
					PROC. REF: AMM 27-60-09					PKG:7	
W2731001 ^S			** PITCH TRIM - PERFORM OPERATIONAL CHECK OF ELEVATOR OVERRIDE ACTUATOR							Service	ATA:27
	MOS	20-Jan-23	24 (+ 14d/-14d)					AIRWORTHINESS			
	HRS	1675	600 (+ 25/-25)								
	AFL	1330									
					PROC. REF: AMM 27-30-14					PKG:8	

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 27 - FLIGHT CONTROLS										
Y2700003 ^S	AILERON CONTROL CABLE SYSTEM - PERFORM VISUAL INSPECTION OF CABLES WITHIN WING									Service ATA:27
	MOS	20-Jan-23	24 (+ 14d/-14d)							
	HRS	1675	600 (+ 25/-25)							
	AFL	1330								
					PROC. REF: AMM 27-00-00					PKG:10
Y2700004 ^S	RUDDER CONTROL CABLE SYSTEM - PERFORM VISUAL INSPECTION OF ACCESSIBLE UPPER AND LOWER CABLES									Service ATA:27
	MOS	20-Jan-23	24 (+ 14d/-14d)							
	HRS	1675	600 (+ 25/-25)							
	AFL	1330								
					PROC. REF: AMM 27-00-00					PKG:8
Y2700005 ^S	ELEVATOR CONTROL CABLE SYSTEM - PERFORM VISUAL INSPECTION OF ACCESSIBLE UPPER AND LOWER CABLES									Service ATA:27
	MOS	20-Jan-23	24 (+ 14d/-14d)							
	HRS	1675	600 (+ 25/-25)							
	AFL	1330								
					PROC. REF: AMM 27-00-00					PKG:8
Y2700006 ^S	RUDDER AND ELEVATOR CONTROL CABLES AND ASSOCIATED PULLEYS, LOCATED IN AFT PRESSURE BULKHEAD SUPPORT CHANNEL - PERFORM VISUAL INSPECTION									Service ATA:27
	MOS	20-Jan-23	24 (+ 14d/-14d)							
	HRS	1675	600 (+ 25/-25)							
	AFL	1330								
					PROC. REF: AMM 27-00-00					PKG:9
Y2710000 ^S	AILERONS, AILERON TRIM TAB AND VISIBLE PORTION OF RODS - PERFORM VISUAL INSPECTION									Service ATA:27
	MOS	20-Jan-23	24 (+ 14d/-14d)							
	HRS	1675	600 (+ 25/-25)							
	AFL	1330								
					PROC. REF: AMM 05-10-00					PKG:10
Y2710001 ^S	PERFORM AILERON BALANCE WEIGHT INSTALLATION AND SUPPORTING STRUCTURE - VISUAL INSPECTION									Service ATA:27
	MOS	20-Jan-23	48 (+ 14d/-14d)							
	HRS	1675	1200 (+ 25/-25)							
	AFL	1330								
					PROC. REF: AMM 05-10-00					PKG:16
Y2710002 ^S	PERFORM AILERON CONTROL SYSTEM - OPERATIONAL CHECK									Service ATA:27
	MOS	20-Jan-23	48 (+ 14d/-14d)							
	HRS	1675	1200 (+ 25/-25)							
	AFL	1330								
					PROC. REF: AMM 27-10-00					PKG:16

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 27 - FLIGHT CONTROLS										
Y2710048 ^S	AILERON TRIM TAB INSTALLATION - PERFORM FREE PLAY CHECK									Service ATA:27
	MOS	11-Sep-18	96 (+ 14d/-14d)							
	HRS	1387.4	2400 (+ 25/-25)							
	AFL	1114								
					PROC. REF: AMM 27-10-04					PKG:22
Y2720000 ^S	RUDDER - PERFORM VISUAL INSPECTION									Service ATA:27
	MOS	20-Jan-23	12 (+ 14d/-14d)							
	HRS	1675	300 (+ 25/-25)							
	AFL	1330								
					PROC. REF: AMM 05-10-00					PKG:2
Y2720001 ^S	PERFORM RUDDER BALANCE WEIGHT INSTALLATION AND SUPPORTING STRUCTURE - VISUAL INSPECTION									Service ATA:27
	MOS	20-Jan-23	48 (+ 14d/-14d)							
	HRS	1675	1200 (+ 25/-25)							
	AFL	1330								
					PROC. REF: AMM 05-10-00					PKG:14
Y2720002 ^S	PERFORM RUDDER CONTROL SYSTEM - OPERATIONAL CHECK									Service ATA:27
	MOS	20-Jan-23	48 (+ 14d/-14d)							
	HRS	1675	1200 (+ 25/-25)							
	AFL	1330								
					PROC. REF: AMM 27-20-00					PKG:14
Y2721000 ^S	RUDDER TRIM TAB AND VISIBLE RODS - PERFORM VISUAL INSPECTION. NOTE: ON AIRCRAFT 45-005 THRU 45-364 NOT MODIFIED BY SB 45-27-34 AND AIRCRAFT 45-005 THRU 45-428 NOT MODIFIED PER SB 45-27-37, REPLACE THE RUDDER TRIM TAB HINGE LOWER COTTER PIN DURING THIS INSPECTION.									Service ATA:27
	MOS	20-Jan-23	12 (+ 14d/-14d)							
	HRS	1675	300 (+ 25/-25)							
	AFL	1330								
					PROC. REF: AMM 05-10-00					PKG:2
Y2730000 ^S	PERFORM CONTROL COLUMNS - VISUAL INSPECTION. PAY PARTICULAR ATTENTION TO AILERON CONTROL WHEEL CABLE DRUM AND BOTTOM CROSSOVER PULLEYS									Service ATA:27
	MOS	20-Jan-23	48 (+ 14d/-14d)							
	HRS	1675	1200 (+ 25/-25)							
	AFL	1330								
					PROC. REF: AMM 05-10-00					PKG:13

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 27 - FLIGHT CONTROLS										
Y2730001 ^S	ELEVATORS - PERFORM VISUAL INSPECTION									Service ATA:27
	MOS	20-Jan-23	12 (+ 14d/-14d)							
	HRS	1675	300 (+ 25/-25)							
	AFL	1330								
					PROC. REF: AMM 05-10-00					PKG:2
Y2730002 ^S	PERFORM ELEVATOR CONTROL SYSTEM - OPERATIONAL CHECK									Service ATA:27
	MOS	20-Jan-23	48 (+ 14d/-14d)							
	HRS	1675	1200 (+ 25/-25)							
	AFL	1330								
					PROC. REF: AMM 27-30-00					PKG:14
Y2730004 ^S	PERFORM CONTROL COLUMNS - INSPECTION. INSPECT CABLE, PULLEYS, BEARINGS, AND ELECTRICAL WIRING									Service ATA:27
	MOS	11-Sep-18	96 (+ 14d/-14d)							
	HRS	1387.4	2400 (+ 25/-25)							
	AFL	1114								
					PROC. REF: AMM 27-00-00					PKG:19
Y2730007 ^S	PERFORM AFT ELEVATOR DISCONNECT - DETAILED VISUAL INSPECTION									Service ATA:27
	MOS	11-Sep-18	96 (+ 14d/-14d)							
	HRS	1387.4	2400 (+ 25/-25)							
	AFL	1114								
					PROC. REF: AMM 05-10-00					PKG:20
Y2740000 ^S	PERFORM PRIMARY PITCH TRIM SYSTEM - OPERATIONAL CHECK									Service ATA:27
	MOS	20-Jan-23	48 (+ 14d/-14d)							
	HRS	1675	1200 (+ 25/-25)							
	AFL	1330								
					PROC. REF: AMM 27-40-00					PKG:14
Y2740001 ^S	PERFORM SECONDARY PITCH TRIM SYSTEM - OPERATIONAL CHECK									Service ATA:27
	MOS	20-Jan-23	48 (+ 14d/-14d)							
	HRS	1675	1200 (+ 25/-25)							
	AFL	1330								
					PROC. REF: AMM 27-40-00					PKG:14
Y2750000 ^S	FLAP DRIVE INSTALLATION - PERFORM VISUAL INSPECTION WITH FLAPS LOWERED									Service ATA:27
	MOS	20-Jan-23	24 (+ 14d/-14d)							
	HRS	1675	600 (+ 25/-25)							
	AFL	1330								
					PROC. REF: AMM 05-10-00					PKG:10

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty
---------	------	------	----------	-----------	--------------------------	-----------	-----------	-------------	-----	----------

ATA 27 - FLIGHT CONTROLS

Y2750001 ^S	FLAPS - PERFORM VISUAL INSPECTION								Service	ATA:27
	MOS	20-Jan-23	12 (+ 14d/-14d)							
	HRS	1675	300 (+ 25/-25)							
	AFL	1330								
PROC. REF: AMM 05-10-00										PKG:4

Y2750053 ^S	FLAP DRIVE ACTUATORS - PERFORM A VISUAL INSPECTION OF THE ACTUATOR ATTACHMENT, PAYING PARTICULAR ATTENTION TO THE GIMBAL PIN RETAINING RINGS								Service	ATA:27
	MOS	20-Jan-23	24 (+ 14d/-14d)							
	HRS	1675	600 (+ 25/-25)							
	AFL	1330								
PROC. REF: AMM 05-10-00										PKG:10

Y2760000 ^S	SPOILER AND SPOILER ACTUATOR - PERFORM VISUAL INSPECTION WITH FLAPS LOWERED AND ACCESS PANELS OPENED								Service	ATA:27
	MOS	20-Jan-23	24 (+ 14d/-14d)							
	HRS	1675	600 (+ 25/-25)							
	AFL	1330								
PROC. REF: AMM 05-10-00										PKG:10

ATA 28 - FUEL

281001	LEFT NO. 1 FUEL, EJECTOR SCAVENGE PUMP								Component	ATA:28
PN:HTE230008	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:44091878	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 28-12-01										

281002	RIGHT NO. 1 FUEL, EJECTOR SCAVENGE PUMP								Component	ATA:28
PN:HTE230008	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:44091873	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 28-12-01										

281003	LEFT NO. 2 FUEL, EJECTOR SCAVENGE PUMP								Component	ATA:28
PN:HTE230008	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:44091877	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 28-12-01										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 28 - FUEL										
281004	RIGHT NO. 2 FUEL, EJECTOR SCAVENGE PUMP									Component ATA:28
PN:HTE230008	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:44091872	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 28-12-01										
281005	LEFT NO. 3 FUEL, EJECTOR SCAVENGE PUMP									Component ATA:28
PN:HTE230008	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:44091876	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 28-12-01										
281006	RIGHT NO. 3 FUEL, EJECTOR SCAVENGE PUMP									Component ATA:28
PN:HTE230008	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:44091871	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 28-12-01										
281007	LEFT NO. 4 FUEL, EJECTOR SCAVENGE PUMP									Component ATA:28
PN:HTE230008	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:44091875	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 28-12-01										
281008	RIGHT NO. 4 FUEL, EJECTOR SCAVENGE PUMP									Component ATA:28
PN:HTE230008	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:11091869	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 28-12-01										
281009	LEFT NO. 5 FUEL, EJECTOR SCAVENGE PUMP									Component ATA:28
PN:HTE230008	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:44091874	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 28-12-01										
281010	RIGHT NO. 5 FUEL, EJECTOR SCAVENGE PUMP									Component ATA:28
PN:HTE230008	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:44091867	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 28-12-01										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 28 - FUEL										
281031	FUEL, FUSELAGE CELL									Component ATA:28
PN:506877	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:106553	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 28-10-02										
281051	FUEL CROSSFLOW SHUTOFF VALVE									Component ATA:28
PN:6628200101-003	MOS/MSC	23-Jul-16	O/C	TSR 3						
SN:0139	HRS	1077.5		TSR 0						
	AFL	918		TSR 0						
PROC. REF: AMM 28-12-02										
281401	SURGE TANK FLOAT VALVE									Component ATA:28
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 28-11-02										
281501	LEFT FLEX FUEL HOSE ASSY									Component ATA:28
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
281502	RIGHT FLEX FUEL HOSE ASSY									Component ATA:28
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
281521	LEFT FUEL TRANSFER CHECK VALVE									Component ATA:28
PN:HTE460072	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:15091009	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 28-12-03										
281522	RIGHT FUEL TRANSFER CHECK VALVE									Component ATA:28
PN:HTE460072	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:15091005	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 28-12-03										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 28 - FUEL											
282001		LEFT FUEL SHUTOFF VALVE								Component	ATA:28
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 28-20-06											
282003		RIGHT FUEL SHUTOFF VALVE								Component	ATA:28
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 28-20-06											
282011		SHUTOFF - REFUEL VALVE								Component	ATA:28
PN:HTE980056-2	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:64081368	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 28-20-10											
282031		LEFT NO. 1 FUEL SUPPLY CHECK VALVE								Component	ATA:28
PN:HTE460071	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:15091023	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 28-20-03											
282032		LEFT NO. 2 FUEL SUPPLY CHECK VALVE								Component	ATA:28
PN:HTE460071	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:6090205	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 28-20-03											
282033		RIGHT NO. 1 FUEL SUPPLY CHECK VALVE								Component	ATA:28
PN:HTE460071	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:1591018	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 28-20-03											
282034		RIGHT NO. 2 FUEL SUPPLY CHECK VALVE								Component	ATA:28
PN:HTE460071	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:15091026	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 28-20-03											

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 28 - FUEL										
282037 RIGHT FUEL SUPPLY SHUT-OFF (L10) VALVE ASSEMBLY Component ATA:28										
PN:EM91-102-2	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:2072	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 28-20-06										
282038 LEFT FUEL SUPPLY SHUT-OFF (L11) VALVE ASSEMBLY Component ATA:28										
PN:EM91-102-2	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:2161	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 28-20-06										
282041 CONTROL - REFUELING PANEL Component ATA:28										
PN:10550P04Y00	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:09031095BA	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 28-20-14										
282051 LEFT CHECK, MOTIVE FLOW VALVE Component ATA:28										
PN:6628200106-003	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:44090193	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 28-20-05										
282052 RIGHT CHECK, MOTIVE FLOW VALVE Component ATA:28										
PN:6628200106-003	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:44090186	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 28-20-05										
282063 PRE-CHECK, SPPR VALVE Component ATA:28										
PN:HTE940032-1	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:25090517	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 28-20-12										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 28 - FUEL											
282064		PILOT, SPPR VALVE								Component	ATA:28
PN:61087-2	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:588	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 28-20-11											
282075		LEFT ASSEMBLY, FUEL MAIN EJECTOR PUMP								Component	ATA:28
PN:HTE230009	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:36090278	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 28-20-01											
282076		RIGHT ASSEMBLY, FUEL MAIN EJECTOR PUMP								Component	ATA:28
PN:HTE230009	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:36090274	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 28-20-01											
282087		LEFT FUEL, STANDBY PUMP								Component	ATA:28
PN:1C12-39	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:1BE11	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 28-20-02											
282088		RIGHT FUEL, STANDBY PUMP								Component	ATA:28
PN:1C12-39	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:1BE10	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 28-20-02											
282601		DEFUEL (B24) SHUTOFF VALVE								Component	ATA:28
PN:EM91-102-2	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:2102	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 28-20-07											
282602		REFUEL CHECK VALVE								Component	ATA:28
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 28-20-09											

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 28 - FUEL											
282603		SINGLE POINT PRESSURE REFUELING (SPPR) ADAPTER							Component	ATA:28	
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:UNKNOWN	HRS	0	TSN 0								
	AFL	0	TSN 0								
PROC. REF: GENERIC NO REF											
282815		APU FUEL SHUTOFF VALVE							Component	ATA:28	
PN:7086048-1	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:082203000949CHRS	HRS	0	TSN 0								
	AFL	0	TSN 0								
PROC. REF: AMM 28-20-04											
284001		ASSEMBLY, FUEL C1 PROBE							Component	ATA:28	
PN:10552T01Y00	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:MN24395	HRS	0	TSN 0								
	AFL	0	TSN 0								
PROC. REF: AMM 28-40-05											
284002		FUEL C2 PROBE							Component	ATA:28	
PN:10665T03Y00	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:MN24382	HRS	0	TSN 0								
	AFL	0	TSN 0								
PROC. REF: AMM 28-40-05											
284003		ASSEMBLY, FUEL C3 PROBE							Component	ATA:28	
PN:10552T03Y00	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:MN24164	HRS	0	TSN 0								
	AFL	0	TSN 0								
PROC. REF: AMM 28-40-05											
284004		ASSEMBLY, FUEL C4 PROBE							Component	ATA:28	
PN:10552T04Y00	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:MN23932	HRS	0	TSN 0								
	AFL	0	TSN 0								
PROC. REF: AMM 28-40-05											
284005		ASSEMBLY, FUEL C5 PROBE							Component	ATA:28	
PN:10552T05Y00	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:24153	HRS	0	TSN 0								
	AFL	0	TSN 0								
PROC. REF: AMM 28-40-05											

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 28 - FUEL											
284006		ASSEMBLY, FUEL C6 PROBE								Component	ATA:28
PN:10552T06Y00	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:MN24018	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 28-40-05											
284008		FUEL C8 PROBE								Component	ATA:28
PN:10552T01Y00	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:MN24387	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 28-40-05											
284009		ASSEMBLY, FUEL C9 PROBE								Component	ATA:28
PN:10665T03Y00	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:MN23894	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 28-40-05											
284010		ASSEMBLY, FUEL C10 PROBE								Component	ATA:28
PN:10552T03Y00	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:MN24159	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 28-40-05											
284011		ASSEMBLY, FUEL C11 PROBE								Component	ATA:28
PN:10552T04Y00	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:MN23148	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 28-40-05											
284012		ASSEMBLY, FUEL C12 PROBE								Component	ATA:28
PN:10552T05Y00	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:23770	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 28-40-05											
284013		ASSEMBLY, FUEL C13 PROBE								Component	ATA:28
PN:10552T06Y00	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:MN23807	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 28-40-05											

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 28 - FUEL											
284014		ASSEMBLY, FUEL C14 PROBE								Component	ATA:28
PN:10552T06Y00	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:MN22341	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 28-40-05											
284015		FUEL C15 PROBE								Component	ATA:28
PN:10665T01Y00	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:MN24265	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 28-40-05											
284016		ASSEMBLY, FUEL C16 PROBE								Component	ATA:28
PN:10552T06Y00	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:22016	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 28-40-05											
284017		FUEL C17 PROBE								Component	ATA:28
PN:10665T01Y00	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:MN23898	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 28-40-05											
284033		FUSELAGE FUEL PROBE								Component	ATA:28
PN:10554T02Y00	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:DTB3237	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 28-40-05											
284035		NO. 1 FUEL, LOW PRESSURE (S21) SWITCH								Component	ATA:28
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 28-40-01											
284036		NO. 2 FUEL, LOW PRESSURE (S21) SWITCH								Component	ATA:28
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 28-40-01											

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 28 - FUEL										
284041	LEFT FLOAT, FUEL (S19 & S20) SWITCH									Component ATA:28
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 28-40-02										
284042	RIGHT FLOAT, FUEL (S19 & S20) SWITCH									Component ATA:28
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 28-40-02										
284045	FUEL QUANTITY SIGNAL CONDITIONER									Component ATA:28
PN:10551B08Y09	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:1136	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 28-40-04										
284047	LEFT FUEL, LOW LEVEL SENSOR									Component ATA:28
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 28-40-03										
284048	RIGHT FUEL, LOW LEVEL SENSOR									Component ATA:28
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 28-40-03										
5-19-00-D2820013	PERFORM INITIAL CLEANING AND LEAK CHECK OF LOW PRESSURE FUEL FILTERS. (NEW AIRCRAFT 50-FLIGHT HOUR CHECK) (ZONE/ACCESS 510AL IRN # D2820013)									Service ATA:28
	MOS/MSC	12-Mar-11	A/R							
	HRS	42.8								
	AFL	31								
PROC. REF: AMM 28-20-15										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 28 - FUEL											
5-19-00-H2840001			* DUAL FUEL FLOW CONVERTOR (DFFC) (P/N 10540B06F07) - PERFORM ACCEPTANCE TEST AND LOW TEMPERATURE SCREENING (IRN H2840001)						Service	ATA:28	
	MOS/MSC	20-Jan-11	N/A					NOT INSTALLED			
	HRS	0									
	AFL	0									
PROC. REF: GENERIC NO REF											
F2840003 ^S			PERFORM ** FUEL QUANTITY SIGNAL CONDITIONER - FUNCTIONAL TEST TO VERIFY WEIGHT-ON-WHEELS (WOW) INPUTS. (EFFECTIVE ON AIRCRAFT 45-005 THRU 45-194 POST SB 45-28-5 AND 45-195 AND SUBSEQUENT.)						Service	ATA:28	
	MOS	20-Jan-23	48 (+ 14d/-14d)					AIRWORTHINESS			
	HRS	1675	1200 (+ 25/-25)								
	AFL	1330									
PROC. REF: AMM 28-40-00											
PKG:14											
Y2810001 ^S			WING TANKS - REMOVE FUEL TANK ACCESS PANELS AND PERFORM VISUAL INSPECTION						Service	ATA:28	
	MOS	20-Jan-23	24 (+ 14d/-14d)								
	HRS	1675	600 (+ 25/-25)								
	AFL	1330									
PROC. REF: AMM 05-10-00											
PKG:10											
Y2810002 ^S			PERFORM WING TANKS - REMOVE FUEL TANK ACCESS PANELS AND PERFORM VISUAL INSPECTION						Service	ATA:28	
	MOS	11-Sep-18	96 (+ 14d/-14d)								
	HRS	1387.4	2400 (+ 25/-25)								
	AFL	1114									
PROC. REF: AMM 05-10-00											
PKG:22											
Y2820000 ^S			LOW PRESSURE FUEL FILTER - REMOVE AND INSPECT FOR CONTAMINATION. CLEAN IF NECESSARY						Service	ATA:28	
	MOS	20-Jan-23	24 (+ 14d/-14d)								
	HRS	1675	600 (+ 25/-25)								
	AFL	1330									
PROC. REF: AMM 28-20-15											
PKG:10											
ATA 29 - HYDRAULIC POWER											
291001			HYDRAULIC RESERVOIR						Component	ATA:29	
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN	0						
SN:UNKNOWN	HRS	0		TSN	0						
	AFL	0		TSN	0						
PROC. REF: AMM 29-10-02											

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 29 - HYDRAULIC POWER											
291012		L8 HYDRAULIC SHUTOFF VALVE								Component	ATA:29
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 29-10-05											
291013		L9 HYDRAULIC SHUTOFF VALVE								Component	ATA:29
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 29-10-05											
291033		RESERVOIR PRESSURIZATION CONTROL MODULE								Component	ATA:29
PN:ZVM11-2	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:08-110346	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 29-10-06											
291034		RESERVOIR FLUID LEVEL SENSOR								Component	ATA:29
PN:3L14F-17	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:827	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 29-30-02											
291045		NO. 1 HYDRAULIC, ENGINE DRIVEN PUMP								Component	ATA:29
PN:6629101000-001	MOS/MSC	18-Dec-16	O/C	TSR 0							
SN:MX772022A	HRS	1162		TSR 0							
	AFL	966		TSR 0							
PROC. REF: AMM 29-10-01											
291046		NO. 2 HYDRAULIC, ENGINE DRIVEN PUMP								Component	ATA:29
PN:848888	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:MX732497A	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 29-10-01											
291051		NO. 1 PRESSURE, MAIN HYDRAULIC SYSTEM SWITCH								Component	ATA:29
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 29-30-03											

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 29 - HYDRAULIC POWER										
291052	NO. 2 PRESSURE, MAIN HYDRAULIC SYSTEM SWITCH									Component ATA:29
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 29-30-03										
291057	MAIN HYDRAULIC SYSTEM ACCUMULATOR									Component ATA:29
PN:88746-1	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:573	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 29-10-04										
291059	MAIN HYDRAULIC FILTER MANIFOLD									Component ATA:29
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 29-10-03										
291069	THERMAL SHUTOFF VALVE									Component ATA:29
PN:98050	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:0846	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 29-10-07										
292001	AUXILIARY FILTER MANIFOLD ASSEMBLY									Component ATA:29
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 29-20-02										
292011	AUXILIARY HYDRAULIC PUMP ASSEMBLY									Component ATA:29
PN:6629201000-015	MOS/MSC	21-Jul-17	O/C							
SN:K0622	HRS	1258.2								
	AFL	1031								
PROC. REF: AMM 29-20-01										
292012	AUXILIARY HYDRAULIC PUMP									Component ATA:29
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 29-20-01										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 29 - HYDRAULIC POWER										
292013 AUXILIARY HYDRAULIC PUMP ELECTRIC MOTOR Component ATA:29										
PN:6629201000-011	MOS/MSC	21-Jul-17	O/C	TSO 1						
SN:371A	HRS	1258.2		TSO 0						
	AFL	1031		TSO 0						
PROC. REF: AMM 29-20-04										
292025 AUXILIARY PRESSURE, HYDRAULIC SYSTEM (S29) SWITCH Component ATA:29										
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 29-30-03										
292401 AUXILIARY HUDRAULIC PRESSURE CHECK VALVE Component ATA:29										
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
293001 GROUND SERVICE CONTROL BOX Component ATA:29										
PN:4529308000-013	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:AS0304	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 29-30-01										
293003 LEFT HYDRAULIC LOW (S8, S9) PRESSURE SWITCH Component ATA:29										
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 29-30-03										
293004 RIGHT HYDRAULIC LOW (S8, S9) PRESSURE SWITCH Component ATA:29										
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 29-30-03										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty
---------	------	------	----------	-----------	--------------------------	-----------	-----------	-------------	-----	----------

ATA 29 - HYDRAULIC POWER

293011	HYDRAULIC PRESSURE TRANSDUCER								Component	ATA:29
PN:APTE-196-1000-4000A	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:7470-4-123	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 29-30-04										

5-19-01-D2910017	REPLACE MAIN HYDRAULIC FILTER MANIFOLD ELEMENTS (D2910017)								Service	ATA:29
	MOS/MSC	20-Jan-11	-							
	HRS	0								
	AFL	0								
PROC. REF: AMM 29-10-03										

5-19-01-D2910018	REPLACE MAIN HYDRAULIC FILTER MANIFOLD ELEMENTS (D2910018)								Service	ATA:29
	MOS	08-Nov-21								
	HRS	1605.6	300 (+ 25/-25)	1905.6	1930.6	230.6 (+ 25)				
	AFL	1281								
PROC. REF: AMM 29-10-03										

5-19-01-O2910005	REPLACE AUXILIARY HYDRAULIC FILTER MANIFOLD ELEMENTS. (REFER TO 29-20-02.) (IRN # O2910005)								Service	ATA:29
	MOS	20-Jan-11								
	HRS	0	2400 (+ 25/-25)	2400	2425	725 (+ 25)				
	AFL	0								
PROC. REF: AMM 29-20-02										

H2920002 ^S	PERFORM HYDRAULIC SYSTEM GROUND SERVICE LEDS - FUNCTIONAL TEST. (EFFECTIVE ON AIRCRAFT 45-005 THRU 45-194 PRE SB 45-29-6.)								Service	ATA:29
	MOS	20-Jan-23	48 (+ 14d/-14d)							
	HRS	1675	1200 (+ 25/-25)							
	AFL	1330								
PROC. REF: AMM 29-30-00										

T2910026 ^S	PERFORM RELIEF FUNCTION OF THE HYDRAULIC RESERVOIR PRESSURIZATION CONTROL MODULE - FUNCTIONAL TEST.								Service	ATA:29
	MOS	20-Jan-23	48 (+ 14d/-14d)							
	HRS	1675	1200 (+ 25/-25)							
	AFL	1330								
PROC. REF: AMM 29-10-06										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty
---------	------	------	----------	-----------	--------------------------	-----------	-----------	-------------	-----	----------

ATA 29 - HYDRAULIC POWER

Y2910001 ^S	PERFORM HYDRAULIC COMPONENTS AND ASSOCIATED PLUMBING (AFT OF FUSELAGE FUEL CELL, FS 495 TO FS 512) - VISUAL INSPECTION.								Service	ATA:29
	MOS	20-Jan-23	48 (+ 14d/-14d)							
	HRS	1675	1200 (+ 25/-25)							
	AFL	1330								
PROC. REF: AMM 05-10-00										PKG:14

Y2910002 ^S	PERFORM HYDRAULIC COMPONENTS AND ASSOCIATED PLUMBING (WHEEL WELL AND FORWARD AREA OF REAR SPAR) - VISUAL INSPECTION								Service	ATA:29
	MOS	20-Jan-23	48 (+ 14d/-14d)							
	HRS	1675	1200 (+ 25/-25)							
	AFL	1330								
PROC. REF: AMM 05-10-00										PKG:17

Y2910003 ^S	PERFORM HYDRAULIC COMPONENTS AND ASSOCIATED PLUMBING (AFT AREA OF REAR SPAR) - VISUAL INSPECTION								Service	ATA:29
	MOS	11-Sep-18	96 (+ 14d/-14d)							
	HRS	1387.4	2400 (+ 25/-25)							
	AFL	1114								
PROC. REF: AMM 05-10-00										PKG:19

Y2920001 ^S	PERFORM AUXILIARY HYDRAULIC SYSTEM - OPERATIONAL CHECK								Service	ATA:29
	MOS	20-Jan-23	48 (+ 14d/-14d)							
	HRS	1675	1200 (+ 25/-25)							
	AFL	1330								
PROC. REF: AMM 29-20-00										PKG:13

ATA 30 - ICE AND RAIN PROTECTION

301006	RELAY (P40) - ANTI-ICE VERTICAL STABILIZER. PANEL ASSY								Component	ATA:30
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN	0					
SN:UNKNOWN	HRS	0		TSN	0					
	AFL	0		TSN	0					
PROC. REF: AMM 30-10-06										

301010	LEFT HORIZONTAL STABILIZER CONTROL (MT47) SENSOR								Component	ATA:30
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN	0					
SN:UNKNOWN	HRS	0		TSN	0					
	AFL	0		TSN	0					
PROC. REF: AMM 30-10-05										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 30 - ICE AND RAIN PROTECTION										
301011 RIGHT HORIZONTAL STABILIZER CONTROL (MT46) SENSOR Component ATA:30										
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 30-10-05										
301051 LEFT CHECK, ANTI-ICE (2.0 DIAMETER) VALVE Component ATA:30										
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 30-10-02										
301052 RIGHT CHECK, ANTI-ICE (2.0 DIAMETER) VALVE Component ATA:30										
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 30-10-02										
301063 LEFT ANTI-ICE PRESSURE REGULATING SHUTOFF (PRSOV L12) VALVE Component ATA:30										
PN:3215616-2	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:1342	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 30-10-01										
301064 RIGHT ANTI-ICE PRESSURE REGULATING SHUTOFF (PRSOV L13) VALVE Component ATA:30										
PN:3215616-2	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:1344	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 30-10-01										
301065 LEFT SHUTTLE, ANTI-ICE VALVE Component ATA:30										
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 30-10-08										
301066 RIGHT SHUTTLE, ANTI-ICE VALVE Component ATA:30										
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 30-10-08										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty
---------	------	------	----------	-----------	--------------------------	-----------	-----------	-------------	-----	----------

ATA 30 - ICE AND RAIN PROTECTION

301240 ANTI-ICE MANIFOLD ASSEMBLY										Component	ATA:30
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 30-10-07											
301401 RH WING OUTBD TUBE ASSEM (ANTI-ICE) CHANGE										Component	ATA:30
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: GENERIC NO REF											
301601 LH ANTI-ICE TUBE ASSEMBLY										Component	ATA:30
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: GENERIC NO REF											
301602 RH ANTI-ICE TUBE ASSEMBLY										Component	ATA:30
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: GENERIC NO REF											
301603 L/H SLIDE, FLEX, JOINT										Component	ATA:30
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: GENERIC NO REF											
301604 STAB, ANTI-ICE ELBOW DUCT										Component	ATA:30
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: GENERIC NO REF											
301605 ANTI-ICE DUCT ASSEMBLY										Component	ATA:30
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: GENERIC NO REF											

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 30 - ICE AND RAIN PROTECTION										
301606	R/H FLEX, SLIDE JOINT									Component ATA:30
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
302001	NO. 1 NACELLE INLET ANTI-ICE SHUTOFF VALVE									Component ATA:30
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 30-20-01										
302002	NO. 2 NACELLE INLET ANTI-ICE SHUTOFF VALVE									Component ATA:30
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 30-20-01										
302013	NO. 1 NACELLE ANTI-ICE PRESSURE SWITCH									Component ATA:30
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 30-20-02										
302014	NO. 2 NACELLE ANTI-ICE PRESSURE SWITCH									Component ATA:30
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 30-20-02										
303501	LEFT NOSE RELAY (P15) BOX									Component ATA:30
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 30-30-01										
303510	RIGHT NOSE RELAY (P16) BOX									Component ATA:30
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 30-30-01										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 30 - ICE AND RAIN PROTECTION											
304021		WINDSHIELD ANTI-ICE CONTROLLER								Component	ATA:30
PN:90825-7	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:630	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 30-40-01											
304060		NO. 1 WING SURFACE TEMPERATURE (MT42) SENSOR								Component	ATA:30
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 30-10-03											
304061		NO. 2 WING SURFACE TEMPERATURE (MT43) SENSOR								Component	ATA:30
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 30-10-03											
304062		NO. 3 WING SURFACE TEMPERATURE (MT44) SENSOR								Component	ATA:30
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 30-10-03											
304063		NO. 4 WING SURFACE TEMPERATURE (MT45) SENSOR								Component	ATA:30
PN:6621000000-057	MOS/MSC	24-Apr-12	O/C								
SN:071C-3668	HRS	345.5									
	AFL	283									
PROC. REF: AMM 30-10-03											
308005		ICE DETECTION PROBE								Component	ATA:30
PN:0871HN2	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:0579	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 30-80-01											
5-19-00-AC3010006		BORESCOPE INSPECTION ANTI-ICE MANIFOLD ASSEMBLY. (ZONE/ACCESS 300 **IRN # AC3010006). REFER TO 30-10-07.								Service	ATA:30
	MOS	16-Dec-16									
	HRS	1162	600 (+ 25/-25)	1762	1787	87 (+ 25)					
	AFL	966									
PROC. REF: AMM 30-10-07											

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 30 - ICE AND RAIN PROTECTION										
5-19-00-Z3020005-LEFT	LEFT * ENGINE INLET ANTI-ICE TUBE ASSEMBLY FROM THE AFT INLET BULKHEAD CONNECTION POINT FORWARD TO SPRAY RING CONNECTION, PERFORM DETAILED VISUAL/BORESCOPE INSPECTION OF THE WELDS INSIDE AND OUTSIDE OF THE TUBE AT BOTH FORWARD AND AFT ENDS.								Service	ATA:30
MOS	08-Nov-21							AIRWORTHINESS		
HRS	1605.6		250		1855.6		180.6			
AFL	1281									
PROC. REF: AMM 30-20-00										
5-19-00-Z3020005-RIGHT	RIGHT * ENGINE INLET ANTI-ICE TUBE ASSEMBLY FROM THE AFT INLET BULKHEAD CONNECTION POINT FORWARD TO SPRAY RING CONNECTION, PERFORM DETAILED VISUAL/BORESCOPE INSPECTION OF THE WELDS INSIDE AND OUTSIDE OF THE TUBE AT BOTH FORWARD AND AFT ENDS.								Service	ATA:30
MOS	08-Nov-21							AIRWORTHINESS		
HRS	1605.6		250		1855.6		180.6			
AFL	1281									
PROC. REF: AMM 30-20-00										
5-19-00-Z3020006-LEFT	LEFT ENGINE INLET ANTI-ICE TUBE ASSEMBLY FROM THE AFT INLET BULKHEAD CONNECTION POINT FORWARD TO SPRAY RING CONNECTION, PERFORM DETAILED VISUAL/BORESCOPE INSPECTION OF THE WELDS INSIDE AND OUTSIDE OF THE TUBE AT BOTH FORWARD AND AFT ENDS								Service	ATA:30
MOS/MSC	20-Jan-11		N/A							
HRS	0									
AFL	0									
PROC. REF: GENERIC NO REF										
5-19-00-Z3020006-RIGHT	RIGHT ENGINE INLET ANTI-ICE TUBE ASSEMBLY FROM THE AFT INLET BULKHEAD CONNECTION POINT FORWARD TO SPRAY RING CONNECTION, PERFORM DETAILED VISUAL/BORESCOPE INSPECTION OF THE WELDS INSIDE AND OUTSIDE OF THE TUBE AT BOTH FORWARD AND AFT ENDS								Service	ATA:30
MOS/MSC	20-Jan-11		N/A							
HRS	0									
AFL	0									
PROC. REF: GENERIC NO REF										
A3020000 ^S	PERFORM ** NACELLE ANTI-ICE SYSTEM - FUNCTIONAL TEST								Service	ATA:30
MOS	20-Jan-23		48 (+ 14d/-14d)					AIRWORTHINESS		
HRS	1675		1200 (+ 25/-25)							
AFL	1330									
PROC. REF: AMM 30-20-00										
PKG:15										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 30 - ICE AND RAIN PROTECTION										
A3030000 ^S PERFORM ** PITOT/STATIC HEAT SYSTEM - OPERATIONAL CHECK Service ATA:30										
	MOS	11-Sep-18	96 (+ 14d/-14d)					AIRWORTHINESS		
	HRS	1387.4	2400 (+ 25/-25)							
	AFL	1114								
PROC. REF: AMM 30-30-00										PKG:19
H3010000 ^S ** WING/STAB ANTI-ICE SWITCH - PERFORM OPERATIONAL CHECK Service ATA:30										
	MOS	20-Jan-23	24 (+ 14d/-14d)					AIRWORTHINESS		
	HRS	1675	600 (+ 25/-25)							
	AFL	1330								
PROC. REF: AMM 30-10-00										PKG:7
T3040000 ^S ** PERFORM FUNCTIONAL TEST OF THE WINDSHIELD ANTI-ICE SYSTEM Service ATA:30										
	MOS	20-Jan-23	24 (+ 14d/-14d)					AIRWORTHINESS		
	HRS	1675	600 (+ 25/-25)							
	AFL	1330								
PROC. REF: AMM 30-40-00										PKG:7
Y3010007 ^S WING ANTI-ICE PICCOLO TUBE - PERFORM DETAILED VISUAL INSPECTION FOR CRACKS AT W.S. 43 AND W.S. 176. Service ATA:30										
	MOS	20-Jan-23	24 (+ 14d/-14d)							
	HRS	1675	600 (+ 25/-25)							
	AFL	1330								
PROC. REF: GENERIC NO REF										PKG:10
Y3080000 ^S PERFORM ICE DETECTION SYSTEM - FUNCTIONAL TEST Service ATA:30										
	MOS	20-Jan-23	48 (+ 14d/-14d)							
	HRS	1675	1200 (+ 25/-25)							
	AFL	1330								
PROC. REF: AMM 30-80-00										PKG:13
ATA 31 - INDICATING/ RECORDING SYSTEMS										
311001 PILOT CIRCUIT BREAKER PANEL ASSY Component ATA:31										
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 24-60-01										
311005 COPILOT CIRCUIT BREAKER PANEL ASSY Component ATA:31										
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 24-60-01										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty
---------	------	------	----------	-----------	--------------------------	-----------	-----------	-------------	-----	----------

ATA 31 - INDICATING/ RECORDING SYSTEMS

311601 GEAR UP/DOWN S47 SWITCH Component ATA:31										
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 32-30-02										
311606 PANEL, CENTER SWITCH REPLACE Component ATA:31										
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 31-11-03										
311805 ENGINE FUEL CONTROL (P7) PANEL ASSY Component ATA:31										
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 31-11-05										
311806 ENGINE/FUEL CONTROL PANEL OVERLAY Component ATA:31										
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
311906 FORWARD QUADRANT SWITCH PANEL (P6) OVERLAY Component ATA:31										
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 31-11-04										
311906-1 RUDDER BOOST (DS48) SWITCH Component ATA:31										
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
312001 PILOT CLOCK Component ATA:31										
PN:M850-5V-LA	MOS/MSC	08-Nov-21	O/C	TSN 0						
SN:A8340	HRS	1605.6		TSN 0						
	AFL	1281		TSN 0						
PROC. REF: AMM 31-21-01										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 31 - INDICATING/ RECORDING SYSTEMS											
312002		COPILOT CLOCK								Component	ATA:31
PN:M850-5V-LA	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:A5218	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 31-21-01											
312011		PILOTS DIGITAL CLOCK BATTERY								Component	ATA:31
PN:E-90	MOS	20-Jan-23	12 (+14d/-14d)	TSN 0	20-Jan-24	03-Feb-24	346 d (+14)	LIFE LIMIT			
SN:UNKNOWN	HRS	1675		TSN 0							
	AFL	1330		TSN 0							
PROC. REF: AMM 31-21-02											
312012		COPILOTS DIGITAL CLOCK BATTERY								Component	ATA:31
PN:E-90	MOS	20-Jan-23	12 (+14d/-14d)	TSN 0	20-Jan-24	03-Feb-24	346 d (+14)	LIFE LIMIT			
SN:UNKNOWN	HRS	1675		TSN 0							
	AFL	1330		TSN 0							
PROC. REF: AMM 31-21-02											
312101		LEFT INCLINOMETER ASSEMBLY								Component	ATA:31
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: GENERIC NO REF											
312104		RIGHT INCLINOMETER ASSEMBLY								Component	ATA:31
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: GENERIC NO REF											
313001		FLIGHT DATA RECORDER								Component	ATA:31
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: GENERIC NO REF											
313001A		DOWNLOAD FLIGHT DATA RECORDER								Service	ATA:31
PN:PN	MOS/MSC	20-Jan-11	N/R					CUSTOMER CODE			
SN:UNKNOWN	HRS	0									
	AFL	0									
PROC. REF: GENERIC NO REF											

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty
---------	------	------	----------	-----------	--------------------------	-----------	-----------	-------------	-----	----------

ATA 31 - INDICATING/ RECORDING SYSTEMS

313003 FDR ACCELEROMETER										Component	ATA:31
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: GENERIC NO REF											
313010 HOBBS METER										Component	ATA:31
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: GENERIC NO REF											
313018 INERTIA, FDR SWITCH										Component	ATA:31
PN:PN	MOS/MSC	20-Jan-11	A/R	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: GENERIC NO REF											
314001 SELCAL DECODER										Component	ATA:31
PN:1200006-102	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:2065	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: GENERIC NO REF											
314011 NO. 1 DATA ACQUISITION (DAU) UNIT										Component	ATA:31
PN:7013348-938	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:09036983	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 31-42-01											
314012 NO. 2 DATA ACQUISITION (DAU) UNIT										Component	ATA:31
PN:7013348-938	MOS/MSC	21-Sep-16	O/C	TSR 3							
SN:08056764	HRS	1113.5		TSR 0							
	AFL	941		TSR 0							
PROC. REF: AMM 31-42-01											
314023 NO. 1 INTEGRATED AVIONICS (IC-600) COMPUTER										Component	ATA:31
PN:7017000-82224	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:09038765	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 31-41-01											

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 31 - INDICATING/ RECORDING SYSTEMS										
314024	NO. 2 INTEGRATED AVIONICS (IC-600) COMPUTER									Component ATA:31
PN:7017000-82224	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:09038766	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 31-41-01										
314051	NO. 1 CENTRAL COMPUTING IM-600 MEMORY MODULE									Component ATA:31
PN:7025973-04214	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:07115308	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 31-41-02										
314052	NO. 2 CENTRAL COMPUTING IM-600 MEMORY MODULE									Component ATA:31
PN:7025973-04214	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:08066054	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 31-41-02										
315001	CREW WARNING PANEL ASSEMBLY									Component ATA:31
PN:90-42801-8	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:1068	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 31-51-01										
316001	NO. 1 DU870 DISPLAY UNIT									Component ATA:31
PN:7014300-901	MOS/MSC	25-Apr-12	O/C	TSN 15						
SN:0902J029	HRS	346.3		TSN 346.3						
	AFL	285		TSN 285						
PROC. REF: AMM 31-60-01										
316001-1	PILOT (# 1) MFD CONTROLLER BEZEL									Component ATA:31
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 31-60-01										
316002	NO. 2 DU870 DISPLAY UNIT									Component ATA:31
PN:7014300-901	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:0902J028	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 31-60-01										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 31 - INDICATING/ RECORDING SYSTEMS											
316002-1		PILOT (# 2) MFD CONTROLLER BEZEL								Component	ATA:31
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 31-60-01											
316003		NO. 3 DU870 DISPLAY UNIT								Component	ATA:31
PN:7014300-901	MOS/MSC	25-Apr-12	O/C	TSN 15							
SN:0902J027	HRS	346.3		TSN 346.3							
	AFL	285		TSN 285							
PROC. REF: AMM 31-60-01											
316003-1		COPILOT (# 3) MFD CONTROLLER BEZEL								Component	ATA:31
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 31-60-01											
316004		NO. 4 DU870 DISPLAY UNIT								Component	ATA:31
PN:7014300-901	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:0902J030	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 31-60-01											
316004-1		COPILOT (# 4) MFD CONTROLLER BEZEL								Component	ATA:31
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 31-60-01											
316005		PILOT EFIS DISPLAY CONTROLLER								Component	ATA:31
PN:7016986-733	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:09027505	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 31-60-02											
316006		COPILOT EFIS DISPLAY CONTROLLER								Component	ATA:31
PN:7016986-733	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:09027504	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 31-60-02											

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty
---------	------	------	----------	-----------	--------------------------	-----------	-----------	-------------	-----	----------

ATA 31 - INDICATING/ RECORDING SYSTEMS

316091	DATA TRANSFER, AFIS UNIT								Component	ATA:31
PN:15655-0101	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:1519	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										

B310000 ^S	** INDICATING/RECORDING SYSTEM - PERFORM OPERATIONAL CHECK								Service	ATA:31
	MOS	20-Jan-23	24 (+ 14d/-14d)					AIRWORTHINESS		
	HRS	1675	600 (+ 25/-25)							
	AFL	1330								
PROC. REF: AMM 31-00-00										PKG:7

ATA 32 - LANDING GEAR

320041	* REPLACE LEFT UPPER MAIN LANDING GEAR LINK PIN (P/N 200-0214) IRN N3220101								Component	ATA:32
PN:200-0214-101	MOS	20-Jan-11		TSN 0				LIFE LIMIT		
SN:H2668	HRS	0		TSN 0						
	AFL	0	10000	TSN 0	10000		8670			
PROC. REF: AMM 32-10-01										

320042	* REPLACE RIGHT UPPER MAIN LANDING GEAR LINK PIN (P/N 200-0214) (IRN N3220101)								Component	ATA:32
PN:200-0214-101	MOS	20-Jan-11		TSN 0				LIFE LIMIT		
SN:H2634	HRS	0		TSN 0						
	AFL	0	10000	TSN 0	10000		8670			
PROC. REF: AMM 32-10-01										

320051	* REPLACE LEFT MAIN LANDING GEAR PISTON PIN (P/N 200-0215). (IRN N3220102)								Component	ATA:32
PN:200-0215-101	MOS	20-Jan-11		TSN 0				LIFE LIMIT		
SN:H1285	HRS	0		TSN 0						
	AFL	0	10000	TSN 0	10000		8670			
PROC. REF: AMM 32-10-01										

320052	* REPLACE RIGHT MAIN LANDING GEAR PISTON PIN (P/N 200-0215) (IRN N3220102) ASSEMBLY								Component	ATA:32
PN:200-0215-101	MOS	20-Jan-11		TSN 0				LIFE LIMIT		
SN:H1226	HRS	0		TSN 0						
	AFL	0	10000	TSN 0	10000		8670			
PROC. REF: AMM 32-10-01										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 32 - LANDING GEAR										
320061	* REPLACE LEFT MAIN LANDING GEAR ACTUATOR PISTON (P/N 200-0301) (IRN N3220103) (JAA IRN Q3220065)									Component ATA:32
PN:200-0301-103	MOS		20-Jan-11	TSN 0				LIFE LIMIT		
SN:H2109	HRS		0	TSN 0						
	AFL		0	17000	TSN 0	17000	15670			
PROC. REF: AMM 32-31-01										
320062	* REPLACE RIGHT MAIN LANDING GEAR ACTUATOR PISTON (P/N 200-0301) (IRN N3220103) (JAA IRN Q3220065)									Component ATA:32
PN:200-0301-103	MOS		20-Jan-11	TSN 0				LIFE LIMIT		
SN:H2116	HRS		0	TSN 0						
	AFL		0	17000	TSN 0	17000	15670			
PROC. REF: AMM 32-31-01										
320071	* REPLACE LEFT MAIN LANDING GEAR ACTUATOR CYLINDER (IRN N3220104) (JAA IRN Q3220066)									Component ATA:32
PN:200-0302-101	MOS		20-Jan-11	TSN 0				LIFE LIMIT		
SN:H1620	HRS		0	TSN 0						
	AFL		0	17000	TSN 0	17000	15670			
PROC. REF: AMM 32-31-01										
320072	* REPLACE RIGHT MAIN LANDING GEAR ACTUATOR CYLINDER (IRN N3220104) (JAA IRN Q3220066)									Component ATA:32
PN:200-0302-101	MOS		20-Jan-11	TSN 0				LIFE LIMIT		
SN:H1590	HRS		0	TSN 0						
	AFL		0	17000	TSN 0	17000	15670			
PROC. REF: AMM 32-31-01										
320081	* REPLACE LEFT MAIN LANDING GEAR END CAP (P/N 200-0303) (IRN T3220105) (JAA IRN T3220067)									Component ATA:32
PN:200-0303-001	MOS		20-Jan-11	TSN 0				LIFE LIMIT		
SN:H1606	HRS		0	TSN 0						
	AFL		0	2387	TSN 0	2387	1057			
PROC. REF: AMM 32-31-01										
320082	* REPLACE RIGHT MAIN LANDING GEAR END CAP (P/N 200-0303) (IRN T3220105) (JAA IRN T3220067)									Component ATA:32
PN:200-0303-001	MOS		20-Jan-11	TSN 0				LIFE LIMIT		
SN:H1612	HRS		0	TSN 0						
	AFL		0	2387	TSN 0	2387	1057			
PROC. REF: AMM 32-31-01										
320091	* REPLACE LEFT MAIN LANDING GEAR ACTUATOR HOUSING (P/N 200-0304) (IRN N3220106) (JAA IRN Q3220068)									Component ATA:32
PN:200-0304-001	MOS		20-Jan-11	TSN 0				LIFE LIMIT		
SN:H1639	HRS		0	TSN 0						
	AFL		0	17000	TSN 0	17000	15670			
PROC. REF: AMM 32-31-01										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 32 - LANDING GEAR										
320092	* REPLACE RIGHT MAIN LANDING GEAR ACTUATOR HOUSING (P/N 200-0304) (IRN N3220106) (JAA IRN Q3220068)									Component ATA:32
PN:200-0304-001	MOS		20-Jan-11	TSN 0				LIFE LIMIT		
SN:H1628	HRS		0	TSN 0						
	AFL		0	17000	TSN 0	17000	15670			
PROC. REF: AMM 32-31-01										
321001	* LEFT MAIN LANDING GEAR STRUT (P/N 6632101000, 200-0200) (IRN N3220012) ASSEMBLY									Component ATA:32
PN:200-0200-013	MOS		20-Jan-11	TSN 0				LIFE LIMIT		
SN:H1575	HRS		0	TSN 0						
	AFL		0	10000	TSN 0	10000	8670			
PROC. REF: AMM 32-10-01										
321001A	PERFORM SPECIAL DETAILED INSPECTION ON LEFT MAIN LANDING GEAR SHOCK STRUTS (IRN AA3220018)									Service ATA:32
	MOS		10-Oct-19	96 (+14d/-14d)	10-Oct-27		24-Oct-27	1705 d (+14)		
	HRS		1509.8							
	AFL		1201	6600 (+25/-25)	7801	7826	6471 (+25)			
PROC. REF: GENERIC NO REF										
321002	* RIGHT MAIN LANDING GEAR STRUT (P/N 6632101000, 200-0200) (IRN N3220012) ASSEMBLY									Component ATA:32
PN:200-0200-014	MOS		20-Jan-11	TSN 0				LIFE LIMIT		
SN:H1576	HRS		0	TSN 0						
	AFL		0	10000	TSN 0	10000	8670			
PROC. REF: AMM 32-10-01										
321002A	PERFORM SPECIAL DETAILED INSPECTION ON RIGHT MAIN LANDING GEAR SHOCK STRUTS (IRN AA3220018)									Service ATA:32
	MOS		10-Oct-19	96 (+14d/-14d)	10-Oct-27		24-Oct-27	1705 d (+14)		
	HRS		1509.8							
	AFL		1201	6600 (+25/-25)	7801	7826	6471 (+25)			
PROC. REF: GENERIC NO REF										
321011	* LEFT MAIN LANDING GEAR SHOCK STRUT CYLINDER (IRN'S N3220116, Q3220137, Q3220128)									Component ATA:32
PN:200-0201-109	MOS		20-Jan-11	TSN 0				LIFE LIMIT		
SN:H0691	HRS		0	TSN 0						
	AFL		0	10000	TSN 0	10000	8670			
PROC. REF: AMM 32-10-01										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 32 - LANDING GEAR										
321011A ULTRASONIC-INSPECTION * LEFT MAIN LANDING GEAR SHOCK STRUT CYLINDER (IRN'S N3220116, Q3220137, Q3220128) * MLG SHOCK STRUT CYLINDER. PERFORM ULTRASONIC INSPECTION OF THE LOWER SERVICE PORT AND FORGING PARTING LINE. IRN L3220118, M3220136, P3220146, (JAA IRN L3220122) Service ATA:32										
PN:200-0201-109	MOS		20-Jan-11							
SN:H0691	HRS		0							
	AFL		0	T:4800		4800	3470			
PROC. REF: NDT PART 4/32-10-00, NDT PART 4/32-10-01										
321012 * RIGHT MAIN LANDING GEAR SHOCK STRUT CYLINDER (IRN'S N3220116, Q3220137, Q3220128) Component ATA:32										
PN:200-0201-110	MOS		20-Jan-11	TSN 0				LIFE LIMIT		
SN:H0731	HRS		0	TSN 0						
	AFL		0	10000	TSN 0	10000	8670			
PROC. REF: AMM 32-10-01										
321012A ULTRASONIC-INSPECTION * RIGHT MAIN LANDING GEAR SHOCK STRUT CYLINDER (IRN'S N3220116, Q3220137, Q3220128) * MLG SHOCK STRUT CYLINDER. PERFORM ULTRASONIC INSPECTION OF THE LOWER SERVICE PORT AND FORGING PARTING LINE. IRN L3220118, M3220136, P3220146, (JAA IRN L3220122) Service ATA:32										
PN:200-0201-110	MOS		20-Jan-11							
SN:H0731	HRS		0							
	AFL		0	T:4800		4800	3470			
PROC. REF: NDT PART 4/32-10-00, NDT PART 4/32-10-01										
321025 * LEFT MAIN LANDING GEAR SIDE-STAY ACTUATOR UPPER PIN (P/N 200-0325) ASSEMBLY Component ATA:32										
PN:200-0325-101	MOS		08-Mar-20	96	TSN 0	08-Mar-28	1855 d	LIFE LIMIT		
SN:HER08U5122A	HRS		1550.5		TSN 0					
	AFL		1226		TSN 0					
PROC. REF: AMM 32-31-01										
321025A MAGNETIC PARTICLE INSPECT * LEFT MAIN LANDING GEAR SIDE-STAY ACTUATOR UPPER PIN (P/N 200-0325) ASSEMBLY * (IRN T3220024) Service ATA:32										
PN:200-0325-101	MOS		08-Mar-20	48		08-Mar-24	394 d	AIRWORTHINESS		
SN:HER08U5122A	HRS		1550.5							
	AFL		1226							
PROC. REF: NDT PART 7/32-10-02, NDT PART 7/32-30-01										
321025B DETAILED VISUAL INSPECTION * LEFT MAIN LANDING GEAR SIDE-STAY ACTUATOR UPPER PIN (P/N 200-0325) ASSEMBLY * (IRN T3220135) Service ATA:32										
PN:200-0325-101	MOS		08-Mar-20	48		08-Mar-24	394 d	AIRWORTHINESS		
SN:HER08U5122A	HRS		1550.5							
	AFL		1226							
PROC. REF: AMM 05-10-00										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 32 - LANDING GEAR											
321026		* RIGHT MAIN LANDING GEAR SIDE STAY ACTUATOR UPPER PIN (P/N 200-0325) ASSEMBLY							Component	ATA:32	
PN:200-0325-101	MOS	08-Mar-20	96	TSN 0	08-Mar-28		1855 d	LIFE LIMIT			
SN:HER08U5097A	HRS	1550.5		TSN 0							
	AFL	1226		TSN 0							
PROC. REF: AMM 32-31-01											
321026A		MAGNETIC PARTICLE INSPECT * RIGHT MAIN LANDING GEAR SIDE STAY ACTUATOR UPPER PIN (P/N 200-0325) ASSEMBLY * (IRN T3220024)							Service	ATA:32	
PN:200-0325-101	MOS	08-Mar-20	48		08-Mar-24		394 d	AIRWORTHINESS			
SN:HER08U5097A	HRS	1550.5									
	AFL	1226									
PROC. REF: NDT PART 7/32-10-02, NDT PART 7/32-30-01											
321026B		DETAILED VISUAL INSPECTION * RIGHT MAIN LANDING GEAR SIDE STAY ACTUATOR UPPER PIN (P/N 200-0325) ASSEMBLY * (IRN T3220135)							Service	ATA:32	
PN:200-0325-101	MOS	08-Mar-20	48		08-Mar-24		394 d	AIRWORTHINESS			
SN:HER08U5097A	HRS	1550.5									
	AFL	1226									
PROC. REF: AMM 05-10-00											
321037		* LEFT MAIN LANDING GEAR SIDE-STAY ACTUATOR LOWER PIN (P/N 200-0217) ASSEMBLY							Component	ATA:32	
PN:200-0217-101	MOS	23-Oct-20	96	TSN 0	23-Oct-28		2084 d	LIFE LIMIT			
SN:HER08U5277	HRS	1570.8		TSN 0							
	AFL	1243		TSN 0							
PROC. REF: GENERIC NO REF											
321037A		MAGNETIC PARTICLE INSPECT * LEFT MAIN LANDING GEAR SIDE-STAY ACTUATOR LOWER PIN (P/N 200-0217) ASSEMBLY * (IRN T3220024)							Service	ATA:32	
PN:200-0217-101	MOS	23-Oct-20	48		23-Oct-24		623 d	AIRWORTHINESS			
SN:HER08U5277	HRS	1570.8									
	AFL	1243									
PROC. REF: NDT PART 7/32-10-02, NDT PART 7/32-30-01											
321037B		DETAILED VISUAL INSPECTION * LEFT MAIN LANDING GEAR SIDE-STAY ACTUATOR LOWER PIN (P/N 200-0217) ASSEMBLY * (IRN T3220135)							Service	ATA:32	
PN:200-0217-101	MOS	23-Oct-20	48		23-Oct-24		623 d	AIRWORTHINESS			
SN:HER08U5277	HRS	1570.8									
	AFL	1243									
PROC. REF: AMM 05-10-00											

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 32 - LANDING GEAR											
321038		* RIGHT MAIN LANDING GEAR SIDE-STAY ACTUATOR LOWER PIN (P/N 200-0217) ASSEMBLY								Component	ATA:32
PN:200-0217-101	MOS	23-Oct-20	96	TSN 0	23-Oct-28		2084 d	LIFE LIMIT			
SN:HER08U5262	HRS	1570.8		TSN 0							
	AFL	1243		TSN 0							
PROC. REF: GENERIC NO REF											
321038A		MAGNETIC PARTICLE INSPECT * RIGHT MAIN LANDING GEAR SIDE-STAY ACTUATOR LOWER PIN (P/N 200-0217) ASSEMBLY * (IRN T3220024)								Service	ATA:32
PN:200-0217-101	MOS	23-Oct-20	48		23-Oct-24		623 d	AIRWORTHINESS			
SN:HER08U5262	HRS	1570.8									
	AFL	1243									
PROC. REF: NDT PART 7/32-10-02, NDT PART 7/32-30-01											
321038B		DETAILED VISUAL INSPECTION * RIGHT MAIN LANDING GEAR SIDE-STAY ACTUATOR LOWER PIN (P/N 200-0217) ASSEMBLY * (IRN T3220135)								Service	ATA:32
PN:200-0217-101	MOS	23-Oct-20	48		23-Oct-24		623 d	AIRWORTHINESS			
SN:HER08U5262	HRS	1570.8									
	AFL	1243									
PROC. REF: AMM 05-10-00											
321049		* LEFT MAIN LANDING GEAR AXLE BEAM (P/N 200-0203) (N3220036) ASSEMBLY								Component	ATA:32
PN:200-0203-001	MOS	20-Jan-11		TSN 0				LIFE LIMIT			
SN:H1264	HRS	0		TSN 0							
	AFL	0	10000	TSN 0	10000		8670				
PROC. REF: AMM 32-10-01											
321049A		INSPECTION * LEFT MAIN LANDING GEAR AXLES - PERFORM MAIN LANDING GEAR AXLE BEAM ASSEMBLY BORESCOPE INSPECTION (IRN T3220007)								Service	ATA:32
	MOS	10-Oct-19	48		10-Oct-23		244 d				
	HRS	1509.8									
	AFL	1201									
PROC. REF: AMM 32-10-01											
321050		* RIGHT MAIN LANDING GEAR AXLE BEAM (P/N 200-0203) (N3220036) ASSEMBLY								Component	ATA:32
PN:200-0203	MOS	02-Jan-15						LIFE LIMIT			
SN:H0434	HRS	877.1									
	AFL	786	10000	TSN 324	10462		9132				
PROC. REF: AMM 32-10-01											

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 32 - LANDING GEAR										
321050A	INSPECTION * RIGHT MAIN LANDING GEAR AXLES - PERFORM MAIN LANDING GEAR AXLE BEAM ASSEMBLY BORESCOPE INSPECTION (IRN T3220007)								Service	ATA:32
	MOS	10-Oct-19	48		10-Oct-23		244 d			
	HRS	1509.8								
	AFL	1201								
PROC. REF: AMM 32-10-01										
321073	LEFT MAIN LANDING GEAR SIDE BRACE ACTUATOR DISPLACEMENT TUBE								Component	ATA:32
PN:200-0305-003	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:H1318	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
321074	RIGHT MAIN LANDING GEAR SIDE BRACE ACTUATOR DISPLACEMENT TUBE								Component	ATA:32
PN:200-0305-003	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:H1345	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
321085	LEFT FORWARD TRUNNION ASSEMBLY								Component	ATA:32
PN:4532103011-011	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:CMI-256	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
321086	RIGHT FORWARD TRUNNION ASSEMBLY								Component	ATA:32
PN:4532103011-012	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:CMI-272	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
321087	LEFT AFT TRUNNION ASSEMBLY								Component	ATA:32
PN:4532103021-009	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:CMI-334	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 32 - LANDING GEAR										
321088	RIGHT AFT TRUNNION ASSEMBLY									Component ATA:32
PN:4532103021-010	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:CMI-383	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
321101	* REPLACE LEFT MAIN LANDING GEAR TRUNNION FORWARD PIN (P/N 200-0212, 200-0213). (IRN N3220023) ASSEMBLY									Component ATA:32
PN:200-0212-103	MOS	20-Jan-11		TSN 0				LIFE LIMIT		
SN:H1361	HRS	0		TSN 0						
	AFL	0	10000	TSN 0	10000		8670			
PROC. REF: AMM 32-10-01										
321101A	MAGNETIC PARTICLE INSPECT LEFT MAIN LANDING GEAR TRUNNION FORWARD PIN - (IRN V3220022)									Service ATA:32
	MOS	10-Oct-19	96 (+ 14d/-14d)		10-Oct-27		24-Oct-27	1705 d (+ 14)		
	HRS	1509.8								
	AFL	1201								
PROC. REF: NDT PART 7/32-10-07, NDT PART 7/32-10-08										
321102	* REPLACE RIGHT MAIN LANDING GEAR TRUNNION FORWARD PIN (P/N 200-0212, 200-0213) (IRN N3220023) ASSEMBLY									Component ATA:32
PN:200-0212-103	MOS	20-Jan-11		TSN 0				LIFE LIMIT		
SN:H1337	HRS	0		TSN 0						
	AFL	0	10000	TSN 0	10000		8670			
PROC. REF: AMM 32-10-01										
321102A	MAGNETIC PARTICLE INSPECT RIGHT MAIN LANDING GEAR TRUNNION FORWARD PIN (IRN V3220022)									Service ATA:32
	MOS	10-Oct-19	96 (+ 14d/-14d)		10-Oct-27		24-Oct-27	1705 d (+ 14)		
	HRS	1509.8								
	AFL	1201								
PROC. REF: NDT PART 7/32-10-07, NDT PART 7/32-10-08										
321103	* REPLACE LEFT MAIN LANDING GEAR TRUNNION AFT PIN (P/N 200-0212, 200-0213) (IRN N3220023) ASSEMBLY									Component ATA:32
PN:200-0213-103	MOS	20-Jan-11		TSN 0				LIFE LIMIT		
SN:H1186	HRS	0		TSN 0						
	AFL	0	10000	TSN 0	10000		8670			
PROC. REF: AMM 32-10-01										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 32 - LANDING GEAR										
321103A MAGNETIC PARTICLE INSPECT LEFT MAIN LANDING GEAR TRUNNION AFT PIN (IRN V3220022) Service ATA:32										
	MOS	10-Oct-19	96 (+ 14d/-14d)		10-Oct-27	24-Oct-27	1705 d (+ 14)			
	HRS	1509.8								
	AFL	1201								
PROC. REF: NDT PART 7/32-10-07, NDT PART 7/32-10-08										
321104 * REPLACE RIGHT MAIN LANDING GEAR AFT TRUNNION PIN (P/N 200-0212, 200-0213) (IRN N3220023) ASSEMBLY Component ATA:32										
PN:200-0213-103	MOS	20-Jan-11		TSN 0				LIFE LIMIT		
SN:H1142	HRS	0		TSN 0						
	AFL	0	10000	TSN 0	10000		8670			
PROC. REF: AMM 32-10-01										
321104A MAGNETIC PARTICLE INSPECT RIGHT MAIN LANDING GEAR AFT TRUNNION PIN (IRN V3220022) Service ATA:32										
	MOS	10-Oct-19	96 (+ 14d/-14d)		10-Oct-27	24-Oct-27	1705 d (+ 14)			
	HRS	1509.8								
	AFL	1201								
PROC. REF: NDT PART 7/32-10-07, NDT PART 7/32-10-08										
32111-2 BRAKE NO. 1 SWIVEL Component ATA:32										
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
321111 LEFT FORWARD LOWER * MAIN LANDING GEAR TRUNNION SHEAR PIN Component ATA:32										
PN:4532103201-001	MOS	20-Jan-11		TSN 0				LIFE LIMIT		
SN:CMI-2401	HRS	0		TSN 0						
	AFL	0	5000	TSN 0	5000		3670			
PROC. REF: AMM 57-10-05										
321111A LEFT FORWARD LOWER * MAIN LANDING GEAR TRUNNION SHEAR PIN - PERFORM VISUAL INSPECTION FOR PIN MIGRATION Service ATA:32										
	MOS/MSC		N/A					NOT APPLICABLE		
	HRS									
	AFL									
PROC. REF: AMM 57-10-05										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 32 - LANDING GEAR										
321112 RIGHT FORWARD LOWER * MAIN LANDING GEAR TRUNNION SHEAR PIN Component ATA:32										
PN:4532103201-001	MOS	20-Jan-11		TSN 0				LIFE LIMIT		
SN:CMI-2133	HRS	0		TSN 0						
	AFL	0	5000	TSN 0	5000		3670			
PROC. REF: AMM 57-10-05										
321112A RIGHT FORWARD LOWER * MAIN LANDING GEAR TRUNNION SHEAR PIN - PERFORM VISUAL INSPECTION FOR PIN MIGRATION Service ATA:32										
	MOS/MSC		N/A					NOT APPLICABLE		
	HRS									
	AFL									
PROC. REF: AMM 57-10-05										
321113 LEFT FORWARD UPPER * MAIN LANDING GEAR TRUNNION SHEAR PIN Component ATA:32										
PN:4532103201-001	MOS	20-Jan-11		TSN 0				LIFE LIMIT		
SN:CMI-2529	HRS	0		TSN 0						
	AFL	0	5000	TSN 0	5000		3670			
PROC. REF: AMM 57-10-05										
321113A LEFT FORWARD UPPER * MAIN LANDING GEAR TRUNNION SHEAR PIN - PERFORM VISUAL INSPECTION FOR PIN MIGRATION Service ATA:32										
	MOS/MSC		N/A					NOT APPLICABLE		
	HRS									
	AFL									
PROC. REF: AMM 57-10-05										
321114 RIGHT FORWARD UPPER * MAIN LANDING GEAR TRUNNION SHEAR PIN Component ATA:32										
PN:4532103201-001	MOS	20-Jan-11		TSN 0				LIFE LIMIT		
SN:CMI-2241	HRS	0		TSN 0						
	AFL	0	5000	TSN 0	5000		3670			
PROC. REF: AMM 57-10-05										
321114A RIGHT FORWARD UPPER * MAIN LANDING GEAR TRUNNION SHEAR PIN - PERFORM VISUAL INSPECTION FOR PIN MIGRATION Service ATA:32										
	MOS/MSC		N/A					NOT APPLICABLE		
	HRS									
	AFL									
PROC. REF: AMM 57-10-05										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 32 - LANDING GEAR										
321117 LEFT AFT UPPER * MAIN LANDING GEAR TRUNNION SHEAR PIN Component ATA:32										
PN:4532103202-001	MOS	20-Jan-11		TSN 0				LIFE LIMIT		
SN:CMI-1203	HRS	0		TSN 0						
	AFL	0	5000	TSN 0	5000		3670			
PROC. REF: AMM 57-10-05										
321117A LEFT AFT UPPER * MAIN LANDING GEAR TRUNNION SHEAR PIN - PERFORM VISUAL INSPECTION FOR PIN MIGRATION Service ATA:32										
	MOS/MSC		N/A					NOT APPLICABLE		
	HRS									
	AFL									
PROC. REF: AMM 57-10-05										
321118 RIGHT AFT UPPER * MAIN LANDING GEAR TRUNNION SHEAR PIN Component ATA:32										
PN:4532103202-001	MOS	20-Jan-11		TSN 0				LIFE LIMIT		
SN:CMI-1191	HRS	0		TSN 0						
	AFL	0	5000	TSN 0	5000		3670			
PROC. REF: AMM 57-10-05										
321118A RIGHT AFT UPPER * MAIN LANDING GEAR TRUNNION SHEAR PIN - PERFORM VISUAL INSPECTION FOR PIN MIGRATION Service ATA:32										
	MOS/MSC		N/A					NOT APPLICABLE		
	HRS									
	AFL									
PROC. REF: AMM 57-10-05										
321119 LEFT AFT LOWER * MAIN LANDING GEAR TRUNNION SHEAR PIN Component ATA:32										
PN:4532103203-001	MOS	20-Jan-11		TSN 0				LIFE LIMIT		
SN:CMI-1189	HRS	0		TSN 0						
	AFL	0	5000	TSN 0	5000		3670			
PROC. REF: AMM 57-10-05										
321119A LEFT AFT LOWER * MAIN LANDING GEAR TRUNNION SHEAR PIN - PERFORM VISUAL INSPECTION FOR PIN MIGRATION Service ATA:32										
	MOS/MSC		N/A					NOT APPLICABLE		
	HRS									
	AFL									
PROC. REF: AMM 57-10-05										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 32 - LANDING GEAR										
321120	RIGHT AFT LOWER * MAIN LANDING GEAR TRUNNION SHEAR PIN									Component ATA:32
PN:4532103203-001	MOS	20-Jan-11		TSN 0				LIFE LIMIT		
SN:CMI-1107	HRS	0		TSN 0						
	AFL	0	5000	TSN 0	5000		3670			
PROC. REF: AMM 57-10-05										
321120A	RIGHT AFT LOWER * MAIN LANDING GEAR TRUNNION SHEAR PIN - PERFORM VISUAL INSPECTION FOR PIN MIGRATION									Service ATA:32
	MOS/MSC		N/A					NOT APPLICABLE		
	HRS									
	AFL									
PROC. REF: AMM 57-10-05										
321201	LEFT MAIN LANDING GEAR OLEO ASSEMBLY									Component ATA:32
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
321202	RIGHT MAIN LANDING GEAR OLEO ASSEMBLY									Component ATA:32
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
321215	* REPLACE LEFT MAIN LANDING GEAR SHOCK STRUT PISTON (P/N 200-0202) (IRN N3220035) ASSEMBLY									Component ATA:32
PN:200-0202-003	MOS	20-Jan-11		TSN 0				LIFE LIMIT		
SN:H1819	HRS	0		TSN 0						
	AFL	0	10000	TSN 0	10000		8670			
PROC. REF: AMM 32-10-01										
321216	* REPLACE RIGHT MAIN LANDING GEAR SHOCK STRUT PISTON (P/N 200-0202) (IRN N3220035) ASSEMBLY									Component ATA:32
PN:200-0202-003	MOS	20-Jan-11		TSN 0				LIFE LIMIT		
SN:H1674	HRS	0		TSN 0						
	AFL	0	10000	TSN 0	10000		8670			
PROC. REF: AMM 32-10-01										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 32 - LANDING GEAR										
321227 * REPLACE LEFT MAIN LANDING GEAR SHOCK STRUT LINK (P/N 200-0204) (IRN N3220037) ASSEMBLY Component ATA:32										
PN:200-0204-001	MOS		20-Jan-11		TSN 0			LIFE LIMIT		
SN:H1523	HRS		0		TSN 0					
	AFL		0	10000	TSN 0	10000	8670			
PROC. REF: AMM 32-10-01										
321228 * REPLACE RIGHT MAIN LANDING GEAR SHOCK STRUT LINK (P/N 200-0204) (IRN N3220037) ASSEMBLY Component ATA:32										
PN:200-0204-001	MOS		20-Jan-11		TSN 0			LIFE LIMIT		
SN:H1529	HRS		0		TSN 0					
	AFL		0	10000	TSN 0	10000	8670			
PROC. REF: AMM 32-10-01										
321301 LEFT MAIN LANDING GEAR OUTBOARD DOOR Component ATA:32										
PN:4552803003-003	MOS/MSC		20-Jan-11	O/C	TSN 0					
SN:E924002	HRS		0		TSN 0					
	AFL		0		TSN 0					
PROC. REF: AMM 52-80-01										
321302 LEFT MAIN LANDING GEAR INBOARD DOOR Component ATA:32										
PN:4552803004-005	MOS/MSC		20-Jan-11	O/C	TSN 0					
SN:E879566	HRS		0		TSN 0					
	AFL		0		TSN 0					
PROC. REF: AMM 52-80-01										
321303 RIGHT MAIN LANDING GEAR INBOARD DOOR Component ATA:32										
PN:4552803004-006	MOS/MSC		20-Jan-11	O/C	TSN 0					
SN:E879573	HRS		0		TSN 0					
	AFL		0		TSN 0					
PROC. REF: AMM 52-80-01										
321304 RIGHT MAIN LANDING GEAR OUTBOARD DOOR Component ATA:32										
PN:4552803003-004	MOS/MSC		20-Jan-11	O/C	TSN 0					
SN:E935743	HRS		0		TSN 0					
	AFL		0		TSN 0					
PROC. REF: AMM 52-80-01										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 32 - LANDING GEAR											
322001		* REPLACE NOSE LANDING GEAR STRUT ASSEMBLY (O3220009) (JAA E3220069)								Component	ATA:32
PN:4532240001-838	MOS	28-Nov-15		TSN 58, TSR 0				LIFE LIMIT			
SN:002	HRS	954.7		TSN 954.7, TSR 0							
	AFL	842	20000	TSN 842, TSR 0	20000		18670				
PROC. REF: AMM 32-20-01											
322002		NOSE LANDING GEAR CYLINDER								Component	ATA:32
PN:2342102-003	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:T769	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 32-32-01											
322003		NOSE LANDING GEAR PISTON								Component	ATA:32
PN:2342104-003	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:F024	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 32-32-01											
322004		NOSE LANDING GEAR ACTUATOR BRACKET								Component	ATA:32
PN:2342111-005	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:R534	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 32-32-01											
322005		NOSE LANDING GEAR FORK								Component	ATA:32
PN:2342116-004	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:R812	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 32-32-01											
322011		* REPLACE NOSE LANDING GEAR ACTUATOR (P/N 6632201000) (O3220010) (JAA IRN E3220073) ASSEMBLY								Component	ATA:32
PN:6632201000-005	MOS	10-Mar-12		TSN 0				LIFE LIMIT			
SN:TASV758	HRS	323.8		TSN 0							
	AFL	269	20000	TSN 0	20269		18939				
PROC. REF: AMM 32-32-01											

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 32 - LANDING GEAR										
322061 * REPLACE NOSE LANDING GEAR TRUNNION AXLE (P/N 2342110) (IRN O3220029 JAA IRN E3220072) ASSEMBLY Component ATA:32										
PN:2342110-003	MOS		20-Jan-11		TSN 0			LIFE LIMIT		
SN:R915	HRS		0		TSN 0					
	AFL		0	20000	TSN 0	20000	18670			
PROC. REF: AMM 32-20-01										
322071 * REPLACE LEFT NOSE GEAR TRUNNION PIN (P/N 2342108) (IRN O3220028 JAA IRN E3220071) ASSEMBLY Component ATA:32										
PN:2342108-003	MOS		20-Jan-11		TSN 0			LIFE LIMIT		
SN:MTI-199	HRS		0		TSN 0					
	AFL		0	20000	TSN 0	20000	18670			
PROC. REF: AMM 32-20-01										
322072 * REPLACE RIGHT NOSE GEAR TRUNNION PIN (P/N 2342108) (IRN O3220028 JAA IRN E3220071) ASSEMBLY Component ATA:32										
PN:2342108-003	MOS		20-Jan-11		TSN 0			LIFE LIMIT		
SN:MTI-164	HRS		0		TSN 0					
	AFL		0	20000	TSN 0	20000	18670			
PROC. REF: AMM 32-20-01										
322095 LEFT NOSE LANDING GEAR DOOR Component ATA:32										
PN:4552800001-007	MOS/MSC		20-Jan-11	O/C	TSN 0					
SN:568	HRS		0		TSN 0					
	AFL		0		TSN 0					
PROC. REF: AMM 52-81-01										
322096 RIGHT NOSE LANDING GEAR DOOR Component ATA:32										
PN:4552800002-007	MOS/MSC		20-Jan-11	O/C	TSN 0					
SN:565	HRS		0		TSN 0					
	AFL		0		TSN 0					
PROC. REF: AMM 52-81-01										
322098 AXLE, PISTON ASSEM, NOSE LANDING GEAR REPLACE Component ATA:32										
PN:2342117-002	MOS/MSC		20-Jan-11	O/C	TSN 0					
SN:R907	HRS		0		TSN 0					
	AFL		0		TSN 0					
PROC. REF: GENERIC NO REF										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 32 - LANDING GEAR										
322111 NOSE LANDING GEAR CHASSIS ASSEMBLY Component ATA:32										
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
322121 NOSE LANDING GEAR UPLOCK MECHANISM Component ATA:32										
PN:2269H000-003	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:1621	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 32-32-02										
323001 LEFT * MAIN LANDING GEAR SIDE BRACE ACTUATOR ASSEMBLY REPLACE Component ATA:32										
PN:200-0300-003	MOS	20-Jan-11		TSN 0				LIFE LIMIT		
SN:H0593	HRS	0		TSN 0						
	AFL	0	17000	TSN 0	17000		15670			
323001A INSPECT LH MAIN LANDING GEAR SIDE-STAY ACTUATOR - DISASSEMBLE ACTUATOR AND PERFORM DETAILED VISUAL INSPECTION. Service ATA:32 (IRN AA3220111)										
	MOS	10-Oct-19	96 (+ 14d/-14d)	Adj -263d	20-Jan-27		03-Feb-27	1442 d (+ 14)		
	HRS	1509.8								
	AFL	1201	10000 (+ 25/-25)		11201		11226	9871 (+ 25)		
PROC. REF: GENERIC NO REF										
323002 RIGHT * MAIN LANDING GEAR SIDE BRACE ACTUATOR ASSEMBLY REPLACE Component ATA:32										
PN:200-0300-004	MOS	20-Jan-11		TSN 0				LIFE LIMIT		
SN:H1593	HRS	0		TSN 0						
	AFL	0	17000	TSN 0	17000		15670			
323002A INSPECT RH MAIN LANDING GEAR SIDE-STAY ACTUATOR - DISASSEMBLE ACTUATOR AND PERFORM DETAILED VISUAL INSPECTION. Service ATA:32 (IRN AA3220111)										
	MOS	10-Oct-19	96 (+ 14d/-14d)	Adj -263d	20-Jan-27		03-Feb-27	1442 d (+ 14)		
	HRS	1509.8								
	AFL	1201	10000 (+ 25/-25)		11201		11226	9871 (+ 25)		
PROC. REF: GENERIC NO REF										
323037 MAIN LANDING GEAR UPLOCK INBD DOOR, LEFT MECHANISM Component ATA:32										
PN:3000H000-005	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:2213	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 32-31-04										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 32 - LANDING GEAR											
323038		MAIN LANDING GEAR UPLOCK INBD DOOR, RIGHT MECHANISM							Component	ATA:32	
PN:3000H000-006	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:2210	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 32-31-04											
323110		NOSE LANDING GEAR DOWN-LOCK (S139) SWITCH							Component	ATA:32	
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 32-60-05											
323220		DOWN AND LOCKED (S96) SWITCH							Component	ATA:32	
PN:604HE162	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:1585	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 32-60-02											
323221		DOWN AND LOCKED (S100) SWITCH							Component	ATA:32	
PN:604HE162	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:1733	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 32-60-02											
323301		* REPLACE LEFT MAIN LANDING GEAR INBOARD DOOR ACTUATOR (P/N 7469-1) CAP SCREWS (IRN L3231024) ASSEMBLY							Component	ATA:32	
PN:7469-1	MOS	20-Jan-11		TSN 0				LIFE LIMIT			
SN:1135	HRS	0	2400	TSN 0	2400		725				
	AFL	0		TSN 0							
PROC. REF: AMM 32-31-02											
323302		* REPLACE RIGHT MAIN LANDING GEAR INBOARD DOOR ACTUATOR (P/N 7469-1) CAP SCREWS (IRN L3231024) ASSEMBLY							Component	ATA:32	
PN:7469-1	MOS	20-Jan-11		TSN 0				LIFE LIMIT			
SN:1049	HRS	0	2400	TSN 0	2400		725				
	AFL	0		TSN 0							
PROC. REF: AMM 32-31-02											
323304		SWITCH ASSEM, ACTUATOR HYD, MLG DOOR REPLACE							Component	ATA:32	
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: GENERIC NO REF											

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 32 - LANDING GEAR										
323305 LEFT MLG ACTUATOR GIMBAL ASSEMBLY Component ATA:32										
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 32-31-06										
323306 RIGHT MLG ACTUATOR GIMBAL ASSEMBLY Component ATA:32										
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 32-31-06										
323307 LEFT MLG SHAFT GIMBAL ASSEMBLY Component ATA:32										
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 32-31-06										
323308 RIGHT MLG SHAFT GIMBAL ASSEMBLY Component ATA:32										
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 32-31-06										
323309 LEFT MLG INBOARD DOOR GIMBAL BRACKET ASSEMBLY Component ATA:32										
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 32-31-06										
323310 RIGHT MLG INBOARD DOOR GIMBAL BRACKET ASSEMBLY Component ATA:32										
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 32-31-06										
323735 CONTROL VALVE Component ATA:32										
PN:2245H000-002	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:1596	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 32-30-01										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 32 - LANDING GEAR											
324001		NO. 1 MAIN LANDING GEAR WHEEL								Component	ATA:32
PN:4532101100-003	MOS/MSC	10-Oct-19	O/C	TSR 0							
SN:2971	HRS	1509.8		TSR 0							
	AFL	1201		TSR 0							
PROC. REF: AMM 32-40-02											
324001A		NON DESTRUCTIVE TEST NO. 1 MAIN LANDING GEAR WHEEL								Service	ATA:32
PN:4532101100-003	MOS/MSC	10-Oct-19	O/C								
SN:2971	HRS	1509.8									
	AFL	1201									
PROC. REF: GENERIC NO REF											
324002		NO. 2 MAIN LANDING GEAR WHEEL								Component	ATA:32
PN:4532101100-003	MOS/MSC	10-Oct-19	O/C	TSR 0							
SN:2892	HRS	1509.8		TSN 1544, TSR 0							
	AFL	1201		TSN 1202, TSR 0							
PROC. REF: AMM 32-40-02											
324002A		NON DESTRUCTIVE TEST NO. 2 MAIN LANDING GEAR WHEEL								Service	ATA:32
PN:4532101100-003	MOS/MSC	10-Oct-19	O/C								
SN:2892	HRS	1509.8									
	AFL	1201									
PROC. REF: GENERIC NO REF											
324003		NO. 3 MAIN LANDING GEAR WHEEL								Component	ATA:32
PN:4532101100-003	MOS/MSC	11-Sep-18	O/C	TSR 0							
SN:2293	HRS	1387.4		TSN 1786.2, TSR 0							
	AFL	1114		TSN 1431, TSR 0							
PROC. REF: AMM 32-40-02											
324003A		NON DESTRUCTIVE TEST NO. 3 MAIN LANDING GEAR WHEEL								Service	ATA:32
PN:4532101100-003	MOS/MSC	11-Sep-18	O/C								
SN:2293	HRS	1387.4									
	AFL	1114									
PROC. REF: GENERIC NO REF											

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 32 - LANDING GEAR										
324004	NO. 4 MAIN LANDING GEAR WHEEL									Component ATA:32
PN:4532101100-003	MOS/MSC	11-Sep-18	O/C	TSR 0						
SN:2861	HRS	1387.4		TSR 0						
	AFL	1114		TSR 0						
PROC. REF: AMM 32-40-02										
324004A	NON DESTRUCTIVE TEST NO. 4 MAIN LANDING GEAR WHEEL									Service ATA:32
PN:4532101100-003	MOS/MSC	11-Sep-18	O/C							
SN:2861	HRS	1387.4								
	AFL	1114								
PROC. REF: GENERIC NO REF										
324005	NOSE GEAR WHEEL ASSEMBLY									Component ATA:32
PN:2342003-077	MOS/MSC	10-Oct-19	O/C	TSR 0						
SN:DEC14-11414	HRS	1509.8		TSR 0						
	AFL	1201		TSR 0						
PROC. REF: AMM 32-40-01										
324021	NO. 1 MAIN LANDING GEAR TIRE									Component ATA:32
PN:226K08-4	MOS/MSC	10-Oct-19	O/C	TSN 0						
SN:UNKNOWN	HRS	1509.8		TSN 0						
	AFL	1201		TSN 0						
PROC. REF: AMM 32-40-02										
324022	NO. 2 MAIN LANDING GEAR TIRE									Component ATA:32
PN:226K08-4	MOS/MSC	10-Oct-19	O/C	TSN 0						
SN:UNKNOWN	HRS	1509.8		TSN 0						
	AFL	1201		TSN 0						
PROC. REF: AMM 32-40-02										
324023	NO. 3 MAIN LANDING GEAR TIRE									Component ATA:32
PN:226K08-4	MOS/MSC	11-Sep-18	O/C	TSN 0						
SN:UNKNOWN	HRS	1387.4		TSN 0						
	AFL	1114		TSN 0						
PROC. REF: AMM 32-40-02										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 32 - LANDING GEAR											
324024		NO. 4 MAIN LANDING GEAR TIRE								Component	ATA:32
PN:226K08-4	MOS/MSC	11-Sep-18	O/C	TSN 0							
SN:UNKNOWN	HRS	1387.4		TSN 0							
	AFL	1114		TSN 0							
PROC. REF: AMM 32-40-02											
324025		NOSE LANDING GEAR TIRE								Component	ATA:32
PN:031-613-8	MOS/MSC	10-Oct-19	O/C	TSN 0							
SN:8302S00298	HRS	1509.8		TSN 0							
	AFL	1201		TSN 0							
PROC. REF: AMM 32-40-01											
324061		LEFT ANTI-SKID CONTROL VALVE								Component	ATA:32
PN:39-787	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:1291	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 32-41-07											
324062		RIGHT ANTI-SKID CONTROL VALVE								Component	ATA:32
PN:39-787	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:1296	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 32-41-07											
324066		LEFT ANTI-SKID SHUTOFF VALVE								Component	ATA:32
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: GENERIC NO REF											
324067		RIGHT ANTI-SKID SHUTOFF VALVE								Component	ATA:32
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: GENERIC NO REF											
324097		BRAKE CONTROL UNIT								Component	ATA:32
PN:42-933-3	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:694A	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 32-41-02											

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 32 - LANDING GEAR										
324108 EMERGENCY PARKING BRAKE CHECK VALVE Component ATA:32										
PN:1C4124	MOS/MSC	23-May-16	O/C	TSN 33						
SN:UNKNOWN	HRS	1039.2		TSN 0						
	AFL	899		TSN 0						
PROC. REF: AMM 32-42-09										
324109 EMERGENCY/PARK BRAKE VALVE Component ATA:32										
PN:8196-5	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:0669	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 32-42-01										
324110 PRESSURE, EMERGENCY/PARK BRAKE TRANSDUCER Component ATA:32										
PN:APTE-196-1000-4000A	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:7577-12-92	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 32-42-03										
324111 NO. 1 ASSEMBLY, MAIN LANDING GEAR BRAKE Component ATA:32										
PN:2-1579-2	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:2564	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 32-41-01										
324111-1 INBOARD BRAKE NO. 1 SWIVEL Component ATA:32										
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 32-41-01										
324111-2 OUTBOARD BRAKE NO. 1 SWIVEL Component ATA:32										
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 32-41-01										
324112 NO. 2 ASSEMBLY, MAIN LANDING GEAR BRAKE Component ATA:32										
PN:2-1579-2	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:2505	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 32-41-01										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 32 - LANDING GEAR											
324112-1		INBOARD BRAKE NO. 2 SWIVEL							Component	ATA:32	
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:UNKNOWN	HRS	0	TSN 0								
	AFL	0	TSN 0								
PROC. REF: AMM 32-41-01											
324112-2		OUTBOARD BRAKE NO. 2 SWIVEL							Component	ATA:32	
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:UNKNOWN	HRS	0	TSN 0								
	AFL	0	TSN 0								
PROC. REF: AMM 32-41-01											
324113		NO. 3 ASSEMBLY, MAIN LANDING GEAR BRAKE							Component	ATA:32	
PN:2-1579-2	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:2546	HRS	0	TSN 0								
	AFL	0	TSN 0								
PROC. REF: AMM 32-41-01											
324113-1		INBOARD BRAKE NO. 3 SWIVEL							Component	ATA:32	
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:UNKNOWN	HRS	0	TSN 0								
	AFL	0	TSN 0								
PROC. REF: AMM 32-41-01											
324113-2		OUTBOARD BRAKE NO. 3 SWIVEL							Component	ATA:32	
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:UNKNOWN	HRS	0	TSN 0								
	AFL	0	TSN 0								
PROC. REF: AMM 32-41-01											
324114		NO. 4 ASSEMBLY, MAIN LANDING GEAR BRAKE							Component	ATA:32	
PN:2-1579-2	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:2535	HRS	0	TSN 0								
	AFL	0	TSN 0								
PROC. REF: AMM 32-41-01											
324114-1		INBOARD BRAKE NO. 4 SWIVEL							Component	ATA:32	
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:UNKNOWN	HRS	0	TSN 0								
	AFL	0	TSN 0								
PROC. REF: AMM 32-41-01											

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 32 - LANDING GEAR											
324114-2		OUTBOARD BRAKE NO. 4 SWIVEL								Component	ATA:32
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 32-41-01											
324201		NO. 1 BRAKE SHUTTLE VALVE								Component	ATA:32
PN:5116-1	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:2281	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 32-42-04											
324202		NO. 2 BRAKE SHUTTLE VALVE								Component	ATA:32
PN:5116-1	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:2113	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 32-42-04											
324203		NO. 3 BRAKE SHUTTLE VALVE								Component	ATA:32
PN:5116-1	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:2291	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 32-42-04											
324204		NO. 4 BRAKE SHUTTLE VALVE								Component	ATA:32
PN:5116-1	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:2264	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 32-42-04											
324205		BRAKE SHUTTLE MODULE								Component	ATA:32
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 32-41-04											
324305		LEFT PILOT BRAKE TRANSDUCER								Component	ATA:32
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 32-41-03											

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 32 - LANDING GEAR											
324306		RIGHT PILOT BRAKE TRANSDUCER								Component	ATA:32
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 32-41-03											
324307		LEFT CO-PILOT BRAKE TRANSDUCER								Component	ATA:32
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: GENERIC NO REF											
324308		RIGHT CO-PILOT BRAKE TRANSDUCER								Component	ATA:32
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: GENERIC NO REF											
324601		SHUTTLE MODULE, ANTI-SKID, BRAKE								Component	ATA:32
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: GENERIC NO REF											
324610-1		LEFT INBOARD BRAKE SWIVEL								Component	ATA:32
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 32-41-01											
324610-2		LEFT OUTBOARD BRAKE SWIVEL								Component	ATA:32
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 32-41-01											
324611-1		RIGHT INBOARD BRAKE SWIVEL								Component	ATA:32
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 32-41-01											

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 32 - LANDING GEAR											
324611-2		RIGHT OUTBOARD BRAKE SWIVEL								Component	ATA:32
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 32-41-01											
324701		NO. 1 HYDRAULIC, BRAKE FUSE								Component	ATA:32
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 32-41-09											
324702		NO. 2 HYDRAULIC, BRAKE FUSE								Component	ATA:32
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 32-41-09											
324703		NO. 3 HYDRAULIC, BRAKE FUSE								Component	ATA:32
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 32-41-09											
324704		NO. 4 HYDRAULIC, BRAKE FUSE								Component	ATA:32
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 32-41-09											
324711		NO. 1 WHEEL SPEED - ANTI-SKID TRANSDUCER								Component	ATA:32
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 32-41-10											
324712		NO. 2 WHEEL SPEED - ANTI-SKID TRANSDUCER								Component	ATA:32
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 32-41-10											

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 32 - LANDING GEAR											
324713		NO. 3 WHEEL SPEED - ANTI-SKID TRANSDUCER								Component	ATA:32
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 32-41-10											
324714		NO. 4 WHEEL SPEED - ANTI-SKID TRANSDUCER								Component	ATA:32
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 32-41-10											
324721		(MT56) PRESSURE BRAKE TRANSDUCER ASSEMBLY								Component	ATA:32
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 32-41-08											
324722		(MT57) PRESSURE BRAKE TRANSDUCER ASSEMBLY								Component	ATA:32
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 32-41-08											
324723		(MT58) PRESSURE BRAKE TRANSDUCER ASSEMBLY								Component	ATA:32
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 32-41-08											
324724		(MT59) PRESSURE BRAKE TRANSDUCER ASSEMBLY								Component	ATA:32
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 32-41-08											
324801		EMERGENCY/PARK BRAKE FUSE								Component	ATA:32
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 32-42-07											

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 32 - LANDING GEAR											
324805		EMER/PARK BRAKE ACCUMULATOR								Component	ATA:32
PN:88744-1	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:595	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 32-42-02											
325007		FILTER, NOSE WHEEL STEERING (P41) BOX								Component	ATA:32
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 32-50-06											
325011		NOSE WHEEL STEERING SERVO ACTUATOR								Component	ATA:32
PN:JR5208C	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:A0547	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 32-50-02											
325021		NOSE WHEEL STEERING GEARBOX								Component	ATA:32
PN:2W3-201D	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:C0595	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 32-50-03											
325031		NOSE WHEEL STEERING COMPUTER								Component	ATA:32
PN:498000-03-03	MOS/MSC	03-Mar-16	O/C								
SN:00763	HRS	995									
	AFL	870									
PROC. REF: AMM 32-50-01											
325035		NOSE WHEEL STEERING POWER SUPPLY								Component	ATA:32
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: GENERIC NO REF											
325041		LEFT NOSE WHEEL STEERING TRANSDUCER								Component	ATA:32
PN:19710 / 3A1-279A	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:A1159	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 32-50-04											

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 32 - LANDING GEAR										
325042 RIGHT NOSE WHEEL STEERING TRANSDUCER Component ATA:32										
PN:19710 / 3A1-279A	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:A1193	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 32-50-04										
325051 * NOSE LANDING GEAR ACTUATOR UPPER PIN (IRN O3220011 OR JAA IRN E3220070) Component ATA:32										
PN:4532302043-007	MOS	20-Jan-11		TSN 0				LIFE LIMIT		
SN:821	HRS	0		TSN 0						
	AFL	0	20000	TSN 0	20000		18670			
PROC. REF: AMM 32-32-01										
326000 NOSE LANDING GEAR WIRE HARNESS Component ATA:32										
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
326104 NOSE LANDING GEAR SQUAT/WOW (S178) SWITCH Component ATA:32										
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 32-50-09										
326105 NO. 1 MAIN GEAR SQUAT SWITCH Component ATA:32										
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 32-60-09										
326106 NO. 2 MAIN GEAR SQUAT SWITCH Component ATA:32										
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 32-60-09										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 32 - LANDING GEAR										
326107	NO. 3 MAIN GEAR SQUAT SWITCH									Component ATA:32
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 32-60-09										
326108	NO. 4 MAIN GEAR SQUAT SWITCH									Component ATA:32
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 32-60-09										
326115	SQUAT SWITCH P21 RELAY BOX									Component ATA:32
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 32-60-08										
5-19-00-D3260006	LUBRICATE NOSE LANDING GEAR SQUAT SWITCH ROTATING DISK ASSEMBLY. EFFECTIVE ON AIRCRAFT 45-001 THRU 45-071 MODIFIED PER SB 45-32-3 AND AIRCRAFT 45-072 THROUGH 45-114 NOT MODIFIED PER SB 45-32-8. (ZONE/ACCESS 700 IRN # D326006)									Service ATA:32
	MOS/MSC	20-Jan-11	N/A							
	HRS	0								
	AFL	0								
PROC. REF: AMM 12-21-01										
5-19-00-J3220120	* MLG TRUNNION SHEAR PIN BUSHING - PERFORM VISUAL INSPECTION FOR BUSHING MIGRATION (IRN J3220120)									Service ATA:32
	MOS/MSC	20-Jan-11	O/C							
	HRS	0								
	AFL	0								
PROC. REF: AMM 57-10-05										
5-19-00-L3220020	* MAIN LANDING GEAR TRUNNION FITTINGS ON MID AND REAR SPAR - PERFORM EDDY CURRENT INSPECTION. (REFER TO NDI MANUAL [NDI-104]. PART 6, 32-11-00 (L3220020)									Service ATA:32
	MOS	20-Jan-11						AIRWORTHINESS		
	HRS	0								
	AFL	0	T:10000		10000		8670			
PROC. REF: NDT PART 6/32-11-00										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 32 - LANDING GEAR										
5-19-00-P3231020	MAIN LANDING GEAR DOOR ACTUATOR GIMBAL ASSEMBLY - PERFORM EDDY CURRENT INSPECTION									Service ATA:32
	MOS/MSC	06-Apr-11	-					N/A BY SERIAL NUMBER		
	HRS	62.4								
WC# : 32.101	AFL	43								
PROC. REF: NDT PART 6/32-13-00										
5-19-00-P3231021	MAIN LANDING GEAR DOOR ACTUATOR GIMBAL SHAFT - PERFORM FLUORESCENT PENETRANT INSPECTION									Service ATA:32
	MOS/MSC	06-Apr-11	-					N/A BY SERIAL NUMBER		
	HRS	62.4								
WC# : 32.102	AFL	43								
PROC. REF: NDT PART 8/32-13-02										
5-19-00-W3231022	MAIN LANDING GEAR INBOARD DOOR GIMBAL BRACKET - PERFORM EDDY CURRENT INSPECTION									Service ATA:32
	MOS/MSC	16-Mar-12	-					N/A BY SERIAL NUMBER		
	HRS	326								
WC# : 32.103	AFL	271								
PROC. REF: NDT PART 6/32-13-01										
5-19-01-F3220045	REPLACE NOSE LANDING GEAR ACTUATOR ATTACHMENT FITTING (ZINC COATED)									Service ATA:32
	MOS/MSC	20-Jan-11	N/A					NOT INSTALLED		
	HRS	0								
	AFL	0								
PROC. REF: AMM 32-32-01										
571010	* REPLACE LEFT MAIN LANDING GEAR SIDE-STAY ACTUATOR FITTING									Component ATA:32
PN:4532103041-009PP	MOS	20-Jan-11		TSN 0				LIFE LIMIT		
SN:19849/5-03	HRS	0		TSN 0						
WC# : 57.010	AFL	0	20000	TSN 0	20000		18670			
PROC. REF: AMM 32-31-01										
571011	* REPLACE RIGHT MAIN LANDING GEAR SIDE-STAY ACTUATOR FITTING									Component ATA:32
PN:4532103041-010PP	MOS	20-Jan-11		TSN 0				LIFE LIMIT		
SN:19850/5-04	HRS	0		TSN 0						
WC# : 57.011	AFL	0	20000	TSN 0	20000		18670			
PROC. REF: AMM 32-31-01										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 32 - LANDING GEAR											
A3230001 ^S			** LANDING GEAR - PERFORM EMERGENCY GEAR EXTENSION FUNCTIONAL TEST							Service	ATA:32
	MOS	20-Jan-23	24 (+ 14d/-14d)					AIRWORTHINESS			
	HRS	1675	600 (+ 25/-25)								
	AFL	1330									
					PROC. REF: AMM 32-33-00					PKG:11	
A3240005 ^S			PERFORM ** BRAKE HYDRAULIC FUSES - FUNCTIONAL TEST							Service	ATA:32
	MOS	20-Jan-23	48 (+ 14d/-14d)					AIRWORTHINESS			
	HRS	1675	1200 (+ 25/-25)								
	AFL	1330									
					PROC. REF: AMM 32-41-09					PKG:17	
A3240006 ^S			PERFORM ** BRAKE SHUTTLE MODULE - FUNCTIONAL TEST							Service	ATA:32
	MOS	20-Jan-23	48 (+ 14d/-14d)					AIRWORTHINESS			
	HRS	1675	1200 (+ 25/-25)								
	AFL	1330									
					PROC. REF: AMM 32-41-04					PKG:17	
A3240007 ^S			PERFORM ** BRAKE SHUTTLE VALVES - FUNCTIONAL TEST							Service	ATA:32
	MOS	11-Sep-18	96 (+ 14d/-14d)					AIRWORTHINESS			
	HRS	1387.4	2400 (+ 25/-25)								
	AFL	1114									
					PROC. REF: AMM 32-42-04					PKG:23	
A3240009 ^S			PERFORM ** BRAKE PRESSURE TRANSDUCERS - FUNCTIONAL TEST							Service	ATA:32
	MOS	20-Jan-11						AIRWORTHINESS			
	HRS	0	4800 (+ 25/-25)								
	AFL	0									
					PROC. REF: AMM 32-41-08					PKG:25	
AB3220016 ^S			PERFORM NOSE LANDING GEAR STRUT ASSEMBLY - SPECIAL DETAILED INSPECTION.							Service	ATA:32
	MOS	20-Jan-11									
	HRS	0									
	AFL	0	10000 (+ 25/-25)								
					PROC. REF: NDT PART 7/32-20-01, NDT PART 7/32-20-02, NDT PART 7/32-20-03, NDT PART 7/32-20-04, NDT PART 8/32-20-01, NDT PART 8/32-20-02, NDT PART 8/32-20-03, NDT PART 8/32-20-04, NDT PART 8/32-20-05					PKG:27	

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 32 - LANDING GEAR											
H3220017 ^S			PERFORM NOSE LANDING GEAR TRUNNION AXLE - VISUAL INSPECTION. IF CORROSION IS FOUND, REMOVE AXLE FROM CYLINDER AND PERFORM FLUORESCENT PENETRANT INSPECTION OF LUG AREA AND MAGNETIC PARTICLE INSPECTION OF AXLE. IF CORROSION IS NOT FOUND, CONDUCT FLUORESCENT PENETRANT INSPECTION OF AXLE PORTION THAT IS EXPOSED FROM CYLINDER.							Service	ATA:32
	MOS	20-Jan-11									
	HRS	0									
	AFL	0	10000 (+ 25/-25)								
					PROC. REF: AMM 05-10-00					PKG:27	
L3220019 ^S			PERFORM NOSE LANDING GEAR ACTUATOR ATTACHMENT PIN - REMOVE PIN AND PERFORM MAGNETIC PARTICLE INSPECTION.							Service	ATA:32
	MOS	20-Jan-11									
	HRS	0									
	AFL	0	10000 (+ 25/-25)								
					PROC. REF: NDT PART 7/32-30-02					PKG:27	
L3220109 ^S			PERFORM NOSE LANDING GEAR ACTUATOR ASSEMBLY - DISASSEMBLE ACTUATOR AND PERFORM DETAILED VISUAL INSPECTION.							Service	ATA:32
	MOS	20-Jan-11									
	HRS	0									
	AFL	0	10000 (+ 25/-25)								
					PROC. REF: GENERIC NO REF					PKG:27	
V3240004 ^S			** EMERGENCY/PARKING BRAKE SWITCH - VERIFY THAT "EMERGENCY/PARKING BRAKE" MESSAGE ILLUMINATES ON EICAS WHEN PARKING BRAKE IS SET AND THROTTLES ARE MOVED ABOVE MCR DETENT.							Service	ATA:32
	MOS	20-Jan-23	24 (+ 14d/-14d)					AIRWORTHINESS			
	HRS	1675	600 (+ 25/-25)								
	AFL	1330									
					PROC. REF: AMM 32-42-01					PKG:11	
V3240008 ^S			** EMERGENCY/PARKING BRAKE CONTROL SYSTEM - PERFORM FUNCTIONAL TEST							Service	ATA:32
	MOS	20-Jan-23	24 (+ 14d/-14d)					AIRWORTHINESS			
	HRS	1675	600 (+ 25/-25)								
	AFL	1330									
					PROC. REF: AMM 32-42-02					PKG:11	
Y3220000 ^S			NOSE LANDING GEAR ASSEMBLY - PERFORM VISUAL INSPECTION							Service	ATA:32
	MOS	20-Jan-23	24 (+ 14d/-14d)								
	HRS	1675	600 (+ 25/-25)								
	AFL	1330									
					PROC. REF: AMM 05-10-00					PKG:11	

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 32 - LANDING GEAR											
Y3220001 ^S			MAIN LANDING GEAR ASSEMBLY - PERFORM VISUAL INSPECTION. INSPECTION TO INCLUDE ACTUATOR, FASTENERS, SUPPORT STRUCTURE, AND SQUAT SWITCHES						Service	ATA:32	
	MOS	20-Jan-23	24 (+ 14d/-14d)								
	HRS	1675	600 (+ 25/-25)								
	AFL	1330									
					PROC. REF: AMM 05-10-00					PKG:11	
Y3220002 ^S			NOSE LANDING GEAR ACTUATOR PRESSURE AND RETURN LINES - PERFORM VISUAL INSPECTION. LOWER ACTUATOR DUST BOOT TO INSPECT LINES						Service	ATA:32	
	MOS	20-Jan-23	24 (+ 14d/-14d)								
	HRS	1675	600 (+ 25/-25)								
	AFL	1330									
					PROC. REF: AMM 05-10-00					PKG:11	
Y3220003 ^S			NOSE GEAR SHOCK STRUT - REMOVE AND REPLACE RETAINER RING LOCKSCREW						Service	ATA:32	
	MOS	20-Jan-23	24 (+ 14d/-14d)								
	HRS	1675	600 (+ 25/-25)								
	AFL	1330									
					PROC. REF: GENERIC NO REF					PKG:11	
Y3220004 ^S			MAIN LANDING GEAR ACTUATOR AND GEAR INBOARD DOOR ACTUATOR ATTACH POINTS - PERFORM VISUAL INSPECTION						Service	ATA:32	
	MOS	20-Jan-23	24 (+ 14d/-14d)								
	HRS	1675	600 (+ 25/-25)								
	AFL	1330									
					PROC. REF: AMM 05-10-00					PKG:11	
Y3220006 ^S			LANDING GEAR ELECTRICAL WIRING - PERFORM VISUAL INSPECTION (THAT PORTION VISIBLE INSIDE WHEEL WELL)						Service	ATA:32	
	MOS	20-Jan-23	24 (+ 14d/-14d)								
	HRS	1675	600 (+ 25/-25)								
	AFL	1330									
					PROC. REF: AMM 05-10-00					PKG:11	
Y3220008 ^S			PERFORM NOSE LANDING GEAR AXLE - REMOVE NOSE LANDING GEAR WHEEL AND PERFORM INSPECTION. INSPECT BOTH INSIDE AND OUTSIDE OF AXLE.						Service	ATA:32	
	MOS	11-Sep-18	48 (+ 14d/-14d)								
	HRS	1387.4	1200 (+ 25/-25)								
	AFL	1114									
					PROC. REF: AMM 32-40-01					PKG:17	

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 32 - LANDING GEAR											
Y3220124 ^S			NOSE LANDING GEAR - PERFORM DETAILED VISUAL INSPECTION OF THE NOSE LANDING GEAR UPLOCK ROLLER BRACKET						Service	ATA:32	
	MOS	20-Jan-23	24 (+ 14d/-14d)								
	HRS	1675	600 (+ 25/-25)								
	AFL	1330									
PROC. REF: AMM 05-10-00										PKG:11	
Y3230002 ^S			MAIN LANDING GEAR FREE FALL ROLLER - PERFORM VISUAL INSPECTION. PAY PARTICULAR ATTENTION TO BINDING OF ROLLERS						Service	ATA:32	
	MOS	20-Jan-23	12 (+ 14d/-14d)								
	HRS	1675	300 (+ 25/-25)								
	AFL	1330									
PROC. REF: AMM 05-10-00										PKG:5	
Y3231023 ^S			MAIN LANDING GEAR INBOARD DOOR ACTUATOR (P/N 7469) END CAP SCREWS - PERFORM DETAILED INSPECTION. (EFFECTIVE ON AIRCRAFT 45-005 THRU 45-276 PRE SB 45-32-19)						Service	ATA:32	
	MOS	20-Jan-23	12 (+ 14d/-14d)								
	HRS	1675	300 (+ 25/-25)								
	AFL	1330									
PROC. REF: AMM 32-31-02										PKG:5	
Y3240000 ^S			NOSE AND MAIN TIRES - PERFORM VISUAL INSPECTION						Service	ATA:32	
	MOS	20-Jan-23	12 (+ 14d/-14d)								
	HRS	1675	300 (+ 25/-25)								
	AFL	1330									
PROC. REF: AMM 12-10-04										PKG:5	
Y3240001 ^S			BRAKE LINES - PERFORM VISUAL INSPECTION. INSPECT ALL BRAKE LINES VISIBLE IN WHEEL WELLS AND ON STRUTS						Service	ATA:32	
	MOS	20-Jan-23	24 (+ 14d/-14d)								
	HRS	1675	600 (+ 25/-25)								
	AFL	1330									
PROC. REF: AMM 05-10-00										PKG:11	
Y3240002 ^S			BRAKE ASSEMBLIES - PERFORM VISUAL INSPECTION WITH PARKING BRAKE SET. WORN BRAKES ARE VISUALLY INDICATED WHEN THE WEAR INDICATOR PINS BECOME EVEN WITH THE OUTER SURFACE OF THE WEAR INDICATOR SLEEVE						Service	ATA:32	
	MOS	20-Jan-23	12 (+ 14d/-14d)								
	HRS	1675	300 (+ 25/-25)								
	AFL	1330									
PROC. REF: AMM 32-41-01										PKG:5	

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty
---------	------	------	----------	-----------	--------------------------	-----------	-----------	-------------	-----	----------

ATA 32 - LANDING GEAR

Y3240003 ^S			PERFORM BRAKE CONTROL SYSTEM LINEAR VARIABLE DIFFERENTIAL TRANSFORMER (LVDT) - VISUAL INSPECTION						Service	ATA:32
	MOS	20-Jan-23	48 (+ 14d/-14d)							
	HRS	1675	1200 (+ 25/-25)							
	AFL	1330								
PROC. REF: AMM 05-10-00									PKG:13	

Y3260005 ^S			NOSE LANDING GEAR SQUAT SWITCH ROTATING DISK ASSEMBLY - LUBRICATE. (EFFECTIVE ON AIRCRAFT 45-001 THRU 45-114 POST SB 45-32-8 AND AIRCRAFT 45-115 AND SUBSEQUENT)						Service	ATA:32
	MOS	20-Jan-23	12 (+ 14d/-14d)							
	HRS	1675	300 (+ 25/-25)							
	AFL	1330								
PROC. REF: AMM 12-21-01									PKG:5	

ATA 33 - LIGHTS

330000			MODIFIED PULSE CONTROLLER						Component	ATA:33
PN:2401S	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:AR01483	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										

331001			NO. 1 LIGHTING CONTROL UNIT						Component	ATA:33
PN:RDC4-1	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:1144	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 33-10-06										

331002			NO. 2 LIGHTING CONTROL UNIT						Component	ATA:33
PN:RDC4-1	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:1146	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 33-10-06										

331010			PILOT FORWARD SWITCH PANEL OVERLAY						Component	ATA:33
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 33-10-05										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 33 - LIGHTS										
331011 PILOT SWITCH PANEL ASSY Component ATA:33										
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
331012 COPILOT FORWARD SWITCH PANEL OVERLAY Component ATA:33										
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 33-10-05										
331013 COPILOT FORWARD SWITCH PANEL ASSY Component ATA:33										
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
331015 CENTER SWITCH (P5) PANEL ASSEMBLY Component ATA:33										
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
331016 CENTER SWITCH PANEL (P5) OVERLAY Component ATA:33										
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 33-10-05										
331017 THROTTLE QUADRANT OVERLAY PANEL Component ATA:33										
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
331018 PILOT AFT CIRCUIT BREAKER PANEL OVERLAY Component ATA:33										
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 33-10-05										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 33 - LIGHTS										
331019 COPILOT AFT CIRCUIT BREAKER PANEL OVERLAY Component ATA:33										
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 33-10-05										
331020 DIMMER CONTROL BOX Component ATA:33										
PN:LT-48G	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:2371	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 33-10-10										
331021 PILOT FWD CIRCUIT BREAKER PANEL OVERLAY Component ATA:33										
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 33-10-05										
331022 CO-PILOT FWD CIRCUIT BREAKER PANEL OVERLAY Component ATA:33										
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 33-10-05										
331023 GLARESHIELD FLOOR FLOODLIGHTS INVERTER Component ATA:33										
PN:6900135-001	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:732	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
331025 COCKPIT MISC RELAY BOX Component ATA:33										
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 33-10-07										
331030 CENTER SWITCH PANEL DIODE (P12) BOX Component ATA:33										
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 33-10-08										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 33 - LIGHTS										
331033 GLARESHIELD FLOODLIGHT POWER SUPPLY Component ATA:33										
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
331040 PILOT REVERSION PANEL (DS55) OVERLAY Component ATA:33										
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
331101 P35 FUSE PANEL ASSY Component ATA:33										
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 33-10-09										
331401-1 NO. 1 LEFT INVERTER (PS5009) SUPPLY PWR Component ATA:33										
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 33-20-10										
331401-10 INVERTER SUPPLY PWR Component ATA:33										
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 33-20-10										
331401-11 INVERTER SUPPLY PWR Component ATA:33										
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 33-20-10										
331401-2 NO. 1 RIGHT INVERTER (PS5003) SUPPLY PWR Component ATA:33										
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 33-20-10										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 33 - LIGHTS											
331401-3		NO. 2 LEFT INVERTER (PS5008) SUPPLY PWR								Component	ATA:33
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 33-20-10											
331401-4		NO. 2 RIGHT INVERTER (PS5004) SUPPLY PWR								Component	ATA:33
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 33-20-10											
331401-5		NO. 3 LEFT INVERTER (PS5007) SUPPLY PWR								Component	ATA:33
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 33-20-10											
331401-6		NO. 3 RIGHT INVERTER (PS5005) SUPPLY PWR								Component	ATA:33
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 33-20-10											
331401-7		NO. 4 LEFT INVERTER (PS5006) SUPPLY PWR								Component	ATA:33
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 33-20-10											
331401-8		NO. 4 RIGHT INVERTER (PS5010) LAV SUPPLY PWR								Component	ATA:33
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 33-20-10											
331401-9		NO. 5 LEFT INVERTER (PS5011) LAV SUPPLY PWR								Component	ATA:33
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 33-20-10											

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 33 - LIGHTS											
332001		RH FWD LIGHTING CONTROL (A5038) UNIT								Component	ATA:33
PN:SP-45-53-2	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:041000169	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 33-20-05											
332002		RH MID FWD LIGHTING CONTROL (A5039) UNIT								Component	ATA:33
PN:SP-45-53-2	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:031000491	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 33-20-05											
332003		RH MID AFT LIGHTING CONTROL (A5040) UNIT								Component	ATA:33
PN:SP-45-53-2	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:031000490	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 33-20-05											
332004		RH AFT LIGHTING CONTROL (A5041) UNIT								Component	ATA:33
PN:SP-45-53-2	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:041000170	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 33-20-05											
332005		L/H FWD LIGHTING CONTROL (A5045) UNIT								Component	ATA:33
PN:SP-45-53-2	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:041000171	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 33-20-05											
332006		LH MID FWD LIGHTING CONTROL (A5044) UNIT								Component	ATA:33
PN:SP-45-53-2	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:041000168	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 33-20-05											
332007		LH MID AFT LIGHTING CONTROL (A5043) UNIT								Component	ATA:33
PN:SP-45-53-2	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:041000167	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 33-20-05											

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 33 - LIGHTS										
332008 LH AFT LIGHTING CONTROL (A5042) UNIT Component ATA:33										
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 33-20-05										
332030 LAVATORY NO SMOKING / RETURN TO SEAT SIGN (DS138) CONTROL UNIT Component ATA:33										
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 33-20-11										
332068 COPILOT LIGHTING CONTROL MODULE Component ATA:33										
PN:SP-45-01-6767	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:051000244	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 33-20-02										
332404 ENTRYWAY CONTROL LIGHT PANEL Component ATA:33										
PN:SP-45-52	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:011000427	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 33-20-01										
333004 TAIL CONE MAINTENANCE LIGHT CHANGE Component ATA:33										
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 33-30-01										
334011 LANDING/TAXI, LEFT LIGHT Component ATA:33										
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 33-40-04										
334012 LANDING/TAXI, RIGHT LIGHT Component ATA:33										
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 33-40-04										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 33 - LIGHTS										
334021 LEFT NAVIGATION (DS37) LIGHT Component ATA:33										
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 33-40-02										
334022 RIGHT NAVIGATION (DS38) LIGHT Component ATA:33										
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 33-40-02										
334023 TAIL NAVIGATION (DS39) LIGHT Component ATA:33										
PN:01-0771011-01	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:00265	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 33-40-02										
334041 COPILOT REVERSION PANEL (DS56) OVERLAY Component ATA:33										
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
334175 RELAY OPTIONS PANEL ASSY Component ATA:33										
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
334332 UPPER ANTI-COLLISION LIGHT Component ATA:33										
PN:GE16386-12-1	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:1491980	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 33-40-01										
334333 LOWER ANTI-COLLISION LIGHT Component ATA:33										
PN:GE16386-12-1	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:1402389	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 33-40-01										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 33 - LIGHTS											
335005		FWD ELS ACTIVATION ASSEMBLY (A81) MODULE								Component	ATA:33
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 33-50-01											
335006		AFT ELS ACTIVATION ASSEMBLY (A82) MODULE								Component	ATA:33
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 33-50-01											
336001		PILOT CHART HOLDER								Component	ATA:33
PN:10-62-01	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:5357	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: GENERIC NO REF											
336002		COPILOT CHART HOLDER								Component	ATA:33
PN:10-62-01	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:6364	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: GENERIC NO REF											
336003		PILOT MAP LIGHT								Component	ATA:33
PN:0204327-001	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:547541	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 33-10-01											
336004		COPILOT MAP LIGHT								Component	ATA:33
PN:0204327-001	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:546558	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 33-10-01											

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 33 - LIGHTS											
Y3310000 ^S		FLIGHT COMPARTMENT LIGHTING - PERFORM OPERATION OF THE FOLLOWING: A. MAP LIGHTS. B. INSTRUMENT PANEL FLUORESCENT LIGHTS. C. INSTRUMENT/INDICATOR LIGHTS. D. LIGHT DIMMING SWITCHES. E. CREW WARNING PANEL. F. PANEL OVERLAYS.							Service	ATA:33	
	MOS	20-Jan-23	12 (+ 14d/-14d)								
	HRS	1675	300 (+ 25/-25)								
	AFL	1330									
PROC. REF: AMM 33-10-00										PKG:1	
Y3340000 ^S		EXTERIOR LIGHTING SYSTEMS - PERFORM OPERATION OF THE FOLLOWING: A. TAXI LIGHTS. B. ANTI-COLLISION BEACONS. C. NAVIGATION LIGHTS. D. STROBE LIGHTS. E. LANDING/RECOGNITION LIGHTS. F. WING ICE INSPECTION LIGHTS. G. EMERGENCY DOOR EGRESS LIGHTS.							Service	ATA:33	
	MOS	20-Jan-23	12 (+ 14d/-14d)								
	HRS	1675	300 (+ 25/-25)								
	AFL	1330									
PROC. REF: AMM 33-40-00, AMM 33-41-00										PKG:2	
Y3350003 ^S		EMERGENCY LIGHTING SYSTEM - PERFORM OPERATIONAL CHECK							Service	ATA:33	
	MOS	20-Jan-23	48 (+ 14d/-14d)								
	HRS	1675	1200 (+ 25/-25)								
	AFL	1330									
PROC. REF: AMM 33-50-00										PKG:14	
ATA 34 - NAVIGATION											
34-00-FAR-91.171		CHECK VOR EQUIPMENT FOR IFR OPERATIONS FAR 91.171							Service	ATA:34	
	MOS/MSC	20-Jan-11	O/C								
	HRS	0									
	AFL	0									
PROC. REF: GENERIC NO REF, FAR FAR 91.171											
341001		NO. 1 AIR DATA COMPUTER							Component	ATA:34	
PN:7030700-71704	MOS/MSC	11-Sep-18	O/C								
SN:09032254	HRS	1387.4									
	AFL	1114									
PROC. REF: AMM 34-17-01											
341001A		TEST/INSPECT NO. 1 AIR DATA COMPUTER							Service	ATA:34	
PN:7030700-71704	MOS	20-Jan-23	24		20-Jan-25		712 d				
SN:09032254	HRS										
	AFL										
PROC. REF: FAR FAR 91.411, AMM 34-17-00, CFR 14 CFR PART 43 APP E											

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 34 - NAVIGATION										
341002	NO. 2 AIR DATA COMPUTER									Component ATA:34
PN:7030700-71704	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:09032255	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 34-17-01										
341002A	TEST/INSPECT NO. 2 AIR DATA COMPUTER									Service ATA:34
PN:7030700-71704	MOS	20-Jan-23	24		20-Jan-25		712 d			
SN:09032255	HRS									
	AFL									
PROC. REF: FAR FAR 91.411, AMM 34-17-00, CFR 14 CFR PART 43 APP E										
341013	STANDBY AIRSPEED INDICATOR									Component ATA:34
PN:26240-1129	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:294487	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 34-18-01										
341025	STANDBY ALTIMETER									Component ATA:34
PN:7634208001-003	MOS/MSC	11-Sep-18	O/C	TSO 0						
SN:171165B	HRS	1387.4		TSO 0						
	AFL	1114		TSO 0						
PROC. REF: AMM 34-15-01										
341025A	TEST/INSPECT STANDBY ALTIMETER									Service ATA:34
PN:7634208001-003	MOS	20-Jan-23	24		20-Jan-25		712 d			
SN:171165B	HRS									
	AFL									
PROC. REF: FAR FAR 91.411, AMM 34-15-01, CFR 14 CFR PART 43 APP E										
341037	LEFT PRIMARY PITOT/STATIC PROBE (P/N 0856TJ1 OR P/N 6634100000-001)									Component ATA:34
PN:0856TJ1	MOS	20-Jan-11		TSN 0				LIFE LIMIT		
SN:262350	HRS	0	15000 (+25/-25)	TSN 0	15000	15025	13325 (+25)			
	AFL	0		TSN 0						
PROC. REF: AMM 34-11-01										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 34 - NAVIGATION											
341037A		TEST/INSPECT LEFT PRIMARY PITOT/STATIC PROBE (P/N 0856TJ1 OR P/N 6634100000-001)								Service	ATA:34
PN:0856TJ1	MOS	20-Jan-23	24		20-Jan-25		712 d				
SN:262350	HRS										
	AFL										
PROC. REF: GENERIC NO REF, FAR FAR 91.411, CFR 14 CFR PART 43 APP E											
341038		RIGHT PRIMARY PITOT/STATIC PROBE (P/N 0856TJ2 OR P/N 6634100000-003)								Component	ATA:34
PN:0856TJ2	MOS	20-Jan-11		TSN 0				LIFE LIMIT			
SN:262450	HRS	0	15000 (+25/-25)	TSN 0	15000	15025	13325 (+25)				
	AFL	0		TSN 0							
PROC. REF: AMM 34-11-01											
341038A		TEST/INSPECT RIGHT PRIMARY PITOT/STATIC PROBE (P/N 0856TJ2 OR P/N 6634100000-003)								Service	ATA:34
PN:0856TJ2	MOS	20-Jan-23	24		20-Jan-25		712 d				
SN:262450	HRS										
	AFL										
PROC. REF: FAR FAR 91.411, AMM 34-11-00, CFR 14 CFR PART 43 APP E											
341049		STANDBY PITOT/STATIC PROBE								Component	ATA:34
PN:0856TJ4	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:261940	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 34-11-01											
341049A		TEST/INSPECT STANDBY PITOT/STATIC PROBE								Service	ATA:34
	MOS	20-Jan-23	24		20-Jan-25		712 d				
	HRS	1675									
	AFL	1330									
PROC. REF: FAR FAR 91.411, AMM 34-11-00, CFR 14 CFR PART 43 APP E											
341061		RADAR ALTIMETER RECEIVER								Component	ATA:34
PN:7001840-936	MOS/MSC	06-Jun-11	O/C								
SN:0407B462	HRS	116.1									
	AFL	76									
PROC. REF: AMM 34-14-01											
341073		FORWARD RADAR ALTIMETER ANTENNA								Component	ATA:34
PN:S67-2002-4	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:522-16789	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 34-14-02											

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty
---------	------	------	----------	-----------	--------------------------	-----------	-----------	-------------	-----	----------

ATA 34 - NAVIGATION

341074		AFT RADAR ALTIMETER ANTENNA								Component	ATA:34
PN:S67-2002-4	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:522-16778	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 34-14-02											

3413-RVSM		FLIGHT CHECK ALTITUDE ALERTER FUNCTION. RVSM COMPLIANT AIRCRAFT.								Service	ATA:34
	MOS/MSC	20-Jan-11	N/R								
	HRS	0									
	AFL	0									
PROC. REF: GENERIC NO REF											

341901		(TAT) TOTAL AIR TEMPERATURE PROBE								Component	ATA:34
PN:102AU1AG	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:B1715	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 34-17-02											

342001		(AHRS) NO. 1 ATTITUDE HEADING REFERENCE COMPUTER								Component	ATA:34
PN:145130-6000	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:2121	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 34-26-01											

342002		(AHRS) NO. 2 ATTITUDE HEADING REFERENCE COMPUTER								Component	ATA:34
PN:145130-6000	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:1382	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 34-26-01											

342003		(AHRS) NO. 1 ATTITUDE HEADING REFERENCE COMPUTER FAN								Component	ATA:34
PN:140691-0000	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:5466	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 34-26-03											

342004		(AHRS) NO. 2 ATTITUDE HEADING REFERENCE COMPUTER FAN								Component	ATA:34
PN:140691-0000	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:5456	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 34-26-03											

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 34 - NAVIGATION											
342037		LEFT FLUX VALVE								Component	ATA:34
PN:7010133	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:0904J368	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 34-26-02											
342038		RIGHT FLUX VALVE								Component	ATA:34
PN:7010133	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:0904J367	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 34-26-02											
342101		DUAL ANGLE OF ATTACK INDICATOR								Component	ATA:34
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: GENERIC NO REF											
342103		STANDBY COMPASS								Component	ATA:34
PN:PAI700-5V	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:69993	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 34-21-01											
342103A		CALIBRATION CHECK STANDBY COMPASS								Service	ATA:34
PN:PAI700-5V	MOS/MSC	09-Dec-13	A/R								
SN:69993	HRS	787.1									
	AFL	714									
PROC. REF: GENERIC NO REF											
342701		LEFT ATTITUDE HEADING REFERENCE SYSTEM (Ahrs) MEMORY MODULE								Component	ATA:34
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 34-26-01											
342702		RIGHT ATTITUDE HEADING REFERENCE SYSTEM (Ahrs) MEMORY MODULE								Component	ATA:34
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 34-26-01											

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 34 - NAVIGATION										
342801	STANDBY ATTITUDE INDICATOR									Component ATA:34
PN:6634208002-003	MOS/MSC	23-Oct-20	O/C	TSR 0						
SN:270705	HRS	1570.8		TSR 0						
	AFL	1243		TSR 0						
PROC. REF: AMM 34-23-01										
343005	MARKER BEACON ANTENNA									Component ATA:34
PN:DMN27-3	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:17202	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 34-30-01										
343008	UPPER GLIDESCOPE (E11) ANTENNA									Component ATA:34
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 34-30-02										
343009	LOWER GLIDESCOPE (E12) ANTENNA									Component ATA:34
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 34-30-02										
343030	MARKER BEACON ANTENNA SPLITTER									Component ATA:34
PN:DMH21-1	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:45298	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 34-30-03										
344101	AIRSERVE COMPUTER CHANGE									Component ATA:34
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
344102	RS-232 CONVERTER CHANGE									Component ATA:34
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 34 - NAVIGATION											
344111		UPPER TCAS ANTENNA								Component	ATA:34
PN:7514081-913	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:ANE32253	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 34-43-02											
344112		LOWER TCAS ANTENNA								Component	ATA:34
PN:7514081-913	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:ANE32447	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 34-43-02											
344143		TCAS PROCESSOR								Component	ATA:34
PN:7517900-55004	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:20010469	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 34-43-01											
344155		TCAS RELAY BOX ASSEMBLY								Component	ATA:34
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 34-43-03											
344167		TCAS CONFIGURATION MODULE								Component	ATA:34
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: GENERIC NO REF											
344171		NO. 1 TCAS UPPER ANTENNA CABLE								Component	ATA:34
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: GENERIC NO REF											
344172		NO. 2 TCAS UPPER ANTENNA CABLE								Component	ATA:34
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: GENERIC NO REF											

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 34 - NAVIGATION											
344173		NO. 3 TCAS UPPER ANTENNA CABLE								Component	ATA:34
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: GENERIC NO REF											
344174		NO. 4 TCAS UPPER ANTENNA CABLE								Component	ATA:34
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: GENERIC NO REF											
344176		UPPER TCAS ADAPTER ASSEMBLY								Component	ATA:34
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: GENERIC NO REF											
344177		LOWER TCAS ADAPTER ASSEMBLY								Component	ATA:34
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: GENERIC NO REF											
344181		NO. 1 TCAS LOWER ANTENNA CABLE								Component	ATA:34
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: GENERIC NO REF											
344182		NO. 2 TCAS LOWER ANTENNA CABLE								Component	ATA:34
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: GENERIC NO REF											
344183		NO. 3 TCAS LOWER ANTENNA CABLE								Component	ATA:34
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: GENERIC NO REF											

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 34 - NAVIGATION											
344184		NO. 4 TCAS LOWER ANTENNA CABLE							Component	ATA:34	
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: GENERIC NO REF											
344201		GPS / XM WEATHER ANTENNA							Component	ATA:34	
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 34-53-01											
344205		WEATHER RADAR RECEIVER/TRANSMITTER/ANTENNA							Component	ATA:34	
PN:7021479-2	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:5331	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 34-42-01											
344207		WEATHER RADAR TRANSCEIVER							Component	ATA:34	
PN:7021450-801	MOS/MSC	08-Sep-14	O/C								
SN:1003B108	HRS	870.1									
	AFL	779									
PROC. REF: AMM 34-42-01											
344209		WEATHER RADAR LIGHTNING SENSOR ANTENNA							Component	ATA:34	
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: GENERIC NO REF											
344221		WEATHER RADAR CONTROLLER							Component	ATA:34	
PN:7008471-407	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:0901B046	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 34-42-02											
344223		LIGHTNING DETECTION PROCESSOR							Component	ATA:34	
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: GENERIC NO REF											

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 34 - NAVIGATION										
344513 TERRAIN AWARENESS WARNING (TAWS) COMPUTER Component ATA:34										
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
344514 TERRAIN AWARENESS WARNING (TAWS) CONFIGURATION MODULE Component ATA:34										
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
344515 TAWS RELAY BOX Component ATA:34										
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
345001 NO. 1 INTEGRATED NAVIGATION UNIT Component ATA:34										
PN:7510100-631	MOS/MSC	25-Jan-11	O/C							
SN:1012C417	HRS	10								
	AFL	7								
PROC. REF: GENERIC NO REF										
345002 NO. 2 INTEGRATED NAVIGATION UNIT Component ATA:34										
PN:7510100-633	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:1003C248	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
345011 NO. 1 NAVIGATION RECEIVER MODULE Component ATA:34										
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
345012 NO. 2 NAVIGATION RECEIVER MODULE Component ATA:34										
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 34 - NAVIGATION											
345013		NO. 1 ADF ANTENNA								Component	ATA:34
PN:7510300-901	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:0811F309	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 34-57-01											
345014		NO. 2 ADF ANTENNA								Component	ATA:34
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 34-57-01											
345024		GPWS CONTROL PANEL								Component	ATA:34
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: GENERIC NO REF											
345025		ENHANCED GROUND PROXIMITY WARNING (EGPWS) COMPUTER								Component	ATA:34
PN:965-0976-040-226-226	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:EMK5-29497	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 34-45-01											
345037		FORWARD ATC ANTENNA								Component	ATA:34
PN:DMN150-2-2	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:120382	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: GENERIC NO REF											
345038		AFT ATC ANTENNA								Component	ATA:34
PN:DMN150-2-2	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:121753	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: GENERIC NO REF											
345049		AFT (NO. 1) DME ANTENNA								Component	ATA:34
PN:DMN150-2-2	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:120366	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 34-55-01											

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 34 - NAVIGATION											
345050		FORWARD (NO. 2) DME ANTENNA								Component	ATA:34
PN:DMN150-9-2	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:12190	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 34-55-01											
345083		LEFT VOR/LOCALIZER ANTENNA								Component	ATA:34
PN:DMN4-17-1/N	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:26712	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 34-51-02											
345084		RIGHT VOR/LOCALIZER ANTENNA								Component	ATA:34
PN:DMN4-17-1/N	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:26711	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 34-51-02											
345201		NAV VHF (A42) DUPLEXER								Component	ATA:34
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 34-51-04											
345260		PHASING COUPLER								Component	ATA:34
PN:DMN4-17-2	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:21271	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 34-51-03											
345501		DME INDICATOR								Component	ATA:34
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: GENERIC NO REF											
345605		LEFT UPPER MODE S ATC ANTENNA								Component	ATA:34
PN:DMN150-2-2	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:121747	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: GENERIC NO REF											

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 34 - NAVIGATION											
345606		RIGHT UPPER MODE S ATC ANTENNA								Component	ATA:34
PN:DMN150-2-2	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:121794	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: GENERIC NO REF											
346001		PILOT FLIGHT MANAGEMENT CONTROL DISPLAY CDU								Component	ATA:34
PN:3017-41-221	MOS/MSC	11-Sep-18	O/C	TSN 0							
SN:2543	HRS	1387.4		TSN 0							
	AFL	1114		TSN 0							
PROC. REF: AMM 34-60-01											
346001A		NO.1 FMS BATTERY REPLACE								Component	ATA:34
PN:PN-UNKNOWN	MOS/MSC	04-Feb-13	A/R								
SN:UNKNOWN	HRS	528.7									
	AFL	457									
PROC. REF: GENERIC NO REF											
346002		COPILOT FLIGHT MANAGEMENT CONTROL DISPLAY CDU								Component	ATA:34
PN:3017-41-221	MOS/MSC	11-Sep-18	O/C	TSN 0							
SN:2542	HRS	1387.4		TSN 0							
	AFL	1114		TSN 0							
PROC. REF: GENERIC NO REF											
346002A		NO.2 FMS BATTERY REPLACE								Component	ATA:34
PN:PN	MOS/MSC	20-Jan-11	A/R	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: GENERIC NO REF											
346021		FMS DATA (DTU) TRANSFER UNIT								Component	ATA:34
PN:1408-00-1	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:651	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 34-60-02											
346025		NO. 1 FLIGHT MANAGEMENT CONFIGURATION MODULE								Component	ATA:34
PN:30171	MOS/MSC	11-Sep-18	O/C								
SN:2682	HRS	1387.4									
	AFL	1114									
PROC. REF: GENERIC NO REF											

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 34 - NAVIGATION											
346026		NO. 2 FLIGHT MANAGEMENT CONFIGURATION MODULE								Component	ATA:34
PN:30171	MOS/MSC	11-Sep-18	O/C	TSN 92							
SN:2683	HRS	1387.4		TSN 1387.4							
	AFL	1114		TSN 1114							
PROC. REF: GENERIC NO REF											
346031		NO. 1 FMS ANTENNA								Component	ATA:34
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: GENERIC NO REF											
346032		NO. 2 FMS ANTENNA								Component	ATA:34
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: GENERIC NO REF											
346090		AFIS DATA MANAGEMENT UNIT								Component	ATA:34
PN:400-045500-003	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:4030	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: GENERIC NO REF											
346092		AFIS (FLIGHT INFORMATION SYSTEM) ANTENNA REPLACE								Component	ATA:34
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: GENERIC NO REF											
347510		NO. 1 GPS ANTENNA								Component	ATA:34
PN:AT2300-326LJ	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:5073	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 34-53-01											
347511		NO. 2 GPS ANTENNA								Component	ATA:34
PN:AT2300-326LJ	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:5085	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 34-53-01											

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 34 - NAVIGATION										
5-19-02-RVSM-L3411062	DETAILED VISUAL INSPECTION OF PITOT-STATIC PROBES RVSM COMPLIANT AIRCRAFT(ZONE/ACCESS 220 IRN # L3411062)								Service	ATA:34
MOS	20-Jan-23	24 (+ 14d/-14d)	Adj -131d	11-Sep-24	25-Sep-24	581 d (+ 14)	RVSM			
HRS	1675									
AFL	1330									
PROC. REF: AMM 34-11-01										
5-19-02-RVSM-M3411052	VERIFY PITCH, ROLL, AND YAW ALIGNMENT OF THE PRIMARY PITOT-STATIC PROBES RVSM COMPLIANT AIRCRAFT (IRN # M3411052)								Service	ATA:34
MOS	20-Jan-23	24 (+ 14d/-14d)	Adj -131d	11-Sep-24	25-Sep-24	581 d (+ 14)	RVSM			
HRS	1675									
AFL	1330									
PROC. REF: AMM 34-11-01										
5-19-02-RVSM-U3411060	PERFORM FUNCTIONAL TEST - AIR DATA SYSTEM (EFFECTIVE ON AIRCRAFT CERTIFIED & MAINTAINED FOR RVSM) (REFER TO 34-17-00) (IRN U3411060)								Service	ATA:34
MOS	20-Jan-23	24 (+ 14d/-14d)	Adj -131d	11-Sep-24	25-Sep-24	581 d (+ 14)	RVSM			
HRS	1675									
AFL	1330									
PROC. REF: AMM 34-17-00										
A3400000 ^S	** NAVIGATION SYSTEMS - PERFORM OPERATIONAL CHECK								Service	ATA:34
MOS	20-Jan-23	24 (+ 14d/-14d)						AIRWORTHINESS		
HRS	1675	600 (+ 25/-25)								
AFL	1330									
PROC. REF: AMM 34-00-00										
ST01509WI-D	INSTALL UPDATED HONEYWELL MARK V ENHANCED GROUND PROXIMITY WARNING SYSTEM (EGPWS W/RAAS)								Service	ATA:34
MOS/MSC	20-Jan-11	O/C						STC-SUPPLEMENTAL TYPE CERTIFICATE		
HRS	0									
AFL	0									
PROC. REF: GENERIC NO REF										
V3420000 ^S	ATTITUDE HEADING REFERENCE UNIT (AHRU) MOUNTING TRAY FAN FILTER - PERFORM VISUAL INSPECTION. ENSURE FILTER IS FREE OF OBSTRUCTIONS.								Service	ATA:34
MOS	20-Jan-23	24 (+ 14d/-14d)								
HRS	1675	600 (+ 25/-25)								
AFL	1330									
PROC. REF: AMM 05-10-00										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 34 - NAVIGATION										
Y3411000 ^S	PITOT-STATIC PROBE - PERFORM VISUAL INSPECTION. ENSURE DRAIN HOLES ARE CLEAR OF OBSTRUCTIONS									Service ATA:34
	MOS	20-Jan-23	24 (+ 14d/-14d)							
	HRS	1675	600 (+ 25/-25)							
	AFL	1330								
					PROC. REF: AMM 34-11-01					PKG:7
Y3440000 ^S	PERFORM RADOME STRUCTURE AND ANTENNA INSTALLATION - VISUAL INSPECTION									Service ATA:34
	MOS	20-Jan-23	48 (+ 14d/-14d)							
	HRS	1675	1200 (+ 25/-25)							
	AFL	1330								
					PROC. REF: AMM 05-10-00					PKG:13
ATA 35 - OXYGEN										
350001	OXYGEN CYLINDER									Component ATA:35
PN:663500000-123	MOS	20-Jan-23	180 (+ 14d/-14d)	TSO 0	01-Jan-35	15-Jan-35	4345 d (+ 14)	LIFE LIMIT		
SN:ALT281-47121	HRS	1675		TSO 0						
	AFL	1330		TSO 0						
			Manufacture Date:: 01-Jan-20		PROC. REF: AMM 35-00-01					
350001A	HYDROSTATIC TEST OXYGEN CYLINDER ** (IRN Q3510005 - STANDARD CAPACITY; Q3510018 - INCREASED CAPACITY)									Service ATA:35
PN:663500000-123	MOS	01-May-20	60 (+ 14d/-14d)		01-May-25	15-May-25	813 d (+ 14)			
SN:ALT281-47121	HRS		5000 (+ 25/-25)		?		?			
	AFL									
					PROC. REF: GENERIC NO REF					
350001C	FUNCTIONAL TEST OXYGEN CYLINDER ** LOW PRESSURE RELIEF VALVE (IRN Q3510005 - STANDARD CAPACITY; Q3510018 - INCREASED CAPACITY)									Service ATA:35
PN:663500000-123	MOS	20-Jan-23	60 (+ 14d/-14d)		20-Jan-28	03-Feb-28	1807 d (+ 14)			
SN:ALT281-47121	HRS	1675	5000 (+ 25/-25)		6675	6700	5000 (+ 25)			
	AFL	1330								
					PROC. REF: GENERIC NO REF					
350013	OXYGEN CYLINDER LOW PRESSURE RELIEF VALVE									Component ATA:35
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: GENERIC NO REF					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 35 - OXYGEN											
350201		TEMP/PRESSURE TRANSDUCER							Component	ATA:35	
PN:10008789	MOS/MSC	20-Jan-23	O/C	TSO 0							
SN:20191358	HRS	1675		TSO 0							
	AFL	1330		TSO 0							
PROC. REF: AMM 35-00-03											
350225		OXYGEN FILL (POST SB 45-12-1) VALVE							Component	ATA:35	
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: GENERIC NO REF											
350230		REMOTE OXYGEN PRESSURE INDICATOR							Component	ATA:35	
PN:P24090	MOS/MSC	23-May-16	O/C	TSN 0							
SN:074	HRS	1039.2		TSN 0							
	AFL	899		TSN 0							
PROC. REF: AMM 35-00-05											
351001		PILOT OXYGEN MASK							Component	ATA:35	
PN:MC10-15-166	MOS/MSC	20-Jan-23	O/C								
SN:SE74066	HRS	1675									
	AFL	1330									
PROC. REF: AMM 35-10-01											
351001A		OVERHAUL PILOT OXYGEN MASK PER MANUFACTURER'S INSTRUCTIONS (IRN # L3510016/O3510006)							Service	ATA:35	
PN:MC10-15-166	MOS		72 (+14d/-14d)		01-Nov-28 (M)	15-Nov-28	2093 d (+14)				
SN:SE74066	HRS										
	AFL										
PROC. REF: GENERIC NO REF											
351002		COPILOT OXYGEN MASK							Component	ATA:35	
PN:MC10-15-166	MOS/MSC	20-Jan-23	O/C	TSO 0							
SN:SE12580	HRS	1675		TSO 0							
	AFL	1330		TSO 0							
PROC. REF: AMM 35-10-01											
351002A		OVERHAUL COPILOT OXYGEN MASK PER MANUFACTURER'S INSTRUCTIONS (IRN # L3510016/O3510006)							Service	ATA:35	
PN:MC10-15-166	MOS		72 (+14d/-14d)		01-Apr-28 (M)	15-Apr-28	1879 d (+14)				
SN:SE12580	HRS										
	AFL										
PROC. REF: GENERIC NO REF											

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 35 - OXYGEN										
351003	PASSENGER OXYGEN MASK (OVHL/SCRAP) - 289 SERIES PAX OXYGEN MASK (REFER ZODIAC / AVOX MANUAL 833-35-01) REPLACE								Component	ATA:35
PN:289-601-228	MOS	08-Nov-21	72 (+14d/-14d)	TSN 0, Adj -1753d	01-Dec-25 (M)	15-Dec-25	1027 d (+14)	VENDOR RECOMMENDATION		
SN:UNKNOWN	HRS	1605.6		TSN 0						
	AFL	1281		TSN 0						
PROC. REF: AMM 35-20-03, SI 833-35-01										
351003A	INSPECTION PASSENGER OXYGEN MASK (INSPECTION) - PERFORM VISUAL INSPECTION OF 289 SERIES PAX OXYGEN MASK (REFER ZODIAC / AVOX MANUAL 833-35-01).								Service	ATA:35
	MOS	08-Nov-21	36 (+14d/-14d)		08-Nov-24	22-Nov-24	639 d (+14)	VENDOR RECOMMENDATION		
	HRS	1605.6								
	AFL	1281								
PROC. REF: GENERIC NO REF, SI 833-35-01										
351005	PILOT CREW OXYGEN OUTLET								Component	ATA:35
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 35-10-01										
351006	COPILOT CREW -OXYGEN OUTLET								Component	ATA:35
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 35-10-01										
352002	ALTITUDE COMPENSATING REGULATOR								Component	ATA:35
PN:6635000000-127	MOS/MSC	06-Nov-17	O/C	TSO 0						
SN:00182	HRS	1300.2		TSO 0						
	AFL	1056		TSO 0						
PROC. REF: AMM 35-20-06										
352011	OXYGEN CONTROL VALVE								Component	ATA:35
PN:P21081	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:0631	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 35-20-01										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 35 - OXYGEN											
352025		OXYGEN CYLINDER REGULATOR								Component	ATA:35
PN:806370-07	MOS/MSC	20-Jan-23	O/C	TSO 31							
SN:C08060915	HRS	1675		TSO 0							
	AFL	1330		TSO 0							
PROC. REF: GENERIC NO REF											
353001		PORTABLE OXYGEN CYLINDER								Component	ATA:35
PN:5500-C1W-BF23A	MOS/MSC	08-Nov-21	O/C	TSN 118							
SN:ST285665	HRS	1605.6									
	AFL	1281									
PROC. REF: AMM 35-00-01											
353001A		HYDROSTATIC CHECK PORTABLE OXYGEN CYLINDER (IRN Q3500024)								Service	ATA:35
PN:5500-C1W-BF23A	MOS	01-Nov-21	60 (+14d/-14d)		01-Nov-26	15-Nov-26	1362 d (+14)				
SN:ST285665	HRS										
	AFL										
PROC. REF: GENERIC NO REF											
353001B		VISUALLY INSPECT PORTABLE OXYGEN CYLINDER PER MANUFACTURER'S INSTRUCTIONS								Service	ATA:35
PN:5500-C1W-BF23A	MOS/MSC		-								
SN:ST285665	HRS										
	AFL										
PROC. REF: GENERIC NO REF											
355111		OXYGEN PRESSURE INDICATOR								Component	ATA:35
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 35-00-05											
5-19-00-K3500021		** OXYGEN SYSTEM LOW PRESSURE SUPPLY HOSES - PERFORM OPERATIONAL CHECK. ENSURE THAT HOSES ARE FREE OF OBSTRUCTIONS.								Service	ATA:35
	MOS/MSC	20-Jan-11	N/A								
	HRS	0									
	AFL	0									
PROC. REF: AMM 35-00-00											

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 35 - OXYGEN											
5-19-00-N3510013			PERFORM ** PERIODIC CHECK OF OXYGEN CYLINDER AND REMOTE OXYGEN FILL VALVES (IRN N3510013)							Service	ATA:35
	MOS/MSC	20-Jan-11	N/A					N/A EQUIPMENT NOT INSTALLED			
	HRS	0									
	AFL	0									
PROC. REF: AMM 35-00-01											
5-19-00-N3510019			PERFORM ** PERIODIC CHECK OF THE OXYGEN CYLINDER AND REMOTE FILL VALVES. EFFECTIVE ON AIRCRAFT EQUIPPED WITH INCREASED CAPACITY OXYGEN SYSTEM. (IRN N3510019)							Service	ATA:35
	MOS	10-Oct-19									
	HRS	1509.8	1500 (+25/-25)	Adj -9.8	3000	3025	1325 (+25)				
	AFL	1201									
PROC. REF: AMM 35-00-01											
5-19-00-Q3510022			PERFORM OXYGEN CYLINDER REGULATOR - OVERHAUL							Service	ATA:35
	MOS/MSC	20-Jan-11	N/A								
	HRS	0									
	AFL	0									
PROC. REF: GENERIC NO REF											
5-19-00-Q3510023			PERFORM OXYGEN CYLINDER REGULATOR - OVERHAUL (EFFECTIVE ON AIRCRAFT EQUIPPED WITH INCREASED CAPACITY OXYGEN SYSTEM)							Service	ATA:35
	MOS	20-Jan-23	60 (+14d/-14d)	Adj -111d	01-Oct-27	15-Oct-27	1696 d (+14)				
	HRS	1675	5000 (+25/-25)		6675	6700	5000 (+25)				
	AFL	1330									
PROC. REF: GENERIC NO REF											
O3510003 ^S			** CABIN LOW PRESSURE OXYGEN DISTRIBUTION FLEX HOSES - PERFORM FUNCTIONAL TEST.							Service	ATA:35
	MOS	20-Jan-23	24 (+14d/-14d)					AIRWORTHINESS			
	HRS	1675	600 (+25/-25)								
	AFL	1330									
PROC. REF: AMM 35-20-00											
S3510014 ^S			** OXYGEN SYSTEM ALTITUDE COMPENSATING REGULATOR - PERFORM FUNCTIONAL TEST. (EFFECTIVE ON AIRCRAFT 45-170 AND SUBSEQUENT AND PRIOR AIRCRAFT MODIFIED BY SB 45-35-1)							Service	ATA:35
	MOS	20-Jan-23	24 (+14d/-14d)					AIRWORTHINESS			
	HRS	1675	600 (+25/-25)								
	AFL	1330									
PROC. REF: AMM 35-20-00											

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 35 - OXYGEN											
W 3510002 ^S		** OXYGEN SYSTEM - PERFORM OPERATIONAL CHECK							Service	ATA:35	
	MOS	20-Jan-23	24 (+ 14d/-14d)					AIRWORTHINESS			
	HRS	1675	600 (+ 25/-25)								
	AFL	1330									
PROC. REF: AMM 35-00-00										PKG:7	
Y3510000 ^S		PERFORM OXYGEN CYLINDER INSTALLATION - VISUAL INSPECTION. CHECK PLUMBING FOR ROUTING, SECURITY, AND CONDITION							Service	ATA:35	
	MOS	20-Jan-23	48 (+ 14d/-14d)								
	HRS	1675	1200 (+ 25/-25)								
	AFL	1330									
PROC. REF: AMM 05-10-00										PKG:13	
Y3510001 ^S		CREW SEAT OXYGEN HOSES - PERFORM VISUAL INSPECTION. PAY PARTICULAR ATTENTION TO AREA WHERE OXYGEN HOSES ENTER CREW SEATS ABOVE COCKPIT FLOOR							Service	ATA:35	
	MOS	20-Jan-23	12 (+ 14d/-14d)								
	HRS	1675	300 (+ 25/-25)								
	AFL	1330									
PROC. REF: AMM 05-10-00										PKG:1	
Y3510017 ^S		OXYGEN CYLINDER INSTALLATION - PERFORM VISUAL INSPECTION. CHECK PLUMBING FOR ROUTING, SECURITY, AND CONDITION. (EFFECTIVE ON AIRCRAFT EQUIPPED WITH INCREASED CAPACITY OXYGEN SYSTEM.)							Service	ATA:35	
	MOS	20-Jan-23	24 (+ 14d/-14d)								
	HRS	1675	600 (+ 25/-25)								
	AFL	1330									
PROC. REF: AMM 05-10-00										PKG:7	
ATA 36 - PNEUMATIC											
361001		LEFT ASSEMBLY, HP TAILCONE OUTBOARD MANIFOLD							Component	ATA:36	
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: GENERIC NO REF											
361002		LEFT ASSEMBLY, ANTI-ICE OUTBOARD MANIFOLD							Component	ATA:36	
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 30-10-07											

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 36 - PNEUMATIC											
361004		LEFT INBOARD HPBA MANIFOLD ASSEMBLY								Component	ATA:36
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 36-10-07											
361005		RIGHT INBOARD HPBA MANIFOLD ASSEMBLY								Component	ATA:36
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 36-10-07											
361015		MANIFOLD ASSEM, CENTER REPLACE								Component	ATA:36
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: GENERIC NO REF											
361016		RIGHT ASSEMBLY, ANTI-ICE OUTBOARD MANIFOLD								Component	ATA:36
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 30-10-07											
361017		RIGHT ASSEMBLY, HP TAILCONE OUTBOARD MANIFOLD								Component	ATA:36
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: GENERIC NO REF											
361020		LEFT HP OVER-TEMP SWITCH								Component	ATA:36
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 36-20-03											
361021		RIGHT HP OVER-TEMP SWITCH								Component	ATA:36
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 36-20-03											

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 36 - PNEUMATIC										
361031	ECS CONTROLLER									Component ATA:36
PN:1165-1-6	MOS/MSC	08-Mar-20	O/C							
SN:9929140	HRS	1550.5								
	AFL	1226								
PROC. REF: AMM 36-10-01										
361040	VALVE, APU BLEED AIR CHECK REPLACE									Component ATA:36
PN:4011-14	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:0368	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 36-10-09										
361050	LOAD CONTROL (SHUTOFF (L5003) VALVE									Component ATA:36
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 36-10-10										
361053	NO. 1 ECS SHUTOFF (L37) VALVE									Component ATA:36
PN:3215468-1	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:1211	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 36-10-03										
361054	NO. 2 ECS SHUTOFF (L38) VALVE									Component ATA:36
PN:3215468-1	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:1228	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 36-10-03										
361055	ECS SHUTOFF VALVE									Component ATA:36
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 36-10-03										
361056	ECS SHUTOFF VALVE									Component ATA:36
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 36-10-03										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 36 - PNEUMATIC										
361065 LEFT TAILCONE HIGH PRESSURE SHUT-OFF (L39) VALVE Component ATA:36										
PN:3291216-2	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:1306	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 36-10-02										
361066 RIGHT TAILCONE HIGH PRESSURE SHUT-OFF (L40) VALVE Component ATA:36										
PN:3291216-2	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:1334	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 36-10-02										
361120 NO. 1 PRESSURE (S79) SWITCH Component ATA:36										
PN:642019-5	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:0780	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 36-10-06										
361121 NO. 2 PRESSURE (S88) SWITCH Component ATA:36										
PN:642019-5	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:0549	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 36-10-06										
361122 LEFT HAND HP BLEED AIR TUBE ASSEMBLY Component ATA:36										
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
361123 RIGHT HAND HP BLEED AIR TUBE ASSEMBLY Component ATA:36										
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
361125 LEFT PYLON LOW PRESSURE TEMPERATURE SENSOR Component ATA:36										
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 36 - PNEUMATIC											
361126		RIGHT PYLON LOW PRESSURE TEMPERATURE SENSOR							Component	ATA:36	
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:UNKNOWN	HRS	0	TSN 0								
	AFL	0	TSN 0								
PROC. REF: GENERIC NO REF											
361127		LEFT TAILCONE LOW PRESSURE (2.0 DIAMETER) CHECK VALVE							Component	ATA:36	
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:UNKNOWN	HRS	0	TSN 0								
	AFL	0	TSN 0								
PROC. REF: GENERIC NO REF											
361128		RIGHT TAILCONE LOW PRESSURE (2.0 DIAMETER) CHECK VALVE							Component	ATA:36	
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:UNKNOWN	HRS	0	TSN 0								
	AFL	0	TSN 0								
PROC. REF: GENERIC NO REF											
361215		ASSEMBLY, HP LEFT NACELLE BLEED AIR MANIFOLD							Component	ATA:36	
PN:LJ01212-001	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:151009-002	HRS	0	TSN 0								
	AFL	0	TSN 0								
PROC. REF: AMM 36-10-07											
361215A		BORESCOPE ASSEMBLY, HP LEFT NACELLE BLEED AIR MANIFOLD BRACKET							Service	ATA:36	
PN:LJ01212-001	MOS/MSC	20-Jan-11	O/C								
SN:151009-002	HRS	0									
	AFL	0									
PROC. REF: AMM 36-10-07											
361216		ASSEMBLY, HP RIGHT NACELLE BLEED AIR MANIFOLD							Component	ATA:36	
PN:LJ01212-002	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:250110-001	HRS	0	TSN 0								
	AFL	0	TSN 0								
PROC. REF: AMM 36-10-07											
361216A		BORESCOPE ASSEMBLY, HP RIGHT NACELLE BLEED AIR MANIFOLD BRACKET							Service	ATA:36	
PN:LJ01212-002	MOS/MSC	20-Jan-11	O/C								
SN:250110-001	HRS	0									
	AFL	0									
PROC. REF: AMM 36-10-07											

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 36 - PNEUMATIC										
361301	APU SERVO AIR CHECK VALVE. EFFECTIVE ON CHECK VALVE S/N 001 THRU 1486. (IRN # K3610013) REPLACE									Component ATA:36
PN:6C1005	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:3758	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 36-15-02										
361302	LEFT ENGINE SERVO AIR CHECK - IRN K3610012 VALVE									Component ATA:36
PN:6C1005	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:3757	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 36-15-02										
361303	RIGHT ENGINE SERVO AIR CHECK - IRN K3610012 VALVE									Component ATA:36
PN:6C1005	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:3695	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 36-15-02										
362005	LEFT FORWARD PYLON OVERHEAT THERMOSTAT (S145) SWITCH									Component ATA:36
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 36-20-02										
362006	LEFT AFT PYLON OVERHEAT THERMOSTAT (S146) SWITCH									Component ATA:36
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 36-20-02										
362007	RIGHT FORWARD PYLON OVERHEAT THERMOSTAT (S147) SWITCH									Component ATA:36
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 36-20-02										
362008	RIGHT AFT PYLON OVERHEAT THERMOSTAT (S148) SWITCH									Component ATA:36
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 36-20-02										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 36 - PNEUMATIC										
5-19-00-D3610002	BORESCOPE INSPECTION HP BLEED AIR MANIFOLD ASSEMBLY ATTACH BRACKET ASSEMBLY FOR CRACKS AT WELD.(IRN D3610002)								Service	ATA:36
	MOS/MSC	20-Jan-11	N/A							
	HRS	0								
	AFL	0								
PROC. REF: AMM 36-10-07										
5-19-00-P3610048-LEFT	PERFORM VISUAL INSPECTION OF HP BLEED MANIFOLD ASSEMBLY (REFER TO 5-10-00.) EFFECTIVE ON AIRCRAFT 45-037 AND SUBSEQUENT, AND PREVIOUS AIRCRAFT MODIFIED PER SB 45-36-2, "PNEUMATIC-REPLACEMENT OF HIGH PRESSURE AIR MANIFOLD ASSEMBLY".								Service	ATA:36
	MOS	20-Jan-11								
	HRS	0	3000 (+100/-100)		3000	3100	1325 (+100)			
	AFL	0								
PROC. REF: GENERIC NO REF										
5-19-00-P3610048-RIGHT	PERFORM VISUAL INSPECTION OF HP BLEED MANIFOLD ASSEMBLY (REFER TO 5-10-00.) EFFECTIVE ON AIRCRAFT 45-037 AND SUBSEQUENT, AND PREVIOUS AIRCRAFT MODIFIED PER SB 45-36-2, "PNEUMATIC-REPLACEMENT OF HIGH PRESSURE AIR MANIFOLD ASSEMBLY".								Service	ATA:36
	MOS	20-Jan-11								
	HRS	0	3000 (+100/-100)		3000	3100	1325 (+100)			
	AFL	0								
PROC. REF: GENERIC NO REF										
A3610000 ^S	** BLEED AIR SYSTEM - PERFORM FUNCTIONAL TEST								Service	ATA:36
	MOS	20-Jan-23	24 (+14d/-14d)					AIRWORTHINESS		
	HRS	1675	600 (+25/-25)							
	AFL	1330								
PROC. REF: AMM 36-10-00										
A3610001 ^S	** PYLON OVERHEAT THERMOSTAT AND ELECTRICAL SYSTEM - PERFORM FUNCTIONAL TEST								Service	ATA:36
	MOS	20-Jan-23	24 (+14d/-14d)					AIRWORTHINESS		
	HRS	1675	600 (+25/-25)							
	AFL	1330								
PROC. REF: AMM 36-20-01										
U3610075 ^S	BORESCOPE INSPECTION ECS BLEED AIR "Y" MANIFOLD (P/N 12945-054-019, 12945-054-025, 12945-054-031, 129-054-037, 12945-054V1-001, 12945-054V2-001, 12945-054V6-001, 4536102027-001) (EFFECTIVE ON AIRCRAFT 45-002 THRU 45-448)								Service	ATA:36
	MOS	20-Jan-11								
	HRS	0	4800 (+25/-25)							
	AFL	0								
PROC. REF: AMM 36-10-00										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 36 - PNEUMATIC											
Y3610061 ^S		HIGH PRESSURE BLEED AIR SHUT-OFF VALVE IN-LINE FILTER - PERFORM CLEANING PROCEDURES.								Service	ATA:36
	MOS	20-Jan-23	24 (+ 14d/-14d)								
	HRS	1675	600 (+ 25/-25)								
	AFL	1330									
PROC. REF: AMM 36-10-02										PKG:8	
ATA 38 - WATER/ WASTE											
380001		TOILET SERVICE PANEL								Component	ATA:38
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 38-30-05											
381009		TOILET HEATED DRAIN MAST ASSY								Component	ATA:38
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: GENERIC NO REF											
383001		TOILET								Component	ATA:38
PN:6638303001-001	MOS/MSC	23-Oct-20	O/C	TSR 0							
SN:U2109	HRS	1570.8		TSR 0							
	AFL	1243		TSR 0							
PROC. REF: AMM 38-30-01											
383002		TOILET TIMER								Component	ATA:38
PN:7638303002-009	MOS/MSC	16-Dec-16	O/C	TSN 0							
SN:T4561	HRS	1162		TSN 0							
	AFL	966		TSN 0							
PROC. REF: AMM 38-30-02											
383005		WATER TANK ASSEMBLY								Component	ATA:38
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: GENERIC NO REF											

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty
---------	------	------	----------	-----------	--------------------------	-----------	-----------	-------------	-----	----------

ATA 38 - WATER/ WASTE

383010		TANK FLOAT SWITCH, TOILET REPLACE								Component	ATA:38
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0				CUSTOMER CODE			
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: GENERIC NO REF											

383011		LAVATORY SINK SHUT OFF VALVE								Component	ATA:38
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: GENERIC NO REF											

384025		TOILET PUMP								Component	ATA:38
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: GENERIC NO REF											

384051		TOILET MACERATOR								Component	ATA:38
PN:5300-1	MOS/MSC	20-Feb-16	O/C	TSN 3							
SN:M5156	HRS	992.4		TSN 0							
	AFL	869		TSN 0							
PROC. REF: GENERIC NO REF											

389050		TOILET CLEAN WATER PUMP								Component	ATA:38
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: GENERIC NO REF											

ATA 49 - AIRBORNE AUXILIARY POWER

490060		ELECTRONIC CONTROL, APU ECU								Component	ATA:49
PN:2119560-3	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:49-N0039	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 49-60-04											

491000		APU - DOWNLOAD APU ECU (TIMES/CYCLES)								Service	ATA:49
	MOS/MSC	08-Mar-20	A/R								
	HRS	790.05									
	APUS	1361									
PROC. REF: AMM 49-60-04											

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 49 - AIRBORNE AUXILIARY POWER										
491011	MAINTENANCE CONTROL, APU PANEL									Component ATA:49
PN:7088001-2	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:DC457	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 49-60-02										
491020	APU, COCKPIT CONTROL PANEL									Component ATA:49
PN:7088000-2	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:DB425	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 49-60-01										
492001	APU - APU COMPRESSOR ROTOR. (P/N 3822523-2 - IRN H4900019) (P/N 3822523-003 - IRN H4900020) ROTOR									Component ATA:49
PN:3822523-003	MOS	02-Mar-10		TSN 0				LIFE LIMIT		
SN:08-03501-21620	HRS	0		TSN 0						
	APUS	0	12000	TSN 0	12000		10504			
PROC. REF: AMM 49-10-01										
492005	APU - APU TURBINE ROTOR (P/N 3842340 - IRN H4900018) CHANGE									Component ATA:49
PN:3842340-2	MOS	02-Mar-10		TSN 0				LIFE LIMIT		
SN:09-156101-07327	HRS	0		TSN 0						
	APUS	0	4000	TSN 0	4000		2504			
PROC. REF: AMM 49-10-01										
493011	APU - APU PRESSURIZING VALVE									Component ATA:49
PN:PN	MOS/MSC	02-Mar-10	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	APUS	0		TSN 0						
PROC. REF: GENERIC NO REF										
493021	APU - APU FILTER BYPASS VALVE									Component ATA:49
PN:PN	MOS/MSC	02-Mar-10	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	APUS	0		TSN 0						
PROC. REF: GENERIC NO REF										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 49 - AIRBORNE AUXILIARY POWER										
493031	APU - APU PRESSURE RELIEF VALVE									Component ATA:49
PN:PN	MOS/MSC	02-Mar-10	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	APUS	0		TSN 0						
PROC. REF: GENERIC NO REF										
493041	APU - APU DIFFERENTIAL PRESSURE VALVE									Component ATA:49
PN:PN	MOS/MSC	02-Mar-10	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	APUS	0		TSN 0						
PROC. REF: GENERIC NO REF										
493051	APU - APU FUEL PUMP									Component ATA:49
PN:PN	MOS/MSC	02-Mar-10	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	APUS	0		TSN 0						
PROC. REF: AMM 49-30-04										
493061	APU - APU DIFFERENTIAL PRESSURE INDICATOR									Component ATA:49
PN:PN	MOS/MSC	02-Mar-10	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	APUS	0		TSN 0						
PROC. REF: GENERIC NO REF										
493071	APU - APU ASSEMBLY, FUEL CONTROL									Component ATA:49
PN:PN	MOS/MSC	02-Mar-10	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	APUS	0		TSN 0						
PROC. REF: AMM 49-30-04										
494011	APU - APU IGNITION EXCITER									Component ATA:49
PN:PN	MOS/MSC	02-Mar-10	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	APUS	0		TSN 0						
PROC. REF: AMM 49-40-04										
494021	APU - APU LOW VOLTAGE IGNITER PLUG									Component ATA:49
PN:PN	MOS/MSC	02-Mar-10	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	APUS	0		TSN 0						
PROC. REF: AMM 49-40-02										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 49 - AIRBORNE AUXILIARY POWER										
494031	APU - APU IGNITION LEAD									Component ATA:49
PN:PN	MOS/MSC	02-Mar-10	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	APUS	0		TSN 0						
PROC. REF: AMM 49-40-03										
494050	IGNITION, APU UNIT									Component ATA:49
PN:3888000-7	MOS/MSC	02-Mar-10	O/C	TSN 0						
SN:J09260450	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 49-40-04										
494060	APU - APU GROUND CONTROL UNIT CHANGE									Component ATA:49
PN:PN	MOS/MSC	02-Mar-10	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	APUS	0		TSN 0						
PROC. REF: GENERIC NO REF										
495001	APU - APU ISOLATION VALVE									Component ATA:49
PN:PN	MOS/MSC	02-Mar-10	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	APUS	0		TSN 0						
PROC. REF: AMM 49-50-01										
495001	COOLING, TAILCONE APU (B31) FAN									Component ATA:49
PN:011809500	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:108317656	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 49-50-01										
495002	TAILCONE ACCESS DOOR COOLING (B30) FAN									Component ATA:49
PN:011809500	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:108317657	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
495040	APU THERMOSTAT (S175) SWITCH									Component ATA:49
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 49 - AIRBORNE AUXILIARY POWER										
495041	APU THERMOSTAT (S176) SWITCH									Component ATA:49
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
495201	STRUT SUPPORT ASSEMBLY									Component ATA:49
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
495202	STRUT SUPPORT ASSEMBLY									Component ATA:49
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
496001	APU - APU REMOTELY LOCATED (ECU) CONTROLLER									Component ATA:49
PN:PN	MOS/MSC	02-Mar-10	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	APUS	0		TSN 0						
PROC. REF: AMM 49-60-04										
496010	APU - APU FUEL LINE REPLACE									Component ATA:49
PN:PN	MOS/MSC	02-Mar-10	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	APUS	0		TSN 0						
PROC. REF: GENERIC NO REF										
496011	APU - APU FUEL SHUTOFF VALVE									Component ATA:49
PN:3876322-1	MOS/MSC	02-Mar-10	O/C	TSN 0						
SN:0418	HRS	0		TSN 0						
	APUS	0		TSN 0						
PROC. REF: GENERIC NO REF										
496021	APU - APU FLOW DIVIDER VALVE									Component ATA:49
PN:PN	MOS/MSC	02-Mar-10	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	APUS	0		TSN 0						
PROC. REF: AMM 49-30-06										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 49 - AIRBORNE AUXILIARY POWER										
496031	APU - APU FUEL SOLENOID VALVE									Component ATA:49
PN:PN	MOS/MSC	02-Mar-10	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	APUS	0		TSN 0						
PROC. REF: AMM 49-30-01										
496041	APU - APU - BLEED AIR SHUTOFF VALVE									Component ATA:49
PN:PN	MOS/MSC	02-Mar-10	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	APUS	0		TSN 0						
PROC. REF: GENERIC NO REF										
497001	APU - APU SPEED SENSOR									Component ATA:49
PN:PN	MOS/MSC	02-Mar-10	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	APUS	0		TSN 0						
PROC. REF: AMM 49-70-04										
497001	APU BITE INDICATOR									Component ATA:49
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
497011	APU - APU EGT THERMOCOUPLE									Component ATA:49
PN:PN	MOS/MSC	02-Mar-10	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	APUS	0		TSN 0						
PROC. REF: AMM 49-70-07										
499025	APU - APU ASSEMBLY, LUBE OIL-PUMP									Component ATA:49
PN:PN	MOS/MSC	02-Mar-10	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	APUS	0		TSN 0						
PROC. REF: AMM 49-90-03										
499037	APU - APU LOW OIL PRESSURE SENSOR									Component ATA:49
PN:PN	MOS/MSC	02-Mar-10	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	APUS	0		TSN 0						
PROC. REF: AMM 49-90-02										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 49 - AIRBORNE AUXILIARY POWER										
499048	APU - INLET TEMP SENSOR									Component ATA:49
PN:PN	MOS/MSC	02-Mar-10	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	APUS	0		TSN 0						
PROC. REF: AMM 49-70-06										
499049	APU - APU OIL TEMPERATURE BULB									Component ATA:49
PN:PN	MOS/MSC	02-Mar-10	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	APUS	0		TSN 0						
PROC. REF: GENERIC NO REF										
499061	APU - APU OIL LEVEL SENSOR									Component ATA:49
PN:PN	MOS/MSC	02-Mar-10	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	APUS	0		TSN 0						
PROC. REF: AMM 49-90-01										
499071	APU - APU ULTIMATE RELIEF VALVE									Component ATA:49
PN:PN	MOS/MSC	02-Mar-10	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	APUS	0		TSN 0						
PROC. REF: GENERIC NO REF										
499081	APU - APU MANIFOLD AND PRIMARY ATOMIZER									Component ATA:49
PN:PN	MOS/MSC	02-Mar-10	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	APUS	0		TSN 0						
PROC. REF: AMM 49-30-05										
499082	APU - APU MANIFOLD AND SECONDARY ATOMIZER									Component ATA:49
PN:PN	MOS/MSC	02-Mar-10	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	APUS	0		TSN 0						
PROC. REF: AMM 49-30-05										
49APU1	APU									Component ATA:49
PN:3800726-1	MOS/MSC		E/C							
SN:P-454	HRS									
WC# : 49.APU1	AFL									
PROC. REF: GENERIC NO REF										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 49 - AIRBORNE AUXILIARY POWER										
5-19-00-O4900008	APU - INSPECT APU CHIP DETECTOR - FOR CONTAMINATION. (ZONE/ACCESS 310JL, 310RR IRN # O4900008)									Service ATA:49
	MOS	20-Jan-23								
	HRS	873.4	750		1623.4		750			
	APUS	1496								
PROC. REF: AMM 49-90-05										
5-19-00-P4900009	APU - CHANGE APU OIL. (ZONE/ACCESS 310JL, 310RR). (IRN # P4900009). (REFER TO 12-10-10.) NOTE: THIS REQUIREMENT IS NOT APPLICABLE FOR OPERATORS ENROLLED IN THE SPECTROMETRIC OIL AND FILTER ANALYSIS PROGRAM (SOAP) SYSTEM PER HONEYWELL SIL# APU-49).									Service ATA:49
	MOS/MSC	20-Jan-23	N/A					NOT APPLICABLE		
	HRS	873.4								
	APUS	1496								
PROC. REF: AMM 12-10-10										
5-19-01-AA4900039	APU FUEL LINE (P/N 4549058032-001) REPLACE									Component ATA:49
PN:PN	MOS	20-Jan-11		TSN 0						
SN:UNKNOWN	HRS	0	4800 (+25/-25)	TSN 0	4800	4825	3125 (+25)			
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
5-19-01-K4900005	APU - REPLACE APU ENGINE FUEL FILTER. IRN # K4900005									Service ATA:49
	MOS	20-Jan-23								
	HRS	873.4	750		1623.4		750			
	APUS	1496								
PROC. REF: AMM 49-30-03										
5-19-01-T4900004	APU - REPLACE APU OIL FILTER. THIS REQUIREMENT IS NOT APPLICABLE FOR OPERATORS ENROLLED IN THE SPECTROMETRIC OIL AND FILTER ANALYSIS PROGRAM (SOAP) SYSTEM PER HONEYWELL SIL# APU-49 (ZONE/ACCESS 310JR, 310QR) (IRN # T4900004)									Service ATA:49
	MOS	20-Jan-23								
	HRS	873.4	750		1623.4		750			
	APUS	1496								
PROC. REF: AMM 49-90-04										
H4900011 ^S	PERFORM ** APU GENERATOR - OVERVOLTAGE PROTECTION CHECK.									Service ATA:49
	MOS	20-Jan-23	48 (+14d/-14d)					AIRWORTHINESS		
	HRS	1675	1200 (+25/-25)							
	AFL	1330								
PROC. REF: AMM 49-40-01										

PKG:13

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 49 - AIRBORNE AUXILIARY POWER										
Y4900000 ^S	AUXILIARY POWER UNIT - PERFORM VISUAL INSPECTION OF EXTERNAL FIREBOX INSTALLATION AND ATTACHING COMPONENTS									Service ATA:49
	MOS	20-Jan-23	12 (+ 14d/-14d)							
	HRS	1675	300 (+ 25/-25)							
	AFL	1330								
					PROC. REF: AMM 05-10-00					PKG:2
Y4900002 ^S	AUXILIARY POWER UNIT - FIRE EXTINGUISHER CONTAINER - PERFORM FUNCTIONAL TEST OF WIRING.									Service ATA:49
	MOS	20-Jan-23	24 (+ 14d/-14d)							
	HRS	1675	600 (+ 25/-25)							
	AFL	1330								
					PROC. REF: AMM 26-22-00					PKG:7
Y4900010 ^S	APU ENGINE FIRE EXTINGUISHER CONTAINER - CHECK CONTAINER PRESSURE GAUGE FOR PROPER PRESSURE.									Service ATA:49
	MOS	20-Jan-23	12 (+ 14d/-14d)							
	HRS	1675	300 (+ 25/-25)							
	AFL	1330								
					PROC. REF: AMM 26-22-00					PKG:2
Y4900012 ^S	APU INLET SCREEN AND OPENING - PERFORM VISUAL INSPECTION									Service ATA:49
	MOS	20-Jan-23	12 (+ 14d/-14d)							
	HRS	1675	300 (+ 25/-25)							
	AFL	1330								
					PROC. REF: AMM 05-10-00					PKG:2
Y4900013 ^S	APU EXHAUST DUCT AREA, INCLUDING FORWARD AND AFT APU EXHAUST FAIRINGS - PERFORM VISUAL INSPECTION									Service ATA:49
	MOS	20-Jan-23	12 (+ 14d/-14d)							
	HRS	1675	300 (+ 25/-25)							
	AFL	1330								
					PROC. REF: AMM 05-10-00					PKG:2
ATA 52 - DOORS										
5-19-02-RVSM-M5240004	INSPECT AVIONIC ACCESS DOOR GAP AND MISMATCH FOR RVSM COMPLIANT AIRCRAFT (IRN # M5240004)									Service ATA:52
	MOS	20-Jan-23	24 (+ 14d/-14d)	Adj -131d	11-Sep-24		25-Sep-24	581 d (+ 14)	RVSM	
	HRS	1675								
	AFL	1330								
					PROC. REF: AMM 52-40-01					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 52 - DOORS										
521001	UPPER CABIN DOOR									Component ATA:52
PN:4552101000-003	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:W546	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 52-10-01										
521002	LOWER CABIN DOOR									Component ATA:52
PN:4552100050V109-001	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:W532	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 52-10-01										
5210053	CABIN DOOR HANDLE - REPLACE									Service ATA:52
	MOS/MSC	20-Jan-11	N/A							
	HRS	0								
	AFL	0								
PROC. REF: AMM 52-10-08, AMM 52-10-13										
521010	LOWER ENTRY DOOR FORWARD GAS DAMPER ASSEMBLY									Component ATA:52
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 52-10-11										
521011	LOWER ENTRY DOOR AFT GAS DAMPER ASSEMBLY									Component ATA:52
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 52-10-11										
522001	EMERGENCY EXIT DOOR ASSEMBLY									Component ATA:52
PN:4552200076V43-001	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:L416	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 52-20-01										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 52 - DOORS										
522010	DOOR ASSY									Component ATA:52
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 52-20-06										
523001	TAILCONE BAGGAGE DOOR ASSEMBLY									Component ATA:52
PN:12045-558V2-001	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:568	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
524001	TAILCONE ACCESS DOOR									Component ATA:52
PN:4552405151-009	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:574	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 52-40-02										
524010	SPPR DOOR ASSY									Component ATA:52
PN:PN	MOS/MSC		O/C							
SN:UNKNOWN	HRS									
	AFL									
PROC. REF: AMM 52-40-03										
A5210009 ^S	PERFORM * EMERGENCY EXIT DOOR RETAINERS - VISUAL INSPECTION. INSPECT DOOR STOP FITTINGS ON EMERGENCY EXIT DOOR FRAMES IN FLANGE RADII. (FS 374 AND 394)									Service ATA:52
	MOS	20-Jan-11						AIRWORTHINESS		
	HRS	0	9600							
	AFL	0								
PROC. REF: GENERIC NO REF										
A5210012 ^S	PERFORM * LOWER PASSENGER DOOR HINGE - VISUAL INSPECTION. INSPECT PIANO HINGE LUGS AND FASTENERS									Service ATA:52
	MOS	20-Jan-11						AIRWORTHINESS		
	HRS	0	9600							
	AFL	0								
PROC. REF: GENERIC NO REF										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 52 - DOORS											
A5210014 ^S			PERFORM * UPPER PASSENGER DOOR TENSION FITTINGS - VISUAL INSPECTION. INSPECT THE FOLLOWING: A. TENSION STUDS AT RETAINING FLANGES. B. RADII AROUND FLANGE PERIPHERY.							Service	ATA:52
	MOS	20-Jan-11						AIRWORTHINESS			
	HRS	0	9600								
	AFL	0									
					PROC. REF: GENERIC NO REF					PKG:26	
AA5210055 ^S			CABIN DOOR HANDLE RAMP ROLLER WHEEL - LUBRICATION							Service	ATA:52
	MOS	20-Jan-23	48 (+ 14d/-14d)								
	HRS	1675	1200 (+ 25/-25)								
	AFL	1330									
					PROC. REF: AMM 12-21-02					PKG:18	
D5210015 ^S			PERFORM * EMERGENCY EXIT DOOR - VISUAL INSPECTION. PAY PARTICULAR ATTENTION TO FLANGES AND FASTENER HOLES OF DOOR STOP FITTINGS.							Service	ATA:52
	MOS	20-Jan-11						AIRWORTHINESS			
	HRS	0	T:9600								
	AFL	0									
					PROC. REF: GENERIC NO REF					PKG:25	
E5210013 ^S			PERFORM * UPPER AND LOWER PASSENGER DOOR LATCH ARMS AND DOOR ATTACHMENTS - VISUAL INSPECTION.							Service	ATA:52
	MOS	20-Jan-11						AIRWORTHINESS			
	HRS	0	T:9600								
	AFL	0									
					PROC. REF: GENERIC NO REF					PKG:25	
F5210016 ^S			PERFORM * UPPER PASSENGER DOOR HINGE - VISUAL INSPECTION. INSPECT UPPER SURFACE OF HINGE FINGERS AT BASE OF LUG.							Service	ATA:52
	MOS	20-Jan-11						AIRWORTHINESS			
	HRS	0	9600								
	AFL	0									
					PROC. REF: GENERIC NO REF					PKG:26	
N5210010 ^S			PERFORM * LOWER PASSENGER DOOR TENSION BOLTS, BOLT RETAINERS, TENSION FITTINGS, AND DOOR ATTACHMENTS - VISUAL INSPECTION.							Service	ATA:52
	MOS	11-Sep-18	96					AIRWORTHINESS			
	HRS	1387.4	2400								
	AFL	1114									
					PROC. REF: GENERIC NO REF					PKG:24	

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 52 - DOORS											
N5210011 ^S			PERFORM * UPPER AND LOWER PASSENGER DOOR LATCH PINS - VISUAL INSPECTION. INSPECT BOLTS AND DOOR END RIB STRUCTURE AT LOCK PINS.							Service	ATA:52
	MOS	11-Sep-18	96					AIRWORTHINESS			
	HRS	1387.4	2400								
	AFL	1114									
					PROC. REF: GENERIC NO REF					PKG:24	
N5210017 ^S			PERFORM * UPPER PASSENGER DOOR TENSION BOLTS, BOLT RETAINERS, TENSION FITTINGS, AND DOOR ATTACHMENTS - VISUAL INSPECTION.							Service	ATA:52
	MOS	11-Sep-18	96					AIRWORTHINESS			
	HRS	1387.4	2400								
	AFL	1114									
					PROC. REF: GENERIC NO REF					PKG:24	
T5210003 ^S			PERFORM EXTERNAL LOWER PASSENGER/CREW DOOR CABLES - VISUAL INSPECTION OF VISIBLE PORTION OF CABLES AND HANDLE AREA							Service	ATA:52
	MOS	20-Jan-23	48 (+ 14d/-14d)								
	HRS	1675	1200 (+ 25/-25)								
	AFL	1330									
					PROC. REF: AMM 05-10-00					PKG:18	
Y5210000 ^S			PERFORM AVIONICS COMPARTMENT ACCESS DOORS AND SEALS - VISUAL INSPECTION							Service	ATA:52
	MOS	20-Jan-23	48 (+ 14d/-14d)								
	HRS	1675	1200 (+ 25/-25)								
	AFL	1330									
					PROC. REF: AMM 05-10-00					PKG:13	
Y5210001 ^S			TAILCONE ACCESS DOOR AND SEAL - PERFORM VISUAL INSPECTION OF DOOR, SEALS, AND LATCHES							Service	ATA:52
	MOS	20-Jan-23	24 (+ 14d/-14d)								
	HRS	1675	600 (+ 25/-25)								
	AFL	1330									
					PROC. REF: AMM 05-10-00					PKG:12	
Y5210002 ^S			BAGGAGE COMPARTMENT DOOR - PERFORM VISUAL INSPECTION OF DOORS, SEALS, AND LATCHES							Service	ATA:52
	MOS	20-Jan-23	24 (+ 14d/-14d)								
	HRS	1675	600 (+ 25/-25)								
	AFL	1330									
					PROC. REF: AMM 05-10-00					PKG:12	

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 52 - DOORS											
Y5210004 ^S			PERFORM UPPER AND LOWER PASSENGER/CREW DOOR - VISUAL INSPECTION OF DOOR STRUCTURE, TENSION FITTINGS, AND HINGE AREA FOR CRACKS AND CORROSION						Service	ATA:52	
	MOS	20-Jan-23	48 (+ 14d/-14d)								
	HRS	1675	1200 (+ 25/-25)								
	AFL	1330									
					PROC. REF: AMM 05-10-00					PKG:18	
Y5210005 ^S			PERFORM INTERNAL LOWER PASSENGER/CREW DOOR CABLES - VISUAL INSPECTION. REMOVE STEP SKIN TO GAIN ACCESS TO CABLES						Service	ATA:52	
	MOS	20-Jan-23	48 (+ 14d/-14d)								
	HRS	1675	1200 (+ 25/-25)								
	AFL	1330									
					PROC. REF: AMM 05-10-00					PKG:18	
Y5210006 ^S			UPPER PASSENGER/CREW DOOR VENT DOOR SPRINGS - PERFORM VISUAL INSPECTION						Service	ATA:52	
	MOS	20-Jan-23	24 (+ 14d/-14d)								
	HRS	1675	600 (+ 25/-25)								
	AFL	1330									
					PROC. REF: AMM 05-10-00					PKG:12	
Y5210008 ^S			EMERGENCY EXIT DOOR INTERNAL AND EXTERNAL HANDLE LATCHING MECHANISM - PERFORM OPERATIONAL CHECK						Service	ATA:52	
	MOS	20-Jan-23	24 (+ 14d/-14d)								
	HRS	1675	600 (+ 25/-25)								
	AFL	1330									
					PROC. REF: AMM 52-20-07					PKG:12	
Y5240000 ^S			PERFORM OXYGEN SYSTEM SERVICING DOOR AND LATCHES - VISUAL INSPECTION FOR CONDITION AND SECURITY. CHECK DECAL FOR CONDITION AND LEGIBILITY						Service	ATA:52	
	MOS	20-Jan-23	48 (+ 14d/-14d)								
	HRS	1675	1200 (+ 25/-25)								
	AFL	1330									
					PROC. REF: AMM 05-10-00					PKG:13	
Y5240003 ^S			PERFORM SINGLE POINT REFUELING ACCESS DOOR - VISUAL INSPECTION.						Service	ATA:52	
	MOS	20-Jan-23	48 (+ 14d/-14d)								
	HRS	1675	1200 (+ 25/-25)								
	AFL	1330									
					PROC. REF: AMM 05-10-00					PKG:14	
ATA 53 - FUSELAGE											
5-19-00-H5323032			* EXTERIOR CABIN WINDOW COAMINGS (UNPAINTED) - PERFORM EDDY CURRENT INSPECTION (IRN H5323032)						Service	ATA:53	
	MOS	08-Nov-21	24		08-Nov-23		273 d	AIRWORTHINESS			
	HRS	1605.6	2400		4005.6		2330.6				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 53 - FUSELAGE										
	AFL	1281	PROC. REF: NDT PART 6/56-20-01							
5-19-00-H5323092	* EXTERIOR CABIN WINDOW COAMINGS (PAINTED) - PERFORM EDDY CURRENT INSPECTION (IRN H5323092)									Service ATA:53
	MOS/MSC	20-Jan-11	N/A							
	HRS	0								
	AFL	0	PROC. REF: NDT PART 6/56-20-01							
5-19-00-T5323166	PERFORM * EXTERNAL SKIN CUT-OUTS/PENETRATIONS (PRESSURE CABIN) - PERFORM DETAILED VISUAL INSPECTION. INSPECT SKIN AND DOUBLERS AT ANTENNAS, ELECTRICAL COMPONENTS, AND ACCESS PANELS (EXCLUDING PITOT/STATIC PROBES, AOA STALL VANES AND WING INSPECTION LIGHT. (REFER TO 5-10-00.) IRN T5323166									Service ATA:53
	MOS	20-Jan-23	144	20-Jan-35		4364 d		MANDATORY		
	HRS	1675	9600	11275		9600				
	AFL	1330	PROC. REF: GENERIC NO REF							
5-19-00-V5323168	EDDY CURRENT INSPECTION * LOWER COUPE RAIL RADIUS/WINDSCREEN RETAINER ATTACH (P/N'S 4553130001-802 THRU 4553130001-809)									Service ATA:53
	MOS/MSC	20-Jan-11	N/A							
	HRS	0								
	AFL	0	PROC. REF: NDT PART 6/53-30-23, NDT PART 6/53-30-24							
5-19-01-U5323167-LEFT	* REPLACE LEFT COUPE RAIL (P/N 4553002003V7000-001, 4553002003V7001-002) (IRN U5323167) ASSEMBLY									Component ATA:53
PN:PN	MOS/MSC	EFF	N/A	TSN 0		NOT APPLICABLE				
SN:UNKNOWN	HRS	EFF	TSN 0							
	AFL	TSN 0								
PROC. REF: AMM 53-10-04										
5-19-01-U5323167-RIGHT	* REPLACE RIGHT COUPE RAIL (4553002003V7000-001, 4553002003V7001-002) (IRN U5323167) ASSEMBLY									Component ATA:53
PN:PN	MOS/MSC	EFF	N/A	TSN 0		NOT APPLICABLE				
SN:UNKNOWN	HRS	EFF	TSN 0							
	AFL	TSN 0								
PROC. REF: AMM 53-10-04										
5-19-02-RVSM-M5313001	PERFORM PITOT-STATIC PROBE ZONE SKIN CONTOUR CHECK OF THE FORWARD FUSELAGE SKIN FOR RVSM COMPLIANT AIRCRAFT (IRN # M5313001)									Service ATA:53
	MOS	20-Jan-23	24 (+14d/-14d)	Adj -131d	11-Sep-24	25-Sep-24	581 d (+14)	RVSM		
	HRS	1675								
	AFL	1330	PROC. REF: AMM 53-00-01							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 53 - FUSELAGE										
530001	FUSELAGE ASSEMBLY									Component ATA:53
PN:4553000010-001	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:L416	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
531001	AFT PRESSURE BULKHEAD									Component ATA:53
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 53-10-01										
531040	LEFT TIE ROD END									Component ATA:53
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 53-10-04										
531041	RIGHT TIE ROD END									Component ATA:53
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 53-10-04										
535001	RADOME									Component ATA:53
PN:H0601-5	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:0631	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 53-50-01										
535601	LEFT DELTA FIN									Component ATA:53
PN:4555501000-015	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:A0312	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 53-56-01										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 53 - FUSELAGE										
535602			RIGHT DELTA FIN						Component	ATA:53
PN:4555501000-018	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:A0324	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 53-56-01										
A5310005 ^S			PERFORM * FUSELAGE FUEL CELL CANTED BULKHEAD (FS 495) - VISUAL INSPECTION, PAYING PARTICULAR ATTENTION TO MAIN CROSSMEMBER. INSPECT FLANGES AND ATTACHMENTS FOR CRACKING.						Service	ATA:53
	MOS	20-Jan-11						AIRWORTHINESS		
	HRS	0	T:9600							
	AFL	0								
PROC. REF: GENERIC NO REF										
PKG:25										
A5310007 ^S			PERFORM * AFT PRESSURE BULKHEAD BOTTOM SHEAR DIAPHRAGM - DETAILED VISUAL INSPECTION. INSPECT BULKHEAD POST ATTACHMENT FASTENER HOLES AND CONTROL CABLE SLOT.						Service	ATA:53
	MOS	20-Jan-11						AIRWORTHINESS		
	HRS	0	9600							
	AFL	0								
PROC. REF: GENERIC NO REF										
PKG:26										
A5323022 ^S			PERFORM * NOSE LANDING GEAR AFT WHEELBOX CLOSING STRUCTURE (FS 150 TO FS 162) - VISUAL INSPECTION. INSPECT THE FOLLOWING: A. PANEL B. CHANNEL STIFFENERS. C. SUPPORT ANGLE. D. ANGLE STIFFENER. E. ZEE STIFFENER.						Service	ATA:53
	MOS	20-Jan-11						AIRWORTHINESS		
	HRS	0	9600							
	AFL	0								
PROC. REF: GENERIC NO REF										
PKG:26										
A5323023 ^S			PERFORM * DRAG LINK ATTACHMENT LUG - VISUAL INSPECTION.						Service	ATA:53
	MOS	20-Jan-11						AIRWORTHINESS		
	HRS	0	T:9600							
	AFL	0								
PROC. REF: GENERIC NO REF										
PKG:25										
A5360001 ^S			PERFORM DELTA FINS - WITH DELTA FINS REMOVED, VISUALLY INSPECT THE FOLLOWING: A. DELTA FIN AFT SPAR. B. DELTA FIN SUPPORT ANGLE. C. INSPECT STIFFENERS CONNECTING TO ATTACH FITTINGS.						Service	ATA:53
	MOS	20-Jan-11								
	HRS	0	9600 (+ 25/-25)							
	AFL	0								
PROC. REF: AMM 05-10-00										
PKG:26										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 53 - FUSELAGE											
D5323039 ^S			PERFORM * MACHINED FUSELAGE FRAME AT FS 466 - DETAILED VISUAL INSPECTION BETWEEN STRINGER 13 LEFT AND RIGHT, PAYING PARTICULAR ATTENTION TO THE BL 10 SPLICES. CONFIRM ANY CRACK INDICATIONS WITH THE EDDY CURRENT PROCEDURES							Service	ATA:53
	MOS	20-Jan-11						AIRWORTHINESS			
	HRS	0		T:9600							
	AFL	0									
										PKG:25	
E5310001 ^S			PERFORM * LONGERON, INTERNAL (BETWEEN FS 384 AND FS 433) - VISUAL INSPECTION.							Service	ATA:53
	MOS	20-Jan-11						AIRWORTHINESS			
	HRS	0		9600							
	AFL	0									
										PKG:26	
E5310002 ^S			PERFORM * FLIGHT DECK LONGERON (FS 149 - FS 196) - VISUAL INSPECTION. INSPECT FLIGHT DECK LONGERON STIFFENERS, WEBS, AND CUTOUTS.							Service	ATA:53
	MOS	20-Jan-11						AIRWORTHINESS			
	HRS	0		9600							
	AFL	0									
										PKG:26	
E5310017 ^S			PERFORM * AFT PRESSURE BULKHEAD BOTTOM CROSSMEMBER (FS 457) - DETAILED VISUAL INSPECTION. INSPECT TEE-SECTION AT FS 457 FLANGE AT ATTACHMENT TO PRESSURE FLOOR.							Service	ATA:53
	MOS	20-Jan-11						AIRWORTHINESS			
	HRS	0		9600							
	AFL	0									
										PKG:26	
E5310018 ^S			PERFORM * AFT PRESSURE BULKHEAD PANEL FACING SHEETS (FS 457) - VISUAL INSPECTION. INSPECT BOTH FRONT AND AFT OF FACING SHEETS.							Service	ATA:53
	MOS	20-Jan-11						AIRWORTHINESS			
	HRS	0		9600							
	AFL	0									
										PKG:26	
E5323025 ^S			PERFORM * FORWARD/AFT WHEELBOX JOINT (FS 150) - VISUAL INSPECTION. INSPECT SPLICE STRAP AFT OF FORWARD PRESSURE BULKHEAD AT INTERSECTION OF ATTACHMENT ANGLE AND FLIGHT DECK LONGERON.							Service	ATA:53
	MOS	20-Jan-11						AIRWORTHINESS			
	HRS	0		9600							
	AFL	0									
										PKG:26	

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 53 - FUSELAGE											
E5323050 ^S			PERFORM * AFT POST/WINDSHIELD RETAINER ATTACHMENT - WITH HEADLINER REMOVED, EDDY CURRENT INSPECTION							Service	ATA:53
	MOS		20-Jan-11					AIRWORTHINESS			
	HRS		0		T:9600						
	AFL		0								
					PROC. REF: NDT PART 6/53-30-04						PKG:25
E5323053 ^S			PERFORM * FRAME ATTACHMENTS TO UPPER AND LOWER COUPE RAILS (FS 171 TO FS 204) - VISUAL INSPECTION. INSPECT THE FOLLOWING: A. FRAME ATTACHMENTS TO LOWER COUPE RAILS AT FS 171, FS 182, FS 196, AND FS 204. B. FRAME ATTACHMENTS TO UPPER COUPE RAILS AT FS 196 AND FS 204. C. GUSSETS AT FASTENER HOLES.							Service	ATA:53
	MOS		20-Jan-11					AIRWORTHINESS			
	HRS		0		9600						
	AFL		0								
					PROC. REF: GENERIC NO REF						PKG:26
E5323054 ^S			PERFORM * TIE-ROD ASSEMBLY (FS 162) (ALUMINUM ENDS) - VISUAL INSPECTION. INSPECT TIE-ROD ENDS, TIE-ROD TUBES, AND TIE-ROD BOLTS.							Service	ATA:53
	MOS		20-Jan-11					AIRWORTHINESS			
	HRS		0		4800						
	AFL		0								
					PROC. REF: GENERIC NO REF						PKG:25
E5323055 ^S			PERFORM * TIE-ROD ASSEMBLY (FS 162) (TITANIUM ENDS) - VISUAL INSPECTION. INSPECT TIE-ROD ENDS, TIE-ROD TUBES, AND TIE-ROD BOLTS.							Service	ATA:53
	MOS		20-Jan-11					AIRWORTHINESS			
	HRS		0		9600						
	AFL		0								
					PROC. REF: AMM NO REF						PKG:26
E5323068 ^S			PERFORM * STRINGER 1 RH BETWEEN FS 533 AND FS 543 - VISUAL INSPECTION. INSPECT STRINGER 1 FLANGE AND SKIN ALONG STRINGER 1 BETWEEN FS 533 AND FS 543.							Service	ATA:53
	MOS		20-Jan-11					AIRWORTHINESS			
	HRS		0		9600						
	AFL		0								
					PROC. REF: GENERIC NO REF						PKG:26
E5323073 ^S			PERFORM * FUSELAGE BOTTOM SKIN PANEL - VISUAL INSPECTION. INSPECT CORNER RADIUS AT JUNCTION OF EXTERNAL LONGERON AND MID SPAR FRAME (FS 435)							Service	ATA:53
	MOS		20-Jan-11					AIRWORTHINESS			
	HRS		0		9600						
	AFL		0								
					PROC. REF: GENERIC NO REF						PKG:26

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 53 - FUSELAGE											
E5323074 ^S			PERFORM * AUXILIARY SKIN PANEL - VISUAL INSPECTION. INSPECT CORNER RADIUS AT JUNCTION OF KEEL BEAM AND REAR SPAR FRAME (FS 466).							Service	ATA:53
	MOS	20-Jan-11						AIRWORTHINESS			
	HRS	0	9600								
	AFL	0									
					PROC. REF: GENERIC NO REF					PKG:26	
E5350000 ^S			PERFORM * BOTTOM KEELBEAM END PADS (FS 384 - FS 486) - VISUAL INSPECTION. INSPECT END PADS AROUND BOLT HOLES AND IN RADII AT FS 433.							Service	ATA:53
	MOS	20-Jan-11						AIRWORTHINESS			
	HRS	0	9600								
	AFL	0									
					PROC. REF: GENERIC NO REF					PKG:26	
F5323056 ^S			PERFORM * TIE-ROD FORK ENDS (ALUMINUM) - FLOURESCENT PENETRANT INSPECTION. (EFFECTIVE ON AIRCRAFT 45-001 THRU 45-058)							Service	ATA:53
	MOS	20-Jan-11						AIRWORTHINESS			
	HRS	0	4800								
	AFL	0									
					PROC. REF: GENERIC NO REF					PKG:25	
F5323081 ^S			PERFORM * TIE-ROD FORK ENDS (TITANIUM, P/N R24889) - FLUORESCENT PENETRANT INSPECTION. (EFFECTIVE ON AIRCRAFT 45-059 AND SUBSEQUENT AND PRIOR AIRCRAFT WITH TITANIUM ROD ASSEMBLY INSTALLED.)							Service	ATA:53
	MOS	20-Jan-11						AIRWORTHINESS			
	HRS	0	9600								
	AFL	0									
					PROC. REF: NDT PART 8/53-10-01					PKG:26	
F5331021 ^S			PERFORM * FORWARD CANTED BULKHEAD (FS 630) - VISUAL INSPECTION. INSPECT AT FRONT SPAR ATTACHMENT FASTENERS.							Service	ATA:53
	MOS	20-Jan-11						AIRWORTHINESS			
	HRS	0	T:9600								
	AFL	0									
					PROC. REF: GENERIC NO REF					PKG:25	
F5331022 ^S			PERFORM * MID CANTED BULKHEAD (FS 657) - VISUAL INSPECTION AT MID SPAR UPPER ATTACHMENT FASTENERS.							Service	ATA:53
	MOS	20-Jan-11						AIRWORTHINESS			
	HRS	0	9600								
	AFL	0									
					PROC. REF: GENERIC NO REF					PKG:26	

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 53 - FUSELAGE											
F5331023 ^S			PERFORM * AFT CANTED BULKHEAD (FS 682) - VISUAL INSPECTION. INSPECT AT REAR SPAR ATTACHMENT FASTENERS.							Service	ATA:53
	MOS	20-Jan-11						AIRWORTHINESS			
	HRS	0	9600								
	AFL	0									
					PROC. REF: GENERIC NO REF					PKG:26	
F5331024 ^S			PERFORM * VERTICAL STABILIZER FRONT ROOT BULKHEAD ATTACHMENT (FS 630) - VISUAL INSPECTION. INSPECT FRONT SPAR ROOT BULKHEAD ATTACHMENT AT FASTENER HOLES.							Service	ATA:53
	MOS	20-Jan-11						AIRWORTHINESS			
	HRS	0	9600								
	AFL	0									
					PROC. REF: GENERIC NO REF					PKG:26	
F5331025 ^S			PERFORM * VERTICAL STABILIZER MID SPAR ROOT BULKHEAD ATTACHMENT (FS 657) - VISUAL INSPECTION. INSPECT MID SPAR ROOT BULKHEAD ATTACHMENT AT FASTENER HOLES.							Service	ATA:53
	MOS	20-Jan-11						AIRWORTHINESS			
	HRS	0	9600								
	AFL	0									
					PROC. REF: GENERIC NO REF					PKG:26	
F5331026 ^S			PERFORM * VERTICAL STABILIZER REAR SPAR ROOT BULKHEAD ATTACHMENT (FS 682) - VISUAL INSPECTION. INSPECT REAR SPAR ROOT BULKHEAD ATTACHMENT AT FASTENER HOLES.							Service	ATA:53
	MOS	20-Jan-11						AIRWORTHINESS			
	HRS	0	9600								
	AFL	0									
					PROC. REF: GENERIC NO REF					PKG:26	
L5311002 ^S			PERFORM * NOSE LANDING GEAR ACTUATOR ATTACHMENT ON FORWARD PRESSURE BULKHEAD - EDDY CURRENT INSPECTION. INSPECT ACTUATOR ATTACHMENT BRACKET LUGS, RADII, AND FASTENER HOLES.							Service	ATA:53
	MOS	20-Jan-11						AIRWORTHINESS			
	HRS	0									
	AFL	0	10000								
					PROC. REF: NDT PART 6/32-12-00					PKG:27	
L5311004 ^S			PERFORM * NOSE LANDING GEAR TRUNNION FITTINGS - VISUAL INSPECTION OF THE TRUNNION FITTINGS AND ATTACHMENT BOLTS.							Service	ATA:53
	MOS	20-Jan-11						AIRWORTHINESS			
	HRS	0									
	AFL	0	10000								
					PROC. REF: GENERIC NO REF					PKG:27	

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 53 - FUSELAGE											
L5311005 ^S			PERFORM * NOSE LANDING GEAR TRUNNION FITTINGS AND SUPPORT STRUCTURE - EDDY CURRENT INSPECTION OF THE TRUNNION SUPPORT STRUCTURE AT THE FORWARD PRESSURE BULKHEAD FLANGE.							Service	ATA:53
	MOS	20-Jan-11						AIRWORTHINESS			
	HRS	0									
	AFL	0	10000								
					PROC. REF: NDT PART 6/32-12-05					PKG:27	
M5323021 ^S			PERFORM * EXTERNAL LONGERON, FASTENER LOCATIONS, AND AREA AROUND WING ATTACHMENTS - VISUAL INSPECTION. INSPECT LONGERON BETWEEN FS 398 AND FS 486, STRINGER 13 LHS & RHS.							Service	ATA:53
	MOS	20-Jan-11						AIRWORTHINESS			
	HRS	0	9600								
	AFL	0									
					PROC. REF: GENERIC NO REF					PKG:26	
M5323034 ^S			PERFORM * UPPER AND LOWER COUPE RAIL AND CENTER POST/ WINDSHIELD RETAINER ATTACHMENT - EDDY CURRENT INSPECTION.							Service	ATA:53
	MOS	20-Jan-11						AIRWORTHINESS			
	HRS	0	9600								
	AFL	0									
					PROC. REF: NDT PART 6/53-30-03					PKG:26	
N5314000 ^S			PERFORM * EMERGENCY EXIT DOOR SKIN CUTOUT CORNERS AND DOUBLERS (FS 370 TO FS 398) - PERFORM EDDY CURRENT INSPECTION.							Service	ATA:53
	MOS	11-Sep-18	96					AIRWORTHINESS			
	HRS	1387.4	2400								
	AFL	1114									
					PROC. REF: NDT PART 6/53-30-01					PKG:19	
N5323026 ^S			PERFORM * UPPER AND LOWER PASSENGER/CREW DOOR SKIN CUTOUT CORNERS (F.S. 224 - F.S. 256) -EDDY CURRENT INSPECTION. INSPECT SKIN AT CORNERS OF PASSENGER/CREW DOOR CUTOUT							Service	ATA:53
	MOS	11-Sep-18	96					AIRWORTHINESS			
	HRS	1387.4	2400								
	AFL	1114									
					PROC. REF: NDT PART 6/53-30-02					PKG:19	
P5310003 ^S			PERFORM * AFT PRESSURE BULKHEAD SUPPORT POST (FS 457) - EDDY CURRENT INSPECTION.							Service	ATA:53
	MOS	20-Jan-11						AIRWORTHINESS			
	HRS	0	9600								
	AFL	0									
					PROC. REF: NDT PART 6/53-30-18					PKG:26	

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 53 - FUSELAGE											
P5310004 ^S			PERFORM * AFT PRESSURE BULKHEAD FRAME PERIPHERY - EDDY CURRENT INSPECTION.							Service	ATA:53
	MOS	20-Jan-11						AIRWORTHINESS			
	HRS	0		T:9600							
	AFL	0									
										PKG:25	
PROC. REF: NDT PART 6/53-30-21											
P5310006 ^S			PERFORM * FORWARD PRESSURE BULKHEAD - EDDY CURRENT INSPECTION.							Service	ATA:53
	MOS	20-Jan-11						AIRWORTHINESS			
	HRS	0		9600							
	AFL	0									
										PKG:26	
PROC. REF: NDT PART 6/53-30-07											
P5320001 ^S			PERFORM * FUSELAGE PRESSURE FLOOR STEP (FS 433 - FS 457) - EDDY CURRENT INSPECTION.							Service	ATA:53
	MOS	20-Jan-11						AIRWORTHINESS			
	HRS	0		9600							
	AFL	0									
										PKG:26	
PROC. REF: NDT PART 6/53-20-01											
P5323024 ^S			PERFORM * FUSELAGE SKIN CUT-OUTS ABOVE FUEL CELL - EDDY CURRENT INSPECTION.							Service	ATA:53
	MOS	20-Jan-11						AIRWORTHINESS			
	HRS	0		T:9600							
	AFL	0									
										PKG:25	
PROC. REF: NDT PART 6/53-30-12											
P5323027 ^S			PERFORM * FUSELAGE FRAME AT FS 412 - EDDY CURRENT INSPECTION.							Service	ATA:53
	MOS	20-Jan-11						AIRWORTHINESS			
	HRS	0		T:9600							
	AFL	0									
										PKG:25	
PROC. REF: NDT PART 6/53-30-20											
P5323029 ^S			PERFORM * MACHINED SPAR FRAMES SYSTEMS CUTOUTS (FS 398, FS 412, FS 432, FS 466) - EDDY CURRENT INSPECTION							Service	ATA:53
	MOS	20-Jan-11						AIRWORTHINESS			
	HRS	0		T:9600							
	AFL	0									
										PKG:25	
PROC. REF: NDT PART 6/53-30-15											
P5323033 ^S			PERFORM * FUSELAGE SKIN AT EMERGENCY DOOR EGRESS-LIGHT AND WING INSPECTION LIGHT - EDDY CURRENT INSPECTION.							Service	ATA:53
	MOS	20-Jan-11						AIRWORTHINESS			
	HRS	0		9600							
	AFL	0									
										PKG:26	
PROC. REF: NDT PART 6/53-40-02											

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 53 - FUSELAGE											
P5323037 ^S			PERFORM * WINDSHIELD COUPE RAIL TIE ROD BRACKET - EDDY CURRENT INSPECTION.							Service	ATA:53
	MOS	20-Jan-11						AIRWORTHINESS			
	HRS	0	9600								
	AFL	0									
										PKG:26	
PROC. REF: NDT PART 6/53-30-09											
P5323038 ^S			PERFORM * WINDSHIELD CENTERPOST TO UPPER COUPE RAIL JOINT ATTACHMENT - EDDY CURRENT INSPECTION							Service	ATA:53
	MOS	20-Jan-11						AIRWORTHINESS			
	HRS	0	T:9600								
	AFL	0									
										PKG:25	
PROC. REF: NDT PART 6/53-30-22											
P5323047 ^S			PERFORM * PRESSURE CABIN FUSELAGE CROWN SKIN - PERFORM EDDY CURRENT INSPECTION.							Service	ATA:53
	MOS	11-Sep-18	96					AIRWORTHINESS			
	HRS	1387.4	2400								
	AFL	1114									
										PKG:19	
PROC. REF: NDT PART 6/53-10-04											
P5323049 ^S			PERFORM * FUSELAGE SKIN AT UPPER AND LOWER COUPE RAIL RUN-OUT JOINTS - EDDY CURRENT INSPECTION.							Service	ATA:53
	MOS	20-Jan-11						AIRWORTHINESS			
	HRS	0	9600								
	AFL	0									
										PKG:26	
PROC. REF: NDT PART 6/53-30-11											
P5323057 ^S			PERFORM * PRESSURE CABIN SKIN AT FUSELAGE STATION 451 - EDDY CURRENT INSPECTION.							Service	ATA:53
	MOS	11-Sep-18	96					AIRWORTHINESS			
	HRS	1387.4	2400								
	AFL	1114									
										PKG:19	
PROC. REF: NDT PART 6/53-30-06											
P5323058 ^S			PERFORM * FUSELAGE SKIN AT F.S. 504 - EDDY CURRENT INSPECTION.							Service	ATA:53
	MOS	20-Jan-11						AIRWORTHINESS			
	HRS	0	T:9600								
	AFL	0									
										PKG:25	
PROC. REF: NDT PART 6/53-30-13											
P5323069 ^S			PERFORM * CIRCUMFERENTIAL SKIN JOINT AT FORWARD PRESSURE BULKHEAD - EDDY CURRENT INSPECTION.							Service	ATA:53
	MOS	20-Jan-11						AIRWORTHINESS			
	HRS	0	9600								
	AFL	0									
										PKG:26	
PROC. REF: NDT PART 6/53-30-08											

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 53 - FUSELAGE											
P5323164 ^S			PERFORM * FUSELAGE SKIN AND DOUBLER AROUND ECS DUCT CUTOUT - EDDY CURRENT INSPECTION.							Service	ATA:53
	MOS	20-Jan-11						AIRWORTHINESS			
	HRS	0	9600								
	AFL	0									
										PKG:26	
PROC. REF: NDT PART 6/53-40-01											
P5323165 ^S			PERFORM * WINDSHIELD CENTER POST TO LOWER COUPE RAIL JOINT ATTACHMENT - EDDY CURRENT INSPECTION.							Service	ATA:53
	MOS	20-Jan-11						AIRWORTHINESS			
	HRS	0	9600								
	AFL	0									
										PKG:26	
PROC. REF: NDT PART 6/53-30-10											
P5360006 ^S			PERFORM DELTA FIN ATTACH BOLT - LIQUID PENETRANT INSPECTION.							Service	ATA:53
	MOS	20-Jan-11									
	HRS	0	9600 (+ 25/-25)								
	AFL	0									
										PKG:26	
PROC. REF: NDT PART 8/53-10-02											
Q5310023 ^S			PERFORM FORWARD AND AFT FUEL CELL BAY STRUCTURE, ANGLE REINFORCEMENT, STRINGER 1, LH & RH - DETAILED VISUAL INSPECTION OF HI-LITE COLLARS							Service	ATA:53
	MOS	20-Jan-11									
	HRS	0	9600 (+ 25/-25)								
	AFL	0									
										PKG:26	
PROC. REF: GENERIC NO REF											
Q5310025 ^S			PERFORM AFT FUSELAGE KEELBEAM LONGERON (LH & RH, BL 5.15, FS 466.30 - 495.12) AND AFT FUSELAGE KEELBEAM LOWER FRAME (FS 466.30, BL 9.55 LH THRU BL 9.55 RH) - DETAILED VISUAL INSPECTION OF HI-LITE COLLARS							Service	ATA:53
	MOS	20-Jan-11									
	HRS	0	9600 (+ 25/-25)								
	AFL	0									
										PKG:26	
PROC. REF: GENERIC NO REF											
Q5323048 ^S			PERFORM * FUSELAGE (PRESSURE CABIN) - EDDY CURRENT INSPECTION. INSPECT PRESSURE CABIN SKIN (LONGITUDINAL SKIN CRACKING)							Service	ATA:53
	MOS	20-Jan-11						AIRWORTHINESS			
	HRS	0	T:9600								
	AFL	0									
										PKG:25	
PROC. REF: NDT PART 6/53-30-05											

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 53 - FUSELAGE											
Q5323051 ^S			PERFORM * LONGITUDINAL JOINTS INSIDE PRESSURE CABIN (FS 220- FS 457) AND SKIN WITHIN ONE STRINGER BAY OF JOINT - EDDY CURRENT INSPECTION. INSPECT SKIN FASTENER HOLES ALONG JOINTS AT STRINGER 10 LH AND RH AND STRINGER 2 RH AND STRINGER 18 RH.							Service	ATA:53
	MOS	20-Jan-11						AIRWORTHINESS			
	HRS	0		T:9600							
	AFL	0									
					PROC. REF: GENERIC NO REF					PKG:25	
Q5323059 ^S			PERFORM * STRINGER TO FRAME JOINTS (FS 162 TO FS 213) - EDDY CURRENT INSPECTION. INSPECT SKIN, STRINGERS, AND FRAMES AT JOINTS.							Service	ATA:53
	MOS	20-Jan-11						AIRWORTHINESS			
	HRS	0		9600							
	AFL	0									
					PROC. REF: GENERIC NO REF					PKG:26	
T5310027 ^S			PERFORM * AFT PRESSURE BULKHEAD TOP MOUNTING STRUCTURE - EDDY CURRENT INSPECTION							Service	ATA:53
	MOS	20-Jan-11						AIRWORTHINESS			
	HRS	0		9600							
	AFL	0									
					PROC. REF: NDT PART 6/53-30-17					PKG:26	
T5321089 ^S			SEAT RAILS - PERFORM DETAILED INSPECTION OF SEAT RAIL (TRACK) SHEAR WEBS FOR CRACKING							Service	ATA:53
	MOS	20-Jan-23		24 (+ 14d/-14d)							
	HRS	1675		600 (+ 25/-25)							
	AFL	1330									
					PROC. REF: AMM 53-20-01					PKG:7	
T5323028 ^S			PERFORM * FUSELAGE TO WING ATTACH FITTINGS - EDDY CURRENT INSPECTION							Service	ATA:53
	MOS	20-Jan-11						AIRWORTHINESS			
	HRS	0		T:9600							
	AFL	0									
					PROC. REF: NDT PART 6/53-30-16					PKG:25	
Y5311001 ^S			PERFORM NOSE LANDING GEAR ACTUATOR ATTACH FITTING AND SURROUNDING STRUCTURE - VISUAL INSPECTION							Service	ATA:53
	MOS	20-Jan-23		48 (+ 14d/-14d)							
	HRS	1675		1200 (+ 25/-25)							
	AFL	1330									
					PROC. REF: AMM 05-10-00					PKG:17	

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 53 - FUSELAGE											
Y5311003 ^S			PERFORM NOSE LANDING GEAR TRUNNION FITTING AND SURROUNDING STRUCTURE - VISUAL INSPECTION						Service	ATA:53	
	MOS	20-Jan-23	48 (+ 14d/-14d)								
	HRS	1675	1200 (+ 25/-25)								
	AFL	1330									
					PROC. REF: AMM 05-10-00					PKG:17	
Y5320000 ^S			CENTER PEDESTAL - PERFORM VISUAL INSPECTION						Service	ATA:53	
	MOS	20-Jan-23	12 (+ 14d/-14d)								
	HRS	1675	300 (+ 25/-25)								
	AFL	1330									
					PROC. REF: AMM 05-10-00					PKG:1	
Y5321010 ^S			FLOORBOARDS AROUND GALLEY, LAVATORY, AND WATER TANK - PERFORM VISUAL INSPECTION						Service	ATA:53	
	MOS	20-Jan-23	12 (+ 14d/-14d)								
	HRS	1675	300 (+ 25/-25)								
	AFL	1330									
					PROC. REF: AMM 53-20-01					PKG:1	
Y5321011 ^S			TAILCONE BAGGAGE COMPARTMENT - PERFORM VISUAL INSPECTION						Service	ATA:53	
	MOS	20-Jan-23	24 (+ 14d/-14d)								
	HRS	1675	600 (+ 25/-25)								
	AFL	1330									
					PROC. REF: AMM 05-10-00					PKG:8	
Y5321088 ^S			PERFORM SEAT RAILS - REMOVE FLOORBOARD 230AL AND PERFORM VISUAL INSPECTION OF SEAT RAILS. IF CORROSION IS DETECTED, REMOVE ALL FLOORBOARDS AND INSPECT ALL SEAT RAILS.						Service	ATA:53	
	MOS	20-Jan-23	48 (+ 14d/-14d)								
	HRS	1675	1200 (+ 25/-25)								
	AFL	1330									
					PROC. REF: GENERIC NO REF					PKG:13	
Y5323020 ^S			PERFORM EXTERNAL FUSELAGE (PRESSURE CABIN) - VISUAL INSPECTION OF ALL CABIN SKINS FROM F.S. 100 TO F.S.458. PAY PARTICULAR ATTENTION TO ALL CUTOUTS AND SKIN JOINTS. NO FAIRING ACCESS REQUIRED.						Service	ATA:53	
	MOS	20-Jan-23	48 (+ 14d/-14d)								
	HRS	1675	1200 (+ 25/-25)								
	AFL	1330									
					PROC. REF: AMM 05-10-00					PKG:13	

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 53 - FUSELAGE											
Y5323031 ^S			PERFORM EXTERIOR CABIN WINDOW COAMINGS AND SURROUNDING FUSELAGE SKIN - VISUAL INSPECTION USING 10X MAGNIFICATION AND ADEQUATE LIGHTING							Service	ATA:53
	MOS	20-Jan-23	48 (+14d/-14d)								
	HRS	1675	1200 (+25/-25)								
	AFL	1330									
					PROC. REF: AMM 05-10-00					PKG:13	
Y5340007 ^S			PERFORM WING ATTACH FITTINGS - VISUAL INSPECTION							Service	ATA:53
	MOS	11-Sep-18	96 (+14d/-14d)								
	HRS	1387.4	2400 (+25/-25)								
	AFL	1114									
					PROC. REF: AMM 05-10-00					PKG:19	
Y5360000 ^S			DELTA FINS - PERFORM VISUAL INSPECTION							Service	ATA:53
	MOS	20-Jan-23	24 (+14d/-14d)								
	HRS	1675	600 (+25/-25)								
	AFL	1330									
					PROC. REF: AMM 05-10-00					PKG:8	
Z5323172 ^S			* SKIN CUT-OUT FOR IRIIDIUM ANTENNAS FS283.88 TO FS308.39 - PERFORM EDDY CURRENT INSPECTION							Service	ATA:53
	MOS/MSC	20-Jan-11	N/A					AIRWORTHINESS			
	HRS	0									
	AFL	0									
					PROC. REF: GENERIC NO REF						
ATA 54 - NACELLES/ PYLONS											
5-19-00-Q5450013-LEFT ^U			FORWARD LEFT ENGINE BEAM AND BEAM FITTING - PERFORM VISUAL INSPECTION, PAYING PARTICULAR ATTENTION OF THE FOLLOWING: A. UPPER CAPPING PLATE AT FASTENER HOLES, AND CHANNEL FLANGE AT FASTENER HOLES. B. BOLT HOLES, ESPECIALLY UPPER BOLT HOLE ON AFT FLANGE							Service	ATA:54
	MOS/MSC	20-Jan-11	N/A								
	HRS	0									
	AFL	0									
5-19-00-Q5450013-RIGHT ^{U†}			RIGHT FORWARD ENGINE BEAM AND BEAM FITTING - PERFORM VISUAL INSPECTION, PAYING PARTICULAR ATTENTION OF THE FOLLOWING: A. UPPER CAPPING PLATE AT FASTENER HOLES, AND CHANNEL FLANGE AT FASTENER HOLES. B. BOLT HOLES, ESPECIALLY UPPER BOLT HOLE ON AFT FLANGE.							Service	ATA:54
	MOS/MSC	20-Jan-11	N/A								
	HRS	0									
	AFL	0									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 54 - NACELLES/ PYLONS										
5-19-01-A5450028	REPLACE AFT ENGINE BEAM ASSEMBLY END FITTINGS (P/N 4553500201-001/-002)									Service ATA:54
	MOS/MS	20-Jan-11	N/A					N/A BY SERIAL NUMBER		
	HRS	0								
	AFL	0								
PROC. REF: AMM 53-40-02										
5-19-01-M5450027	REPLACE FORWARD ENGINE BEAM ASSEMBLY END FITTINGS (P/N 4553500101-003/4)									Service ATA:54
	MOS	20-Jan-11								
	HRS	0	10000 (+ 25/-25)		10000	10025	8325 (+ 25)			
	AFL	0								
PROC. REF: AMM 53-40-02										
5450054	LEFT FORWARD ENGINE BEAM AND BEAM FITTING - PERFORM VISUAL INSPECTION, PAYING PARTICULAR ATTENTION OF THE FOLLOWING: A. UPPER CAPPING PLATE AT FASTENER HOLES, AND CHANNEL FLANGE AT FASTENER HOLES. B. BOLT HOLES, ESPECIALLY UPPER BOLT HOLE ON AFT FLANGE.									Service ATA:54
	MOS	20-Jan-11								
	HRS	0	6000 (+ 100/-100)		6000	6100	4325 (+ 100)			
	AFL	0								
PROC. REF: AMM 05-10-00										
5450054	RIGHT FORWARD ENGINE BEAM AND BEAM FITTING - PERFORM VISUAL INSPECTION, PAYING PARTICULAR ATTENTION OF THE FOLLOWING: A. UPPER CAPPING PLATE AT FASTENER HOLES, AND CHANNEL FLANGE AT FASTENER HOLES. B. BOLT HOLES, ESPECIALLY UPPER BOLT HOLE ON AFT FLANGE.									Service ATA:54
	MOS	20-Jan-11								
	HRS	0	6000 (+ 100/-100)		6000	6100	4325 (+ 100)			
	AFL	0								
PROC. REF: AMM 05-10-00										
545019	* REPLACE LEFT AFT ENGINE BEAM TO FRAME ATTACHMENT (IRN P5450020) BOLT									Component ATA:54
PN:PN	MOS	20-Jan-11	TSN 0					LIFE LIMIT		
SN:UNKNOWN	HRS	0	9600	TSN 0	9600		7925			
	AFL	0	TSN 0							
PROC. REF: GENERIC NO REF										
545020	* REPLACE RIGHT AFT ENGINE BEAM TO FRAME ATTACHMENT (IRN P5450020) BOLT									Component ATA:54
PN:PN	MOS	20-Jan-11	TSN 0					LIFE LIMIT		
SN:UNKNOWN	HRS	0	9600	TSN 0	9600		7925			
	AFL	0	TSN 0							
PROC. REF: GENERIC NO REF										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 54 - NACELLES/ PYLONS										
545021	* REPLACE LEFT AFT ENGINE MOUNT TO END FITTING ATTACH (IRN A5450022) BOLT									Component ATA:54
PN:PN	MOS	20-Jan-11		TSN 0				LIFE LIMIT		
SN:UNKNOWN	HRS	0	9600	TSN 0	9600		7925			
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
545022	* REPLACE RIGHT AFT ENGINE MOUNT TO END FITTING ATTACH (IRN A5450022) BOLT									Component ATA:54
PN:PN	MOS	20-Jan-11		TSN 0				LIFE LIMIT		
SN:UNKNOWN	HRS	0	9600	TSN 0	9600		7925			
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
545023	* REPLACE LEFT ENGINE TO AFT ENGINE MOUNT ATTACH (IRN P5450023) BOLT									Component ATA:54
PN:PN	MOS	20-Jan-11		TSN 0				LIFE LIMIT		
SN:UNKNOWN	HRS	0	9600	TSN 0	9600		7925			
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
545024	* REPLACE RIGHT ENGINE TO AFT ENGINE MOUNT ATTACH (IRN P5450023) BOLT									Component ATA:54
PN:PN	MOS	20-Jan-11		TSN 0				LIFE LIMIT		
SN:UNKNOWN	HRS	0	9600	TSN 0	9600		7925			
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
A5450026 ^S	PERFORM * ENGINE DRAG STRUT - EDDY CURRENT INSPECTION									Service ATA:54
	MOS	20-Jan-11						AIRWORTHINESS		
	HRS	0	T:9600							
	AFL	0								
PROC. REF: NDT PART 6/54-50-01										PKG:25
E5450029 ^S	PERFORM * AFT ENGINE BEAM - VISUAL INSPECTION. INSPECT UPPER CAPPING PLATE, AROUND FASTENER HOLES IN THE CAPPING PLATE, AND CHANNEL FLANGE.									Service ATA:54
	MOS	20-Jan-11						AIRWORTHINESS		
	HRS	0	T:9600							
	AFL	0								
PROC. REF: GENERIC NO REF										PKG:25

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 54 - NACELLES/ PYLONS											
F5450019 ^S			PERFORM * AFT ENGINE BEAM ATTACHMENT TO FRAMES - VISUAL INSPECTION. INSPECT AFT ENGINE BEAM ATTACHMENT TO FRAMES.							Service	ATA:54
	MOS	20-Jan-11						AIRWORTHINESS			
	HRS	0		T:9600							
	AFL	0									
			PROC. REF: GENERIC NO REF								PKG:25
H5450012 ^S			PERFORM * FRAMES 39/40 (FS 512/518) AT ENGINE BEAM ATTACHMENT - EDDY CURRENT INSPECTION. INSPECT OUTER FLANGE AND FRAME WEB AT ENGINE BEAM ATTACHMENT.							Service	ATA:54
	MOS	20-Jan-11						AIRWORTHINESS			
	HRS	0		T:9600							
	AFL	0									
			PROC. REF: NDT PART 6/54-50-03								PKG:25
M5450015 ^S			PERFORM * FORWARD ENGINE BEAM, SPAR CAP, AND WEB - EDDY CURRENT INSPECTION							Service	ATA:54
	MOS	20-Jan-11						AIRWORTHINESS			
	HRS	0		T:9600							
	AFL	0									
			PROC. REF: NDT PART 6/54-50-05								PKG:25
M5450018 ^S			PERFORM * FORWARD ENGINE MOUNT ATTACHMENT BOLTS - FLUORESCENT LIQUID PENETRANT INSPECTION.							Service	ATA:54
	MOS	20-Jan-11						AIRWORTHINESS			
	HRS	0		T:9600							
	AFL	0									
			PROC. REF: NDT PART 8/71-20-01								PKG:25
P5450011 ^S			PERFORM * DRAG STRUT ATTACHMENT FITTINGS - EDDY CURRENT INSPECTION.							Service	ATA:54
	MOS	20-Jan-11						AIRWORTHINESS			
	HRS	0		T:9600							
	AFL	0									
			PROC. REF: NDT PART 6/53-10-03								PKG:25
P5450016 ^S			PERFORM * FORWARD ENGINE BEAM END FITTING - EDDY CURRENT INSPECTION.							Service	ATA:54
	MOS	20-Jan-11						AIRWORTHINESS			
	HRS	0		T:9600							
	AFL	0									
			PROC. REF: NDT PART 6/54-50-02								PKG:25
P5450017 ^S			PERFORM * FORWARD ENGINE BEAM TO FRAME ATTACH BOLTS - LIQUID PENETRANT INSPECTION.							Service	ATA:54
	MOS	20-Jan-11						AIRWORTHINESS			
	HRS	0		T:9600							
	AFL	0									
			PROC. REF: NDT PART 8/53-40-01								PKG:25

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 54 - NACELLES/ PYLONS											
P5450021 ^S			PERFORM * ENGINE AFT ISOLATOR MOUNT FITTINGS - LIQUID PENETRANT INSPECTION.							Service	ATA:54
	MOS	20-Jan-11						AIRWORTHINESS			
	HRS	0		T:9600							
	AFL	0									
										PKG:25	
PROC. REF: NDT PART 8/71-20-03											
P5450024 ^S			PERFORM * FUSELAGE FRAMES AT FS 543.55 AND 546.15 TO AFT BEAM ATTACHMENT - EDDY CURRENT INSPECTION.							Service	ATA:54
	MOS	20-Jan-11						AIRWORTHINESS			
	HRS	0		T:9600							
	AFL	0									
										PKG:25	
PROC. REF: NDT PART 6/53-30-14											
P5450025 ^S			PERFORM * FORWARD ENGINE BEAM AND FRAMES AT ATTACH HOLES - EDDY CURRENT INSPECTION							Service	ATA:54
	MOS	20-Jan-11						AIRWORTHINESS			
	HRS	0		T:9600							
	AFL	0									
										PKG:25	
PROC. REF: NDT PART 6/54-50-03											
P5450030 ^S			PERFORM * AFT ENGINE BEAM END FITTING - EDDY CURRENT INSPECTION.							Service	ATA:54
	MOS	20-Jan-11						AIRWORTHINESS			
	HRS	0		T:9600							
	AFL	0									
										PKG:25	
PROC. REF: NDT PART 6/54-50-04											
Y5410002 ^S			PERFORM PYLONS - VISUAL INSPECTION. INSPECT HILITE COLLARS COMMON TO MAIN ENGINE BEAM EXTERNAL TO FUSELAGE							Service	ATA:54
	MOS	20-Jan-23	48 (+ 14d/-14d)								
	HRS	1675	1200 (+ 25/-25)								
	AFL	1330									
										PKG:14	
PROC. REF: AMM 54-00-01											
ATA 55 - STABILIZERS											
5-19-00-M5510010			EDDY CURRENT INSPECTION * HORIZONTAL STABILIZER AFT ROOT RIB. INSPECT AFT ROOT RIB INTERNAL BETWEEN MID SPAR AND AFT SPAR AND UPPER AND LOWER SKINS EXTERNAL AT ATTACHMENT FASTENERS. (REFER TO NDI MANUAL {NDI-104}, PART 6, 55-10-03.)							Service	ATA:55
	MOS	20-Jan-11						AIRWORTHINESS			
	HRS	0		T:4800	4800		3125				
	AFL	0									
										PKG:14	
PROC. REF: NDT PART 6/55-10-03											

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 55 - STABILIZERS											
5-19-00-W5510091			PERFORM * HORIZONTAL STABILIZER HINGE PRIMARY AND SECONDARY PIVOT PIN INSTALLATION AND ATTACHING HARDWARE - PERFORM DETAILED VISUAL INSPECTION. (REFER TO 55-10-00.)							Service	ATA:55
	MOS		10-Oct-19					MANDATORY			
	HRS		1509.8	625		2134.8	459.8				
	AFL		1201								
PROC. REF: AMM 55-10-00											
5510034			HORIZONTAL STABILIZER PRIMARY AND SECONDARY BOLTS ANDBUSHINGS - PERFORM DETAILED INSPECTION							Service	ATA:55
	MOS										
	HRS	EFF	4800 (+25/-25)		4800 *	4825	3125 (+25)				
	AFL										
PROC. REF: AMM 55-10-00											
551005			HORIZONTAL STABILIZER ASSEMBLY							Component	ATA:55
PN:4555101001V46-001	MOS/MSC		20-Jan-11	O/C	TSN 0						
SN:A0290	HRS		0		TSN 0						
	AFL		0		TSN 0						
PROC. REF: AMM 27-40-01											
552031			LEFT ELEVATOR ASSEMBLY							Component	ATA:55
PN:4555201005-007	MOS/MSC		20-Jan-11	O/C	TSN 0						
SN:A0296	HRS		0		TSN 0						
	AFL		0		TSN 0						
PROC. REF: AMM 27-30-01											
552032			RIGHT ELEVATOR ASSEMBLY							Component	ATA:55
PN:4555201005-008	MOS/MSC		20-Jan-11	O/C	TSN 0						
SN:A0296	HRS		0		TSN 0						
	AFL		0		TSN 0						
PROC. REF: AMM 27-30-01											
553000			TAILCONE/VERTICAL STABILIZER ASSEMBLY							Component	ATA:55
PN:4555301001-001	MOS/MSC		20-Jan-11	O/C	TSN 0						
SN:A0289	HRS		0		TSN 0						
	AFL		0		TSN 0						
PROC. REF: GENERIC NO REF											

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 55 - STABILIZERS										
554005	RUDDER ASSEMBLY									Component ATA:55
PN:4555401000-021	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:A0299	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 27-20-01										
A5510014 ^S	PERFORM * VERTICAL STABILIZER PIVOT FITTING BOTTOM PLATE - DETAILED VISUAL INSPECTION. INSPECT AFT PORTION OF BOTTOM PLATE THROUGH LIGHTENING HOLE IN TOP PLATE, FORWARD PORTION OF BOTTOM PLATE THROUGH TOP PLATE CUTOUTS, AND BOTTOM OF OUTSIDE EXPOSED SURFACE OF PIVOT FITTING.									Service ATA:55
	MOS	20-Jan-11						AIRWORTHINESS		
	HRS	0	9600							
	AFL	0								
PROC. REF: GENERIC NO REF										
A5510021 ^S	PERFORM * HORIZONTAL MID SPAR FROM CANTED RIB # 2 TO CANTED RIB # 3 - DETAILED VISUAL INSPECTION.									Service ATA:55
	MOS	20-Jan-11						AIRWORTHINESS		
	HRS	0	9600							
	AFL	0								
PROC. REF: GENERIC NO REF										
A5540000 ^S	PERFORM * RUDDER ROOT RIB CAP (FS 698) - VISUAL INSPECTION. INSPECT AROUND FASTENER HOLES AND LIGHTENING HOLES.									Service ATA:55
	MOS	20-Jan-11						AIRWORTHINESS		
	HRS	0	9600							
	AFL	0								
PROC. REF: GENERIC NO REF										
E5510074 ^S	PERFORM * HORIZONTAL STABILIZER REAR SPAR FROM CANTED RIB # 2 TO CANTED RIB # 3 - VISUAL INSPECTION. INSPECT REAR SPAR CAP AND FASTENERS.									Service ATA:55
	MOS	20-Jan-11						AIRWORTHINESS		
	HRS	0	9600							
	AFL	0								
PROC. REF: GENERIC NO REF										
E5510075 ^S	PERFORM * HORIZONTAL STABILIZER OUTBOARD SPARS AND SKINS OUTBOARD OF CANTED RIB # 3 - VISUAL INSPECTION. INSPECT SPAR CAPS AND FASTENERS.									Service ATA:55
	MOS	20-Jan-11						AIRWORTHINESS		
	HRS	0	9600							
	AFL	0								
PROC. REF: GENERIC NO REF										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 55 - STABILIZERS											
E5510076 ^S			PERFORM * HORIZONTAL STABILIZER FRONT SPAR FROM CANTED RIB # 2 TO CANTED RIB # 3 - VISUAL INSPECTION. INSPECT FRONT SPAR CAP AND FASTENERS.							Service	ATA:55
	MOS	20-Jan-11						AIRWORTHINESS			
	HRS	0	9600								
	AFL	0									
					PROC. REF: GENERIC NO REF					PKG:26	
E5520003 ^S			PERFORM * ELEVATOR FRONT SPAR - VISUAL INSPECTION. INSPECT SPAR CAP AT FASTENER HOLES.							Service	ATA:55
	MOS	20-Jan-11						AIRWORTHINESS			
	HRS	0	9600								
	AFL	0									
					PROC. REF: GENERIC NO REF					PKG:26	
E5520004 ^S			PERFORM * ELEVATOR RIB # 1 CAP - VISUAL INSPECTION OF RIB # 1 CAP CROSS SECTION AND RIB CAP FLANGES AT TORQUE TUBE.							Service	ATA:55
	MOS	20-Jan-11						AIRWORTHINESS			
	HRS	0	9600								
	AFL	0									
					PROC. REF: GENERIC NO REF					PKG:26	
G5510000 ^S			PERFORM * HORIZONTAL STABILIZER ACTUATOR ATTACHMENT FITTINGS - EDDY CURRENT INSPECTION.							Service	ATA:55
	MOS	20-Jan-11						AIRWORTHINESS			
	HRS	0	4800								
	AFL	0									
					PROC. REF: NDT PART 6/55-10-01					PKG:25	
G5510023 ^S			PERFORM * HORIZONTAL STABILIZER ACTUATOR VERTICAL TAIL ATTACHMENT - EDDY CURRENT INSPECTION.							Service	ATA:55
	MOS	20-Jan-11						AIRWORTHINESS			
	HRS	0	4800								
	AFL	0									
					PROC. REF: NDT PART 6/55-30-01					PKG:25	
H5510033 ^S			PERFORM * HORIZONTAL STABILIZER ACTUATOR ATTACHMENT BOLTS - LIQUID PENETRANT INSPECTION.							Service	ATA:55
	MOS	20-Jan-11						AIRWORTHINESS			
	HRS	0	4800								
	AFL	0									
					PROC. REF: NDT PART 8/27-40-01					PKG:25	

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 55 - STABILIZERS											
L5540005 ^S			EDDY CURRENT INSPECTION * RUDDER TRIM TAB							Service	ATA:55
	MOS	20-Jan-11						BRAZILIAN REQUIREMENT			
	HRS	0	4800								
	AFL	0									
					PROC. REF: NDT PART 6/55-30-08					PKG:25	
N5510005 ^S			PERFORM * HORIZONTAL STABILIZER REAR SPAR CAP - EDDY CURRENT INSPECTION. INSPECT REAR SPAR CAP AND WEB AT CENTER SPLICE.							Service	ATA:55
	MOS	11-Sep-18	96					AIRWORTHINESS			
	HRS	1387.4	2400								
	AFL	1114									
					PROC. REF: NDT PART 6/55-10-05					PKG:20	
N5510015 ^S			PERFORM * VERTICAL STABILIZER PIVOT FITTING TOP PLATE - EDDY CURRENT INSPECTION.							Service	ATA:55
	MOS	11-Sep-18	96					AIRWORTHINESS			
	HRS	1387.4	2400								
	AFL	1114									
					PROC. REF: NDT PART 6/55-30-02					PKG:20	
N5510016 ^S			PERFORM * VERTICAL STABILIZER PIVOT FITTING TOWER SECTION FORWARD RADIUS - EDDY CURRENT INSPECTION. INSPECT PIVOT FITTING AT TOWER SECTION RADIUS, PIVOT FITTING AND TOP PLATE AROUND ADJACENT FASTENERS, AND PIVOT FITTING SIDES AT TOWER SECTION RADIUS							Service	ATA:55
	MOS	11-Sep-18	96					AIRWORTHINESS			
	HRS	1387.4	2400								
	AFL	1114									
					PROC. REF: NDT PART 6/55-30-03					PKG:20	
N5510069 ^S			PERFORM * HORIZONTAL STABILIZER MID SPAR FLANGE ROOT RIB ATTACHMENT - EDDY CURRENT INSPECTION							Service	ATA:55
	MOS	11-Sep-18	96					AIRWORTHINESS			
	HRS	1387.4	2400								
	AFL	1114									
					PROC. REF: NDT PART 6/55-10-02					PKG:20	
N5510082 ^S			PERFORM * HORIZONTAL STABILIZER REAR SPAR FLANGE ROOT RIB ATTACHMENT - EDDY CURRENT INSPECTION							Service	ATA:55
	MOS	11-Sep-18	96					AIRWORTHINESS			
	HRS	1387.4	2400								
	AFL	1114									
					PROC. REF: NDT PART 6/55-10-04					PKG:20	

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty		
ATA 55 - STABILIZERS												
P5510006 ^S			PERFORM * VERTICAL STABILIZER FRONT SPAR AND MID SPAR - RADIOGRAPHIC INSPECTION.								Service	ATA:55
	MOS	20-Jan-11						AIRWORTHINESS				
	HRS	0	9600									
	AFL	0										
					PROC. REF: NDT PART 2/55-30-01						PKG:26	
P5510008 ^S			PERFORM * HORIZONTAL STABILIZER PRIMARY AND SECONDARY ATTACH BOLTS - MAGNETIC PARTICLE INSPECTION.								Service	ATA:55
	MOS	20-Jan-11						AIRWORTHINESS				
	HRS	0	9600									
	AFL	0										
					PROC. REF: NDT PART 7/55-30-02, NDT PART 7/55-30-03						PKG:26	
P5510009 ^S			PERFORM * HORIZONTAL STABILIZER MID SPAR CAP B.L. 0.0 TO B.L. 4.0 - X-RAY INSPECTION.								Service	ATA:55
	MOS	11-Sep-18	96					AIRWORTHINESS				
	HRS	1387.4	2400									
	AFL	1114										
					PROC. REF: NDT PART 2/55-10-03						PKG:20	
P5510011 ^S			PERFORM * HORIZONTAL STABILIZER MID-SPAR AND REAR-SPAR UPPER FLANGE AT ROOT RIB - RADIOGRAPHIC INSPECTION.								Service	ATA:55
	MOS	20-Jan-11						AIRWORTHINESS				
	HRS	0	9600									
	AFL	0										
					PROC. REF: NDT PART 2/55-10-01						PKG:26	
P5510017 ^S			PERFORM * VERTICAL STABILIZER PIVOT FITTING TOWER SECTION - EDDY CURRENT INSPECTION								Service	ATA:55
	MOS	11-Sep-18	96					AIRWORTHINESS				
	HRS	1387.4	2400									
	AFL	1114										
					PROC. REF: NDT PART 6/55-30-05						PKG:20	
P5510018 ^S			PERFORM * VERTICAL STABILIZER PIVOT FITTING LUGS - EDDY CURRENT INSPECTION.								Service	ATA:55
	MOS	20-Jan-11						AIRWORTHINESS				
	HRS	0	9600									
	AFL	0										
					PROC. REF: NDT PART 6/55-30-04						PKG:26	
P5510019 ^S			PERFORM * ELEVATOR HINGES ON HORIZONTAL STABILIZER - EDDY CURRENT INSPECTION.								Service	ATA:55
	MOS	20-Jan-11						AIRWORTHINESS				
	HRS	0	9600									
	AFL	0										
					PROC. REF: NDT PART 6/55-20-02						PKG:26	

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 55 - STABILIZERS											
P5510020 ^S			PERFORM * HORIZONTAL MID-SPAR UPPER CAP - EDDY CURRENT INSPECTION.							Service	ATA:55
	MOS	20-Jan-11						AIRWORTHINESS			
	HRS	0	9600								
	AFL	0									
					PROC. REF: NDT PART 6/55-10-07						PKG:26
P5510024 ^S			PERFORM * ELEVATOR CONTROL HORN - EDDY CURRENT INSPECTION.							Service	ATA:55
	MOS	20-Jan-11						AIRWORTHINESS			
	HRS	0	9600								
	AFL	0									
					PROC. REF: NDT PART 6/55-20-01						PKG:26
P5510070 ^S			PERFORM * HORIZONTAL STABILIZER FRONT SPAR - RADIOGRAPHIC INSPECTION.							Service	ATA:55
	MOS	20-Jan-11						AIRWORTHINESS			
	HRS	0	9600								
	AFL	0									
					PROC. REF: NDT PART 2/55-10-02						PKG:26
P5510073 ^S			PERFORM * HORIZONTAL REAR SPAR UPPER CAP - EDDY CURRENT INSPECTION.							Service	ATA:55
	MOS	20-Jan-11						AIRWORTHINESS			
	HRS	0	9600								
	AFL	0									
					PROC. REF: NDT PART 6/55-10-07						PKG:26
P5510092 ^S			PERFORM * HORIZONTAL STABILIZER UPPER-SPAR-SPLICE DOUBLER - EDDY CURRENT INSPECTION.							Service	ATA:55
	MOS	11-Sep-18	96					AIRWORTHINESS			
	HRS	1387.4	2400								
	AFL	1114									
					PROC. REF: NDT PART 6/55-10-06						PKG:20
P5520001 ^S			PERFORM * ELEVATOR HINGE ATTACH BOLT - MAGNETIC PARTICLE INSPECTION.							Service	ATA:55
	MOS	20-Jan-11						AIRWORTHINESS			
	HRS	0	9600								
	AFL	0									
					PROC. REF: NDT PART 7/27-30-01						PKG:26
P5520002 ^S			PERFORM * ELEVATOR HINGE PIN - LIQUID PENETRANT INSPECTION. (EFFECTIVE ON AIRCRAFT 45-001 THRU 45-014)							Service	ATA:55
	MOS	20-Jan-11						AIRWORTHINESS			
	HRS	0	9600								
	AFL	0									
					PROC. REF: NDT PART 8/55-30-01						PKG:26

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 55 - STABILIZERS											
P5520021 ^S			PERFORM * ELEVATOR HINGE FITTINGS - EDDY CURRENT INSPECTION. (EFFECTIVE ON AIRCRAFT 45-015 AND SUBSEQUENT.)							Service	ATA:55
	MOS	20-Jan-11						AIRWORTHINESS			
	HRS	0	9600								
	AFL	0									
										PKG:26	
PROC. REF: NDT PART 6/55-30-07											
P5520022 ^S			PERFORM * ELEVATOR HINGE PRIMARY AND SECONDARY ATTACH BOLTS - LIQUID PENETRANT INSPECTION.							Service	ATA:55
	MOS	20-Jan-11						AIRWORTHINESS			
	HRS	0	9600								
	AFL	0									
										PKG:26	
PROC. REF: NDT PART 8/27-30-01, NDT PART 8/27-30-02											
P5540001 ^S			PERFORM * RUDDER SPAR - DETAILED VISUAL INSPECTION. INSPECT SPAR CAPS AND FASTENERS.							Service	ATA:55
	MOS	20-Jan-11						AIRWORTHINESS			
	HRS	0	9600								
	AFL	0									
										PKG:26	
PROC. REF: GENERIC NO REF											
P5540002 ^S			PERFORM * RUDDER ATTACH BOLT - LIQUID PENETRANT INSPECTION.							Service	ATA:55
	MOS	20-Jan-11						AIRWORTHINESS			
	HRS	0	9600								
	AFL	0									
										PKG:26	
PROC. REF: NDT PART 8/55-30-02											
Q5510007 ^S			PERFORM * VERTICAL STABILIZER SKIN AND LOWER AFT SPAR CAP - EDDY CURRENT INSPECTION.							Service	ATA:55
	MOS	20-Jan-11						AIRWORTHINESS			
	HRS	0	9600								
	AFL	0									
										PKG:26	
PROC. REF: NDT PART 6/55-30-06											
Q5530011 ^S			PERFORM * VERTICAL STABILIZER SKIN AND UPPER AFT SPAR CAP - EDDY CURRENT INSPECTION.							Service	ATA:55
	MOS	11-Sep-18	96					AIRWORTHINESS			
	HRS	1387.4	2400								
	AFL	1114									
										PKG:20	
PROC. REF: NDT PART 6/55-30-06											
T5510004 ^S			PERFORM * RUDDER HINGE FITTINGS - VISUAL INSPECTION. CONTROL SURFACE REMOVAL NOT REQUIRED.							Service	ATA:55
	MOS	20-Jan-11						AIRWORTHINESS			
	HRS	0	9600								
	AFL	0									
										PKG:26	
PROC. REF: GENERIC NO REF											

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 55 - STABILIZERS											
Y5510001 ^S			PERFORM HORIZONTAL STABILIZER - EXTERNAL VISUAL INSPECTION						Service	ATA:55	
	MOS	20-Jan-23	48 (+ 14d/-14d)								
	HRS	1675	1200 (+ 25/-25)								
	AFL	1330									
					PROC. REF: AMM 05-10-00					PKG:14	
Y5510002 ^S			PERFORM ELEVATOR HINGES ON HORIZONTAL STABILIZER - VISUAL INSPECTION. INSPECT HINGE LUGS ON HORIZONTAL TAIL SIDE OF JOINT. INSPECT HILITE COLLARS AT BL 0.0 AND OUTBOARD ELEVATOR HINGE						Service	ATA:55	
	MOS	20-Jan-23	48 (+ 14d/-14d)								
	HRS	1675	1200 (+ 25/-25)								
	AFL	1330									
					PROC. REF: GENERIC NO REF					PKG:14	
Y5510003 ^S			PERFORM VERTICAL STABILIZER PIVOT FITTING - VISUAL INSPECTION. INSPECT HILITE COLLARS COMMON TO THE PIVOT FITTING (MID SPAR, AFT SPAR, TOP PLATE, AND UP/DOWN SPRING BRACKET).						Service	ATA:55	
	MOS	20-Jan-23	48 (+ 14d/-14d)								
	HRS	1675	1200 (+ 25/-25)								
	AFL	1330									
					PROC. REF: AMM 55-00-01					PKG:14	
Y5510093 ^S			PERFORM HORIZONTAL STABILIZER - VISUAL INSPECTION OF HILITE COLLARS IN THE FOLLOWING AREAS:- FORWARD SPAR TO BL 0.0 RIB.- CENTER SPAR TO BL 0.0 RIB.- CENTER SPAR SPLICE PLATE.- AFT SPAR SPLICE PLATE.- ROOT RIBS AT BL 3.70 (RIGHT AND LEFT).- UPPER DOUBLER SPAR SPLICE, BL 0.0.- HSTA UPPER ATTACH FITTING STRUCTURE						Service	ATA:55	
	MOS	20-Jan-23	48 (+ 14d/-14d)								
	HRS	1675	1200 (+ 25/-25)								
	AFL	1330									
					PROC. REF: AMM 55-00-01					PKG:14	
Y5510094 ^S			PERFORM LOWER BRACKET, HORIZONTAL STABILIZER TRIM ACTUATOR - BORESCOPE INSPECTION OF HILITE COLLARS COMMON TO RIB # 6 AND MID SPAR						Service	ATA:55	
	MOS	20-Jan-23	48 (+ 14d/-14d)								
	HRS	1675	1200 (+ 25/-25)								
	AFL	1330									
					PROC. REF: AMM 55-10-00					PKG:14	
Y5540012 ^S			RUDDER TORQUE TUBE - LOOSEN TORQUE TUBE BONDING CLAMP AND PERFORM DETAILED VISUAL INSPECTION OF AREA AROUND BONDING CLAMP FOR CORROSION. NOTE: PERFORM BONDING CHECK OF CLAMP AND BONDING JUMPERS AFTER REINSTALLATION OF CLAMP.						Service	ATA:55	
	MOS	20-Jan-23	12 (+ 14d/-14d)								
	HRS	1675	300 (+ 25/-25)								
	AFL	1330									
					PROC. REF: AMM 27-20-01					PKG:2	

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 56 - WINDOWS											
5-19-00-W5600002		** WINDSHIELD - PERFORM RAIN REMOVAL COATING EFFECTIVENESS TEST (IRN W5600002)								Service	ATA:56
	MOS	20-Jan-23	12 (+ 14d/-14d)		20-Jan-24		346 d (+ 14)	AIRWORTHINESS			
	HRS	1675									
	AFL	1330									
PROC. REF: AMM 56-10-01, AMM 56-10-01											
561001		LEFT WINDSHIELD ASSEMBLY								Component	ATA:56
	PN:6656100001-001	MOS/MSC	10-Oct-12	O/C	TSN 0						
	SN:1187	HRS	461.9		TSN 0						
	AFL	394			TSN 0						
PROC. REF: AMM 56-10-01, AMM 56-10-01											
561001A		ULTRASONIC-INSPECTION LEFT WINDSHIELD ASSEMBLY STRUCTURAL PLIES (IRN N5600003)								Service	ATA:56
	PN:6656100001-001	MOS/MSC		N/A				AIRWORTHINESS			
	SN:1187	HRS									
	AFL										
PROC. REF: NDT PART 4/56-10-01											
561001B		PERFORM INSPECTION LEFT WINDSHIELD ASSEMBLY BOLT HOLES (IRN N5600012)								Service	ATA:56
	PN:6656100001-001	MOS	10-Oct-12					AIRWORTHINESS			
	SN:1187	HRS	461.9	4800	5261.9		3586.9				
	AFL	394									
PROC. REF: AMM 56-10-01											
561002		RIGHT WINDSHIELD ASSEMBLY								Component	ATA:56
	PN:P01400-6	MOS/MSC	20-Jan-11	O/C	TSN 0						
	SN:986	HRS	0		TSN 0						
	AFL	0			TSN 0						
PROC. REF: AMM 56-10-01, AMM 56-10-01											
561002A		ULTRASONIC-INSPECTION RIGHT WINDSHIELD ASSEMBLY STRUCTURAL PLIES (IRN N5600003)								Service	ATA:56
	PN:P01400-6	MOS	20-Jan-11					AIRWORTHINESS			
	SN:986	HRS	0	4800	4800		3125				
	AFL	0									
PROC. REF: NDT PART 4/56-10-01											

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 56 - WINDOWS											
561002B		PERFORM INSPECTION RIGHT WINDSHIELD ASSEMBLY BOLT HOLE (IRN N5600012)								Service	ATA:56
PN:P01400-6	MOS	20-Jan-11						AIRWORTHINESS			
SN:986	HRS	0	4800		4800		3125				
	AFL	0									
PROC. REF: AMM 56-10-01											
562010-1		LEFT NO.1 WINDOW CABIN								Component	ATA:56
PN:PN	MOS/MSC	20-Jan-11	O/C		TSN 0						
SN:UNKNOWN	HRS	0			TSN 0						
	AFL	0			TSN 0						
PROC. REF: AMM 56-20-01											
562010-10		RIGHT NO.5 WINDOW CABIN								Component	ATA:56
PN:PN	MOS/MSC	20-Jan-11	O/C		TSN 0						
SN:UNKNOWN	HRS	0			TSN 0						
	AFL	0			TSN 0						
PROC. REF: AMM 56-20-01											
562010-11		LEFT NO.6 WINDOW CABIN								Component	ATA:56
PN:PN	MOS/MSC	20-Jan-11	O/C		TSN 0						
SN:UNKNOWN	HRS	0			TSN 0						
	AFL	0			TSN 0						
PROC. REF: AMM 56-20-01											
562010-12		RIGHT NO.6 EMERGENCY EXIT WINDOW								Component	ATA:56
PN:PN	MOS/MSC	20-Jan-11	O/C		TSN 0						
SN:UNKNOWN	HRS	0			TSN 0						
	AFL	0			TSN 0						
PROC. REF: AMM 56-20-01											
562010-13		LEFT NO.7 WINDOW CABIN								Component	ATA:56
PN:PN	MOS/MSC	20-Jan-11	O/C		TSN 0						
SN:UNKNOWN	HRS	0			TSN 0						
	AFL	0			TSN 0						
PROC. REF: AMM 56-20-01											
562010-14		RIGHT NO.7 WINDOW CABIN								Component	ATA:56
PN:PN	MOS/MSC	20-Jan-11	O/C		TSN 0						
SN:UNKNOWN	HRS	0			TSN 0						
	AFL	0			TSN 0						
PROC. REF: AMM 56-20-01											

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty
---------	------	------	----------	-----------	--------------------------	-----------	-----------	-------------	-----	----------

ATA 56 - WINDOWS

562010-15		LEFT NO.8 WINDOW CABIN								Component	ATA:56
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 56-20-01											
562010-16		EMERGENCY EXIT WINDOW CABIN								Component	ATA:56
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 52-20-06											
562010-2		RIGHT NO.1 WINDOW CABIN								Component	ATA:56
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 56-20-01											
562010-3		LEFT NO.2 WINDOW CABIN								Component	ATA:56
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 56-20-01											
562010-4		RIGHT NO.2 WINDOW CABIN								Component	ATA:56
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 56-20-01											
562010-5		LEFT NO.3 WINDOW CABIN								Component	ATA:56
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 56-20-01											
562010-6		RIGHT NO.3 WINDOW CABIN								Component	ATA:56
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 56-20-01											

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 56 - WINDOWS											
562010-7		LEFT NO.4 WINDOW CABIN								Component	ATA:56
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:UNKNOWN	HRS	0	TSN 0								
	AFL	0	TSN 0								
PROC. REF: AMM 56-20-01											
562010-8		RIGHT NO.4 WINDOW CABIN								Component	ATA:56
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:UNKNOWN	HRS	0	TSN 0								
	AFL	0	TSN 0								
PROC. REF: AMM 56-20-01											
562010-9		LEFT NO.5 WINDOW CABIN								Component	ATA:56
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:UNKNOWN	HRS	0	TSN 0								
	AFL	0	TSN 0								
PROC. REF: AMM 56-20-01											
L5600010 ^S		PERFORM * CABIN WINDOWS (INCLUDING THE EMERGENCY EXIT WINDOW) - DETAILED VISUAL INSPECTION								Service	ATA:56
	MOS	20-Jan-11					AIRWORTHINESS				
	HRS	0	4800								
	AFL	0									
PROC. REF: GENERIC NO REF											
PKG:25											
Y5600000 ^S		WINDSHIELDS - PERFORM VISUAL INSPECTION (INTERIOR AND EXTERIOR)								Service	ATA:56
	MOS	20-Jan-23	12 (+14d/-14d)								
	HRS	1675	300 (+25/-25)								
	AFL	1330									
PROC. REF: AMM 05-10-00											
PKG:1											
Y5600001 ^S		CABIN WINDOWS - PERFORM VISUAL INSPECTION								Service	ATA:56
	MOS	20-Jan-23	24 (+14d/-14d)								
	HRS	1675	600 (+25/-25)								
	AFL	1330									
PROC. REF: AMM 05-10-00											
PKG:7											
Y5600013 ^S		WINDSHIELDS - PERFORM VISUAL INSPECTION OF THE AERODYNAMIC SEAL. IF REPAIRS TO THE SEAL ARE NEEDED, REFER TO 56-10-01.								Service	ATA:56
	MOS	20-Jan-23	12 (+14d/-14d)								
	HRS	1675	300 (+25/-25)								
	AFL	1330									
PROC. REF: AMM 56-10-01, AMM 56-10-01											
PKG:1											

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 57 - WINGS										
5-19-00-E5750051	VISUALLY INSPECT * FLAP MAIN TRACK ROLLERS WITH FLAPS REMOVED (IRN E5750051)									Service ATA:57
MOS	20-Jan-11							AIRWORTHINESS		
HRS	0		T:10000		10000		8325			
AFL	0									
PROC. REF: AMM 05-10-00										
5-19-00-E5750052	VISUALLY INSPECT * FLAP NOSE ROLLERS WITH FLAPS REMOVED (IRN E5750052)									Service ATA:57
MOS	20-Jan-11							AIRWORTHINESS		
HRS	0		T:7200		7200		5525			
AFL	0									
PROC. REF: AMM 05-10-00										
5-19-00-N5710002	VISUALLY INSPECT * WING BOX MID SPAR LOWER CAP, OUTBOARD OF JOINT AT WS 137 BETWEEN RIBS 7 AND 8. N5710002 (PRE SB 45-11-5)									Service ATA:57
MOS	20-Jan-11							AIRWORTHINESS		
HRS	0		T:9600		9600		7925			
AFL	0									
PROC. REF: AMM 05-10-00										
5-19-00-N5710008	NON DESTRUCTIVE INSPECT * WING BOX SPAR LOWER CAP - PERFORM NDI INSPECTION. N5710008 (PRE SB 45-11-5)									Service ATA:57
MOS	20-Jan-11							AIRWORTHINESS		
HRS	0		T:9600		9600		7925			
AFL	0									
PROC. REF: NDT PART 4/57-30-03										
5-19-00-N5710009	NON DESTRUCTIVE TEST * WING BOX MID SPAR LOWER CAP JOINT AT WS 137 - PERFORM NDI INSPECTION. N5710009 (PRE SB 45-11-5)									Service ATA:57
MOS	20-Jan-11							AIRWORTHINESS		
HRS	0		T:9600		9600		7925			
AFL	0									
PROC. REF: NDT PART 2/57-10-02										
5-19-00-N5710010	NON DESTRUCTIVE INSPECT * WING BOX REAR SPAR LOWER CAP INBOARD OF JOINT WS 81 - PERFORM NDI INSPECTION. N5710010 (PRE SB 45-11-5)									Service ATA:57
MOS	20-Jan-11							AIRWORTHINESS		
HRS	0		T:9600		9600		7925			
AFL	0									
PROC. REF: NDT PART 4/57-30-01										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty		
ATA 57 - WINGS												
5-19-00-N5710012			* WING BOX REAR SPAR LOWER CAP OUTBOARD OF JOINT AT WS 81 TO RIB # 6 - PERFORM DETAILED VISUAL INSPECTION. INSPECT OUTER REAR SPAR LOWER CAP AND AFT LOWER SKIN PANEL OUTBOARD OF REAR SPLICE AT WS 90. (REFER TO 5-10-00.) (EFFECTIVE ON AIRCRAFT NOT MODIFIED BY SB 45-11-5, "INCREASE MAXIMUM ZERO FUEL WEIGHT (16,500 POUNDS).")								Service	ATA:57
	MOS	20-Jan-11						AIRWORTHINESS				
	HRS	0	T:9600		9600		7925					
	AFL	0										
			PROC. REF: AMM 05-10-00									
5-19-00-N5710013			NON DESTRUCTIVE INSPECT * WING BOX REAR SPAR LOWER CAP SKIN TERMINATION AT MS 48 - PERFORM NDI INSPECTION. N5710013 (PRE SB 45-11-5)								Service	ATA:57
	MOS	20-Jan-11						AIRWORTHINESS				
	HRS	0	T:10000		10000		8325					
	AFL	0										
			PROC. REF: NDT PART 6/57-20-04									
5-19-00-N5710026			NON DESTRUCTIVE INSPECT * WING BOX SPAR LOWER CAP - PERFORM NDI INSPECTION. INSPECT MID SPAR LOWER CAP OUTBOARD OF ROOT RIB AT WS 33 TO WS 99. N5710026 (PRE SB 45-11-5)								Service	ATA:57
	MOS							AIRWORTHINESS				
	HRS		T:10000		10000		8325					
	AFL											
			PROC. REF: NDT PART 4/57-30-03									
5-19-00-N5710123			EDDY CURRENT INSPECT * WING BOX MID SPAR LOWER CAP AT TRUNNION FITTING - PERFORM EDDY CURRENT INSPECTION AT TRUNNION FITTING. N5710123 (PRE SB 45-11-5)								Service	ATA:57
	MOS	20-Jan-11						AIRWORTHINESS				
	HRS	0	T:9600		9600		7925					
	AFL	0										
			PROC. REF: NDT PART 6/57-10-01									
5-19-00-N5710148			EDDY CURRENT INSPECTION * WING CENTER SECTION REAR SPAR - PERFORM EDDY CURRENT INSPECTION, INSPECT REAR SPAR LOWER CAP FROM CENTERLINE TO WS 33 N5710148 (POST SB 45-11-5)								Service	ATA:57
	MOS/MS	20-Jan-11	N/A									
	HRS	0										
	AFL	0										
			PROC. REF: NDT PART 6/57-20-02									
5-19-00-N5710149			EDDY CURRENT INSPECTION * WING CENTER SECTION FORWARD AND AFT RIBS AT WS6 AND FORWARD RIBS AT WS 17 - PERFORM EDDY CURRENT INSPECTION. N5710149 (POST SB 45-11-5)								Service	ATA:57
	MOS/MS	20-Jan-11	N/A									
	HRS	0										
	AFL	0										
			PROC. REF: NDT PART 6/57-10-06									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty		
ATA 57 - WINGS												
5-19-00-N5710150			ULTRASONIC-INSPECTION * WING BOX MID SPAR LOWER CAP - PERFORM ULTRASONIC INSPECTION, INSPECT MID SPAR LOWER CAP AND LOWER SKIN PANELS BETWEEN WS99 AND WS137. N5710150 (POST SB 45-11-5)								Service	ATA:57
	MOS/MSC	20-Jan-11	N/A									
	HRS	0										
	AFL	0										
PROC. REF: NDT PART 4/57-30-03												
5-19-00-N5710151			X-RAY INSPECTION * WING BOX MID SPAR LOWER CAP JOINT AT WS137 - PERFORM X-RAY INSPECTION. INSPECT MID SPAR CENTER/OUTER JOINT. N5710151 (POST SB 45-11-5)								Service	ATA:57
	MOS/MSC	20-Jan-11	N/A									
	HRS	0										
	AFL	0										
PROC. REF: NDT PART 2/57-10-02												
5-19-00-N5710152			ULTRASONIC-INSPECTION * WING BOX REAR SPAR LOWER CAP INBOARD OF JOINT AT WS81 - PERFORM ULTRASONIC INSPECTION, INSPECT REAR SPAR LOWER CAP BETWEEN SKIN TERMINATION AT WS 48 CLOSING RIB AT WS 60. N5710152 (POST SB 45-11-5)								Service	ATA:57
	MOS/MSC	20-Jan-11	A/R									
	HRS	0										
	AFL	0										
PROC. REF: NDT PART 4/57-30-01												
5-19-00-N5710153			X-RAY INSPECTION * WING BOX REAR SPAR LOWER CAP JOINT AT WS 81 - PERFORM X-RAY INSPECTION. INSPECT CENTER AND OUTER REAR SPARS, LOWER SPLICE PLATE, AND LOWER SKIN BETWEEN WS 60 AND WS 90. N5710153 (POST SB 45-11-5)								Service	ATA:57
	MOS/MSC	20-Jan-11	N/A									
	HRS	0										
	AFL	0										
PROC. REF: NDT PART 2/57-10-03												
5-19-00-N5710155			EDDY CURRENT INSPECTION * WING BOX REAR SPAR LOWER CAP SKIN TERMINATION AT MS 48 - PERFORM EDDY CURRENT INSPECTION. INSPECT REAR SPAR LOWER CAP BETWEEN WS33 AND WS 48. N5710155 (POST SB 45-11-5)								Service	ATA:57
	MOS/MSC	20-Jan-11	N/A									
	HRS	0										
	AFL	0										
PROC. REF: NDT PART 6/57-20-04												
5-19-00-N5710158			EDDY CURRENT INSPECTION * CENTER SECTION FRONT SPAR LOWER CAP - PEFORM EDDY CURRENT INSPECTION. INSPECT CENTER WING FRONT SPAR LOWER CAP BETWEEN SKIN TERMINATIONS (WS31 LEFT TO WS31 RIGHT) N5710158 (POST SB 45-11-5)								Service	ATA:57
	MOS/MSC	20-Jan-11	N/A									
	HRS	0										
	AFL	0										
PROC. REF: NDT PART 6/57-10-03												

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 57 - WINGS											
5-19-00-N5710159			ULTRASONIC-INSPECTION * WING BOX MID SPAR LOWER CAP - PERFORM ULTRASONIC INSPECTION. INSPECT MID SPAR LOWER CAP OUTBOARD OF ROOT RIB AT WS 33 TO WS 99. N5710159 (POST SB 45-11-5)						Service	ATA:57	
	MOS/MSC	20-Jan-11	N/A								
	HRS	0									
	AFL	0									
PROC. REF: NDT PART 4/57-30-03											
5-19-00-N5710160			EDDY CURRENT INSPECTION * WING BOX MID SPAR LOWER CAP, SKIN TERMINATION AT WS 33 - PERFORM BOLT HOLE EDDY CURRENT INSPECTION. INSPECT MID SPAR LOWER CAP UNDERNEATH ROOT RIB (WS 33) AT POINT OF SKIN TERMINATION. N5710160 (POST SB 45-11-5)						Service	ATA:57	
	MOS/MSC	20-Jan-11	N/A								
	HRS	0									
	AFL	0									
PROC. REF: NDT PART 6/57-10-11											
5-19-00-N5710163			EDDY CURRENT INSPECTION * CENTER SECTION MID SPAR CENTERLINE JOINT - PERFORM EDDY CURRENT INSPECTION. INSPECT CENTER MID SPAR (CENTERLINE TO WS 17), LOWER SPLICE PLATE, AND CENTER MID SPAR JOINT FITTING LOWER CAP. N5710163 (POST SB 45-11-5)						Service	ATA:57	
	MOS/MSC	20-Jan-11	N/A					NOT APPLICABLE			
	HRS	0									
	AFL	0									
PROC. REF: NDT PART 6/57-10-08, NDT PART 6/57-10-10											
5-19-00-N5710164			EDDY CURRENT INSPECTION * CENTER SECTION MID SPAR LOWER CAP - PERFORM EDDY CURRENT INSPECTION. INSPECT MID SPAR FROM CENTERLINE SPLICE PLATE TO SKIN TERMINATION AT MS 33. N5710164 (POST SB 45-11-5)						Service	ATA:57	
	MOS/MSC	20-Jan-11	A/R								
	HRS	0									
	AFL	0									
PROC. REF: NDT PART 6/57-10-02											
5-19-00-N5710165			EDDY CURRENT INSPECTION * WING BOX REAR SPAR FLAP TRACK CUT-OUTS - PERFORM EDDY CURRENT INSPECTION. INSPECT FLAP TRACK CUT-OUTS AT WS65, WS 126 AND WS184 ON REAR SPAR. N5710165 (POST SB 45-11-5)						Service	ATA:57	
	MOS/MSC	20-Jan-11	A/R								
	HRS	0									
	AFL	0									
PROC. REF: NDT PART 6/57-20-01											
5-19-00-N5710168			EDDY CURRENT INSPECTION * WING BOX MID SPAR LOWER CAP - PERFORM EDDY CURRENT INSPECTION AT TRUNNION FITTING. N5710168 (POST SB 45-11-5)						Service	ATA:57	
	MOS/MSC	20-Jan-11	N/A								
	HRS	0									
	AFL	0									
PROC. REF: NDT PART 6/57-10-01											

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty		
ATA 57 - WINGS												
5-19-00-N5710169			EDDY CURRENT INSPECTION * MID SPAR AT RIB # 2 NEAR WS48 - PERFORM BOLT HOLE EDDY CURRENT INSPECTION. N5710169 (POST SB 45-11-5)								Service	ATA:57
	MOS	20-Jan-11										
	HRS	0	T:7700		7700		6025					
	AFL	0										
PROC. REF: NDT PART 6/57-10-11												
5-19-00-N5710170			EDDY CURRENT INSPECTION * MID SPAR AT RIB # 3 NEAR WS60 - PERFORM BOLT HOLE EDDY CURRENT INSPECTION. N5710170 (POST SB 45-11-5)								Service	ATA:57
	MOS	20-Jan-11										
	HRS	0	T:7700		7700		6025					
	AFL	0										
PROC. REF: NDT PART 6/57-10-11												
5-19-00-N5710171			EDDY CURRENT INSPECTION * FORWARD FLANGE FASTENERS AT REAR SPAR BETWEEN WS 52 AND WS 60 - PERFORM BOLT HOLE EDDY CURRENT INSPECTION. N5710171 (POST SB 45-11-5)								Service	ATA:57
	MOS/MSC	20-Jan-11	N/A									
	HRS	0										
	AFL	0										
PROC. REF: NDT PART 6/57-20-03												
5-19-00-N5710172			ULTRASONIC-INSPECTION * WING BOX MID SPAR LOWER CAP - PERFORM ULTRASONIC INSPECTION AT TRUNNION FITTING. N5710172 (PRE SB 45-11-5)								Service	ATA:57
	MOS	20-Jan-11										
	HRS	0	T:9600		9600		7925					
	AFL	0										
PROC. REF: NDT PART 4/57-10-00												
5-19-00-N5710173			ULTRASONIC-INSPECTION * WING BOX MID SPAR LOWER CAP - PERFORM ULTRASONIC INSPECTION AT TRUNNION FITTING. N5710173 (POST SB 45-11-5)								Service	ATA:57
	MOS/MSC	20-Jan-11	N/A									
	HRS	0										
	AFL	0										
PROC. REF: NDT PART 4/57-10-00												
5-19-00-N5710174			ULTRASONIC-INSPECTION * WING BOX REAR SPAR LOWER CAP SKIN TERMINATION AT WS 48 - PERFORM ULTRASONIC INSPECTION. INSPECT REAR SPAR LOWER CAP BETWEEN WS 33 AND WS 48. N5710174 (PRE SB 45-11-5)								Service	ATA:57
	MOS	20-Jan-11										
	HRS	0	T:10000		10000		8325					
	AFL	0										
PROC. REF: NDT PART 4/57-30-04												

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 57 - WINGS											
5-19-00-N5710175		ULTRASONIC-INSPECTION * WING BOX REAR SPAR LOWER CAP SKIN TERMINATION AT MS 48 - PERFORM ULTRASONIC INSPECTION. INSPECT REAR SPAR LOWER CAP BETWEEN WS 33 AND WS 48. N5710175 (POST SB 45-11-5)								Service	ATA:57
	MOS/MSC	20-Jan-11	N/A								
	HRS	0									
	AFL	0									
PROC. REF: NDT PART 4/57-30-04											
5-19-00-N5710177		ULTRASONIC-INSPECTION * WING MID SPAR (CENTER SECTION) LOWER CAP AND CENTER JOINT FITTING - PERFORM ULTRASONIC INSPECTION. N5710177 (POST SB 45-11-5)								Service	ATA:57
	MOS/MSC	20-Jan-11	N/A								
	HRS	0									
	AFL	0									
PROC. REF: NDT PART 4/57-30-05											
571001		WING ASSEMBLY								Component	ATA:57
PN:4557000004-001	MOS/MSC	20-Jan-11	O/C	TSN	0						
SN:F05792600545	HRS	0	TSN 0								
	AFL	0	TSN 0								
PROC. REF: AMM 57-10-00											
5710190		* LEFT WING CENTER SECTION (PANELS 510AC, 510BC, 510BL AND 610BR REMOVED AND PANELS 510AL, 610AR, 720BL, AND 730BR LOWERED) - PERFORM VISUAL INSPECTION. INSPECT STRUCTURE FOR CORROSION OR DETERIORATION OF PROTECTIVE TREATMENT.								Service	ATA:57
	MOS	23-Oct-20	96 (+ 14d/-14d)		23-Oct-28	06-Nov-28	2084 d (+ 14)				
	HRS	1570.8									
	AFL	1243									
PROC. REF: AMM 57-10-00											
5710190		* RIGHT WING CENTER SECTION (PANELS 510AC, 510BC, 510BL AND 610BR REMOVED AND PANELS 510AL, 610AR, 720BL, AND 730BR LOWERED) - PERFORM VISUAL INSPECTION. INSPECT STRUCTURE FOR CORROSION OR DETERIORATION OF PROTECTIVE TREATMENT.								Service	ATA:57
	MOS	23-Oct-20	96 (+ 14d/-14d)		23-Oct-28	06-Nov-28	2084 d (+ 14)				
	HRS	1570.8									
	AFL	1243									
PROC. REF: AMM 57-10-00											
571066		REAR TRUNNION BREAK OUT BLOCK REPLACE								Component	ATA:57
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN	0						
SN:UNKNOWN	HRS	0	TSN 0								
	AFL	0	TSN 0								
PROC. REF: GENERIC NO REF											

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 57 - WINGS											
573001		LEFT WINGLET FILLER								Component	ATA:57
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: GENERIC NO REF											
573002		RIGHT WINGLET FILLER								Component	ATA:57
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: GENERIC NO REF											
573090		LEFT WING WINGLET								Component	ATA:57
PN:6657300100-001	MOS/MSC	21-Apr-14	O/C								
SN:361	HRS	815.4									
	AFL	741									
PROC. REF: AMM 57-30-01											
573091		LEFT WINGLET LEADING EDGE ASSEMBLY								Component	ATA:57
PN:4557300003-013	MOS/MSC	21-Apr-14	O/C	TSN 0							
SN:NONE	HRS	815.4		TSN 0							
	AFL	741		TSN 0							
PROC. REF: AMM 57-30-01											
573092		RIGHT WING WINGLET								Component	ATA:57
PN:4557300006-002/00	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:E804084	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 57-30-01											
573093		RIGHT WINGLET LEADING EDGE ASSEMBLY								Component	ATA:57
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 57-30-01											

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 57 - WINGS										
574005 LEFT INBOARD LEADING EDGE Component ATA:57										
PN:4557400005-039	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:E924025	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 57-40-01										
574007 RIGHT INBOARD LEADING EDGE Component ATA:57										
PN:4557400005-040	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:E893494	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 57-40-01										
574011 LEFT INBOARD LEADING EDGE ACCESS SECTION Component ATA:57										
PN:4557400005-037	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:E823412	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 57-40-01										
574013 RIGHT INBOARD LEADING EDGE ACCESS SECTION Component ATA:57										
PN:4557400005-038	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:E927975	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 57-40-01										
574033 LEFT CENTER LEADING EDGE Component ATA:57										
PN:4557400005-041	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:E437318	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 57-40-01										
574035 RIGHT CENTER LEADING EDGE Component ATA:57										
PN:4557400005-042	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:E924403	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 57-40-01										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 57 - WINGS										
574039	LEFT OUTBOARD LEADING EDGE ACCESS SECTION									Component ATA:57
PN:4557400005-045	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:E898952	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 57-40-01										
574041	RIGHT OUTBOARD LEADING EDGE ACCESS SECTION									Component ATA:57
PN:4557400005-044	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:E927983	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 57-40-01										
574050	LEFT OUTBOARD LEADING EDGE									Component ATA:57
PN:4557400005-043	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:E924410	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 57-40-01										
574051	RIGHT OUTBOARD LEADING EDGE									Component ATA:57
PN:4557400005-046	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:E924413	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 57-40-01										
575001	LEFT FLAP ASSEMBLY									Component ATA:57
PN:4557500006-009	MOS/MSC	23-Oct-20	O/C	TSN 117, TSR 0						
SN:F03820300545	HRS	1570.8		TSN 1570.8, TSR 0						
	AFL	1243		TSN 1243, TSR 0						
PROC. REF: AMM 27-50-01										
575002	RIGHT FLAP ASSEMBLY									Component ATA:57
PN:4557500006-010	MOS/MSC	23-Oct-20	O/C	TSN 117, TSR 0						
SN:F03822700545	HRS	1570.8		TSN 1570.8, TSR 0						
	AFL	1243		TSN 1243, TSR 0						
PROC. REF: AMM 27-50-01										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 57 - WINGS										
576001	LEFT AILERON									Component ATA:57
PN:4557600003-001	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:F076918	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 27-10-02										
576002	RIGHT AILERON									Component ATA:57
PN:4557600003-002	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:F076916	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 27-10-02										
576003	UPPER AILERON QUADRANT ASSEMBLY									Component ATA:57
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 27-10-07										
576004	LOWER AILERON QUADRANT ASSEMBLY									Component ATA:57
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 27-10-07										
576010	LEFT AILERON BALANCE TAB ASSEMBLY									Component ATA:57
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
576011	RIGHT AILERON BALANCE TAB ASSEMBLY									Component ATA:57
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 57 - WINGS										
576037	REPLACE LEFT AILERON (ZONE/ACCESS 540/640 * IRN # A5760004) BOLTS								Component	ATA:57
PN:PN	MOS	20-Jan-11		TSN 0				REPLACE		
SN:UNKNOWN	HRS	0	9600	TSN 0	9600		7925			
	AFL	0		TSN 0						
PROC. REF: AMM 27-10-02										
576038	REPLACE RIGHT AILERON (ZONE/ACCESS 540/640 * IRN # A5760004) BOLTS								Component	ATA:57
PN:PN	MOS	20-Jan-11		TSN 0				REPLACE		
SN:UNKNOWN	HRS	0	9600	TSN 0	9600		7925			
	AFL	0		TSN 0						
PROC. REF: AMM 27-10-02										
577001	LEFT SPOILER								Component	ATA:57
PN:4557700003-043	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:989490400538	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 27-60-01										
577002	RIGHT SPOILER								Component	ATA:57
PN:4557700003-044	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:E736823	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 27-60-01										
E5710005 ^S	PERFORM * WING CENTER SECTION SPAR UPPER CAPS - VISUAL INSPECTION. INSPECT FRONT, MID, AND REAR SPAR UPPER CAPS FROM CENTERLINE TO SKIN TERMINATION AT WS 33.								Service	ATA:57
	MOS	20-Jan-11						AIRWORTHINESS		
	HRS	0	9600							
	AFL	0								
PROC. REF: GENERIC NO REF										
PKG:26										
E5710019 ^S	PERFORM * WING BOX, UPPER SKIN, SKIN/STRINGER AND SPAR CAPS - VISUAL INSPECTION. INSPECT UPPER WING SPAR CAPS, SKIN PANEL, AND STRINGERS OF OUTER WING								Service	ATA:57
	MOS	20-Jan-11						AIRWORTHINESS		
	HRS	0	9600							
	AFL	0								
PROC. REF: GENERIC NO REF										
PKG:26										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 57 - WINGS											
E5710020 ^S			PERFORM * WING BOX RIBS - VISUAL INSPECTION. INSPECT ALL WING BOX RIBS EXCEPT CLOSING RIB BETWEEN FRONT AND MID SPARS AND CLOSING RIB BETWEEN MID AND REAR SPAR.							Service	ATA:57
	MOS	20-Jan-11						AIRWORTHINESS			
	HRS	0	9600								
	AFL	0									
					PROC. REF: GENERIC NO REF					PKG:26	
E5760006 ^S			PERFORM * AILERON BASIC STRUCTURE - VISUAL INSPECTION							Service	ATA:57
	MOS	20-Jan-11						AIRWORTHINESS			
	HRS	0	9600								
	AFL	0									
					PROC. REF: GENERIC NO REF					PKG:26	
L5710124 ^S			PERFORM * AILERON DRIVE SUPPORT - ULTRASONIC INSPECTION.							Service	ATA:57
	MOS	20-Jan-11						AIRWORTHINESS			
	HRS	0	4800								
	AFL	0									
					PROC. REF: NDT PART 4/27-10-01					PKG:25	
N5710004 ^S			PERFORM * WING CENTER SECTION REAR SPAR - EDDY CURRENT INSPECTION. INSPECT REAR SPAR LOWER CAP FROM CENTERLINE TO WS 33. (PRE SB 45-11-5)							Service	ATA:57
	MOS	20-Jan-11						AIRWORTHINESS			
	HRS	0	T:9600								
	AFL	0									
					PROC. REF: NDT PART 6/57-20-02					PKG:25	
N5710006 ^S			PERFORM * WING CENTER SECTION FORWARD AND AFT RIBS AT WS 6 AND FORWARD RIBS AT WS 17 - EDDY CURRENT INSPECTION. (PRE SB 45-11-5)							Service	ATA:57
	MOS	20-Jan-11						AIRWORTHINESS			
	HRS	0	T:9600								
	AFL	0									
					PROC. REF: NDT PART 6/57-10-06					PKG:25	
N5710011 ^S			PERFORM * WING BOX REAR SPAR LOWER CAP JOINT AT WS 81 - X-RAY INSPECTION. INSPECT CENTER AND OUTER REAR SPARS, LOWER SPLICE PLATE, AND LOWER SKIN BETWEEN WS 60 AND WS 90. (PRE SB 45-11-5)							Service	ATA:57
	MOS	11-Sep-18	96					AIRWORTHINESS			
	HRS	1387.4	2400								
	AFL	1114									
					PROC. REF: NDT PART 2/57-10-03					PKG:22	

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 57 - WINGS											
N5710014 ^S			PERFORM * WING BOX REAR SPAR FLAP TRACK CUTOUTS - EDDY CURRENT INSPECTION. INSPECT FLAP TRACK CUTOUTS AT WS 65, WS 126, AND WS 184 ON REAR SPAR. (PRE SB 45-11-5)							Service	ATA:57
	MOS	20-Jan-11						AIRWORTHINESS			
	HRS	0		T:9600							
	AFL	0									
					PROC. REF: NDT PART 6/57-20-01					PKG:25	
N5710016 ^S			PERFORM * WING BOX BASIC SKIN/STRINGER, LOWER SKIN - VISUAL INSPECTION. INSPECT OUTBOARD WING FORWARD AND AFT LOWER SKIN PANELS AND STRINGERS. (PRE SB 45-11-5)							Service	ATA:57
	MOS	20-Jan-11						AIRWORTHINESS			
	HRS	0		T:9600							
	AFL	0									
					PROC. REF: GENERIC NO REF					PKG:25	
N5710017 ^S			PERFORM * WING BOX BASIC SKIN/STRINGER AT STRINGER RUN-OUT, LOWER SKIN - VISUAL INSPECTION. INSPECT STRINGER RUN-OUTS IN FORWARD AND AFT LOWER SKIN PANELS. (PRE SB 45-11-5)							Service	ATA:57
	MOS	20-Jan-11						AIRWORTHINESS			
	HRS	0		9600							
	AFL	0									
					PROC. REF: GENERIC NO REF					PKG:26	
N5710021 ^S			PERFORM * CENTER SECTION MID SPAR LOWER CAP - EDDY CURRENT INSPECTION. INSPECT MID SPAR FROM CENTERLINE SPLICE PLATE TO SKIN TERMINATION AT MS 33 (PRE SB 45-11-5)							Service	ATA:57
	MOS	11-Sep-18	96					AIRWORTHINESS			
	HRS	1387.4	2400								
	AFL	1114									
					PROC. REF: NDT PART 6/57-10-02					PKG:22	
N5710022 ^S			PERFORM * CENTER SECTION MID SPAR CENTERLINE JOINT - EDDY CURRENT INSPECTION. INSPECT CENTER MID SPAR (CENTERLINE TO WS 17), LOWER SPLICE PLATE, AND CENTER MID SPAR JOINT FITTING LOWER CAP. (PRE SB 45-11-5)							Service	ATA:57
	MOS	11-Sep-18	96					AIRWORTHINESS			
	HRS	1387.4	2400								
	AFL	1114									
					PROC. REF: NDT PART 6/57-10-08, NDT PART 6/57-10-10					PKG:22	
N5710023 ^S			PERFORM * CENTER SECTION FRONT SPAR LOWER CAP - EDDY CURRENT INSPECTION. INSPECT CENTER WING FRONT SPAR LOWER CAP BETWEEN SKIN TERMINATIONS(W/31 LEFT TO W/31 RIGHT). (PRE SB 45-11-5)							Service	ATA:57
	MOS	11-Sep-18	96					AIRWORTHINESS			
	HRS	1387.4	2400								
	AFL	1114									
					PROC. REF: NDT PART 6/57-10-03					PKG:22	

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 57 - WINGS											
N5710028 ^S			PERFORM * WING BOX MID SPAR LOWER CAP, SKIN TERMINATION AT WS 33 - BOLT HOLE EDDY CURRENT INSPECTION. INSPECT MID SPAR LOWER CAP UNDERNEATH ROOT RIB (WS 33) AT POINT OF SKIN TERMINATION. (PRE SB 45-11-5)							Service	ATA:57
	MOS	20-Jan-11						AIRWORTHINESS			
	HRS	0		T:9600							
	AFL	0									
					PROC. REF: NDT PART 6/57-10-11					PKG:25	
N5710031 ^S			PERFORM * WING BOX SKIN ACCESS COVER HOLES - EDDY CURRENT INSPECTION. INSPECT ACCESS HOLES IN FORWARD AND AFT LOWER SKIN PANELS. (PRE SB 45-11-5)							Service	ATA:57
	MOS	20-Jan-11						AIRWORTHINESS			
	HRS	0		T:9600							
	AFL	0									
					PROC. REF: NDT PART 6/57-30-01					PKG:25	
N5710037 ^S			PERFORM * WING BOX FRONT SPAR LOWER CAP - VISUAL INSPECTION. INSPECT FRONT SPAR LOWER CAP AND LOWER FORWARD SKIN OUTBOARD OF MID-SPAR STATION(MS) 55. (PRE SB 45-11-5)							Service	ATA:57
	MOS	11-Sep-18	96					AIRWORTHINESS			
	HRS	1387.4	2400								
	AFL	1114									
					PROC. REF: GENERIC NO REF					PKG:22	
N5710084 ^S			PERFORM SPOILER, CENTER HINGE SPOILER SIDE - NDI INSPECTION.							Service	ATA:57
	MOS	11-Sep-18	96 (+ 14d/-14d)								
	HRS	1387.4	2400 (+ 25/-25)								
	AFL	1114									
					PROC. REF: NDT PART 6/57-40-01					PKG:22	
N5710121 ^S			PERFORM * WING BOX MID SPAR, OUTBOARD OF RIB # 8 - VISUAL INSPECTION AT WS 156 AND OUTBOARD TO WS 260. (PRE SB 45-11-5)							Service	ATA:57
	MOS	20-Jan-11						AIRWORTHINESS			
	HRS	0		T:9600							
	AFL	0									
					PROC. REF: GENERIC NO REF					PKG:25	
N5710122 ^S			PERFORM * WING BOX REAR SPAR, OUTBOARD OF RIB # 6 - VISUAL INSPECTION AT WS 118 AND OUTBOARD TO WS 260. (PRE SB 45-11-5)							Service	ATA:57
	MOS	20-Jan-11						AIRWORTHINESS			
	HRS	0		T:9600							
	AFL	0									
					PROC. REF: GENERIC NO REF					PKG:25	

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 57 - WINGS											
N5710137 ^S			PERFORM * MID SPAR AT RIB # 2 NEAR WS 48 - BOLT HOLE EDDY CURRENT INSPECTION. (PRE SB 45-11-5)								Service ATA:57
	MOS	20-Jan-11						AIRWORTHINESS			
	HRS	0		T:9600							
	AFL	0									
										PROC. REF: NDT PART 6/57-10-11	
										PKG:25	
N5710138 ^S			PERFORM * MID SPAR AT RIB # 3 NEAR WS 60 - BOLT HOLE EDDY CURRENT INSPECTION. (PRE SB 45-11-5)								Service ATA:57
	MOS	20-Jan-11						AIRWORTHINESS			
	HRS	0		T:9600							
	AFL	0									
										PROC. REF: NDT PART 6/57-10-11	
										PKG:25	
N5710139 ^S			PERFORM * FORWARD FLANGE FASTENERS AT REAR SPAR BETWEEN WS 52 AND WS 60 - BOLT HOLE EDDY CURRENT INSPECTION. (PRE SB 45-11-5)								Service ATA:57
	MOS	11-Sep-18	96					AIRWORTHINESS			
	HRS	1387.4	2400								
	AFL	1114									
										PROC. REF: NDT PART 6/57-20-03	
										PKG:22	
N5710157 ^S			PERFORM * WING BOX BASIC SKIN/STRINGER AT STRINGER RUN-OUT, LOWER SKIN - VISUAL INSPECTION. INSPECT STRINGER RUN-OUTS IN FORWARD AND AFT LOWER SKIN PANELS. (POST SB 45-11-5)								Service ATA:57
	MOS	20-Jan-11						AIRWORTHINESS			
	HRS	0		T:9600							
	AFL	0									
										PROC. REF: GENERIC NO REF	
										PKG:25	
N5710161 ^S			PERFORM * WING BOX SKIN ACCESS COVER HOLES - EDDY CURRENT INSPECTION. INSPECT ACCESS HOLES IN FORWARD AND AFT LOWER SKIN PANELS. (POST SB 45-11-5)								Service ATA:57
	MOS	11-Sep-18	96					AIRWORTHINESS			
	HRS	1387.4	2400								
	AFL	1114									
										PROC. REF: NDT PART 6/57-30-01	
										PKG:22	
N5710176 ^S			PERFORM * WING MID-SPAR (CENTER SECTION) LOWER CAP AND CENTER-JOINT FITTING - ULTRASONIC INSPECTION. (PRE SB 45-11-5)								Service ATA:57
	MOS	11-Sep-18	96					AIRWORTHINESS			
	HRS	1387.4	2400								
	AFL	1114									
										PROC. REF: NDT PART 4/57-30-05	
										PKG:22	

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 57 - WINGS											
N5750005 ^S			PERFORM * FLAP MAIN TRACK HINGE FITTINGS, TRACK, AND FLAP BOX SIDES - VISUAL INSPECTION. INSPECT MAIN TRACK HINGE FITTINGS ON TRACK AND FLAP BOX SIDES.							Service	ATA:57
	MOS	11-Sep-18	96					AIRWORTHINESS			
	HRS	1387.4	2400								
	AFL	1114									
					PROC. REF: GENERIC NO REF					PKG:22	
P5710001 ^S			PERFORM * WING DRAG LINK ATTACH FITTING - MAGNETIC PARTICLE INSPECTION							Service	ATA:57
	MOS	11-Sep-18	96					AIRWORTHINESS			
	HRS	1387.4	2400								
	AFL	1114									
					PROC. REF: NDT PART 7/57-30-02					PKG:22	
P5710007 ^S			PERFORM * WING TO FUSELAGE ATTACH FITTINGS AND LINKS - EDDY CURRENT INSPECTION							Service	ATA:57
	MOS	20-Jan-11						AIRWORTHINESS			
	HRS	0	T:9600								
	AFL	0									
					PROC. REF: NDT PART 6/57-10-12					PKG:25	
P5710015 ^S			PERFORM * WING REAR SPAR AT AILERON HINGE - EDDY CURRENT INSPECTION.							Service	ATA:57
	MOS	20-Jan-11						AIRWORTHINESS			
	HRS	0	T:9600								
	AFL	0									
					PROC. REF: NDT PART 6/57-10-20					PKG:25	
P5710018 ^S			PERFORM * WING LOWER SKIN AT MID-SPAR SPAN-WISE JOINT - EDDY CURRENT INSPECTION.							Service	ATA:57
	MOS	20-Jan-11						AIRWORTHINESS			
	HRS	0	9600								
	AFL	0									
					PROC. REF: NDT PART 6/57-10-09					PKG:26	
P5710024 ^S			PERFORM * WING REAR-SPAR SIDE-STAY-FITTING SUPPORT STRUCTURE - EDDY CURRENT INSPECTION							Service	ATA:57
	MOS	20-Jan-11						AIRWORTHINESS			
	HRS	0	T:9600								
	AFL	0									
					PROC. REF: NDT PART 6/57-20-06					PKG:25	
P5710025 ^S			PERFORM * WING FRONT SPAR LOWER CAP FROM WS 33.0 TO WS 60.0 - RADIOGRAPHIC INSPECTION.							Service	ATA:57
	MOS	11-Sep-18	96					AIRWORTHINESS			
	HRS	1387.4	2400								
	AFL	1114									
					PROC. REF: NDT PART 2/57-10-01					PKG:22	

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 57 - WINGS											
P5710029 ^S			PERFORM * WING MID-SPAR VERTICAL WEB - EDDY CURRENT INSPECTION.							Service	ATA:57
	MOS	20-Jan-11						AIRWORTHINESS			
	HRS	0	9600								
	AFL	0									
					PROC. REF: NDT PART 6/57-10-07						PKG:26
P5710030 ^S			PERFORM * WING REAR SPAR VERTICAL WEB - EDDY CURRENT INSPECTION.							Service	ATA:57
	MOS	20-Jan-11						AIRWORTHINESS			
	HRS	0	9600								
	AFL	0									
					PROC. REF: NDT PART 6/57-20-05						PKG:26
P5710032 ^S			PERFORM * WING RIB UPPER-AFT-FLANGE FILLET RADIUS AT WS 33.0 - ULTRASONIC INSPECTION							Service	ATA:57
	MOS	20-Jan-11						AIRWORTHINESS			
	HRS	0	T:9600								
	AFL	0									
					PROC. REF: NDT PART 4/57-30-02						PKG:25
P5710033 ^S			PERFORM * WING ACCESS HOLE IN CLOSING RIB BETWEEN MID SPAR AND REAR SPAR - EDDY CURRENT INSPECTION.							Service	ATA:57
	MOS	20-Jan-11						AIRWORTHINESS			
	HRS	0	T:9600								
	AFL	0									
					PROC. REF: NDT PART 6/57-10-05						PKG:25
P5710034 ^S			PERFORM * WING BOX JOINT TO WINGLET - EDDY CURRENT INSPECTION.							Service	ATA:57
	MOS	20-Jan-11						AIRWORTHINESS			
	HRS	0	T:9600								
	AFL	0									
					PROC. REF: NDT PART 6/57-10-13						PKG:25
P5710035 ^S			PERFORM * WING LOWER SKIN AT DRAIN HOLE - EDDY CURRENT INSPECTION.							Service	ATA:57
	MOS	20-Jan-11						AIRWORTHINESS			
	HRS	0	T:9600								
	AFL	0									
					PROC. REF: NDT PART 6/57-30-02						PKG:25
P5710083 ^S			PERFORM * FLAP BOX BASIC STRUCTURE - EDDY CURRENT INSPECTION.							Service	ATA:57
	MOS	20-Jan-11						AIRWORTHINESS			
	HRS	0	T:9600								
	AFL	0									
					PROC. REF: NDT PART 6/57-40-02						PKG:25

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 57 - WINGS											
P5710085 ^S			PERFORM SPOILER UPPER SKIN - EDDY CURRENT INSPECTION.								Service ATA:57
	MOS	20-Jan-11									
	HRS	0		T:9600 (+ 25/-25)							
	AFL	0									
					PROC. REF: NDT PART 6/57-10-16					PKG:25	
P5710086 ^S			PERFORM SPOILER BOLTS AND HINGE PINS - MAGNETIC PARTICLE INSPECTION.								Service ATA:57
	MOS	20-Jan-11									
	HRS	0		T:9600 (+ 25/-25)							
	AFL	0									
					PROC. REF: NDT PART 7/27-10-01					PKG:25	
P5710181 ^S			PERFORM * WING DRAG LINK TUBE - MAGNETIC PARTICLE INSPECTION.								Service ATA:57
	MOS	11-Sep-18	96					AIRWORTHINESS			
	HRS	1387.4	2400								
	AFL	1114									
					PROC. REF: NDT PART 7/57-30-01					PKG:22	
P5710182 ^S			PERFORM * WING DRAG LINK ATTACH BOLTS - LIQUID PENETRANT INSPECTION								Service ATA:57
	MOS	11-Sep-18	96					AIRWORTHINESS			
	HRS	1387.4	2400								
	AFL	1114									
					PROC. REF: NDT PART 8/57-10-01					PKG:22	
P5710183 ^S			PERFORM * WING DRAG-LINK CLEVIS - MAGNETIC PARTICLE INSPECTION.								Service ATA:57
	MOS	11-Sep-18	96					AIRWORTHINESS			
	HRS	1387.4	2400								
	AFL	1114									
					PROC. REF: NDT PART 7/57-10-01					PKG:22	
P5710184 ^S			PERFORM * WING ATTACH BOLTS - FLUORESCENT PENETRANT INSPECTION.								Service ATA:57
	MOS	20-Jan-11						AIRWORTHINESS			
	HRS	0		T:9600							
	AFL	0									
					PROC. REF: NDT PART 8/57-10-02					PKG:25	
P5710185 ^S			PERFORM * WING ATTACH LINKS - MAGNETIC PARTICLE INSPECTION.								Service ATA:57
	MOS	20-Jan-11						AIRWORTHINESS			
	HRS	0		T:9600							
	AFL	0									
					PROC. REF: NDT PART 7/57-10-03					PKG:25	

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 57 - WINGS											
P5710186 ^S			PERFORM * WING ATTACH FITTINGS AT MID SPAR AND REAR SPAR - MAGNETIC PARTICLE INSPECTION							Service	ATA:57
	MOS	20-Jan-11						AIRWORTHINESS			
	HRS	0		T:9600							
	AFL	0									
					PROC. REF: NDT PART 7/57-10-02					PKG:25	
P5750002 ^S			PERFORM * FLAP FRONT-SPAR CUTOUTS - EDDY CURRENT INSPECTION.							Service	ATA:57
	MOS	11-Sep-18	96					AIRWORTHINESS			
	HRS	1387.4	2400								
	AFL	1114									
					PROC. REF: NDT PART 6/57-10-15					PKG:22	
P5750003 ^S			PERFORM * FLAP NOSE-ROLLER RIBS - EDDY CURRENT INSPECTION.							Service	ATA:57
	MOS	20-Jan-11						AIRWORTHINESS			
	HRS	0		T:9600							
	AFL	0									
					PROC. REF: NDT PART 6/57-10-14					PKG:25	
P5750004 ^S			PERFORM * FLAP ACTUATOR SUPPORT RIBS - EDDY CURRENT INSPECTION.							Service	ATA:57
	MOS	20-Jan-11						AIRWORTHINESS			
	HRS	0	9600								
	AFL	0									
					PROC. REF: NDT PART 6/57-10-21					PKG:26	
P5750048 ^S			PERFORM * FLAP TRACKS - MAGNETIC PARTICLE INSPECTION.							Service	ATA:57
	MOS	20-Jan-11						AIRWORTHINESS			
	HRS	0	9600								
	AFL	0									
					PROC. REF: NDT PART 7/57-71-01					PKG:26	
P5750049 ^S			PERFORM * FLAP NOSE ROLLER TRACKS - MAGNETIC PARTICLE INSPECTION WITH FLAPS REMOVED.							Service	ATA:57
	MOS	20-Jan-11						AIRWORTHINESS			
	HRS	0	9600								
	AFL	0									
					PROC. REF: NDT PART 7/57-10-04					PKG:26	
P5750053 ^S			PERFORM * FLAP TRACK SUPPORT RIBS - EDDY CURRENT INSPECTION.							Service	ATA:57
	MOS	20-Jan-11						AIRWORTHINESS			
	HRS	0	9600								
	AFL	0									
					PROC. REF: NDT PART 6/57-10-17					PKG:26	

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 57 - WINGS											
P5750068 ^S			PERFORM * FLAP FRONT-SPAR RIB SUPPORT STRUCTURE - EDDY CURRENT INSPECTION							Service	ATA:57
	MOS	20-Jan-11						AIRWORTHINESS			
	HRS	0		T:9600							
	AFL	0									
										PKG:25	
PROC. REF: NDT PART 6/57-10-26											
P5760000 ^S			PERFORM * AILERON ACTUATOR HINGE FITTING - EDDY CURRENT INSPECTION.							Service	ATA:57
	MOS	20-Jan-11						AIRWORTHINESS			
	HRS	0		9600							
	AFL	0									
										PKG:26	
PROC. REF: NDT PART 6/57-10-25											
P5760001 ^S			PERFORM * AILERON SKIN - EDDY CURRENT INSPECTION							Service	ATA:57
	MOS	20-Jan-11						AIRWORTHINESS			
	HRS	0		9600							
	AFL	0									
										PKG:26	
PROC. REF: NDT PART 6/57-10-19											
P5760002 ^S			PERFORM * AILERON BALANCE TAB HINGE FITTINGS - EDDY CURRENT INSPECTION							Service	ATA:57
	MOS	11-Sep-18	96					AIRWORTHINESS			
	HRS	1387.4	2400								
	AFL	1114									
										PKG:22	
PROC. REF: NDT PART 6/57-60-01											
P5760003 ^S			PERFORM * AILERON TRIM AND BALANCE TAB FRONT SPARS - RADIOGRAPHIC INSPECTION							Service	ATA:57
	MOS	20-Jan-11						AIRWORTHINESS			
	HRS	0		T:9600							
	AFL	0									
										PKG:25	
PROC. REF: NDT PART 2/57-60-01											
P5760005 ^S			PERFORM * AILERON HINGE LUGS AND FITTINGS - EDDY CURRENT INSPECTION							Service	ATA:57
	MOS	20-Jan-11						AIRWORTHINESS			
	HRS	0		9600							
	AFL	0									
										PKG:26	
PROC. REF: NDT PART 6/57-10-24											
P5760014 ^S			PERFORM * AILERON HINGE SUPPORT STRUCTURE - EDDY CURRENT INSPECTION							Service	ATA:57
	MOS	20-Jan-11						AIRWORTHINESS			
	HRS	0		9600							
	AFL	0									
										PKG:26	
PROC. REF: NDT PART 6/57-10-23											

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 57 - WINGS											
P5770000 ^S			PERFORM SPOILER HINGE ASSEMBLIES AND ACTUATOR FITTING - EDDY CURRENT INSPECTION.						Service	ATA:57	
	MOS	20-Jan-11									
	HRS	0		T:9600 (+25/-25)							
	AFL	0									
					PROC. REF: NDT PART 6/57-10-22					PKG:25	
Q5710156 ^S			PERFORM * WING BOX BASIC SKIN/STRINGER, LOWER SKIN - VISUAL INSPECTION. INSPECT OUTBOARD WING FORWARD AND AFT LOWER SKIN PANELS AND STRINGERS. (POST SB 45-11-5)						Service	ATA:57	
	MOS	11-Sep-18		96 (+14d/-14d)				AIRWORTHINESS			
	HRS	1387.4		2400 (+25/-25)							
	AFL	1114									
					PROC. REF: GENERIC NO REF					PKG:22	
Q5710162 ^S			PERFORM * WING BOX FRONT SPAR LOWER CAP - VISUAL INSPECTION. INSPECT FRONT SPAR LOWER CAP AND LOWER FORWARD SKIN OUTBOARD OF MID-SPAR STATION (MS) 55. (POST SB 45-11-5)						Service	ATA:57	
	MOS	11-Sep-18		96 (+14d/-14d)				AIRWORTHINESS			
	HRS	1387.4		2400 (+25/-25)							
	AFL	1114									
					PROC. REF: AMM 05-10-00					PKG:22	
Q5710166 ^S			PERFORM * WING BOX MID SPAR, OUTBOARD OF RIB # 8 - VISUAL INSPECTION AT WS 156 AND OUTBOARD TO WS 260. (POST SB 45-11-5)						Service	ATA:57	
	MOS	11-Sep-18		96 (+14d/-14d)				AIRWORTHINESS			
	HRS	1387.4		2400 (+25/-25)							
	AFL	1114									
					PROC. REF: AMM 05-10-00					PKG:22	
Q5710167 ^S			PERFORM * WING BOX REAR SPAR, OUTBOARD OF RIB # 6 - VISUAL INSPECTION AT WS 118 AND OUTBOARD TO WS 260. (POST SB 45-11-5)						Service	ATA:57	
	MOS	11-Sep-18		96 (+14d/-14d)				AIRWORTHINESS			
	HRS	1387.4		2400 (+25/-25)							
	AFL	1114									
					PROC. REF: AMM 05-10-00					PKG:22	
U5710147 ^S			* WING BOX MID SPAR LOWER CAP, OUTBOARD OF JOINT AT WS 137 BETWEEN RIB # 7 AND # 8 - PERFORM DETAILED VISUAL INSPECTION. INSPECT MID SPAR LOWER CAP AND LOWER SKIN PANELS. (POST SB 45-11-5)						Service	ATA:57	
	MOS	20-Jan-23		24				AIRWORTHINESS			
	HRS	1675		600							
	AFL	1330									
					PROC. REF: GENERIC NO REF					PKG:10	

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 57 - WINGS											
U5710154 ^S			* WING BOX REAR SPAR LOWER CAP, OUTBOARD OF JOINT AT WS 81 TO RIB # 6 - PERFORM DETAILED VISUAL INSPECTION. INSPECT OUTER REAR SPAR LOWER CAP AND AFT LOWER SKIN PANEL OUTBOARD OF REAR SPLICE AT WS 90. (POST SB 45-11-5)						Service	ATA:57	
	MOS	20-Jan-23	24					AIRWORTHINESS			
	HRS	1675	600								
	AFL	1330									
					PROC. REF: GENERIC NO REF					PKG:10	
V5710039 ^S			PERFORM WINGLET SKIN - EDDY CURRENT INSPECTION						Service	ATA:57	
	MOS	20-Jan-11						AIRWORTHINESS			
	HRS	0	T:9600								
	AFL	0									
					PROC. REF: NDT PART 6/57-10-18					PKG:25	
Y5700001 ^S			WINGLET - PERFORM VISUAL INSPECTION						Service	ATA:57	
	MOS	20-Jan-23	12 (+ 14d/-14d)								
	HRS	1675	300 (+ 25/-25)								
	AFL	1330									
					PROC. REF: AMM 05-10-00					PKG:4	
Y5700002 ^S			FLUX VALVE BRACKET - VISUALLY INSPECT FOR CRACKS. (EFFECTIVE ON AIRCRAFT 45-006 THRU 45-131 PRE SB 45-57-4)						Service	ATA:57	
	MOS	20-Jan-23	12 (+ 14d/-14d)								
	HRS	1675	300 (+ 25/-25)								
	AFL	1330									
					PROC. REF: GENERIC NO REF					PKG:4	
Y5710000 ^S			PERFORM WING - EXTERNAL VISUAL INSPECTION FROM BL 0.00 TO WS 260						Service	ATA:57	
	MOS	20-Jan-23	48 (+ 14d/-14d)								
	HRS	1675	1200 (+ 25/-25)								
	AFL	1330									
					PROC. REF: AMM 05-10-00					PKG:16	
Y5710180 ^S			EXTERNAL LOWER WING SKIN - PERFORM VISUAL INSPECTION.						Service	ATA:57	
	MOS	20-Jan-23	24 (+ 14d/-14d)								
	HRS	1675	600 (+ 25/-25)								
	AFL	1330									
					PROC. REF: AMM 05-10-00					PKG:10	
Y5730013 ^S			AILERON BRUSH SEALS - PERFORM DETAILED INSPECTION.						Service	ATA:57	
	MOS	08-Nov-21	12 (+ 14d/-14d)								
	HRS	1605.6	300 (+ 25/-25)								
	AFL	1281									
					PROC. REF: AMM 57-60-01					PKG:4	

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 57 - WINGS											
Y5750067 ^S			PERFORM FLAP BRACKETS (P/N A159019-1 AND A159022-1) - DETAILED VISUAL INSPECTION.						Service	ATA:57	
	MOS	11-Sep-18	96 (+ 14d/-14d)								
	HRS	1387.4	2400 (+ 25/-25)								
	AFL	1114									
			PROC. REF: AMM 05-10-00								PKG:22
Y5750069 ^S			FLAPS - PERFORM VISUAL INSPECTION OF FLAP NOSE ROLLERS, FLAP TRACKS, FLAP NOSE ROLLER TRACKS, AND FLAP MAIN TRACK ROLLERS.						Service	ATA:57	
	MOS	20-Jan-23	12 (+ 14d/-14d)								
	HRS	1675	300 (+ 25/-25)								
	AFL	1330									
			PROC. REF: AMM 05-10-00								PKG:4
Y5750071 ^S			PERFORM FLAPS - WITH FLAPS REMOVED, DETAILED VISUAL INSPECTION OF FLAP NOSE ROLLERS, FLAP TRACKS, FLAP NOSE ROLLER TRACKS, AND FLAP MAIN TRACK ROLLERS.						Service	ATA:57	
	MOS	20-Jan-23	48 (+ 14d/-14d)								
	HRS	1675	1200 (+ 25/-25)								
	AFL	1330									
			PROC. REF: AMM 05-10-00								PKG:16
ATA 71 - POWER PLANT											
5-19-00-Q7110004-LEFT			TAP TEST NO. 1 ENGINE NACELLE INLET (ZONE/ACCESS 430/440 IRN Q7110004). (REFER TO 71-10-01.)						Service	ATA:71	
	MOS	16-Dec-16									
	HRS	1162	2500 (+ 100/-100)		3662	3762	1987 (+ 100)				
	AFL	966									
			PROC. REF: AMM 71-10-01								
5-19-00-Q7110004-RIGHT			TAP TEST NO. 2 ENGINE NACELLE INLET (ZONE/ACCESS 430/440 IRN Q7110004). (REFER TO 71-10-01.)						Service	ATA:71	
	MOS	16-Dec-16									
	HRS	1162	2500 (+ 100/-100)		3662	3762	1987 (+ 100)				
	AFL	966									
			PROC. REF: AMM 71-10-01								
5-19-00-R7100032			L/H ENGINE NACELLE TUBES - PERFORM DETAILED VISUAL INSPECTION.						Service	ATA:71	
	MOS/MS	20-Jan-11	N/A					NOT APPLICABLE			
	HRS	0									
	AFL	0									
			PROC. REF: AMM 71-10-03								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 71 - POWER PLANT											
5-19-01-V7120074L		LEFT ENGINE * REPLACE AFT ENGINE MOUNT BOLT (P/N 4571408525-001)(REFER TO 71-00-01.)								Component	ATA:71
PN:PN	MOS/MSC	20-Jan-11	E/C	TSN 0				AIRWORTHINESS			
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 71-20-00											
5-19-01-V7120074R		RIGHT ENGINE * REPLACE AFT ENGINE MOUNT BOLT (P/N 4571408525-001)(REFER TO 71-00-01.)								Component	ATA:71
PN:PN	MOS/MSC	20-Jan-11	E/C	TSN 0				AIRWORTHINESS			
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 71-20-00											
710001 ^U		NO. 1 ASSEMBLY ENGINE								Component	ATA:71
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
710002 ^U		NO. 2 ASSEMBLY ENGINE								Component	ATA:71
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
710100		NO. 1 ENGINE - MAIN ENGINE WIRING HARNESS ASSEMBLY								Component	ATA:71
PN:PN	MOS/MSC	01-Apr-10	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	ENC	0		TSN 0							
PROC. REF: LMM 72-00-02, LMM 72-00-02											
710100		NO. 2 ENGINE - MAIN ENGINE WIRING HARNESS ASSEMBLY								Component	ATA:71
PN:PN	MOS/MSC	02-Apr-10	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	ENC	0		TSN 0							
PROC. REF: LMM 72-00-02, LMM 72-00-02											
710130 ^S		NO. 1 ENGINE - INSPECT TAILPIPE/LPT3 ROTOR ASSEMBLY-VISUALLY INSPECT FOR FOREIGN OBJECT DAMAGE, THERMAL DISTRESS, AND LEAKS.								Service	ATA:71
	MOS	10-Oct-19									
	HRS	1509.8	850 (-350)								
	ENC	1206									
PROC. REF: LMM 72-00-00											

PKG:0

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 71 - POWER PLANT											
710130 ^S			NO. 2 ENGINE - INSPECT TAILPIPE/LPT3 ROTOR ASSEMBLY-VISUALLY INSPECT FOR FOREIGN OBJECT DAMAGE, THERMAL DISTRESS, AND LEAKS.						Service	ATA:71	
	MOS		10-Oct-19								
	HRS		1509.8		850 (-350)						
	ENC		1204								
										PROC. REF: LMM 72-00-00	
										PKG:0	
710140 ^S			NO. 1 ENGINE - INSPECT INLET/FAN AREA - INSPECT FOR FOREIGN OBJECT DAMAGE AND LEAKAGE (REFER TO PARAGRAPH 4.B)						Service	ATA:71	
	MOS		10-Oct-19								
	HRS		1509.8		850 (-350)						
	ENC		1206								
										PROC. REF: LMM 72-00-00, LMM 72-00-00	
										PKG:0	
710140 ^S			NO. 2 ENGINE - INSPECT INLET/FAN AREA - INSPECT FOR FOREIGN OBJECT DAMAGE AND LEAKAGE (REFER TO PARAGRAPH 4.B)						Service	ATA:71	
	MOS		10-Oct-19								
	HRS		1509.8		850 (-350)						
	ENC		1204								
										PROC. REF: LMM 72-00-00, LMM 72-00-00	
										PKG:0	
711001			NO. 1 ENGINE FORWARD MOUNT						Component	ATA:71	
PN:PN	MOS/MSC		20-Jan-11	O/C		TSN 0					
SN:UNKNOWN	HRS		0			TSN 0					
	AFL		0			TSN 0					
										PROC. REF: AMM 71-20-00	
711002			NO. 2 ENGINE FORWARD MOUNT						Component	ATA:71	
PN:PN	MOS/MSC		20-Jan-11	O/C		TSN 0					
SN:UNKNOWN	HRS		0			TSN 0					
	AFL		0			TSN 0					
										PROC. REF: AMM 71-20-00	
7120002 ^S			NO. 1 ENGINE AFT ISOLATOR - PERFORM INSPECTION OF ISOLATOR AND ASSOCIATED PARTS						Service	ATA:71	
	MOS		20-Jan-11								
	HRS		0		5000 (+100/-100)						
	AFL		0								
										PROC. REF: AMM 71-20-00	
7120002			NO. 1 ENGINE ALL ISOLATORS - PERFORM INSPECTION OF ISOLATORS AND ASSOCIATED PARTS						Service	ATA:71	
	MOS/MSC		20-Jan-11	N/A							
	HRS		0								
	AFL		0								
										PROC. REF: AMM 71-20-00	

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty		
ATA 71 - POWER PLANT												
7120002 ^S			NO. 1 ENGINE FORWARD LOWER ISOLATOR - PERFORM INSPECTION OF ISOLATOR AND ASSOCIATED PARTS								Service	ATA:71
	MOS		20-Jan-11									
	HRS	0			5000 (+ 100/-100)							
	AFL	0										
PROC. REF: AMM 71-20-00												
7120002 ^S			NO. 1 ENGINE FORWARD UPPER ISOLATOR - PERFORM INSPECTION OF ISOLATOR AND ASSOCIATED PARTS								Service	ATA:71
	MOS		20-Jan-11									
	HRS	0			5000 (+ 100/-100)							
	AFL	0										
PROC. REF: AMM 71-20-00												
7120002 ^S			NO. 2 ENGINE AFT ISOLATOR - PERFORM INSPECTION OF ISOLATOR AND ASSOCIATED PARTS								Service	ATA:71
	MOS		20-Jan-11									
	HRS	0			5000 (+ 100/-100)							
	AFL	0										
PROC. REF: AMM 71-20-00												
7120002			NO. 2 ENGINE ALL ISOLATORS - PERFORM INSPECTION OF ISOLATORS AND ASSOCIATED PARTS								Service	ATA:71
	MOS/MSC		20-Jan-11	N/A								
	HRS	0										
	AFL	0										
PROC. REF: AMM 71-20-00												
7120002 ^S			NO. 2 ENGINE FORWARD LOWER ISOLATOR - PERFORM INSPECTION OF ISOLATOR AND ASSOCIATED PARTS								Service	ATA:71
	MOS		20-Jan-11									
	HRS	0			5000 (+ 100/-100)							
	AFL	0										
PROC. REF: AMM 71-20-00												
7120002 ^S			NO. 2 ENGINE FORWARD UPPER ISOLATOR - PERFORM INSPECTION OF ISOLATOR AND ASSOCIATED PARTS								Service	ATA:71
	MOS		20-Jan-11									
	HRS	0			5000 (+ 100/-100)							
	AFL	0										
PROC. REF: AMM 71-20-00												
7120004			REPLACE ALL FORWARD AND AFT ENGINE MOUNT ISOLATOR HOUSINGS								Component	ATA:71
	MOS		20-Jan-11						LIFE LIMIT			
	HRS	0			15000 (+ 25/-25)	15000	15025	13325 (+ 25)				
	AFL	0										
PROC. REF: AMM 71-20-00												

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 71 - POWER PLANT										
7120004 ^S REPLACE NO. 1 ENGINE AFT ENGINE MOUNT ISOLATOR HOUSING Component ATA:71										
PN:PN	MOS	20-Jan-11		TSN 0				LIFE LIMIT		
SN:UNKNOWN	HRS	0	15000	TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 71-20-00										
7120004 ^S REPLACE NO. 1 ENGINE FORWARD LOWER ENGINE MOUNT ISOLATOR HOUSING Component ATA:71										
PN:PN	MOS	20-Jan-11		TSN 0				LIFE LIMIT		
SN:UNKNOWN	HRS	0	15000	TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 71-20-00										
7120004 ^S REPLACE NO. 1 ENGINE FORWARD UPPER ENGINE MOUNT ISOLATOR HOUSING Component ATA:71										
PN:PN	MOS	20-Jan-11		TSN 0				LIFE LIMIT		
SN:UNKNOWN	HRS	0	15000	TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 71-20-00										
7120004 ^S REPLACE NO. 2 ENGINE AFT ENGINE MOUNT ISOLATOR HOUSING Component ATA:71										
PN:PN	MOS	20-Jan-11		TSN 0				LIFE LIMIT		
SN:UNKNOWN	HRS	0	15000	TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 71-20-00										
7120004 ^S REPLACE NO. 2 ENGINE FORWARD LOWER ENGINE MOUNT ISOLATOR HOUSING Component ATA:71										
PN:PN	MOS	20-Jan-11		TSN 0				LIFE LIMIT		
SN:UNKNOWN	HRS	0	15000	TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 71-20-00										
7120004 ^S REPLACE NO. 2 ENGINE FORWARD UPPER ENGINE MOUNT ISOLATOR HOUSING Component ATA:71										
PN:PN	MOS	20-Jan-11		TSN 0				LIFE LIMIT		
SN:UNKNOWN	HRS	0	15000	TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 71-20-00										
7120005 ^S REPLACE NO. 1 ENGINE AFT ENGINE MOUNT ISOLATOR METAL MESH ELEMENTS Component ATA:71										
PN:PN	MOS	20-Jan-11		TSN 0				LIFE LIMIT		
SN:UNKNOWN	HRS	0	5000 (+ 100/-100)	TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 71-20-00										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 71 - POWER PLANT										
7120005	REPLACE NO. 1 ENGINE ALL ENGINE MOUNT ISOLATOR BONDED MOUNTING ELEMENTS									Component ATA:71
	MOS/MSC	20-Jan-11	N/A							
	HRS	0								
	AFL	0								
PROC. REF: AMM 71-20-00										
7120005 ^S	REPLACE NO. 1 ENGINE FORWARD LOWER ENGINE MOUNT ISOLATOR BONDED MOUNTING ELEMENTS									Component ATA:71
PN:PN	MOS	20-Jan-11		TSN 0				LIFE LIMIT		
SN:UNKNOWN	HRS	0	5000 (+ 100/-100)	TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 71-20-00										
7120005 ^S	REPLACE NO. 1 ENGINE FORWARD UPPER ENGINE MOUNT ISOLATOR BONDED MOUNTING ELEMENTS									Component ATA:71
PN:PN	MOS	20-Jan-11		TSN 0				LIFE LIMIT		
SN:UNKNOWN	HRS	0	5000	TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 71-20-00										
7120005 ^S	REPLACE NO. 2 ENGINE AFT ENGINE MOUNT ISOLATOR METAL MESH ELEMENTS									Component ATA:71
PN:PN	MOS	20-Jan-11		TSN 0				LIFE LIMIT		
SN:UNKNOWN	HRS	0	5000 (+ 100/-100)	TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 71-20-00										
7120005	REPLACE NO. 2 ENGINE ALL ENGINE MOUNT ISOLATOR BONDED MOUNTING ELEMENTS									Component ATA:71
	MOS/MSC	20-Jan-11	N/A							
	HRS	0								
	AFL	0								
PROC. REF: AMM 71-20-00										
7120005 ^S	REPLACE NO. 2 ENGINE FORWARD LOWER ENGINE MOUNT ISOLATOR BONDED MOUNTING ELEMENTS									Component ATA:71
PN:PN	MOS	20-Jan-11		TSN 0				LIFE LIMIT		
SN:UNKNOWN	HRS	0	5000 (+ 100/-100)	TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 71-20-00										
7120005 ^S	REPLACE NO. 2 ENGINE FORWARD UPPER ENGINE MOUNT ISOLATOR BONDED MOUNTING ELEMENTS									Component ATA:71
PN:PN	MOS	20-Jan-11		TSN 0				LIFE LIMIT		
SN:UNKNOWN	HRS	0	5000	TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 71-20-00										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 71 - POWER PLANT										
7120006 REPLACE NO. 1 ENGINE AFT ENGINE MOUNT ISOLATOR METAL MESH ELEMENTS Component ATA:71										
PN:PN	MOS/MSC	20-Jan-11	N/A	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 71-20-00										
7120006 REPLACE NO. 1 ENGINE ALL ENGINE MOUNT ISOLATOR FORWARD BONDED MOUNTING AND AFT MOUNT METAL MESH ELEMENTS Component ATA:71										
PN:PN	MOS/MSC	20-Jan-11	N/A	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 71-20-00										
7120006 REPLACE NO. 1 ENGINE FORWARD LOWER ENGINE MOUNT ISOLATOR BONDED MOUNTING ELEMENTS Component ATA:71										
PN:PN	MOS/MSC	20-Jan-11	N/A	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 71-20-00										
7120006 REPLACE NO. 1 ENGINE FORWARD UPPER ENGINE MOUNT ISOLATOR BONDED MOUNTING ELEMENTS Component ATA:71										
PN:PN	MOS/MSC	20-Jan-11	N/A	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 71-20-00										
7120006 REPLACE NO. 2 ENGINE AFT ENGINE MOUNT ISOLATOR METAL MESH ELEMENTS Component ATA:71										
PN:PN	MOS/MSC	20-Jan-11	N/A	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 71-20-00										
7120006 REPLACE NO. 2 ENGINE ALL ENGINE MOUNT ISOLATOR FORWARD BONDED MOUNTING AND AFT MOUNT METAL MESH ELEMENTS Component ATA:71										
PN:PN	MOS/MSC	20-Jan-11	N/A	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 71-20-00										
7120006 REPLACE NO. 2 ENGINE FORWARD LOWER ENGINE MOUNT ISOLATOR BONDED MOUNTING ELEMENTS Component ATA:71										
PN:PN	MOS/MSC	20-Jan-11	N/A	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 71-20-00										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 71 - POWER PLANT										
7120006	REPLACE NO. 2 ENGINE FORWARD UPPER ENGINE MOUNT ISOLATOR BONDED MOUNTING ELEMENTS									Component ATA:71
PN:PN	MOS/MSC	20-Jan-11	N/A	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 71-20-00										
712005	NO. 1 ENGINE AFT MOUNT ISOLATOR ASSEMBLY									Component ATA:71
PN:LM-833-SA18	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:LK1899	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 71-20-00										
712006	NO. 2 ENGINE AFT MOUNT ISOLATOR ASSEMBLY									Component ATA:71
PN:LM-833-SA18	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:LK1895	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 71-20-00										
7120069 ^S	NO. 1 ENGINE AFT ISOLATOR - PERFORM VISUAL INSPECTION OF ISOLATOR AND ASSOCIATED PARTS									Service ATA:71
	MOS	20-Jan-11								
	HRS	0	2500 (+ 100/-100)							
	AFL	0								
PROC. REF: AMM 71-20-00										
7120069	NO. 1 ENGINE ALL ISOLATORS - PERFORM VISUAL INSPECTION OF ISOLATORS AND ASSOCIATED PARTS									Service ATA:71
	MOS	20-Jan-11								
	HRS	0	3000 (+ 100/-100)	3000	3100	1325 (+ 100)				
	AFL	0								
PROC. REF: AMM 71-20-00										
7120069 ^S	NO. 1 ENGINE FORWARD LOWER ISOLATOR - PERFORM VISUAL INSPECTION OF ISOLATOR AND ASSOCIATED PARTS									Service ATA:71
	MOS	20-Jan-11								
	HRS	0	2500 (+ 100/-100)							
	AFL	0								
PROC. REF: AMM 71-20-00										
7120069 ^S	NO. 1 ENGINE FORWARD UPPER ISOLATOR - PERFORM VISUAL INSPECTION OF ISOLATOR AND ASSOCIATED PARTS									Service ATA:71
	MOS	20-Jan-11								
	HRS	0	2500 (+ 100/-100)							
	AFL	0								
PROC. REF: AMM 71-20-00										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty		
ATA 71 - POWER PLANT												
7120069 ^S			NO. 2 ENGINE AFT ISOLATOR - PERFORM VISUAL INSPECTION OF ISOLATOR AND ASSOCIATED PARTS								Service	ATA:71
	MOS		20-Jan-11									
	HRS	0		2500 (+ 100/-100)								
	AFL	0										
PROC. REF: AMM 71-20-00												
7120069			NO. 2 ENGINE ALL ISOLATORS - PERFORM VISUAL INSPECTION OF ISOLATORS AND ASSOCIATED PARTS								Service	ATA:71
	MOS		20-Jan-11									
	HRS	0		3000 (+ 100/-100)	3000	3100	1325 (+ 100)					
	AFL	0										
PROC. REF: AMM 71-20-00												
7120069 ^S			NO. 2 ENGINE FORWARD LOWER ISOLATOR - PERFORM VISUAL INSPECTION OF ISOLATOR AND ASSOCIATED PARTS								Service	ATA:71
	MOS		20-Jan-11									
	HRS	0		2500 (+ 100/-100)								
	AFL	0										
PROC. REF: AMM 71-20-00												
7120069 ^S			NO. 2 ENGINE FORWARD UPPER ISOLATOR - PERFORM VISUAL INSPECTION OF ISOLATOR AND ASSOCIATED PARTS								Service	ATA:71
	MOS		20-Jan-11									
	HRS	0		2500 (+ 100/-100)								
	AFL	0										
PROC. REF: AMM 71-20-00												
712007			NO. 1 ENGINE FORWARD UPPER MOUNT ISOLATOR ASSEMBLY								Component	ATA:71
PN:LM-833-45	MOS/MS		20-Jan-11	O/C	TSN 0							
SN:LK6728	HRS	0			TSN 0							
	AFL	0			TSN 0							
PROC. REF: AMM 71-20-00												
7120070 ^S			REPLACE NO. 1 ENGINE AFT ENGINE MOUNT ISOLATOR METAL MESH ELEMENTS								Component	ATA:71
PN:PN	MOS		20-Jan-11		TSN 0			LIFE LIMIT				
SN:UNKNOWN	HRS	0		6000 (+ 100/-100)	TSN 0							
	AFL	0			TSN 0							
PROC. REF: AMM 71-20-00												
7120070			REPLACE NO. 1 ENGINE ALL ENGINE MOUNT ISOLATOR BONDED MOUNTING ELEMENTS								Component	ATA:71
	MOS		20-Jan-11					LIFE LIMIT				
	HRS	0		6000 (+ 100/-100)	6000	6100	4325 (+ 100)					
	AFL	0										
PROC. REF: AMM 71-20-00												

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 71 - POWER PLANT										
7120070 ^S REPLACE NO. 1 ENGINE FORWARD LOWER ENGINE MOUNT ISOLATOR BONDED MOUNTING ELEMENTS Component ATA:71										
PN:PN	MOS	20-Jan-11		TSN 0				LIFE LIMIT		
SN:UNKNOWN	HRS	0	6000 (+ 100/-100)	TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 71-20-00										
7120070 ^S REPLACE NO. 1 ENGINE FORWARD UPPER ENGINE MOUNT ISOLATOR BONDED MOUNTING ELEMENTS Component ATA:71										
PN:PN	MOS	20-Jan-11		TSN 0				LIFE LIMIT		
SN:UNKNOWN	HRS	0	6000 (+ 100/-100)	TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 71-20-00										
7120070 ^S REPLACE NO. 2 ENGINE AFT ENGINE MOUNT ISOLATOR METAL MESH ELEMENTS Component ATA:71										
PN:PN	MOS	20-Jan-11		TSN 0				LIFE LIMIT		
SN:UNKNOWN	HRS	0	6000 (+ 100/-100)	TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 71-20-00										
7120070 REPLACE NO. 2 ENGINE ALL ENGINE MOUNT ISOLATOR BONDED MOUNTING ELEMENTS Component ATA:71										
	MOS	20-Jan-11						LIFE LIMIT		
	HRS	0	6000 (+ 100/-100)		6000	6100	4325 (+ 100)			
	AFL	0								
PROC. REF: AMM 71-20-00										
7120070 ^S REPLACE NO. 2 ENGINE FORWARD LOWER ENGINE MOUNT ISOLATOR BONDED MOUNTING ELEMENTS Component ATA:71										
PN:PN	MOS	20-Jan-11		TSN 0				LIFE LIMIT		
SN:UNKNOWN	HRS	0	6000 (+ 100/-100)	TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 71-20-00										
7120070 ^S REPLACE NO. 2 ENGINE FORWARD UPPER ENGINE MOUNT ISOLATOR BONDED MOUNTING ELEMENTS Component ATA:71										
PN:PN	MOS	20-Jan-11		TSN 0				LIFE LIMIT		
SN:UNKNOWN	HRS	0	6000 (+ 100/-100)	TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 71-20-00										
7120073 ^S NO. 1 ENGINE AFT ISOLATOR - PERFORM INSPECTION OF ISOLATOR AND ASSOCIATED PARTS Service ATA:71										
	MOS	20-Jan-11								
	HRS	0	6000 (+ 100/-100)							
	AFL	0								
PROC. REF: AMM 71-20-00										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty		
ATA 71 - POWER PLANT												
7120073			NO. 1 ENGINE ALL ISOLATORS - PERFORM INSPECTION OF ISOLATORS AND ASSOCIATED PARTS								Service	ATA:71
	MOS		20-Jan-11									
	HRS	0		6000 (+ 100/-100)	6000	6100	4325 (+ 100)					
	AFL	0										
PROC. REF: AMM 71-20-00												
7120073 ^S			NO. 1 ENGINE FORWARD LOWER ISOLATOR - PERFORM INSPECTION OF ISOLATOR AND ASSOCIATED PARTS								Service	ATA:71
	MOS		20-Jan-11									
	HRS	0		6000 (+ 100/-100)								
	AFL	0										
PROC. REF: AMM 71-20-00												
7120073 ^S			NO. 1 ENGINE FORWARD UPPER ISOLATOR - PERFORM INSPECTION OF ISOLATOR AND ASSOCIATED PARTS								Service	ATA:71
	MOS		20-Jan-11									
	HRS	0		6000 (+ 100/-100)								
	AFL	0										
PROC. REF: AMM 71-20-00												
7120073 ^S			NO. 2 ENGINE AFT ISOLATOR - PERFORM INSPECTION OF ISOLATOR AND ASSOCIATED PARTS								Service	ATA:71
	MOS		20-Jan-11									
	HRS	0		6000 (+ 100/-100)								
	AFL	0										
PROC. REF: AMM 71-20-00												
7120073			NO. 2 ENGINE ALL ISOLATORS - PERFORM INSPECTION OF ISOLATORS AND ASSOCIATED PARTS								Service	ATA:71
	MOS		20-Jan-11									
	HRS	0		6000 (+ 100/-100)	6000	6100	4325 (+ 100)					
	AFL	0										
PROC. REF: AMM 71-20-00												
7120073 ^S			NO. 2 ENGINE FORWARD LOWER ISOLATOR - PERFORM INSPECTION OF ISOLATOR AND ASSOCIATED PARTS								Service	ATA:71
	MOS		20-Jan-11									
	HRS	0		6000 (+ 100/-100)								
	AFL	0										
PROC. REF: AMM 71-20-00												
7120073 ^S			NO. 2 ENGINE FORWARD UPPER ISOLATOR - PERFORM INSPECTION OF ISOLATOR AND ASSOCIATED PARTS								Service	ATA:71
	MOS		20-Jan-11									
	HRS	0		6000 (+ 100/-100)								
	AFL	0										
PROC. REF: AMM 71-20-00												

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 71 - POWER PLANT										
712008	NO. 2 ENGINE FORWARD UPPER MOUNT ISOLATOR ASSEMBLY									Component ATA:71
PN:LM-833-45	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:LK6727	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 71-20-00										
712009	NO. 1 ENGINE FORWARD LOWER MOUNT ISOLATOR ASSEMBLY									Component ATA:71
PN:LM-833-45	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:LK6726	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 71-20-00										
712010	NO. 2 ENGINE FORWARD LOWER MOUNT ISOLATOR ASSEMBLY									Component ATA:71
PN:LM-833-45	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:LK6725	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: NDT PART 7/32-10-03, NDT PART 7/32-10-04, NDT PART 7/32-10-08, NDT PART 8/32-10-02, NDT PART 8/54-30-01, NDT PART 8/54-30-02, AMM 71-20-00										
712045	NO. 1 ENGINE AFT MOUNT									Component ATA:71
PN:4571200011-003	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:CDF-1281	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 71-20-00										
712046	NO. 2 ENGINE AFT MOUNT									Component ATA:71
PN:4571200011-003	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:CDF-1369	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 71-20-00										
714010 ^S	NO. 1 ENGINE - CHECK ELECTRICAL WIRES AND CONNECTIONS - VISUALLY INSPECT FOR SECURITY AND DAMAGE									Service ATA:71
	MOS	10-Oct-19								
	HRS	1509.8	850 (-350)							
	ENC	1206								
PROC. REF: LMM 72-00-00										
										PKG:0

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 71 - POWER PLANT											
714010 ^S			NO. 2 ENGINE - CHECK ELECTRICAL WIRES AND CONNECTIONS - VISUALLY INSPECT FOR SECURITY AND DAMAGE						Service	ATA:71	
	MOS	10-Oct-19									
	HRS	1509.8	850 (-350)								
	ENC	1204									
					PROC. REF: LMM 72-00-00					PKG:0	
715010 ^S			NO. 1 ENGINE - CHECK PLUMBING LINES AND CONNECTIONS - VISUALLY INSPECT FOR SECURITY, LOOSE OR BROKEN CLAMPS OR BRACKETS, LEAKS, CRACKS, CUTS, OR RUBBING						Service	ATA:71	
	MOS	10-Oct-19									
	HRS	1509.8	850 (-350)								
	ENC	1206									
					PROC. REF: LMM 72-00-00					PKG:0	
715010 ^S			NO. 2 ENGINE - CHECK PLUMBING LINES AND CONNECTIONS - VISUALLY INSPECT FOR SECURITY, LOOSE OR BROKEN CLAMPS OR BRACKETS, LEAKS, CRACKS, CUTS, OR RUBBING						Service	ATA:71	
	MOS	10-Oct-19									
	HRS	1509.8	850 (-350)								
	ENC	1204									
					PROC. REF: LMM 72-00-00					PKG:0	
716005			NO. 1 ENGINE INLET NACELLE						Component	ATA:71	
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
					PROC. REF: AMM 71-10-01						
716006			NO. 2 ENGINE INLET NACELLE						Component	ATA:71	
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
					PROC. REF: AMM 71-10-01						
71EN1			NO. 1 ENGINE						Component	ATA:71	
PN:3060084-1	MOS/MSC		E/C								
SN:P-132199C	HRS										
WC# : 71.EN1	AFL										
					PROC. REF: AMM 71-00-01						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 71 - POWER PLANT										
71EN2			NO. 2 ENGINE						Component	ATA:71
PN:3060084-1	MOS/MS			E/C						
SN:P-132200C	HRS									
WC# : 71.EN2	AFL									
PROC. REF: AMM 71-00-01										
P7120001 ^S			PERFORM * FORWARD ENGINE MOUNT - EDDY CURRENT INSPECTION.						Service	ATA:71
	MOS	20-Jan-11						AIRWORTHINESS		
	HRS	0	T:9600							
	AFL	0								
PROC. REF: NDT PART 6/71-10-01										
PKG:25										
Y7100002 ^S			LOWER ENGINE COWLING - VISUALLY INSPECT LATCH CHANNELS FOR CHAFING.						Service	ATA:71
	MOS	20-Jan-23	24 (+ 14d/-14d)							
	HRS	1675	600 (+ 25/-25)							
	AFL	1330								
PROC. REF: AMM 05-10-00										
PKG:9										
Y7110000 ^S			ENGINE NACELLE - PERFORM VISUAL INSPECTION. INSPECT INLET BULKHEAD, STRUCTURE, PLUMBING, SKIN SPOT WELDS, ANTI-ICE OUTLET SCREEN, AND FASTENERS FOR SECURITY, CRACKS, AND GENERAL CONDITION.						Service	ATA:71
	MOS	20-Jan-23	24 (+ 14d/-14d)							
	HRS	1675	600 (+ 25/-25)							
	AFL	1330								
PROC. REF: AMM 05-10-00										
PKG:9										
Y7110001 ^S			ENGINE INLET LIP AND DUCT - PERFORM VISUAL INSPECTION.						Service	ATA:71
	MOS	20-Jan-23	24 (+ 14d/-14d)							
	HRS	1675	600 (+ 25/-25)							
	AFL	1330								
PROC. REF: AMM 05-10-00										
PKG:9										
Y7110002 ^S			ENGINE STARTER/GENERATOR INLET AND EXHAUST DUCT AND SEALS - PERFORM VISUAL INSPECTION.						Service	ATA:71
	MOS	20-Jan-23	24 (+ 14d/-14d)							
	HRS	1675	600 (+ 25/-25)							
	AFL	1330								
PROC. REF: AMM 05-10-00										
PKG:9										
Y7110003 ^S			ENGINE ALTERNATOR EXHAUST DUCT AND SEALS - PERFORM VISUAL INSPECTION.						Service	ATA:71
	MOS	20-Jan-23	24 (+ 14d/-14d)							
	HRS	1675	600 (+ 25/-25)							
	AFL	1330								
PROC. REF: AMM 05-10-00										
PKG:9										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 71 - POWER PLANT											
Y7120000 ^S			FORWARD ENGINE MOUNTS - PERFORM VISUAL INSPECTION.						Service	ATA:71	
	MOS	20-Jan-23	12 (+ 14d/-14d)								
	HRS	1675	300 (+ 25/-25)								
	AFL	1330									
PROC. REF: AMM 05-10-00										PKG:3	
ATA 72 - ENGINE											
72-AS-720005			NO. 1 ENGINE - INSPECT MAJOR PERIODIC PER MANUFACTURERS INSTRUCTIONS						Service	ATA:72	
	MOS	01-Apr-10									
	HRS	0	3000 (+ 100)		(3000)	3100	1325 (+ 100)				
					3000						
	ENC	0									
PROC. REF: LMM 72-00-00											
72-AS-720005			NO. 2 ENGINE - INSPECT MAJOR PERIODIC PER MANUFACTURERS INSTRUCTIONS						Service	ATA:72	
	MOS	02-Apr-10									
	HRS	0	3000 (+ 100)		(3000)	3100	1325 (+ 100)				
					3000						
	ENC	0									
PROC. REF: LMM 72-00-00											
72-AS-720006 ^S			NO. 1 ENGINE - INSPECT COMB CHAMBER PLENUM CASE INSP PER MANUFACTURERS INSTRUCTIONS						Service	ATA:72	
	MOS	01-Apr-10									
	HRS	0	3000 (+ 100/-100)								
	ENC	0									
PROC. REF: GENERIC NO REF											
72-AS-720006 ^S			NO. 2 ENGINE - INSPECT COMB CHAMBER PLENUM CASE INSP PER MANUFACTURERS INSTRUCTIONS						Service	ATA:72	
	MOS	02-Apr-10									
	HRS	0	3000 (+ 100/-100)								
	ENC	0									
PROC. REF: GENERIC NO REF											
72-AS-720007			NO. 1 ENGINE - INSPECT COMPRESSOR ZONE PER MANUFACTURERS INSTRUCTIONS						Service	ATA:72	
	MOS	01-Apr-10									
	HRS	0	6000 (+ 200)		(6000)	6200	4325 (+ 200)				
					6000						
	ENC	0									
PROC. REF: LMM 72-00-00											

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty		
ATA 72 - ENGINE												
72-AS-720007			NO. 2 ENGINE - INSPECT COMPRESSOR ZONE PER MANUFACTURERS INSTRUCTIONS								Service	ATA:72
	MOS		02-Apr-10									
	HRS	0		6000 (+ 200)	(6000)	6200	4325 (+ 200)					
	ENC	0			6000							
PROC. REF: LMM 72-00-00												
72-AS-720008 ^S			NO. 1 ENGINE - INSPECT AGB PER MANUFACTURERS INSTRUCTIONS								Service	ATA:72
	MOS		01-Apr-10									
	HRS	0		6000 (+ 200/-200)								
	ENC	0										
PROC. REF: GENERIC NO REF, LMM 72-60-02												
72-AS-720008 ^S			NO. 2 ENGINE - INSPECT AGB PER MANUFACTURERS INSTRUCTIONS								Service	ATA:72
	MOS		02-Apr-10									
	HRS	0		6000 (+ 200/-200)								
	ENC	0										
PROC. REF: GENERIC NO REF, LMM 72-60-02												
72-AS-720010			NO. 1 ENGINE - ANALYSIS OIL AND FILTER (BASELINE/SPECIAL REQUIREMENT) (SOAP)								Service	ATA:72
	MOS/MSC		20-Jan-11	A/R								
	HRS		8.1									
	ENC		5									
PROC. REF: LMM 72-00-00												
72-AS-720010			NO. 2 ENGINE - ANALYSIS OIL AND FILTER (BASELINE/SPECIAL REQUIREMENT) (SOAP)								Service	ATA:72
	MOS/MSC		20-Jan-11	A/R								
	HRS		8.1									
	ENC		5									
PROC. REF: LMM 72-00-00												
72-AS-720011			NO. 1 ENGINE - REPLACE FUEL FILTER ELEMENT (25-HR INITIAL)								Service	ATA:72
	MOS/MSC		20-Jan-11	A/R								
	HRS		8.1									
	ENC		5									
PROC. REF: LMM 73-21-02												
72-AS-720011			NO. 2 ENGINE - REPLACE FUEL FILTER ELEMENT (25-HR INITIAL)								Service	ATA:72
	MOS/MSC		20-Jan-11	A/R								
	HRS		8.1									
	ENC		5									
PROC. REF: LMM 73-21-02												

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 72 - ENGINE										
720110	NO. 1 ENGINE - ACCESSORY GEARBOX									Component ATA:72
PN:PN	MOS/MSC	01-Apr-10	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: LMM 72-60-02										
720110	NO. 2 ENGINE - ACCESSORY GEARBOX									Component ATA:72
PN:PN	MOS/MSC	02-Apr-10	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: LMM 72-60-02										
720244	NO. 1 ENGINE - NO. 6 CARBON SEAL ASSEMBLY									Component ATA:72
PN:PN	MOS/MSC	01-Apr-10	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
720244	NO. 2 ENGINE - NO. 6 CARBON SEAL ASSEMBLY									Component ATA:72
PN:PN	MOS/MSC	02-Apr-10	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
720245	NO. 1 ENGINE - NO. 6 BEARING ASSEMBLY									Component ATA:72
PN:PN	MOS/MSC	01-Apr-10	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
720245	NO. 2 ENGINE - NO. 6 BEARING ASSEMBLY									Component ATA:72
PN:PN	MOS/MSC	02-Apr-10	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
722001	NO. 1 ENGINE - FAN INLET HOUSING ASSEMBLY									Component ATA:72
PN:PN	MOS/MSC	01-Apr-10	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 72 - ENGINE										
722001	NO. 2 ENGINE - FAN INLET HOUSING ASSEMBLY									Component ATA:72
PN:PN	MOS/MSC	02-Apr-10	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
723002	NO. 1 ENGINE - NO. 3 CARBON SEAL ASSEMBLY									Component ATA:72
PN:PN	MOS/MSC	01-Apr-10	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: LMM 72-30-01										
723002	NO. 2 ENGINE - NO. 3 CARBON SEAL ASSEMBLY									Component ATA:72
PN:PN	MOS/MSC	02-Apr-10	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: LMM 72-30-01										
723010 ^S	NO. 1 ENGINE - CHECK CARBON SEAL HEALTH									Service ATA:72
	MOS	10-Oct-19								
	HRS	1509.8	1650 (-150)							
	ENC	1206								
PROC. REF: LMM 72-00-00										
723010 ^S	NO. 2 ENGINE - CHECK CARBON SEAL HEALTH									Service ATA:72
	MOS	10-Oct-19								
	HRS	1509.8	1650 (-150)							
	ENC	1204								
PROC. REF: LMM 72-00-00										
723011	NO. 1 ENGINE - NO. 4 CARBON SEAL RUNNER									Component ATA:72
PN:PN	MOS/MSC	01-Apr-10	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
723011	NO. 2 ENGINE - NO. 4 CARBON SEAL RUNNER									Component ATA:72
PN:PN	MOS/MSC	02-Apr-10	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 72 - ENGINE											
723012			NO. 1 ENGINE - NO. 4 CARBON SEAL ASSEMBLY						Component		ATA:72
PN:PN	MOS/MSC	01-Apr-10	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	ENC	0		TSN 0							
PROC. REF: GENERIC NO REF											
723012			NO. 2 ENGINE - NO. 4 CARBON SEAL ASSEMBLY						Component		ATA:72
PN:PN	MOS/MSC	02-Apr-10	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	ENC	0		TSN 0							
PROC. REF: GENERIC NO REF											
723013			NO. 1 ENGINE - NO. 5 CARBON SEAL RUNNER						Component		ATA:72
PN:PN	MOS/MSC	01-Apr-10	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	ENC	0		TSN 0							
PROC. REF: GENERIC NO REF											
723013			NO. 2 ENGINE - NO. 5 CARBON SEAL RUNNER						Component		ATA:72
PN:PN	MOS/MSC	02-Apr-10	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	ENC	0		TSN 0							
PROC. REF: GENERIC NO REF											
723014			NO. 1 ENGINE - NO. 5 CARBON SEAL ASSEMBLY						Component		ATA:72
PN:PN	MOS/MSC	01-Apr-10	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	ENC	0		TSN 0							
PROC. REF: GENERIC NO REF											
723014			NO. 2 ENGINE - NO. 5 CARBON SEAL ASSEMBLY						Component		ATA:72
PN:PN	MOS/MSC	02-Apr-10	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	ENC	0		TSN 0							
PROC. REF: GENERIC NO REF											
723081			NO. 1 ENGINE - ROTATING, AIR 2ND STAGE SEAL						Component		ATA:72
PN:PN	MOS/MSC	01-Apr-10	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	ENC	0		TSN 0							
PROC. REF: GENERIC NO REF											

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 72 - ENGINE										
723081	NO. 2 ENGINE - ROTATING, AIR 2ND STAGE SEAL									Component ATA:72
PN:PN	MOS/MSC	02-Apr-10	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
725007	NO. 1 ENGINE - HIGH PRESSURE TURBINE (HPT) NOZZLE ASSEMBLY									Component ATA:72
PN:PN	MOS/MSC	01-Apr-10	A/R	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
WC# : 72.500	ENC	0		TSN 0						
PROC. REF: LMM 72-50-07										
725007	NO. 2 ENGINE - HIGH PRESSURE TURBINE (HPT) NOZZLE ASSEMBLY									Component ATA:72
PN:PN	MOS/MSC	02-Apr-10	A/R	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
WC# : 72.500	ENC	0		TSN 0						
PROC. REF: LMM 72-50-07										
725010	NO. 1 ENGINE - 1ST-STAGE LOW PRESSURE TURBINE (LPT) DISC									Component ATA:72
PN:PN	MOS	01-Apr-10		TSN 0				LIFE LIMIT		
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0	12000	TSN 0	(12000) 11995		10665			
PROC. REF: LMM 72-50-04										
725010	NO. 2 ENGINE - 1ST-STAGE LOW PRESSURE TURBINE (LPT) DISC									Component ATA:72
PN:PN	MOS	02-Apr-10		TSN 0				LIFE LIMIT		
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0	12000	TSN 0	(12000) 11997		10667			
PROC. REF: LMM 72-50-04										
725017	NO. 1 ENGINE - HPT SHROUD SLEEVE									Component ATA:72
PN:PN	MOS/MSC	01-Apr-10	O/C	TSN 0				CUSTOMER CODE		
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: LMM 72-50-07										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 72 - ENGINE										
725017	NO. 2 ENGINE - HPT SHROUD SLEEVE									Component ATA:72
PN:PN	MOS/MSC	02-Apr-10	O/C	TSN 0				CUSTOMER CODE		
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: LMM 72-50-07										
725020	NO. 1 ENGINE - 2ND-STAGE LOW PRESSURE TURBINE (LPT) DISC									Component ATA:72
PN:PN	MOS	01-Apr-10		TSN 0				LIFE LIMIT		
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0	12000	TSN 0	(12000) 11995		10665			
PROC. REF: LMM 72-50-04										
725020	NO. 2 ENGINE - 2ND-STAGE LOW PRESSURE TURBINE (LPT) DISC									Component ATA:72
PN:PN	MOS	02-Apr-10		TSN 0				LIFE LIMIT		
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0	12000	TSN 0	(12000) 11997		10667			
PROC. REF: LMM 72-50-04										
725021	NO. 1 ENGINE - 2ND-STAGE LPT NOZZLE RETAINER									Component ATA:72
PN:PN	MOS/MSC	01-Apr-10	O/C	TSN 0				CUSTOMER CODE		
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: LMM 72-50-04										
725021	NO. 2 ENGINE - 2ND-STAGE LPT NOZZLE RETAINER									Component ATA:72
PN:PN	MOS/MSC	02-Apr-10	O/C	TSN 0				CUSTOMER CODE		
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: LMM 72-50-04										
725022	NO. 1 ENGINE - 2ND-STAGE LPT NOZZLE SHROUD									Component ATA:72
PN:PN	MOS/MSC	01-Apr-10	O/C	TSN 0				CUSTOMER CODE		
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: LMM 72-50-04										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 72 - ENGINE										
725022	NO. 2 ENGINE - 2ND-STAGE LPT NOZZLE SHROUD									Component ATA:72
PN:PN	MOS/MSC	02-Apr-10	O/C	TSN 0				CUSTOMER CODE		
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: LMM 72-50-04										
725030	NO. 1 ENGINE - 3RD-STAGE LOW PRESSURE TURBINE (LPT) DISC									Component ATA:72
PN:PN	MOS	01-Apr-10		TSN 0				LIFE LIMIT		
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0	12000	TSN 0	(12000) 11995		10665			
PROC. REF: LMM 72-50-04										
725030	NO. 2 ENGINE - 3RD-STAGE LOW PRESSURE TURBINE (LPT) DISC									Component ATA:72
PN:PN	MOS	02-Apr-10		TSN 0				LIFE LIMIT		
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0	12000	TSN 0	(12000) 11997		10667			
PROC. REF: LMM 72-50-04										
725031	NO. 1 ENGINE - 3RD-STAGE LTP BLADES									Component ATA:72
PN:PN	MOS/MSC	01-Apr-10	O/C	TSN 0				CUSTOMER CODE		
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: LMM 72-50-04										
725031	NO. 2 ENGINE - 3RD-STAGE LTP BLADES									Component ATA:72
PN:PN	MOS/MSC	02-Apr-10	O/C	TSN 0				CUSTOMER CODE		
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: LMM 72-50-04										
725040	NO. 1 ENGINE - HIGH PRESSURE TURBINE (HPT) DISC									Component ATA:72
PN:PN	MOS	01-Apr-10		TSN 0				LIFE LIMIT		
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0	10000	TSN 0	(10000) 9995		8665			
PROC. REF: LMM 72-50-07										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 72 - ENGINE										
725040	NO. 2 ENGINE - HIGH PRESSURE TURBINE (HPT) DISC									Component ATA:72
PN:PN	MOS	02-Apr-10		TSN 0				LIFE LIMIT		
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0	10000	TSN 0	(10000) 9997		8667			
PROC. REF: LMM 72-50-07										
725045	NO. 1 ENGINE - HIGH PRESSURE TURBINE (HPT) ASSY									Component ATA:72
PN:PN	MOS/MSC	01-Apr-10	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
725045	NO. 2 ENGINE - HIGH PRESSURE TURBINE (HPT) ASSY									Component ATA:72
PN:PN	MOS/MSC	02-Apr-10	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
725050	NO. 1 ENGINE - FAN DISC									Component ATA:72
PN:3060287-2	MOS	06-Nov-17						LIFE LIMIT		
SN:081365106313	HRS	1300.2								
	ENC	1061	20000	TSN 1061	(20000) 19995		18665			
PROC. REF: GENERIC NO REF										
725050	NO. 2 ENGINE - FAN DISC									Component ATA:72
PN:3060287-2	MOS	06-Nov-17						LIFE LIMIT		
SN:09-13651-00301	HRS	1300.2								
	ENC	1059	20000	TSN 1059	(20000) 19997		18667			
PROC. REF: GENERIC NO REF										
725060	NO. 1 ENGINE - 1ST-STAGE LOW PRESSURE COMPRESSOR (LPC) DISC									Component ATA:72
PN:PN	MOS	01-Apr-10		TSN 0				LIFE LIMIT		
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0	10000	TSN 0	(10000) 9995		8665			
PROC. REF: LMM 72-30-04										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 72 - ENGINE										
725060	NO. 2 ENGINE - 1ST-STAGE LOW PRESSURE COMPRESSOR (LPC) DISC									Component ATA:72
PN:PN	MOS	02-Apr-10		TSN 0				LIFE LIMIT		
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0	10000	TSN 0	(10000) 9997		8667			
PROC. REF: LMM 72-30-04										
725070	NO. 1 ENGINE - 2ND-STAGE LOW PRESSURE COMPRESSOR (LPC) DISC									Component ATA:72
PN:PN	MOS	01-Apr-10		TSN 0				LIFE LIMIT		
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0	10000	TSN 0	(10000) 9995		8665			
PROC. REF: LMM 72-30-04										
725070	NO. 2 ENGINE - 2ND-STAGE LOW PRESSURE COMPRESSOR (LPC) DISC									Component ATA:72
PN:PN	MOS	02-Apr-10		TSN 0				LIFE LIMIT		
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0	10000	TSN 0	(10000) 9997		8667			
PROC. REF: LMM 72-30-04										
725071	NO. 1 ENGINE - COMBUSTION LINER									Component ATA:72
PN:PN	MOS/MSC	01-Apr-10	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: LMM 72-40-03										
725071	NO. 2 ENGINE - COMBUSTION LINER									Component ATA:72
PN:PN	MOS/MSC	02-Apr-10	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: LMM 72-40-03										
725080	NO. 1 ENGINE - 3RD-STAGE LOW PRESSURE COMPRESSOR (LPC) DISC									Component ATA:72
PN:PN	MOS	01-Apr-10		TSN 0				LIFE LIMIT		
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0	10000	TSN 0	(10000) 9995		8665			
PROC. REF: LMM 72-30-04										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 72 - ENGINE										
725080	NO. 2 ENGINE - 3RD-STAGE LOW PRESSURE COMPRESSOR (LPC) DISC									Component ATA:72
PN:PN	MOS	02-Apr-10		TSN 0				LIFE LIMIT		
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0	10000	TSN 0	(10000) 9997		8667			
PROC. REF: LMM 72-30-04										
725081	NO. 1 ENGINE - OUTER TRANSITION LINER									Component ATA:72
PN:PN	MOS/MSC	01-Apr-10	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: LMM 72-40-03										
725081	NO. 2 ENGINE - OUTER TRANSITION LINER									Component ATA:72
PN:PN	MOS/MSC	02-Apr-10	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: LMM 72-40-03										
725090	NO. 1 ENGINE - 4TH-STAGE LOW PRESSURE COMPRESSOR (LPC) DISC									Component ATA:72
PN:PN	MOS	01-Apr-10		TSN 0				LIFE LIMIT		
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0	20000	TSN 0	(20000) 19995		18665			
PROC. REF: LMM 72-30-04										
725090	NO. 2 ENGINE - 4TH-STAGE LOW PRESSURE COMPRESSOR (LPC) DISC									Component ATA:72
PN:PN	MOS	02-Apr-10		TSN 0				LIFE LIMIT		
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0	20000	TSN 0	(20000) 19997		18667			
PROC. REF: LMM 72-30-04										
725110	NO. 1 ENGINE - LOW PRESSURE COMPRESSOR TIE ROD									Component ATA:72
PN:PN	MOS/MSC	01-Apr-10	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: LMM 72-30-10, LMM 72-30-10, LMM 72-30-10										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 72 - ENGINE										
725110	NO. 2 ENGINE - LOW PRESSURE COMPRESSOR TIE ROD									Component ATA:72
PN:PN	MOS/MSC	02-Apr-10	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: LMM 72-30-10, LMM 72-30-10, LMM 72-30-10										
725120	NO. 1 ENGINE - HIGH PRESSURE COMPRESSOR ROTOR IMPELLER									Component ATA:72
PN:PN	MOS	01-Apr-10		TSN 0				LIFE LIMIT		
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0	8000	TSN 0	(8000) 7995		6665			
PROC. REF: LMM 72-50-06										
725120	NO. 2 ENGINE - HIGH PRESSURE COMPRESSOR ROTOR IMPELLER									Component ATA:72
PN:PN	MOS	02-Apr-10		TSN 0				LIFE LIMIT		
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0	8000	TSN 0	(8000) 7997		6667			
PROC. REF: LMM 72-50-06										
725130	NO. 1 ENGINE - FAN SPINNER									Component ATA:72
PN:PN	MOS	01-Apr-10		TSN 0				LIFE LIMIT		
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0	20000	TSN 0	(20000) 19995		18665			
PROC. REF: LMM 72-70-01										
725130	NO. 2 ENGINE - FAN SPINNER									Component ATA:72
PN:PN	MOS	02-Apr-10		TSN 0				LIFE LIMIT		
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0	20000	TSN 0	(20000) 19997		18667			
PROC. REF: LMM 72-70-01										
725140	NO. 1 ENGINE - FAN DRIVE SHAFT									Component ATA:72
PN:PN	MOS/MSC	01-Apr-10	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 72 - ENGINE										
725140	NO. 2 ENGINE - FAN DRIVE SHAFT									Component ATA:72
PN:PN	MOS/MSC	02-Apr-10	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
725141	NO. 1 ENGINE - FAN ROLLER BEARING									Component ATA:72
PN:PN	MOS/MSC	01-Apr-10	O/C	TSN 0				CUSTOMER CODE		
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
725141	NO. 2 ENGINE - FAN ROLLER BEARING									Component ATA:72
PN:PN	MOS/MSC	02-Apr-10	O/C	TSN 0				CUSTOMER CODE		
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
725160	NO. 1 ENGINE - FORWARD ROTOR HIGH PRESSURE SEAL									Component ATA:72
PN:PN	MOS	01-Apr-10		TSN 0				LIFE LIMIT		
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0	7000	TSN 0	(7000) 6995		5665			
PROC. REF: LMM 72-70-03										
725160	NO. 2 ENGINE - FORWARD ROTOR HIGH PRESSURE SEAL									Component ATA:72
PN:PN	MOS	02-Apr-10		TSN 0				LIFE LIMIT		
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0	7000	TSN 0	(7000) 6997		5667			
PROC. REF: LMM 72-70-03										
725170	NO. 1 ENGINE - HIGH PRESSURE SHOULDERED SHAFT									Component ATA:72
PN:PN	MOS/MSC	01-Apr-10	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 72 - ENGINE										
725170	NO. 2 ENGINE - HIGH PRESSURE SHOULDERED SHAFT									Component ATA:72
PN:PN	MOS/MSC	02-Apr-10	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
725180	NO. 1 ENGINE - COMBUSTION PLENUM CASE									Component ATA:72
PN:PN	MOS/MSC	01-Apr-10	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: LMM 72-40-04, LMM 72-40-04										
725180	NO. 2 ENGINE - COMBUSTION PLENUM CASE									Component ATA:72
PN:PN	MOS/MSC	02-Apr-10	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: LMM 72-40-04, LMM 72-40-04										
725210	NO. 1 ENGINE - HIGH PRESSURE TURBINE FORWARD SEAL PLATE									Component ATA:72
PN:PN	MOS	01-Apr-10		TSN 0				LIFE LIMIT		
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0	10000	TSN 0	(10000) 9995		8665			
PROC. REF: GENERIC NO REF										
725210	NO. 2 ENGINE - HIGH PRESSURE TURBINE FORWARD SEAL PLATE									Component ATA:72
PN:PN	MOS	02-Apr-10		TSN 0				LIFE LIMIT		
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0	10000	TSN 0	(10000) 9997		8667			
PROC. REF: GENERIC NO REF										
725220	NO. 1 ENGINE - TURBINE INTERSTAGE TRANSITION DUCT									Component ATA:72
PN:PN	MOS/MSC	01-Apr-10	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 72 - ENGINE										
725220	NO. 2 ENGINE - TURBINE INTERSTAGE TRANSITION DUCT									Component ATA:72
PN:PN	MOS/MSC	02-Apr-10	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
725230	NO. 1 ENGINE - LOW PRESSURE TURBINE (LPT) 1 NOZZLE SEAL SUPPORT									Component ATA:72
PN:PN	MOS/MSC	01-Apr-10	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: LMM 72-50-04										
725230	NO. 2 ENGINE - LOW PRESSURE TURBINE (LPT) 1 NOZZLE SEAL SUPPORT									Component ATA:72
PN:PN	MOS/MSC	02-Apr-10	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: LMM 72-50-04										
725240	NO. 1 ENGINE - LOW PRESSURE TURBINE (LPT) 1 NOZZLE ASSEMBLY									Component ATA:72
PN:PN	MOS/MSC	01-Apr-10	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: LMM 72-50-04										
725240	NO. 2 ENGINE - LOW PRESSURE TURBINE (LPT) 1 NOZZLE ASSEMBLY									Component ATA:72
PN:PN	MOS/MSC	02-Apr-10	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: LMM 72-50-04										
725250	NO. 1 ENGINE - FORWARD SHAFT HIGH PRESSURE TURBINE (HPT) COUPLING									Component ATA:72
PN:PN	MOS/MSC	01-Apr-10	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
725250	NO. 2 ENGINE - FORWARD SHAFT HIGH PRESSURE TURBINE (HPT) COUPLING									Component ATA:72
PN:PN	MOS/MSC	02-Apr-10	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 72 - ENGINE										
725260	NO. 1 ENGINE - AFT HIGH PRESSURE TURBINE (HPT) SHAFT COUPLING									Component ATA:72
PN:PN	MOS/MSC	01-Apr-10	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
725260	NO. 2 ENGINE - AFT HIGH PRESSURE TURBINE (HPT) SHAFT COUPLING									Component ATA:72
PN:PN	MOS/MSC	02-Apr-10	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
725270	NO. 1 ENGINE - NOZZLE LOW PRESSURE TURBINE (LPT) (A5) SEAL									Component ATA:72
PN:PN	MOS/MSC	01-Apr-10	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
725270	NO. 2 ENGINE - NOZZLE LOW PRESSURE TURBINE (LPT) (A5) SEAL									Component ATA:72
PN:PN	MOS/MSC	02-Apr-10	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
726005	NO. 1 ENGINE - TRANSFER GEARBOX ASSEMBLY									Component ATA:72
PN:PN	MOS/MSC	01-Apr-10	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: LMM 72-60-03										
726005	NO. 2 ENGINE - TRANSFER GEARBOX ASSEMBLY									Component ATA:72
PN:PN	MOS/MSC	02-Apr-10	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: LMM 72-60-03										
726010	NO. 1 ENGINE - FORWARD OIL PUMP SPUR ANNULAR BALL BEARING									Component ATA:72
PN:PN	MOS/MSC	01-Apr-10	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF, LMM 72-00-00										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 72 - ENGINE										
726010	NO. 2 ENGINE - FORWARD OIL PUMP SPUR ANNULAR BALL BEARING									Component ATA:72
PN:PN	MOS/MSC	02-Apr-10	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF, LMM 72-00-00										
726011	NO. 1 ENGINE - AFT OIL PUMP SPUR ANNULAR BALL BEARING									Component ATA:72
PN:PN	MOS/MSC	01-Apr-10	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
726011	NO. 2 ENGINE - AFT OIL PUMP SPUR ANNULAR BALL BEARING									Component ATA:72
PN:PN	MOS/MSC	02-Apr-10	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
726012	NO. 1 ENGINE - FORWARD ALTERNATOR SPU ANNULAR BALL BEARING									Component ATA:72
PN:PN	MOS/MSC	01-Apr-10	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
726012	NO. 2 ENGINE - FORWARD ALTERNATOR SPU ANNULAR BALL BEARING									Component ATA:72
PN:PN	MOS/MSC	02-Apr-10	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
726013	NO. 1 ENGINE - AFT ALTERNATOR SPU ANNULAR BEARING									Component ATA:72
PN:PN	MOS/MSC	01-Apr-10	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
726013	NO. 2 ENGINE - AFT ALTERNATOR SPU ANNULAR BEARING									Component ATA:72
PN:PN	MOS/MSC	02-Apr-10	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 72 - ENGINE										
726014	NO. 1 ENGINE - FORWARD AIR-OIL SEPARATOR ANNULAR BALL BEARING									Component ATA:72
PN:PN	MOS/MSC	01-Apr-10	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
726014	NO. 2 ENGINE - FORWARD AIR-OIL SEPARATOR ANNULAR BALL BEARING									Component ATA:72
PN:PN	MOS/MSC	02-Apr-10	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
726015	NO. 1 ENGINE - AFT AIR-OIL SEPARATOR ANNULAR BALL BEARING									Component ATA:72
PN:PN	MOS/MSC	01-Apr-10	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
726015	NO. 2 ENGINE - AFT AIR-OIL SEPARATOR ANNULAR BALL BEARING									Component ATA:72
PN:PN	MOS/MSC	02-Apr-10	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
726016	NO. 1 ENGINE - FORWARD STARTER/GENERATOR SPU ANNULAR BALL BEARING									Component ATA:72
PN:PN	MOS/MSC	01-Apr-10	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
726016	NO. 2 ENGINE - FORWARD STARTER/GENERATOR SPU ANNULAR BALL BEARING									Component ATA:72
PN:PN	MOS/MSC	02-Apr-10	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
726017	NO. 1 ENGINE - AFT STARTER/GENERATOR SPU ANNULAR BEARING									Component ATA:72
PN:PN	MOS/MSC	01-Apr-10	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 72 - ENGINE										
726017	NO. 2 ENGINE - AFT STARTER/GENERATOR SPU ANNULAR BEARING									Component ATA:72
PN:PN	MOS/MSC	02-Apr-10	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
727001	NO. 1 ENGINE - BYPASS FAN STATOR									Component ATA:72
PN:PN	MOS/MSC	01-Apr-10	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: LMM 72-70-04										
727001	NO. 2 ENGINE - BYPASS FAN STATOR									Component ATA:72
PN:PN	MOS/MSC	02-Apr-10	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: LMM 72-70-04										
727005	NO. 1 ENGINE - UPPER FAN DUCT ASSEMBLY									Component ATA:72
PN:3061300-5-T42087	MOS/MSC	11-Mar-14	O/C							
SN:09-181898-00443	HRS	815.4								
	ENC	747								
PROC. REF: LMM 72-70-05										
727005	NO. 2 ENGINE - UPPER FAN DUCT ASSEMBLY									Component ATA:72
PN:3061300-5-T42087	MOS/MSC	11-Mar-14	O/C							
SN:9-181898-0455	HRS	815.4								
	ENC	744								
PROC. REF: LMM 72-70-05										
727006	NO. 1 ENGINE - LOWER FAN DUCT ASSEMBLY									Component ATA:72
PN:PN	MOS/MSC	01-Apr-10	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: LMM 72-70-05										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty		
ATA 72 - ENGINE												
727006			NO. 2 ENGINE - LOWER FAN DUCT ASSEMBLY								Component	ATA:72
PN:PN	MOS/MSC	02-Apr-10	O/C	TSN 0								
SN:UNKNOWN	HRS	0	TSN 0									
	ENC	0	TSN 0									
PROC. REF: LMM 72-70-05												
727010 ^S			NO. 1 ENGINE - INSPECT BYPASS STATOR VANE ASSEMBLY.								Service	ATA:72
	MOS	16-Dec-16										
	HRS	1162	1200 (+ 100/-200)									
	ENC	971										
PROC. REF: GENERIC NO REF, LMM 72-70-04, LMM 72-70-04, LMM 72-70-04												
727010 ^S			NO. 2 ENGINE - INSPECT BYPASS STATOR VANE ASSEMBLY.								Service	ATA:72
	MOS	16-Dec-16										
	HRS	1162	1200 (+ 100/-200)									
	ENC	969										
PROC. REF: GENERIC NO REF, LMM 72-70-04, LMM 72-70-04, LMM 72-70-04												
727101			NO. 1 ENGINE - NO. 1 CARBON SEAL ASSEMBLY								Component	ATA:72
PN:PN	MOS/MSC	01-Apr-10	O/C	TSN 0								
SN:UNKNOWN	HRS	0	TSN 0									
	ENC	0	TSN 0									
PROC. REF: GENERIC NO REF												
727101			NO. 2 ENGINE - NO. 1 CARBON SEAL ASSEMBLY								Component	ATA:72
PN:PN	MOS/MSC	02-Apr-10	O/C	TSN 0								
SN:UNKNOWN	HRS	0	TSN 0									
	ENC	0	TSN 0									
PROC. REF: GENERIC NO REF												
727102			NO. 1 ENGINE - NO. 1 CARBON SEAL RUNNER								Component	ATA:72
PN:PN	MOS/MSC	01-Apr-10	O/C	TSN 0								
SN:UNKNOWN	HRS	0	TSN 0									
	ENC	0	TSN 0									
PROC. REF: GENERIC NO REF												
727102			NO. 2 ENGINE - NO. 1 CARBON SEAL RUNNER								Component	ATA:72
PN:PN	MOS/MSC	02-Apr-10	O/C	TSN 0								
SN:UNKNOWN	HRS	0	TSN 0									
	ENC	0	TSN 0									
PROC. REF: GENERIC NO REF												

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 72 - ENGINE										
727103	NO. 1 ENGINE - NO. 1 BEARING ASSEMBLY									Component ATA:72
PN:PN	MOS/MSC	01-Apr-10	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
727103	NO. 2 ENGINE - NO. 1 BEARING ASSEMBLY									Component ATA:72
PN:PN	MOS/MSC	02-Apr-10	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
727105	NO. 1 ENGINE - HELICAL RING GEAR									Component ATA:72
PN:PN	MOS/MSC	01-Apr-10	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
727105	NO. 2 ENGINE - HELICAL RING GEAR									Component ATA:72
PN:PN	MOS/MSC	02-Apr-10	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
727203	NO. 1 ENGINE - NO. 3 BALL BEARING									Component ATA:72
PN:PN	MOS/MSC	01-Apr-10	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: LMM 72-30-01										
727203	NO. 2 ENGINE - NO. 3 BALL BEARING									Component ATA:72
PN:PN	MOS/MSC	02-Apr-10	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: LMM 72-30-01										
727210	NO. 1 ENGINE - PLANET HOUSING ASSEMBLY									Component ATA:72
PN:PN	MOS/MSC	01-Apr-10	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: LMM 72-72-03										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 72 - ENGINE											
727210		NO. 2 ENGINE - PLANET HOUSING ASSEMBLY							Component	ATA:72	
PN:PN	MOS/MSC	02-Apr-10	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	ENC	0		TSN 0							
PROC. REF: LMM 72-72-03											
727210-1		NO. 1 ENGINE - NO. 1 PLANET GEAR ASSEMBLY							Component	ATA:72	
PN:PN	MOS/MSC	01-Apr-10	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	ENC	0		TSN 0							
PROC. REF: LMM 72-72-03											
727210-1		NO. 2 ENGINE - NO. 1 PLANET GEAR ASSEMBLY							Component	ATA:72	
PN:PN	MOS/MSC	02-Apr-10	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	ENC	0		TSN 0							
PROC. REF: LMM 72-72-03											
727210-2		NO. 1 ENGINE - NO. 2 PLANET GEAR ASSEMBLY							Component	ATA:72	
PN:PN	MOS/MSC	01-Apr-10	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	ENC	0		TSN 0							
PROC. REF: LMM 72-72-03											
727210-2		NO. 2 ENGINE - NO. 2 PLANET GEAR ASSEMBLY							Component	ATA:72	
PN:PN	MOS/MSC	02-Apr-10	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	ENC	0		TSN 0							
PROC. REF: LMM 72-72-03											
727210-3		NO. 1 ENGINE - NO. 3 PLANET GEAR ASSEMBLY							Component	ATA:72	
PN:PN	MOS/MSC	01-Apr-10	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	ENC	0		TSN 0							
PROC. REF: LMM 72-72-03											
727210-3		NO. 2 ENGINE - NO. 3 PLANET GEAR ASSEMBLY							Component	ATA:72	
PN:PN	MOS/MSC	02-Apr-10	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	ENC	0		TSN 0							
PROC. REF: LMM 72-72-03											

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 72 - ENGINE											
727210-4		NO. 1 ENGINE - NO. 4 PLANET GEAR ASSEMBLY							Component	ATA:72	
PN:PN	MOS/MSC	01-Apr-10	O/C	TSN 0							
SN:UNKNOWN	HRS	0	TSN 0								
	ENC	0	TSN 0								
PROC. REF: LMM 72-72-03											
727210-4		NO. 2 ENGINE - NO. 4 PLANET GEAR ASSEMBLY							Component	ATA:72	
PN:PN	MOS/MSC	02-Apr-10	O/C	TSN 0							
SN:UNKNOWN	HRS	0	TSN 0								
	ENC	0	TSN 0								
PROC. REF: LMM 72-72-03											
727210-5		NO. 1 ENGINE - NO. 5 PLANET GEAR ASSEMBLY							Component	ATA:72	
PN:PN	MOS/MSC	01-Apr-10	O/C	TSN 0							
SN:UNKNOWN	HRS	0	TSN 0								
	ENC	0	TSN 0								
PROC. REF: LMM 72-72-03											
727210-5		NO. 2 ENGINE - NO. 5 PLANET GEAR ASSEMBLY							Component	ATA:72	
PN:PN	MOS/MSC	02-Apr-10	O/C	TSN 0							
SN:UNKNOWN	HRS	0	TSN 0								
	ENC	0	TSN 0								
PROC. REF: LMM 72-72-03											
ATA 73 - ENGINE FUEL AND CONTROL											
730110		NO. 1 ENGINE - FUEL CONTROL UNIT							Component	ATA:73	
PN:PN	MOS/MSC	01-Apr-10	O/C	TSN 0							
SN:UNKNOWN	HRS	0	TSN 0								
	ENC	0	TSN 0								
PROC. REF: LMM 73-20-01											
730110		NO. 2 ENGINE - FUEL CONTROL UNIT							Component	ATA:73	
PN:PN	MOS/MSC	02-Apr-10	O/C	TSN 0							
SN:UNKNOWN	HRS	0	TSN 0								
	ENC	0	TSN 0								
PROC. REF: LMM 73-20-01											
730120 ^S		NO. 1 ENGINE - REPLACE FUEL FILTER ELEMENT							Service	ATA:73	
	MOS	11-Sep-18									
	HRS	1387.4	600 (+ 50/-100)								
	ENC	1122									
PROC. REF: LMM 73-21-02, LMM 73-21-02											
PKG:0											

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 73 - ENGINE FUEL AND CONTROL											
730120 ^S			NO. 2 ENGINE - REPLACE FUEL FILTER ELEMENT						Service	ATA:73	
	MOS		11-Sep-18								
	HRS		1387.4		600 (+ 50/-100)						
	ENC		1120								
PROC. REF: LMM 73-21-02, LMM 73-21-02										PKG:0	
730130			NO. 1 ENGINE - ENGINE FUEL PUMP ASSEMBLY						Component	ATA:73	
PN:PN	MOS/MSC		01-Apr-10	O/C	TSN 0						
SN:UNKNOWN	HRS		0		TSN 0						
	ENC		0		TSN 0						
PROC. REF: LMM 73-20-01, LMM 73-20-01, LMM 73-20-01											
730130			NO. 2 ENGINE - ENGINE FUEL PUMP ASSEMBLY						Component	ATA:73	
PN:PN	MOS/MSC		02-Apr-10	O/C	TSN 0						
SN:UNKNOWN	HRS		0		TSN 0						
	ENC		0		TSN 0						
PROC. REF: LMM 73-20-01, LMM 73-20-01, LMM 73-20-01											
731001			NO. 1 ENGINE - MOTIVE FLOW FUEL PUMP ASSEMBLY						Component	ATA:73	
PN:765279C	MOS/MSC		11-Sep-18	O/C							
SN:1649	HRS		1387.4								
	ENC		1119								
PROC. REF: LMM 73-21-02											
731001			NO. 2 ENGINE - MOTIVE FLOW FUEL PUMP ASSEMBLY						Component	ATA:73	
PN:3060759-1	MOS/MSC		11-Sep-18	O/C							
SN:1662	HRS		1387.4								
	ENC		1117								
PROC. REF: LMM 73-21-02											
731005-1			NO. 1 ENGINE - NO. 1 FUEL MANIFOLD NOZZLE ASSEMBLY						Component	ATA:73	
PN:PN	MOS/MSC		01-Apr-10	O/C	TSN 0						
SN:UNKNOWN	HRS		0		TSN 0						
	ENC		0		TSN 0						
PROC. REF: LMM 73-10-01											
731005-1			NO. 2 ENGINE - NO. 1 FUEL MANIFOLD NOZZLE ASSEMBLY						Component	ATA:73	
PN:PN	MOS/MSC		02-Apr-10	O/C	TSN 0						
SN:UNKNOWN	HRS		0		TSN 0						
	ENC		0		TSN 0						
PROC. REF: LMM 73-10-01											

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty
---------	------	------	----------	-----------	--------------------------	-----------	-----------	-------------	-----	----------

ATA 73 - ENGINE FUEL AND CONTROL

731005-10 NO. 1 ENGINE - NO. 10 FUEL MANIFOLD NOZZLE ASSEMBLY Component ATA:73										
PN:PN	MOS/MSC	01-Apr-10	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: LMM 73-10-01										
731005-10 NO. 2 ENGINE - NO. 10 FUEL MANIFOLD NOZZLE ASSEMBLY Component ATA:73										
PN:PN	MOS/MSC	02-Apr-10	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: LMM 73-10-01										
731005-11 NO. 1 ENGINE - NO. 11 FUEL MANIFOLD NOZZLE ASSEMBLY Component ATA:73										
PN:PN	MOS/MSC	01-Apr-10	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: LMM 73-10-01										
731005-11 NO. 2 ENGINE - NO. 11 FUEL MANIFOLD NOZZLE ASSEMBLY Component ATA:73										
PN:PN	MOS/MSC	02-Apr-10	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: LMM 73-10-01										
731005-12 NO. 1 ENGINE - NO. 12 FUEL MANIFOLD NOZZLE ASSEMBLY Component ATA:73										
PN:PN	MOS/MSC	01-Apr-10	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: LMM 73-10-01										
731005-12 NO. 2 ENGINE - NO. 12 FUEL MANIFOLD NOZZLE ASSEMBLY Component ATA:73										
PN:PN	MOS/MSC	02-Apr-10	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: LMM 73-10-01										
731005-2 NO. 1 ENGINE - NO. 2 FUEL MANIFOLD NOZZLE ASSEMBLY Component ATA:73										
PN:PN	MOS/MSC	01-Apr-10	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: LMM 73-10-01										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 73 - ENGINE FUEL AND CONTROL										
731005-2 NO. 2 ENGINE - NO. 2 FUEL MANIFOLD NOZZLE ASSEMBLY Component ATA:73										
PN:PN	MOS/MSC	02-Apr-10	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: LMM 73-10-01										
731005-3 NO. 1 ENGINE - NO. 3 FUEL MANIFOLD NOZZLE ASSEMBLY Component ATA:73										
PN:PN	MOS/MSC	01-Apr-10	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: LMM 73-10-01										
731005-3 NO. 2 ENGINE - NO. 3 FUEL MANIFOLD NOZZLE ASSEMBLY Component ATA:73										
PN:PN	MOS/MSC	02-Apr-10	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: LMM 73-10-01										
731005-4 NO. 1 ENGINE - NO. 4 FUEL MANIFOLD NOZZLE ASSEMBLY Component ATA:73										
PN:PN	MOS/MSC	01-Apr-10	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: LMM 73-10-01										
731005-4 NO. 2 ENGINE - NO. 4 FUEL MANIFOLD NOZZLE ASSEMBLY Component ATA:73										
PN:PN	MOS/MSC	02-Apr-10	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: LMM 73-10-01										
731005-5 NO. 1 ENGINE - NO. 5 FUEL MANIFOLD NOZZLE ASSEMBLY Component ATA:73										
PN:PN	MOS/MSC	01-Apr-10	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: LMM 73-10-01										
731005-5 NO. 2 ENGINE - NO. 5 FUEL MANIFOLD NOZZLE ASSEMBLY Component ATA:73										
PN:PN	MOS/MSC	02-Apr-10	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: LMM 73-10-01										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 73 - ENGINE FUEL AND CONTROL										
731005-6 NO. 1 ENGINE - NO. 6 FUEL MANIFOLD NOZZLE ASSEMBLY Component ATA:73										
PN:PN	MOS/MSC	01-Apr-10	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: LMM 73-10-01										
731005-6 NO. 2 ENGINE - NO. 6 FUEL MANIFOLD NOZZLE ASSEMBLY Component ATA:73										
PN:PN	MOS/MSC	02-Apr-10	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: LMM 73-10-01										
731005-7 NO. 1 ENGINE - NO. 7 FUEL MANIFOLD NOZZLE ASSEMBLY Component ATA:73										
PN:PN	MOS/MSC	01-Apr-10	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: LMM 73-10-01										
731005-7 NO. 2 ENGINE - NO. 7 FUEL MANIFOLD NOZZLE ASSEMBLY Component ATA:73										
PN:PN	MOS/MSC	02-Apr-10	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: LMM 73-10-01										
731005-8 NO. 1 ENGINE - NO. 8 FUEL MANIFOLD NOZZLE ASSEMBLY Component ATA:73										
PN:PN	MOS/MSC	01-Apr-10	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: LMM 73-10-01										
731005-8 NO. 2 ENGINE - NO. 8 FUEL MANIFOLD NOZZLE ASSEMBLY Component ATA:73										
PN:PN	MOS/MSC	02-Apr-10	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: LMM 73-10-01										
731005-9 NO. 1 ENGINE - NO. 9 FUEL MANIFOLD NOZZLE ASSEMBLY Component ATA:73										
PN:PN	MOS/MSC	01-Apr-10	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: LMM 73-10-01										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 73 - ENGINE FUEL AND CONTROL										
731005-9	NO. 2 ENGINE - NO. 9 FUEL MANIFOLD NOZZLE ASSEMBLY									Component ATA:73
PN:PN	MOS/MSC	02-Apr-10	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: LMM 73-10-01										
731015	NO. 1 ENGINE - FUEL PUMP PRESSURE DIFFERENTIAL INDICATOR									Component ATA:73
PN:PN	MOS/MSC	01-Apr-10	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: LMM 73-20-01										
731015	NO. 2 ENGINE - FUEL PUMP PRESSURE DIFFERENTIAL INDICATOR									Component ATA:73
PN:PN	MOS/MSC	02-Apr-10	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: LMM 73-20-01										
731110	NO. 1 ENGINE - PRESSURE LIMITER (PCD) VALVE									Component ATA:73
PN:PN	MOS/MSC	01-Apr-10	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: LMM 73-20-01										
731110	NO. 2 ENGINE - PRESSURE LIMITER (PCD) VALVE									Component ATA:73
PN:PN	MOS/MSC	02-Apr-10	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: LMM 73-20-01										
731120	NO. 1 ENGINE - FUEL FLOW DIVIDER/DRAIN VALVE									Component ATA:73
PN:PN	MOS/MSC	01-Apr-10	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
731120	NO. 2 ENGINE - FUEL FLOW DIVIDER/DRAIN VALVE									Component ATA:73
PN:PN	MOS/MSC	02-Apr-10	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty
---------	------	------	----------	-----------	--------------------------	-----------	-----------	-------------	-----	----------

ATA 73 - ENGINE FUEL AND CONTROL

732102 NO. 1 ENGINE - RELIEF VALVE										Component	ATA:73
PN:PN	MOS/MSC	01-Apr-10	O/C	TSN	0						
SN:UNKNOWN	HRS	0		TSN	0						
	ENC	0		TSN	0						
PROC. REF: GENERIC NO REF											

732102 NO. 2 ENGINE - RELIEF VALVE										Component	ATA:73
PN:PN	MOS/MSC	02-Apr-10	O/C	TSN	0						
SN:UNKNOWN	HRS	0		TSN	0						
	ENC	0		TSN	0						
PROC. REF: GENERIC NO REF											

732120 ^S NO. 1 ENGINE - INSPECT MOTIVE FLOW FUEL PUMP DRIVE SPLINE										Service	ATA:73
	MOS	11-Sep-18									
	HRS	1387.4	600 (+ 50/-100)								
	ENC	1122									
PROC. REF: LMM 72-00-00, LMM 73-21-04											
											PKG:0

732120 ^S NO. 2 ENGINE - INSPECT MOTIVE FLOW FUEL PUMP DRIVE SPLINE										Service	ATA:73
	MOS	11-Sep-18									
	HRS	1387.4	600 (+ 50/-100)								
	ENC	1120									
PROC. REF: LMM 72-00-00, LMM 73-21-04											
											PKG:0

733001 NO. 1 ENGINE FUEL FLOW TRANSDUCER										Component	ATA:73
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN	0						
SN:UNKNOWN	HRS	0		TSN	0						
	AFL	0		TSN	0						
PROC. REF: AMM 73-31-01											

733002 NO. 2 ENGINE FUEL FLOW TRANSDUCER										Component	ATA:73
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN	0						
SN:UNKNOWN	HRS	0		TSN	0						
	AFL	0		TSN	0						
PROC. REF: AMM 73-31-01											

733013 DUAL FUEL FLOW (DFFC) CONVERTER										Component	ATA:73
PN:10540B08F07	MOS/MSC	20-Jan-11	O/C	TSN	0						
SN:09021197A	HRS	0		TSN	0						
	AFL	0		TSN	0						
PROC. REF: AMM 73-31-02											

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty
---------	------	------	----------	-----------	--------------------------	-----------	-----------	-------------	-----	----------

ATA 73 - ENGINE FUEL AND CONTROL

733031 LEFT ENGINE FUEL TEMPERATURE BULB										Component	ATA:73
PN:MS28034-3	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:U6703	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 73-31-03											

733032 RIGHT ENGINE FUEL TEMPERATURE BULB										Component	ATA:73
PN:MS28034-3	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:U3421	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 73-31-03											

ATA 74 - IGNITION

740110 NO. 1 ENGINE - IGNITION UNIT										Component	ATA:74
PN:PN	MOS/MSC	01-Apr-10	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	ENC	0		TSN 0							
PROC. REF: LMM 74-00-01											

740110 NO. 2 ENGINE - IGNITION UNIT										Component	ATA:74
PN:PN	MOS/MSC	02-Apr-10	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	ENC	0		TSN 0							
PROC. REF: LMM 74-00-01											

740130 NO. 1 ENGINE - 5 O'CLOCK IGNITER (# 1 POSITION) PLUG										Component	ATA:74
PN:PN	MOS/MSC	01-Apr-10	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	ENC	0		TSN 0							
PROC. REF: LMM 74-00-01											

740130 NO. 2 ENGINE - 5 O'CLOCK IGNITER (# 1 POSITION) PLUG										Component	ATA:74
PN:PN	MOS/MSC	02-Apr-10	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	ENC	0		TSN 0							
PROC. REF: LMM 74-00-01											

740140 ^S NO. 1 ENGINE - REMOVE AND INSPECT 5 O'CLOCK IGNITER PLUG AND LEAD										Service	ATA:74
	MOS	10-Oct-19									
	HRS	1509.8	1650 (-150)								
	ENC	1206									
PROC. REF: LMM 74-00-01, LMM 74-00-01											

PKG:0

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 74 - IGNITION											
740140 ^S			NO. 2 ENGINE - REMOVE AND INSPECT 5 O'CLOCK IGNITER PLUG AND LEAD						Service	ATA:74	
	MOS	10-Oct-19									
	HRS	1509.8	1650	(-150)							
	ENC	1204									
										PKG:0	
PROC. REF: LMM 74-00-01, LMM 74-00-01											
740150			NO. 1 ENGINE - 7 O'CLOCK IGNITER (# 2 POSITION) PLUG						Component	ATA:74	
PN:PN	MOS/MSC	01-Apr-10	O/C		TSN 0						
SN:UNKNOWN	HRS	0			TSN 0						
	ENC	0			TSN 0						
										PKG:0	
PROC. REF: LMM 74-00-01											
740150			NO. 2 ENGINE - 7 O'CLOCK IGNITER (# 2 POSITION) PLUG						Component	ATA:74	
PN:PN	MOS/MSC	02-Apr-10	O/C		TSN 0						
SN:UNKNOWN	HRS	0			TSN 0						
	ENC	0			TSN 0						
										PKG:0	
PROC. REF: LMM 74-00-01											
740160 ^S			NO. 1 ENGINE - REMOVE AND INSPECT 7 O'CLOCK IGNITER PLUG AND LEAD						Service	ATA:74	
	MOS	10-Oct-19									
	HRS	1509.8	1650	(-150)							
	ENC	1206									
										PKG:0	
PROC. REF: LMM 74-00-01											
740160 ^S			NO. 2 ENGINE - REMOVE AND INSPECT 7 O'CLOCK IGNITER PLUG AND LEAD						Service	ATA:74	
	MOS	10-Oct-19									
	HRS	1509.8	1650	(-150)							
	ENC	1204									
										PKG:0	
PROC. REF: LMM 74-00-01											
742011			NO. 1 ENGINE - NO. 1 IGNITION (IPC 20 REFERENCE) LEAD						Component	ATA:74	
PN:PN	MOS/MSC	01-Apr-10	O/C		TSN 0						
SN:UNKNOWN	HRS	0			TSN 0						
	ENC	0			TSN 0						
										PKG:0	
PROC. REF: LMM 74-00-01											
742011			NO. 2 ENGINE - NO. 1 IGNITION (IPC 20 REFERENCE) LEAD						Component	ATA:74	
PN:PN	MOS/MSC	02-Apr-10	O/C		TSN 0						
SN:UNKNOWN	HRS	0			TSN 0						
	ENC	0			TSN 0						
										PKG:0	
PROC. REF: LMM 74-00-01											

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 74 - IGNITION											
742012		NO. 1 ENGINE - NO. 2 IGNITION (IPC 25 REFERENCE) LEAD								Component	ATA:74
PN:PN	MOS/MSC	01-Apr-10	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	ENC	0		TSN 0							
PROC. REF: LMM 74-00-01											
742012		NO. 2 ENGINE - NO. 2 IGNITION (IPC 25 REFERENCE) LEAD								Component	ATA:74
PN:PN	MOS/MSC	02-Apr-10	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	ENC	0		TSN 0							
PROC. REF: LMM 74-00-01											
742020		NO. 1 ENGINE - IGNITION EXCITER								Component	ATA:74
PN:PN	MOS/MSC	01-Apr-10	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	ENC	0		TSN 0							
PROC. REF: GENERIC NO REF											
742020		NO. 2 ENGINE - IGNITION EXCITER								Component	ATA:74
PN:PN	MOS/MSC	02-Apr-10	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	ENC	0		TSN 0							
PROC. REF: GENERIC NO REF											
743001		TAIL CONE RELAY (P13) PANEL								Component	ATA:74
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 74-30-01											
743001-1		EMERGENCY LIGHTING (P-51) RELAY								Component	ATA:74
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: GENERIC NO REF											
743005-1		K22 RELAY								Component	ATA:74
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: GENERIC NO REF											

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty
---------	------	------	----------	-----------	--------------------------	-----------	-----------	-------------	-----	----------

ATA 74 - IGNITION

743005-2 K61 RELAY Component ATA:74										
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										

ATA 75 - AIR

754210 NO. 1 ENGINE - INLET PRESSURE AND TEMPERATURE SENSOR Component ATA:75										
PN:PN	MOS/MSC	01-Apr-10	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: LMM 75-40-01, LMM 75-40-01, LMM 75-40-01										

754210 NO. 2 ENGINE - INLET PRESSURE AND TEMPERATURE SENSOR Component ATA:75										
PN:PN	MOS/MSC	02-Apr-10	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: LMM 75-40-01, LMM 75-40-01, LMM 75-40-01										

761310 NO. 1 ENGINE - SURGE BLEED VALVE Component ATA:75										
PN:PN	MOS/MSC	01-Apr-10	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: LMM 76-10-01, LMM 76-10-01, LMM 76-10-01										

761310 NO. 2 ENGINE - SURGE BLEED VALVE Component ATA:75										
PN:PN	MOS/MSC	02-Apr-10	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: LMM 76-10-01, LMM 76-10-01, LMM 76-10-01										

ATA 76 - ENGINE CONTROLS

761013 THROTTLE CONTROL MODULE Component ATA:76										
PN:6676101000-021	MOS/MSC	23-Oct-20	O/C							
SN:318	HRS	1570.8								
	AFL	1243								
PROC. REF: AMM 76-10-02										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty
---------	------	------	----------	-----------	--------------------------	-----------	-----------	-------------	-----	----------

ATA 76 - ENGINE CONTROLS

761201 AFT LEFT THROTTLE CABLE Component ATA:76										
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 76-10-01										
761202 AFT RIGHT THROTTLE CABLE Component ATA:76										
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 76-10-01										
761203 LEFT FORWARD THROTTLE CABLE Component ATA:76										
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 76-10-01										
761204 RIGHT FORWARD THROTTLE CABLE Component ATA:76										
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 76-10-01										
761320 NO. 1 ENGINE - SOLENOID CONTROLLER VALVE Component ATA:76										
PN:PN	MOS/MSC	01-Apr-10	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: LMM 76-10-01, LMM 76-10-01, LMM 76-10-01										
761320 NO. 2 ENGINE - SOLENOID CONTROLLER VALVE Component ATA:76										
PN:PN	MOS/MSC	02-Apr-10	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: LMM 76-10-01, LMM 76-10-01, LMM 76-10-01										
761330 NO. 1 ENGINE - ENGINE (DEEC) COMPUTER Component ATA:76										
PN:2118882-1008	MOS/MSC	01-Apr-10	O/C	TSN 0						
SN:20-BK0010	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: LMM 76-10-02, LMM 76-10-02, LMM 76-10-02										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty
---------	------	------	----------	-----------	--------------------------	-----------	-----------	-------------	-----	----------

ATA 76 - ENGINE CONTROLS

761330			NO. 2 ENGINE - ENGINE (DEEC) COMPUTER						Component	ATA:76
PN:2118882-1008	MOS/MSC	02-Apr-10	O/C	TSN 0						
SN:20-BK0009	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: LMM 76-10-02, LMM 76-10-02, LMM 76-10-02										

761330A			NO. 1 ENGINE - DOWNLOAD ENGINE (DEEC) COMPUTER ECTM						Service	ATA:76
PN:2118882-1008	MOS/MSC	08-Mar-20	A/R							
SN:20-BK0010	HRS	1550.5								
	ENC	1231								
PROC. REF: MSC CAMP EHM ADENDUM, LMM 76-10-02, LMM 72-00-00										

761330A			NO. 2 ENGINE - DOWNLOAD ENGINE (DEEC) COMPUTER ECTM						Service	ATA:76
PN:2118882-1008	MOS/MSC	08-Mar-20	A/R							
SN:20-BK0009	HRS	1550.5								
	ENC	1229								
PROC. REF: MSC CAMP EHM ADENDUM, LMM 76-10-02, LMM 72-00-00										

Y7600000 ^S			PERFORM ENGINE DEEC WIRE HARNESS SHIELD OVERBRAIDS AND SHIELD TERMINATIONS - VISUAL INSPECTION						Service	ATA:76
	MOS	20-Jan-23	48 (+14d/-14d)							
	HRS	1675	1200 (+25/-25)							
	AFL	1330								
PROC. REF: AMM 05-10-00										
										PKG:15

Y7600001 ^S			PERFORM THRUST LEVER CONTROL MODULE - FUNCTIONAL TEST						Service	ATA:76
	MOS	20-Jan-23	48 (+14d/-14d)							
	HRS	1675	1200 (+25/-25)							
	AFL	1330								
PROC. REF: AMM 76-10-02										
										PKG:13

Y7610007 ^S			PERFORM ENGINE CONTROL CABLES - VISUAL INSPECTION OF FORWARD AND AFT CABLE CONNECTION.						Service	ATA:76
	MOS	20-Jan-23	48 (+14d/-14d)							
	HRS	1675	1200 (+25/-25)							
	AFL	1330								
PROC. REF: AMM 05-10-00										
										PKG:14

ATA 77 - ENGINE INDICATING

770101			NO. 1 ENGINE - N1 MONOPOLE						Component	ATA:77
PN:PN	MOS/MSC	01-Apr-10	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: LMM 77-10-02										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 77 - ENGINE INDICATING										
770101	NO. 2 ENGINE - N1 MONOPOLE									Component ATA:77
PN:PN	MOS/MSC	02-Apr-10	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: LMM 77-10-02										
770110	NO. 1 ENGINE - N1 LEAD MONOPOLE									Component ATA:77
PN:PN	MOS/MSC	01-Apr-10	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: LMM 77-10-02										
770110	NO. 2 ENGINE - N1 LEAD MONOPOLE									Component ATA:77
PN:PN	MOS/MSC	02-Apr-10	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: LMM 77-10-02										
771210	NO. 1 ENGINE - N1 COMPENSATOR									Component ATA:77
PN:PN	MOS/MSC	01-Apr-10	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: LMM 77-10-03, LMM 77-10-03, LMM 77-10-03										
771210	NO. 2 ENGINE - N1 COMPENSATOR									Component ATA:77
PN:PN	MOS/MSC	02-Apr-10	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: LMM 77-10-03, LMM 77-10-03, LMM 77-10-03										
771220	NO. 1 ENGINE - N2 MONOPOLE									Component ATA:77
PN:PN	MOS/MSC	01-Apr-10	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: LMM 77-10-05, LMM 77-10-05, LMM 77-10-05										
771220	NO. 2 ENGINE - N2 MONOPOLE									Component ATA:77
PN:PN	MOS/MSC	02-Apr-10	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: LMM 77-10-05, LMM 77-10-05, LMM 77-10-05										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 77 - ENGINE INDICATING										
772210	NO. 1 ENGINE - ITT HARNESS ASSEMBLY									Component ATA:77
PN:PN	MOS/MSC	01-Apr-10	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: LMM 77-20-01, LMM 77-20-01, LMM 77-20-01, LMM 77-20-01										
772210	NO. 2 ENGINE - ITT HARNESS ASSEMBLY									Component ATA:77
PN:PN	MOS/MSC	02-Apr-10	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: LMM 77-20-01, LMM 77-20-01, LMM 77-20-01, LMM 77-20-01										
774001	ENGINE VIBRATION MONITOR BOX									Component ATA:77
PN:241-241-000-501	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:AD63638	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 77-41-01										
774010	P36 RELAY BOX									Component ATA:77
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 77-41-03										
774011	LEFT ENGINE VIBRATION ACCELEROMETER									Component ATA:77
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 77-41-02										
774012	RIGHT ENGINE VIBRATION ACCELEROMETER									Component ATA:77
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 77-41-02										
Y7741000 ^S	PERFORM ENGINE VIBRATION MONITORING SYSTEM - FUNCTIONAL TEST.									Service ATA:77
	MOS	11-Sep-18	96 (+ 14d/-14d)							
	HRS	1387.4	2400 (+ 25/-25)							
	AFL	1114								
PROC. REF: AMM 77-41-00										

PKG:21

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty
---------	------	------	----------	-----------	--------------------------	-----------	-----------	-------------	-----	----------

ATA 78 - EXHAUST

5-19-00-R7830007	PERFORM - THRUST REVERSER - PERFORM CONDUCTIVITY CHECK OF RH THRUST REVERSER DOOR SKIN AND COWL ADJACENT TO APU EXHAUST								Service	ATA:78
	MOS		20-Jan-11							
	HRS		0							
	AFL		0							
	APH		0		1200 (+25/-25)	1200	1225	326.6 (+25)		
PROC. REF: NDT PART 6/78-30-01										

783001	LEFT THRUST REVERSER								Component	ATA:78
PN:LJ7830101-5	MOS/MSC		20-Jan-11	O/C	TSN 0					
SN:A30040554	HRS		0		TSN 0					
	AFL		0		TSN 0					
PROC. REF: AMM 78-31-00										

783002	RIGHT THRUST REVERSER								Component	ATA:78
PN:LJ7830101-6	MOS/MSC		20-Jan-11	O/C	TSN 0					
SN:A30040554	HRS		0		TSN 0					
	AFL		0		TSN 0					
PROC. REF: AMM 78-31-00										

783025	TRANSFORMER/RECTIFIER ELECTRONIC CONTROL UNIT								Component	ATA:78
PN:PN	MOS/MSC		20-Jan-11	O/C	TSN 0					
SN:UNKNOWN	HRS		0		TSN 0					
	AFL		0		TSN 0					
PROC. REF: GENERIC NO REF										

783037	NO. 1 GPM HYDRAULIC CONTROL VALVE								Component	ATA:78
PN:PN	MOS/MSC		20-Jan-11	O/C	TSN 0					
SN:UNKNOWN	HRS		0		TSN 0					
	AFL		0		TSN 0					
PROC. REF: AMM 78-32-10										

783038	NO. 2 GPM HYDRAULIC CONTROL VALVE								Component	ATA:78
PN:PN	MOS/MSC		20-Jan-11	O/C	TSN 0					
SN:UNKNOWN	HRS		0		TSN 0					
	AFL		0		TSN 0					
PROC. REF: AMM 78-32-10										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 78 - EXHAUST										
783051	LEFT OUTBOARD THRUST REVERSER ACTUATOR									Component ATA:78
PN:LJ7833100-3/B	MOS/MSC	28-Dec-13	O/C	TSO 0						
SN:A30040751	HRS	796.9		TSO 0						
	AFL	723		TSO 0						
PROC. REF: AMM 78-32-20										
783052	LEFT INBOARD THRUST REVERSER ACTUATOR									Component ATA:78
PN:LJ7833100-4	MOS/MSC	11-Sep-18	O/C	TSO 0						
SN:A30041265	HRS	1387.4		TSO 0						
	AFL	1114		TSO 0						
PROC. REF: AMM 78-32-20										
783053	RIGHT INBOARD THRUST REVERSER ACTUATOR									Component ATA:78
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 78-32-20										
783054	RIGHT OUTBOARD THRUST REVERSER ACTUATOR									Component ATA:78
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 78-32-20										
783061	NO. 1 CONTROL, THRUST REVERSER HYDRAULIC VALVE									Component ATA:78
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 78-32-10										
783062	NO. 2 CONTROL, THRUST REVERSER HYDRAULIC VALVE									Component ATA:78
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 78-32-10										
783101	LEFT THRUST REVERSER HYDRAULIC ISOLATION VALVE									Component ATA:78
PN:LJ7835200-5	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:1246	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 78-30-02										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 78 - EXHAUST										
783102	RIGHT THRUST REVERSER HYDRAULIC ISOLATION VALVE									Component ATA:78
PN:LJ7835200-5	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:1234	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 78-30-02										
783150	LEFT HAND INBOARD LATCHBOX ACTUATOR									Component ATA:78
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 78-32-30										
783151	RIGHT HAND INBOARD LATCHBOX ACTUATOR									Component ATA:78
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 78-32-30										
783210	LEFT THRUST REVERSER CONTROL VALVE									Component ATA:78
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
783211	RIGHT THRUST REVERSER CONTROL VALVE									Component ATA:78
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
783220	NO. 1 ENGINE THROTTLE RETARD ACTUATOR									Component ATA:78
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 78-32-40										
783221	NO. 2 ENGINE THROTTLE RETARD ACTUATOR									Component ATA:78
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 78-32-40										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 78 - EXHAUST											
783301		LEFT THRUST REVERSER CONTROL BOX							Component	ATA:78	
PN:LJ7836706-3	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:00691	HRS	0	TSN 0								
	AFL	0	TSN 0								
PROC. REF: AMM 78-33-10											
783302		RIGHT THRUST REVERSER CONTROL BOX							Component	ATA:78	
PN:LJ7836706-3	MOS/MSC	20-Jan-11	O/C	TSN 0							
SN:00688	HRS	0	TSN 0								
	AFL	0	TSN 0								
PROC. REF: AMM 78-33-10											
783320		LEFT OUTBOARD THRUST REVERSER WIRE HARNESS							Component	ATA:78	
PN:PN	MOS/MSC	20-Jan-11	C/C	TSN 0							
SN:UNKNOWN	HRS	0	TSN 0								
	AFL	0	TSN 0								
PROC. REF: AMM 78-33-20											
783321		LEFT INBOARD THRUST REVERSER WIRE HARNESS							Component	ATA:78	
PN:PN	MOS/MSC	20-Jan-11	C/C	TSN 0							
SN:UNKNOWN	HRS	0	TSN 0								
	AFL	0	TSN 0								
PROC. REF: AMM 78-33-20											
783322		RIGHT INBOARD THRUST REVERSER WIRE HARNESS							Component	ATA:78	
PN:PN	MOS/MSC	20-Jan-11	C/C	TSN 0							
SN:UNKNOWN	HRS	0	TSN 0								
	AFL	0	TSN 0								
PROC. REF: AMM 78-33-20											
783323		RIGHT OUTBOARD THRUST REVERSER WIRE HARNESS							Component	ATA:78	
PN:PN	MOS/MSC	20-Jan-11	C/C	TSN 0							
SN:UNKNOWN	HRS	0	TSN 0								
	AFL	0	TSN 0								
PROC. REF: AMM 78-33-20											
D7830078 ^S	PERFORM ** THRUST REVERSER SYSTEM THROTTLE RETARD ACTUATOR - OPERATIONAL CHECK							Service	ATA:78		
	MOS	11-Sep-18	96 (+ 14d/-14d)					AIRWORTHINESS			
	HRS	1387.4	2400 (+ 25/-25)								
	AFL	1114									
PROC. REF: AMM 78-32-40											
PKG:21											

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 78 - EXHAUST											
H7830081 ^S			PERFORM THRUST REVERSERS - REMOVE LINK ROD ASSEMBLIES AND PERFORM MAGNETIC PARTICLE INSPECTION.						Service	ATA:78	
	MOS	11-Sep-18	96 (+ 14d/-14d)								
	HRS	1387.4	2400 (+ 25/-25)								
	AFL	1114									
			PROC. REF: NDT PART 7/78-30-01								PKG:21
H7830082 ^S			PERFORM THRUST REVERSERS - REMOVE THRUST REVERSER DOOR ASSEMBLIES AND PERFORM EDDY CURRENT INSPECTION OF PIVOT FITTING AND DOOR HINGES.						Service	ATA:78	
	MOS	11-Sep-18	96 (+ 14d/-14d)								
	HRS	1387.4	2400 (+ 25/-25)								
	AFL	1114									
			PROC. REF: NDT PART 6/78-30-02, NDT PART 6/78-30-03								PKG:21
Y7830000 ^S			PERFORM EXHAUST NOZZLE - VISUAL INSPECTION						Service	ATA:78	
	MOS	11-Sep-18	96 (+ 14d/-14d)								
	HRS	1387.4	2400 (+ 25/-25)								
	AFL	1114									
			PROC. REF: AMM 05-10-00								PKG:21
Y7830001 ^S			PERFORM THRUST REVERSER INNER FAN DUCT ASSEMBLY - VISUAL INSPECTION. INSPECT FROM EXHAUST END ONLY						Service	ATA:78	
	MOS	20-Jan-23	48 (+ 14d/-14d)								
	HRS	1675	1200 (+ 25/-25)								
	AFL	1330									
			PROC. REF: AMM 05-10-00								PKG:15
Y7830002 ^S			PERFORM THRUST REVERSER DOOR AND HINGE FITTINGS - VISUAL INSPECTION						Service	ATA:78	
	MOS	20-Jan-23	48 (+ 14d/-14d)								
	HRS	1675	1200 (+ 25/-25)								
	AFL	1330									
			PROC. REF: AMM 05-10-00								PKG:15
Y7830003 ^S			PERFORM THRUST REVERSER PRIMARY ACTUATOR AND LATCH ASSEMBLY - VISUAL INSPECTION						Service	ATA:78	
	MOS	20-Jan-23	48 (+ 14d/-14d)								
	HRS	1675	1200 (+ 25/-25)								
	AFL	1330									
			PROC. REF: AMM 05-10-00								PKG:15

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty
---------	------	------	----------	-----------	--------------------------	-----------	-----------	-------------	-----	----------

ATA 78 - EXHAUST

Y7830004 ^S			PERFORM THRUST REVERSER HYDRAULIC CONTROL VALVE (HCV), THROTTLE RETARD ACTUATOR, AND ASSOCIATED PLUMBING - VISUAL INSPECTION						Service	ATA:78
	MOS	20-Jan-23	48 (+ 14d/-14d)							
	HRS	1675	1200 (+ 25/-25)							
	AFL	1330								
					PROC. REF: AMM 05-10-00				PKG:15	

Y7830005 ^S			PERFORM THRUST REVERSER DOOR SEALS AND RETAINERS - VISUAL INSPECTION						Service	ATA:78
	MOS	20-Jan-23	48 (+ 14d/-14d)							
	HRS	1675	1200 (+ 25/-25)							
	AFL	1330								
					PROC. REF: AMM 05-10-00				PKG:15	

Y7830006 ^S			PERFORM THRUST REVERSER WIRE HARNESS - VISUAL INSPECTION.						Service	ATA:78
	MOS	20-Jan-23	48 (+ 14d/-14d)							
	HRS	1675	1200 (+ 25/-25)							
	AFL	1330								
					PROC. REF: AMM 05-10-00				PKG:15	

ATA 79 - OIL

790110			NO. 1 ENGINE - OIL PUMP						Component	ATA:79
PN:3060785-2	MOS/MSC	05-Nov-11	O/C							
SN:041405700276	HRS	229			TSN 2869.9, TSO 0					
	ENC	180			TSN 2008, TSO 0					
					PROC. REF: LMM 79-20-03					

790110			NO. 2 ENGINE - OIL PUMP						Component	ATA:79
PN:PN	MOS/MSC	02-Apr-10	O/C		TSN 0					
SN:UNKNOWN	HRS	0			TSN 0					
	ENC	0			TSN 0					
					PROC. REF: LMM 79-20-03					

790130 ^S			NO. 1 ENGINE - ANALYSIS OIL AND FILTER (SOAP)						Service	ATA:79
	MOS	20-Jan-23								
	HRS	1675	200 (+ 50/-50)							
	ENC	1335								
					PROC. REF: LMM 72-00-00				PKG:0	

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty		
ATA 79 - OIL												
790130 ^S			NO. 2 ENGINE - ANALYSIS OIL AND FILTER (SOAP)								Service	ATA:79
	MOS	20-Jan-23										
	HRS	1675	200 (+ 50/-50)									
	ENC	1333										
					PROC. REF: LMM 72-00-00					PKG:0		
790140 ^S			NO. 1 ENGINE - PERFORM OIL CHANGE								Service	ATA:79
	MOS	16-Dec-16										
	HRS	1162	1200 (+ 100/-200)									
	ENC	971										
					PROC. REF: LMM 72-00-00					PKG:0		
790140 ^S			NO. 2 ENGINE - PERFORM OIL CHANGE								Service	ATA:79
	MOS	16-Dec-16										
	HRS	1162	1200 (+ 100/-200)									
	ENC	969										
					PROC. REF: LMM 72-00-00					PKG:0		
790150 ^S			NO. 1 ENGINE - INSPECT CHIP DETECTOR FOR CONTAMINATION AND PERFORM RESISTANCE CHECK								Service	ATA:79
	MOS	11-Sep-18										
	HRS	1387.4	600 (+ 50/-100)									
	ENC	1122										
					PROC. REF: LMM 79-10-01, LMM 79-10-01					PKG:0		
790150 ^S			NO. 2 ENGINE - INSPECT CHIP DETECTOR FOR CONTAMINATION AND PERFORM RESISTANCE CHECK								Service	ATA:79
	MOS	11-Sep-18										
	HRS	1387.4	600 (+ 50/-100)									
	ENC	1120										
					PROC. REF: LMM 79-10-01, LMM 79-10-01					PKG:0		
790160 ^S			NO. 1 ENGINE - INSPECT CHIP DETECTOR FOR CONTAMINATION								Service	ATA:79
	MOS	20-Jan-23										
	HRS	1675	200 (+ 50/-50)									
	ENC	1335										
					PROC. REF: LMM 79-10-01, LMM 79-10-01					PKG:0		
790160 ^S			NO. 2 ENGINE - INSPECT CHIP DETECTOR FOR CONTAMINATION								Service	ATA:79
	MOS	20-Jan-23										
	HRS	1675	200 (+ 50/-50)									
	ENC	1333										
					PROC. REF: LMM 79-10-01, LMM 79-10-01					PKG:0		

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 79 - OIL											
791001			NO. 1 ENGINE - ENGINE OIL CHIP DETECTOR								Component ATA:79
PN:PN	MOS/MSC	08-Mar-20	O/C								
SN:UNKNOWN	HRS	1550.5									
	ENC	1231									
PROC. REF: LMM 79-10-01											
791001			NO. 2 ENGINE - ENGINE OIL CHIP DETECTOR								Component ATA:79
PN:PN	MOS/MSC	08-Mar-20	O/C								
SN:UNKNOWN	HRS	1550.5									
	ENC	1229									
PROC. REF: LMM 79-10-01											
792002			NO. 1 ENGINE - AIR BREATHER VALVE ASSEMBLY CHANGE								Component ATA:79
PN:PN	MOS/MSC	01-Apr-10	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	ENC	0		TSN 0							
PROC. REF: LMM 79-20-02											
792002			NO. 2 ENGINE - AIR BREATHER VALVE ASSEMBLY CHANGE								Component ATA:79
PN:PN	MOS/MSC	02-Apr-10	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	ENC	0		TSN 0							
PROC. REF: LMM 79-20-02											
792008			NO. 1 ENGINE - OIL FLOW REDUCTION VALVE								Component ATA:79
PN:PN	MOS/MSC	01-Apr-10	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	ENC	0		TSN 0							
PROC. REF: LMM 79-20-08											
792008			NO. 2 ENGINE - OIL FLOW REDUCTION VALVE								Component ATA:79
PN:PN	MOS/MSC	02-Apr-10	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	ENC	0		TSN 0							
PROC. REF: LMM 79-20-08											
792011			NO. 1 ENGINE - FUEL/OIL VALVE								Component ATA:79
PN:PN	MOS/MSC	01-Apr-10	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	ENC	0		TSN 0							
PROC. REF: LMM 79-30-01											

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 79 - OIL										
792011	NO. 2 ENGINE - FUEL/OIL VALVE									Component ATA:79
PN:PN	MOS/MSC	02-Apr-10	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: LMM 79-30-01										
792012	NO. 1 ENGINE - OIL TEMPERATURE REGULATOR									Component ATA:79
PN:PN	MOS/MSC	01-Apr-10	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: LMM 79-20-03										
792012	NO. 2 ENGINE - OIL TEMPERATURE REGULATOR									Component ATA:79
PN:PN	MOS/MSC	02-Apr-10	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: LMM 79-20-03										
792020	NO. 1 ENGINE - OIL CHECK VALVE ASSEMBLY									Component ATA:79
PN:PN	MOS/MSC	01-Apr-10	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
792020	NO. 2 ENGINE - OIL CHECK VALVE ASSEMBLY									Component ATA:79
PN:PN	MOS/MSC	02-Apr-10	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
792037	NO. 1 OIL PRESSURE SWITCH									Component ATA:79
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 79-30-02										
792038	NO. 2 OIL PRESSURE SWITCH									Component ATA:79
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 79-30-02										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 79 - OIL											
792220			NO. 1 ENGINE - UPPER OIL COOLER ASSEMBLY						Component		ATA:79
PN:PN	MOS/MSC	01-Apr-10	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	ENC	0		TSN 0							
PROC. REF: LMM 79-20-10											
792220			NO. 2 ENGINE - UPPER OIL COOLER ASSEMBLY						Component		ATA:79
PN:PN	MOS/MSC	02-Apr-10	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	ENC	0		TSN 0							
PROC. REF: LMM 79-20-10											
792230			NO. 1 ENGINE - LOWER LEFT OIL COOLER ASSEMBLY						Component		ATA:79
PN:PN	MOS/MSC	01-Apr-10	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	ENC	0		TSN 0							
PROC. REF: LMM 79-20-10											
792230			NO. 2 ENGINE - LOWER LEFT OIL COOLER ASSEMBLY						Component		ATA:79
PN:PN	MOS/MSC	02-Apr-10	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	ENC	0		TSN 0							
PROC. REF: LMM 79-20-10											
792240			NO. 1 ENGINE - LOWER RIGHT OIL COOLER ASSEMBLY						Component		ATA:79
PN:PN	MOS/MSC	01-Apr-10	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	ENC	0		TSN 0							
PROC. REF: LMM 79-20-10											
792240			NO. 2 ENGINE - LOWER RIGHT OIL COOLER ASSEMBLY						Component		ATA:79
PN:PN	MOS/MSC	02-Apr-10	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	ENC	0		TSN 0							
PROC. REF: LMM 79-20-10											
792250			NO. 1 ENGINE - PRESSURE BREATHER VALVE						Component		ATA:79
PN:PN	MOS/MSC	01-Apr-10	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	ENC	0		TSN 0							
PROC. REF: LMM 79-20-02											

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 79 - OIL										
792250	NO. 2 ENGINE - PRESSURE BREATHER VALVE									Component ATA:79
PN:PN	MOS/MSC	02-Apr-10	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: LMM 79-20-02										
792260	NO. 1 ENGINE - OIL TEMPERATURE CONTROL VALVE									Component ATA:79
PN:PN	MOS/MSC	01-Apr-10	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: LMM 79-30-01										
792260	NO. 2 ENGINE - OIL TEMPERATURE CONTROL VALVE									Component ATA:79
PN:PN	MOS/MSC	02-Apr-10	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: LMM 79-30-01										
793001	NO. 1 ENGINE OIL PRESSURE TRANSDUCER									Component ATA:79
PN:7679300000-001	MOS/MSC	01-Sep-11	O/C							
SN:7583-15-680	HRS	193.4								
	AFL	130								
PROC. REF: AMM 79-30-01										
793002	NO. 2 ENGINE OIL PRESSURE TRANSDUCER									Component ATA:79
PN:7679300000-001	MOS/MSC	01-Sep-11	O/C							
SN:7528-2-221	HRS	193.4								
	AFL	130								
PROC. REF: AMM 79-30-01										
793011	LEFT TEMPERATURE OIL BULB									Component ATA:79
PN:MS28034-3	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:N3474	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 79-30-03										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 79 - OIL										
793012	RIGHT TEMPERATURE OIL BULB									Component ATA:79
PN:MS28034-3	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:N3479	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 79-30-03										
793013	APU TEMPERATURE OIL BULB									Component ATA:79
PN:PN	MOS/MSC	20-Jan-11	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 79-30-03										
793064	NO. 1 ENGINE - TEMP BULB									Component ATA:79
PN:PN	MOS/MSC	01-Apr-10	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
793064	NO. 2 ENGINE - TEMP BULB									Component ATA:79
PN:PN	MOS/MSC	02-Apr-10	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
793310	NO. 1 ENGINE - OIL FILTER BYPASS VALVE									Component ATA:79
PN:PN	MOS/MSC	01-Apr-10	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: LMM 79-30-01										
793310	NO. 2 ENGINE - OIL FILTER BYPASS VALVE									Component ATA:79
PN:PN	MOS/MSC	02-Apr-10	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: LMM 79-30-01										
793315 ^S	NO. 1 ENGINE - CHECK OIL FILTER BYPASS VALVE CIRCUIT/THERMAL LOCKOUT SWITCH									Service ATA:79
	MOS/MSC	01-Apr-10	N/A							
	HRS	0								
	ENC	0								
PROC. REF: LMM 79-30-01										
										PKG:0

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-416 RegNo: N450FC HRS: 1675 AFL: 1330 As Of: 20-Jan-2023

08-Feb-2023 02:13 PM

PN & SN	Unit	C/ W	Interval	TSX/ Adj.	Next Due (ENG/ APU) A/ C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 79 - OIL											
793315 ^S			NO. 2 ENGINE - CHECK OIL FILTER BYPASS VALVE CIRCUIT/THERMAL LOCKOUT SWITCH						Service	ATA:79	
	MOS/MSC	02-Apr-10	N/A								
	HRS	0									
	ENC	0									
PROC. REF: LMM 79-30-01										PKG:0	
793316			NO. 1 ENGINE - THERMO LOCKOUT VALVE SWITCH ASSEMBLY						Component	ATA:79	
PN:PN	MOS/MSC	01-Apr-10	O/C	TSN	0						
SN:UNKNOWN	HRS	0		TSN	0						
	ENC	0		TSN	0						
PROC. REF: GENERIC NO REF											
793316			NO. 2 ENGINE - THERMO LOCKOUT VALVE SWITCH ASSEMBLY						Component	ATA:79	
PN:PN	MOS/MSC	02-Apr-10	O/C	TSN	0						
SN:UNKNOWN	HRS	0		TSN	0						
	ENC	0		TSN	0						
PROC. REF: GENERIC NO REF											
793320			NO. 1 ENGINE - FUEL HEATER / OIL COOLER ASSEMBLY						Component	ATA:79	
PN:PN	MOS/MSC	01-Apr-10	O/C	TSN	0						
SN:UNKNOWN	HRS	0		TSN	0						
	ENC	0		TSN	0						
PROC. REF: LMM 79-20-07											
793320			NO. 2 ENGINE - FUEL HEATER / OIL COOLER ASSEMBLY						Component	ATA:79	
PN:PN	MOS/MSC	02-Apr-10	O/C	TSN	0						
SN:UNKNOWN	HRS	0		TSN	0						
	ENC	0		TSN	0						
PROC. REF: LMM 79-20-07											
ATA 85 - FUEL CELL SYSTEMS											
859000			SUBMIT LOGBOOK ENTRIES FOR ELOGBOOK						Service	ATA:85	
	MOS/MSC	20-Jan-11	A/R								
	HRS	0									
	AFL	0									
PROC. REF: GENERIC NO REF											

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/ W (M)-Manual Due U-User Task Ex-Excluded Task